



Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist
Ron Jones

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B000375
Date Received: 05/07/98
Date Analyzed: 05/09/98

Job ID / Site: Jay Partridge/Kitchen Roof

FASI Job ID: 2921-7

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
JP98421-1R	19804329						
Layer: Off-White Stones			ND				
Layer: Black Tar			ND				
Layer: Black Fibrous Tar			ND				
Layer: Black Tar			ND				
Layer: Black Fibrous Tar			ND				
Layer: Tan Fibrous Material			ND				

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (40%) Fibrous Glass (ND)
Comment: Bulk complex sample.

JP98421-2R	19804330						
Layer: Black Fibrous Tar			ND				
Layer: Black Tar			ND				
Layer: Black Fibrous Tar			ND				
Layer: Black Tar			ND				
Layer: Black Fibrous Tar			ND				
Layer: Black Tar			ND				
Layer: Tan Fibrous Material			ND				

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (45%) Fibrous Glass (ND)
Comment: Bulk complex sample.


Dave Sandusky, Laboratory Director, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full with approval from Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.



BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: 530-891-3194 FAX: 530-891-3194	DATE: 5-4-98
		Circle the Method and Turn Around Time ____ hr/12hr/24hr/48hr/Ext	Results Needed: 5-11-98 1:30pm
		PLM: <u>Standard</u> Point Count	By FAX Gravimetry Prep
		CONTACT: RON JONES	
P.O.# NONE	JOB #	TEM: QUAL. / QUANT. / WATER	
SITE: JAY PARTRIDGE Kitchen Roof		AA/Flame AA/Furnace ICP	
		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
JP98421-1R	4/21/98	Roofing System, Lower Roof, NE corner, behind kitchen. Unit C
JP98421-2R	4/21/98	Roofing System, Center of lower roof behind kitchen. Unit C
		NOTE: Please analyze these samples for asbestos,
		using the PLM method, and reporting by layer.

Sampled by: JIM RICH / EOS ENVIRONMENTAL		Date: 4/21/98	Time: 7:00 p.m.
Relinquished by: JIM RICH		Received By: RON JONES	
Date/Time: 5-4-98 10:00 p.m.		Date/Time: 5-4-98 10:00 p.m.	
		Sealed Condition (circle one) YES / NO	
Relinquished by: RON JONES		Received By: Airborne Express	
Date/Time: 5-5-98 3:00 p.m.		Date/Time: 5-6-98 3:00 p.m.	
		Sealed Condition (circle one) YES / NO	

RECEIVED MAY 07 1998

Hans

APX

SIX-MONTH SURVEILLANCE

Page 1 of 2

DISTRICT Chico Unified School District

DATE December 19, 1996

SCHOOL J. Partridge Elementary

INSPECTOR Rob Peters

R.P.

HOMOG. ASBESTOS

MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

A	9" VFT	1-5	All Rooms	1-4	
A	AC Plas	1-5	Classrooms	5-8 (rm 7&9 slight wall damage - old)	
A	AC Plas	1-5	Staff Room	1-4	
A	L mud jnt	Assumed	Boiler Room	5-8 PW STR - WO issued	
A	S mud jnt	Assumed	Boiler Room	1-4	
A	Tran panl	Assumed	Under Entry Windows	1-4	
B	9" VFT	1-5	All Rooms	1-4	
B	AC Plas	1-5	All Rooms	5-8 Rms 12,13,14 slight wall damage - old	
C	PW Str	70-75	MPR Storage Rooms	1-4	
C	PW Str	70-75	Kitchen Water Heater Room	1-4	
C	9" VFT Gn	1-5	Kitchen & MPR	1-4	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

POSTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 2

DISTRICT Chico Unified School District

DATE December 19, 1996

9/16/98

SCHOOL J. Partridge Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
C	Mud Jnts	Assumed	By Dishwasher	1-4
C	9" VFT Gn	1-5	All Rooms	1-4
C	AD Plas	1-5	RR, Hall, MPR, Classrm 12, Kindergarten	1-4
C	Tran Pipe	Assumed	Kitchen Water Heater Room	1-4
D	Drywall	None Detected	All Rooms	
D	2x4 FCPS	None Detected	All Rooms	
*			New Portable	No Letter

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 1 of 2

DISTRICT Chico Unified School District

DATE December 11, 1995

1-2-98

SCHOOL J. Partridge Elementary

INSPECTOR Ron Jones

HOMOG. ASBESTOS

BLDG. MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

A	9" VFT	1-5	All Rooms	1-4	
A	AC Plas	1-5	Classrooms	1-4	(rm 7&9 slight wall damage - old)
A	AC Plas	1-5	Staff Room	1-4	
A	L mud jnt	Assumed	Boiler Room	1-4	
A	S mud jnt	Assumed	Boiler Room	1-4	
A	Tran panl	Assumed	Under Entry Windows	1-4	
B	9" VFT	1-5	All Rooms	1-4	
B	AC Plas	1-5	All Rooms	1-4	Rms 12,13,14 slight wall damage - old
C	PW Str	70-75	MPR Storage Rooms	1-4	
C	PW Str	70-75	Kitchen Water Heater Room	1-4	
C	9" VFT Gn	1-5	Kitchen & MPR	1-4	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

2 in Larry's closed or close ceiling

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 2

DISTRICT Chico Unified School District

DATE December 11, 1995

1-2-98

SCHOOL J. Partridge Elementary

INSPECTOR Ron Jones

BLDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

C	Mud Jnts	Assumed	By Dishwasher	1-4	✓
C	9" VFT Gn	1-5	All Rooms	1-4	✓
C	AD Plas	1-5	RR, Hall, MPR, Classrm 12, Kindergarten	1-4	✓
C	Tran Pipe	Assumed	Kitchen Water Heater Room	1-4	✓
D	Drywall	None Detected	All Rooms		✓
D	2x4 FCPs	None Detected	All Rooms		✓
*			New Portable	No Letter	✓

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

EOS ENVIRONMENTAL, INC.

ENVIRONMENTAL AND OCCUPATIONAL HEALTH SERVICES

507 MISSION STREET, SOUTH PASADENA, CA 91030
TEL. (626) 441-7050 * FAX (626) 441-0016

2110-21ST STREET #150, SACRAMENTO, CA 95814
TEL. (916) 452-5884 * FAX (916) 452-5912

**AHERA RE-INSPECTION
DOCUMENTATION**

CHICO UNIFIED SCHOOL DISTRICT

**1998
Asbestos Three Year Re-Inspection**

PARTRIDGE ELEMENTARY SCHOOL

APRIL 9, 1998

TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY**
- II. MATERIAL INVENTORY**
- III. POSITIVE MATERIAL LIST**
- IV. MISSING MATERIAL LIST**
- V. DIAGRAMS**
- VI. FIELD NOTES**
- VII. INSPECTOR'S QUALIFICATIONS**

EXECUTIVE SUMMARY

EXECUTIVE SUMMARY

On April 9 , 1998 , EOS Environmental, Inc. performed a visual re-inspection for asbestos containing building materials, (ACBM) at Partridge Elementary. The purpose of the re-inspection was to comply with the U. S. Environmental Protection Agency (EPA) CRF 763 - AHERA requirement for a three year re-inspection.

Prior to the re-inspection, previous inspection reports were reviewed in order to determine which building materials had been previously tested and found to be asbestos containing, which were found not to contain asbestos, and if any materials had not been tested.

After the review of previous building inspections, a complete visual walk-through inspection of the site was performed. The visual inspection determined that conditions at Partridge were such that all non friables and friables were in good condition at the time of this inspection.

Sampling was done at Partridge. All samples were negative for ACBM's. See Lab report under Field Notes.

MATERIAL INVENTORY

MATERIAL CODES

ACS - Acoustical Ceiling Spray
ACT - Acoustical Ceiling Tile
ACP - Acoustical Ceiling Panels
AIR - Air Cell
ASF - Asphalt
ASP - Asbestos Paper
BBM - Baseboard Mastic
BOI - Boiler Insulation
BOL - Blown-In Insulation
BRK - Brick
BUR - Built-up Roofing
CAP - Cement Asbestos Pipe
CAS - Cement Asbestos Siding
CIN - Cinder Block
CEM - Cement
CER - Ceramic
CUR - Curtains
DEB - Debris
DRY - Drywall
DTM - Drywall Taping Mud
ELB - Pipe Elbow (fittings)
EXP - Exterior Panels
FIR - Fire Rated Brick
FLT - Floor Tile
FRD - Fire Rated Door
FUR - Furnace Pad
GAS - Gasket
MAS - Mastic
MIS - Miscellaneous
MOR - Mortar
P/C - Pipe Cover
PLA - Plaster
SFL - Vinyl Floor Sheeting
SFP - Sprayed-on Fireproofing
SOL - Soil
STC - Stucco
TAP - Tape
TAR - Tar
RFS - Composite Roofing Shingles
RFT - Roofing Felt
ROL - Rolled Roofing Material
WOV - Woven Cloth Joint Expansion
WPY - Window Putty

MATERIAL INVENTORY

Pg. 1

Partridge Elementary School

4-9-98

 James M. Rich
 # 96-2035

MAT. CODE	DESCRIPTION OF MATERIAL	AREA FOUND	CAT.	FRI.	ORIGINAL AMOUNT	AMOUNT LEFT	HAS AB.
FLT	9" VFT	Bldg. A All Rooms	MISC	No	9000 SF	9000 SF	Yes
PLA	AC Plaster	Bldg. A Classrooms	SUR	No	3200 SF	3200 SF	Yes
PLA	AC Plaster	Bldg. A Staff Room	SUR	No	288 SF	288 SF	Yes
ELB	Lg. Pipe Fitting	Bldg. A Boiler Rm.	TSI	No	22 ea.	22 ea.	As.
ELB	Sm. Pipe Fitting	Bldg. A Boiler Rm.	TSI	No	26 ea.	26 ea.	As.
EXP	Transite Panels	Bldg. A Under Entry Windows	MISC	No	?	?	As.
FLT	9" VFT	Bldg. B All Rooms	MISC	No	2800 SF	2800 SF	Yes
PLA	AC Plaster	Bldg. B All Rooms	SUR	No	1600 SF	1600 SF	Yes
P/C	Pipe Covering	Bldg. C MPR Stor. Rm.	TSI	No	80 LF	80 LF	Yes
P/C	Pipe Covering	Bldg. C Kit., Wtr. Htr. Rm.	TSI	No	157 LF	157 LF	Yes
FLT	9" VFT Green	Bldg. C Kit., MPR	MISC	No	?	?	Yes

Pg. 2

James M. Rich
96-2035

4-9-98

[illegible]

POSITIVE MATERIAL LIST

POSITIVE MATERIALS

Pg. 1

Partridge Elementary School

James M. Rich
96-2035

4-9-98

AREA NAME	SPACE NAME	ORIG. AMOUNT	AMOUNT LEFT	UNIT	MAT. CODE	UNIT PRICE	BUDGET CALC.
Bldg. A	All Rooms	9000 SF	9000 SF	SF	FLT		
Bldg. A	Classrooms	3200 SF	3200 SF	SF	PLA		
Bldg. A	Staff Room	288 SF	288 SF	SF	PLA		
Bldg. A	Boiler Rm.	22 ea.	22 ea.	ea.	ELB		
Bldg. A	Boiler Rm.	26 ea.	26 ea.	ea.	ELB		
Bldg. A	Under Entry Windows	?	?	SF	EXP		
Bldg. B	All Rooms	2800 SF	2800 SF	SF	FLT		
Bldg. B	All Rooms	1600 SF	1600 SF	SF	PLA		
Bldg. C	MPR Stor. Rm.	80 LF	80 LF	LF	P/C		
Bldg. C	Kit., Wtr. Htr. Rm.	157 LF	157 LF	LF	P/C		
Bldg. C	Kit., MPR	?	?	SF	FLT		

Partridge Elementary School

James M. Rich
96-2035

4-9-98

[illegible]

MISSING MATERIAL LIST

MISSING MATERIALS

Pg. 1


Partridge Elementary School

James M. Rich
96-2035

4-9-98

[illegible]

DIAGRAMS



JAY E. PARTRIDGE ELEMENTARY

FIELD NOTES

These levels should be used to establish both immediate and long range plans to act on the recommendations. The Priority Levels were selected for one of the following options:

Priority Level 1 - Isolate area, restrict access and respond as soon as possible.

Priority Level 2 - Schedule Response Action as soon as possible, reduce potential for disturbance.

Priority Level 3 - Schedule response Action as soon as practical, reduce potential for disturbance.

Priority Level 4 - Schedule Response Action as soon as practical.

Priority Level 5 - Schedule Response Action upon upgrade of system or material.

Cleaning Levels:

Level 1 - Initial cleaning should be done as soon as possible and additional cleaning should be done once every two months until the ACM is removed.

Level 2 - Initial cleaning should be done as soon as possible and additional cleaning should be done once every six months until the ACM is removed.

Level 3 - The material is non-friable therefore initial or additional cleaning is not necessary.

Level 4 - Initial or additional cleaning is not required for this material.

RESPONSE ACTIONS AND PRIORITY LEVELS:

Response Actions have been recommended for all friable or assumed friable ACM that was found during the inspection. The Response Actions were selected from one of the following options:

1. Removal
2. Repair
3. Enclosure
4. Encapsulation
5. Operations and Maintenance Program
6. Periodic Surveillance

Inspector:

J.R.

Cert. #

96-2035

Inspection Date

4-9-98

Site:

Partridge

Material				Area:					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
							1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

NO FRIABLES on site

Inspector:

Cert. #

Inspection Date

Site:

Material				Area:					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
							1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector:

Cert. #

Inspection Date

Site:

Material				Area:					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
							1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector:

Cert. #

Inspection Date

Site:

Material				Area:					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
							1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

Jay Partridge 4-21-98 19:00

1-R Roofing System NE Corner - Lower Roof
behind Kitchen Unit ~~C~~ C
Not Tested
und 34 Report

2-R Roofing System center of Roof (Lower)
behind Kitchen Unit ~~C~~ C

1-S Stucco (Wall) NE Corner Unit ~~C~~ C Beside Kitchen

2-S Stucco (Wall) NE Corner Unit D - Library

3-S Stucco (Wall) N Corner Unit B by ^{Class} Room 14

4-S Stucco (Wall) NW Corner Unit A by Boys RR

5-S Stucco (Wall) N Corner Unit C By Kind. Room 2

EMSL Analytical, Inc.

1720 S. Amphlett Blvd., Suite 130

San Mateo, CA 94402

Phone: (650) 570-5401 Fax: (650) 570-5402

EMSL

Attn.: Marc/ Jim

EOS Environmental Inc.

2110 21st Street

Suite #150

Sacramento, CA 95814

Thursday, May 28, 1998

Ref Number: CA982772

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: CUSD-Jay Partridge Elementary School/S 500

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	NONFIBROUS
JP98421-1/STC	Unit C-North East Corner by Kitchen (Stucco)	Tan Fibrous Heterogeneous	Crushed	None Detected		5% Cellulose	40% Quartz 20% Gypsum 35% Matrix
JP98421-2/STC	Unit D-North East Corner-(Stucco)	Tan Fibrous Heterogeneous	Crushed	None Detected		5% Cellulose	45% Quartz 20% Gypsum 30% Matrix
JP98421-3/STC	Unit B- North Corner by Classroom # 14 (Stucco)	Tan Fibrous Heterogeneous	Crushed	None Detected		5% Cellulose	40% Quartz 25% Gypsum 30% Matrix
JP98421-4/STC	Unit A-North West Corner by Boy's Restroom (Stucco)	Tan Fibrous Heterogeneous	Crushed	None Detected		5% Cellulose	35% Quartz 25% Gypsum 35% Matrix
JP98421-5/STC	Unit C-North Corner by Kindergarden Rm # 2 (Stucco)	Tan Fibrous Heterogeneous	Crushed	None Detected		5% Cellulose	40% Quartz 20% Gypsum 35% Quartz

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method


Ryan Cozart
Analyst

Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



EMSL Analytical, Inc
 1720 S. Amphlett Blvd., Suite 130, San Mateo, CA 94402
 Phone (415) 570-5401 Fax (415) 570-5402 Pager (415) 578-5620



CHAIN OF CUSTODY

EMSL Representative: _____

Your Company Name: _____

EMSL-Bill to: _____

Street: _____

E.O.S. Environmental, Inc.

Street: _____

Box #: _____

2110 21st Street #150

Box #: _____

City/State: _____

Sacramento, CA Zip 95818

City/State: _____

Zip: _____

Phone Results to: Name _____

Telephone #: _____

Marc / Jim(916) 452-5884

Fax Results to: Name _____

Fax Number: _____

Marc / Jim(916) 452-5912

Project Name/Number: _____

CUSP - Jay Partridge
Elementary School / 8500

Purchase Order #: _____

MATRIX

- | | | |
|--|---|-------------------------------|
| ☐ Air | ☐ Floor Tile | ☐ Soil |
| ☒ Bulk | ☐ Drinking Water | ☐ Dust |
| ☐ Wipe | ☐ Wastewater | |

TURNAROUND

- | | | | |
|--|-----------------------------------|----------------------------------|------------------------------------|
| ☐ 6-10 Days | ☐ 72 Hours | ☐ 24 Hour | ☐ Same Day* |
| ☒ 5 Days | ☐ 48 Hours | ☐ 12 Hour | ☐ 6 Hours |
- *S.D. - A.M. delivery by Fed. Ex. Results by Mid-night or earlier

- NIOSH**
- ☒ NIOSH 7400
- ☐ OSHA
- ☐ Other: _____

- TEM AIR**
- ☐ AHERA
- ☐ NIOSH 7402
- ☐ Level I
- ☐ Level II

- TEM WATER**
- ☐ Wastewater
- ☐ Drinking Water EPA 100.2
- ☐ Water - NY Wastewater
- ☐ Water-NY Drinking Water

- PLM**
- ☒ EPA 600
- ☐ NOB
- ☐ Point Count
- ☐ Other: _____

- TEM BULK**
- ☐ Drop Mount (Qualitative)
- ☐ Chatfield
- ☐ Chatfield / SEM QC
- ☐ Conventional (Quantitative)
- ☐ EMSL Method
- ☐ NOB
- ☐ NOB / SEM QC
- ☐ Micro Vac - Quantitative
- ☐ Micro Vac - Qualitative

- TEM WIPE**
- ☐ Quantitative
- ☐ Qualitative

- SEM**
- ☐ Qualitative
- ☐ Quantitative

- XRD**
- ☐ Asbestos
- ☐ Silica

OTHER

☐ _____

Client Sample # (s) _____

JP98421-1/STC • JP98421-5/STC

Total Samples: _____

5

Relinquished: _____

Date: 5-19-98Time: 5:00

Received: _____

Date: 5/21/98Time: 9:05am

Received: _____

Date: _____

Time: _____

NOTE: Please duplicate this form and use additional sheets if necessary.

INSPECTOR'S QUALIFICATIONS

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT
2211 Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 FAX (916) 483-0572



608302035C

128 132

September 18, 1997

James Rich
E.O.S. Environmental Inc.
2110 21st Street, Suite 150
Sacramento, CA 95818

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. To maintain your certification, please abide by the rules printed on the back of the certification card.

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist

RA/dor

Attachment

cc: File

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

James M. Rich

Name

Certification No. 86-2035

Expires on 11/8/98

This certification was issued by the Division of Occupational Safety and Health as authorized by Section 7100 of the Business and Professions Code.