## SIX-MONTH SURVEILLANCE

Page 1 of 1

25-91-6 STATEMENTS A GOOD . MOTHITAINON 1996 INSPECTOR Rob Peters December 17. DATE DISTRICT Chico Unified School District ASBESTOS District Office HOMOG. SCHOOL

CONDITION: CODE & COMMENTS	1-4	10	10	10					
LOCATION	Computer Room Office	Basement Crawl Space	Basement Crawl Space	Basement Crawl Space		•			
MATERIAL	1-5%	80-85%	10-15%	25-35%					
MAT.#	9" VFT	PW Str	PW Jnt	PW Debris					
BLDG.	Т	П	ᇤ	1					

### CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (2) DAMAGED

(4) NO

(1) GOOD

GENERAL CONDITION:

CHANGE IN CONDITION:

(5) YES (IF YES, EXPLAIN UNDER COMMENTS)

<u>ABATED</u>: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED



(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

86-62

# SIX-MONTH SURVEILLANCE

Page 1 of 1

1-27-98

INSPECTOR Ron Jones. DATE DISTRICT Chico Unified School District SCHOOL District Office

CONDITION: CODE & COMMENTS	7-4 7	10 €	10 %	10 €				
LOCATION	Computer Room Office	Basement Crawl Space	Basement Crawl Space	Basement Crawl Space				
ASBESTOS MATERIAL LOCATION	1-5%	80-85%	10-15%	25-35%				
HOMOG. MAT.#	9" VFT	PW Str	PW Jnt	PW Debris				
BLDG.	Н	П	1	1				

## CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (1) GOOD (2) DAMAGED

GENERAL CONDITION:

- (5) YES (IF YES, EXPLAIN UNDER COMMENTS) (4) NO CHANGE IN CONDITION:
- <u>ABATED</u>: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

### EOS ENVIRONMENTAL, INC. ENVIRONMENTAL AND OCCUPATIONAL HEALTH SERVICES

507 MISSION STREET, SOUTH PASADENA, CA 91030 TEL. (626) 441-7050 \* FAX (626) 441-0016

2110-21ST STREET #150, SACRAMENTO, CA 95814 TEL. (916) 452-5884 \* FAX (916) 452-5912

### AHERA RE-INSPECTION DOCUMENTATION

CHICO UNIFIED SCHOOL DISTRICT

1998 Asbestos Three Year Re-Inspection

DISTRICT OFFICE

**APRIL 13, 1998** 

### TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY
- II. MATERIAL INVENTORY
- III. POSITIVE MATERIAL LIST
- IV. MISSING MATERIAL LIST
- V. DIAGRAMS
- VI. FIELD NOTES
- VII. INSPECTOR'S QUALIFICATIONS

### **EXECUTIVE SUMMARY**

### **EXECUTIVE SUMMARY**

On April 13, 1998, EOS Environmental, Inc. performed a visual re-inspection for asbestos containing building materials, (ACBM) at District Office. The purpose of the re-inspection was to comply with the U. S. Environmental Protection Agency (EPA) CRF 763 - AHERA requirement for a three year re-inspection.

Prior to the re-inspection, previous inspection reports were reviewed in order to determine which building materials had been previously tested and found to be asbestos containing, which were found not to contain asbestos, and if any materials had not been tested.

After the review of previous building inspections, a complete visual walk-through inspection of the site was performed. The visual inspection determined that conditions at District Office were such that all non friables were in good condition. All friables were also in good condition at the time of this inspection.

### **MATERIAL INVENTORY**

### MATERIAL CODES

ACS - Acoustical Ceiling Spray

ACT - Acoustical Ceiling Tile

ACP - Acoustical Ceiling Panels

AIR - Air Cell

ASF - Asphalt

ASP - Asbestos Paper

BBM - Baseboard Mastic

**BOI** - Boiler Insulation

**BOL** - Blown-In Insulation

**BRK** - Brick

BUR - Built-up Roofing

CAP - Cement Asbestos Pipe

CAS - Cement Asbestos Siding

CIN - Cinder Block

**CEM - Cement** 

**CER - Ceramic** 

**CUR - Curtains** 

**DEB** - Debris

DRY - Drywall

DTM - Drywall Taping Mud

ELB - Pipe Elbow (fittings)

**EXP** - Exterior Panels

FIR - Fire Rated Brick

FLT - Floor Tile

FRD - Fire Rated Door

FUR - Furnace Pad

GAS - Gasket

MAS - Mastic

MIS - Miscellaneous

MOR - Mortar

P/C - Pipe Cover

PLA - Plaster

SFL - Vinyl Floor Sheeting

SFP - Sprayed-on Fireproofing

SOL - Soil

STC - Stucco

TAP - Tape

TAR - Tar

RFS - Composite Roofing Shingles

RFT - Roofing Felt

**ROL - Rolled Roofing Material** 

WOV - Woven Cloth Joint Expansion

WPY - Window Putty

District Office

4-13-98

James M, Rich # 96-2035

MAT.	DESCRIPTION OF MATERIAL	AREA FOUND	CAT.	FRI.	ORIGINAL AMOUNT	AMOUNT LEFT	HAS AB.
FLT	9" VFT Beige	Bldg. 1 Computer Rm. Office	MISC	No	100 SF	100 SF	Yes
P/C	Pipe Covering	Bldg. 1 Basement Crawl Sp.	TSI	Yes	350 LF	350 LF	Yes
ELB	Pipe Fittings	Bldg. 1 Basement Crawl Sp.	TSI	Yes	25 ea.	25 ea.	Yes
DEB	Pipe Covering Debris	Bldg. 1 Basement Crawl Sp.	TSI	Yes	250 SF	250 SF	Yes
					}		



District Office

James M. Rich # 96-2035 4-13-98

				-	" OO 22		
AREA NAME	SPACE NAME	ORIG. AMOUNT	AMOUNT LEFT	UNIT	MAT.	UNIT PRICE	BUDGET CALC.
Bldg. 1	Computer Rm. Office	100 SF	100 SF	SF	FLT		
Bldg. 1	Basement Crawl Sp.	350 LF	350 LF	LF	P/C		
Bldg. 1	Basement Crawl Sp.	25 ea.	25 ea.	ea.	ELB		
Bldg. 1	Basement Crawl Sp.	250 SF	250 SF	ŞF	DEB		
							-
							,



District Office

James M. Rich # 96-2035

4-13-98

MAT.	DESCRIPTION	LOCATION	AMOUNT REMOVED	AMOUNT LEFT
CODE			KENIOVED	
	No missing materials this		į	
	No missing materials this report based on 1995 report.			
			1	
	,			
			}	
				]
			,	1
			-	
}				
				1
			1	ļ
ļ	-		ļ	
<u> </u>				
}				
Ì			Ì	
	1	i		1
Ì			1	
			1	
		1		
1				
				}
		1		
	}			1
			<u> </u>	<del> </del>
		l	<u> </u>	



### **FIELD NOTES**

These levels should be used to establish both immediate and long range plans to act on the recommendations. The Priority Levels were selected for one of the following options:

- Priority Level 1 Isolate area, restrict access and respond as soon as possible.
- Priority Level 2 Schedule Response Action as soon as possible, reduce potential for disturbance.
- Priority Level 3 Schedule response Action as soon as practical, reduce potential for disturbance.
- Priority Level 4 Schedule Response Action as soon as practical.
- Priority Level 5 Schedule Response Action upon upgrade of system or material.

### Cleaning Levels:

- Level 1 Initial cleaning should be done as soon as possible and additional cleaning should be done once every two months until the ACM is removed.
- Level 2 Initial cleaning should be done as soon as possible and additional cleaning should be done once every six months until the ACM is removed.
- Level 3 The material is non-friable therefore initial or additional cleaning is not necessary.
- Level 4 Initial or additional cleaning is not required for this material.

### RESPONSE ACTIONS AND PRIORITY LEVELS:

Response Actions have been recommended for all friable or assumed friable ACM that was found during the inspection. The Response Actions were selected from one of the following options:

- 1. Removal
- 2. Repair
- 3. Enclosure
- 4. Encapsulation
- 5. Operations and Maintenance Program
- 6. Periodic Surveillance

Inspector: J. \_\_ Z. \_\_ Site: DIST. OFFice

Cert.#

al 9	" Ber	- VAI	7-	Area: Co	-outer	RM -0	Efice		
waterial				Current	Potential	Approx.	Priority	Cleaning	Response
Code	Friable	Accessibility	Type	Condition	Condition	Amount of ACM	Level	Level	Action
MISC.	<i>N</i> .	High		FAIR	FAIR	100 🗹	1234 🕭	1 2 3 🚯	123456

Justification:

Implementation

End:

Notes: The hos plot of Scull Mark From Removing of Cobinets No losse Tite present.

Inspector: 5:- Rid Cert. #

Inspection Date 4/13/78

Site: D.,T OFFIL-

Material ,	or wa	201 STAL.	Rus	Area: Br	5 + MosenT	CAUNT	Space		
Material		7		Current	Potential	Approx.	Priority	Cleaning	Response
Code	Friable	Accessibility	Туре	Condition	Condition	Amount of ACM	Level	Level	Action
ASI	Y	Low		Dong.	Dang	350 W.CT.	1 2 3 4	1 2 3 4	1 2 <b>3</b> 4 5 6

Implementation

End:

Notes: Material Deteriorated - Moteral Isolated + Restarted

Inspector: 5. ....

Inspection Date 4//3/98

Site: P. st. Offren

رجاه	sa Wa	op-M-d.	Bopts	Area: B	سه رم ۵ که	t Campul	Some		
waterial				Current	Potential	Арргох.	Priority	Cleaning	Response
Code	Friable	Accessibility	Туре	Condition	Condition	Amount of ACM	Level	Level	Action
TSI	r	Low		Day.	Overg.	~25 50.75	12 <b>3</b> 45	1 2 Ø 4	123 <b>6</b> 956

Start:

End:

Notes: Motental Isolated & Restricted.

Inspector: 5: Rich

Inspection Date 4//3/95

Sile pint. Office

Material	or Wa	yn - Deh	reis	Area: BA	seman	- Casond	Some		
Material				Current	Potential	Approx. *	Priority	Cleaning	Response
Code	Friable	Accessibility	Туре	Condition	Condition	Amount of ACM	Level	Level	Action
TSI	1	Lon		DAME.	Dung	250 1	1 2 15) 4 5	1 2 (3) 4	123 <b>6</b> )56

Notes: Debris in dint under neath pipe Lugging Material Isoloted & ResTricted.



DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT
2211 Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 FAX (916) 483-0572

132



608302035C 128

James Rich

E.O.S. Environmental Inc.
2110 21st Street, Suite 150

Sacramento CA 95818

September 19, 1997

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. To maintain your certification, please abide by the rules printed on the back of the certification card.

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days <u>before</u> the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely.

Rick Axe, CIH

Rich Use

Senior Industrial Hygienist

**RA/dor** 

Attachment

cc: File

State of California
Division of Occupational Safety and Health

**Coruffed Asbestos Consultant** 

7. D

Certification No. \_85-2035 ...

Explos on 11/6/96

This confection was broad by the Division of Occupantumal Safety and Haulik as distributed by Synthese 7-199 de very of the Basinuss and Professions Chile.