

July 31, 2007

Mr. Leroy A. Christophersen, PHR Safety & Loss Control Coordinator Chico Unified School District 2455 Carmichael Drive Chico, CA 95928

RE:

Triennial AHERA Three-Year Reinspection

Dear Mr. Christophersen:

Enclosed is the data obtained from the AHERA Three-Year Reinspections Entek Consulting Group (Entek) conducted between April 11, 2007 and May 10, 2007. The documents included with this letter are the "Three-Year Reinspection Homogeneous ACBM Material Records" covering all buildings known from the original inspection to contain ACBM. The sites inspected were Academy for Change, Bidwell Junior High, Chapman Elementary, Chico Country Day, Chico Junior High School, Chico Senior High School, Citrus Elementary, Cohasset Elementary, Corporation Yard, District Office, Fair View High School, Hooker Oak Elementary, Loma Vista Elementary, Marigold Elementary, McManus Elementary, Neal Dow Elementary, Nord Elementary, Parkview Elementary, Pleasant Valley High School, Rosedale Elementary, Shasta Elementary, and Sierra View Elementary Schools. These are also provided on the enclosed diskette as per our contract. In an effort to assist with your Six-Month Surveillances, Entek has included on the CD blank forms with the current data from the Three-Year Reinspections.

Fax (916) 632-6812

You should review the updated Homogeneous Materials Reports to familiarize yourself with the current status of asbestos containing materials and identified suspect asbestos materials. It is the District's responsibility to assure that the school's site copy of the Management Plan is up to date and consistent with the District's Management Plan for that site. This is very important, and if not done can cause the District to be penalized during an EPA site visit or investigation.

Entek wants to remind you that materials containing "trace" amounts of asbestos must be considered in the event of renovations or demolitions. Although building materials containing trace amounts of asbestos (<1%) are not regulated under EPA, Cal/OSHA does regulate work practices with materials containing 0.1% asbestos. The original AHERA inspection contains information regarding materials with trace amounts of asbestos.

Entek collected two (2) asbestos bulk samples during the reinspections. One sample was collected at Loma Vista Elementary School and one at Chico High School. See the results of each sample in the following tables.

Loma Vista Elementary School; Unit A, North Building

Suspe	ct Materials Found or A	Assumed TO Contain >1% Asbestos Cor	itent (RACM)
Material	Asbestos Content	Location	Entek Sample Number
White 12" Floor Tile	1-5% Chrysotile	South East Corner of Room 16 Near Room 13	ECG-07-465-01A

Su	spect Materials Fo	und NOT TO Contain Asbestos or Considered N	on-Suspect
Material	Asbestos Content	Location	Entek Sample Number
Yellow Mastic	None Detected	South East Corner of Room 16 Near Room 13	ECG-07-465-01A

ASBESTOS LEAD MOLD INDOOR AIR QUALITY NOISE MONITORING TRAINING HEALTH AND SAFETY AUDITS



Mr. Leroy A. Christophersen, PHR Safety & Loss Control Coordinator Chico Unified School District July 31, 2007 Page Two

Chico High School, Building LH-800, MPR

Suspect Materials Fo	und NOT TO Conta	in Asbestos or Considered N	Non-Suspect
Material	Asbestos Content	Location	Entek Sample Number
White Linoleum on Columns	None Detected	Building LH-800, MPR	ECG-07-465-02A
Yellow Mastic	None Detected	Building LH-800, MPR	ECG-07-465-02A

When you provide your annual notification to parents and staff, include information regarding this three-year reinspection. Enclosed is a suggested format for your notification letter. Please note that you must include in your Management Plans a description of the steps you take to notify. It is also important that your Management Plans be updated after any and all actions conducted which impact asbestos containing materials.

Please remember that Entek did not inspect new buildings or portable classrooms which were placed on the District sites since the original EPA AHERA inspection. It is the District's responsibility to obtain letters of certification from the Architect, Construction Superintendent, or manufacturer of new building materials, indicating there is no asbestos in the new buildings (constructed after October 12, 1988) or new building materials. A copy of these certification letters must be included in your Management Plans, both at the school site and at the LEA Designees office site. It is still required of School Districts to send a copy of these certification letters to the US EPA AHERA unit; Region IX in San Francisco.

It is not necessary to send a copy of the three-year reinspection to the OPSC or EPA. However, the report should be included in your Management Plan. I want to thank you for your cooperation. If you have any questions, please feel free to contact me at (916) 632-6800.

Sincerely,

William Esparza

Certified Asbestos Consultant

William Esparzatz

DOSH #99-2579

Enclosures

Z:\Shannon\3-YEAR REINSPECTIONS\Chico USD\2007\Final.Ltr7-31-07.wpd

Below is a suggested letter to district personnel, building occupants, and parents that meets the AHERA requirement of annual notification. Regardless of the notification letter used, a signed and dated copy should be included in the Management Plan. The AHERA designee must also include in the Management Plan a brief statement describing the steps taken to notify. Include the date(s) of the six-month surveillances, and include any other actions taken with regards to asbestos.

Date:	
То:	Parents, PTA, Teachers, Maintenance, Staff
From:	AHERA Designee
RE:	Asbestos Hazard Emergency Response Act (AHERA) Asbestos Inspections and Management Plans.
required three-y reinspections for Country Day, Ch Elementary, Co Loma Vista Ele Nord Elementar Shasta Elemen 2007 and May	chool District has hired Entek Consulting Group, Inc. (Entek), to complete the ear reinspection of all asbestos-containing building materials in the District. The or Academy for Change, Bidwell Junior High, Chapman Elementary, Chico nico Junior High School, Chico Senior High School, Citrus Elementary, Cohasset reporation Yard, District Office, Fair View High School, Hooker Oak Elementary, mentary, Marigold Elementary, McManus Elementary, Neal Dow Elementary, y, Parkview Elementary, Pleasant Valley High School, Rosedale Elementary, tary, and Sierra View Elementary Schools were completed between April 11, 10, 2007 by an accredited inspector, and the reinspection data has been of the Management Plan.
Also, during the Plan.	past year the District has performed the required six-month surveillances on This information is also incorporated into the Management
the office of the	istrict's Management Plan is available for review during normal office hours in If copies of the plan ominal duplicating fee may be charged.
Authorized Sign	ature
Date	

State of California Division of Occupational Safety and Health

Certified Asbestos Consultant

William Esparza

Name

Certification No. 99–2579

05/03/08

Expires on.

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code



COE E GENTER FOR OCCUPATIONAL

8 ENVIRONMENTAL HEALTH

SANDERS IN THE SELECTION OF THE SELECTIO

University of California Berkeley

This certifies that

William Esparza

has attended the eight hour course

AHERA Refresher for Asbestos Inspectors & Management

February 5, 2007

and has completed the requisite training for asbestos accreditation under TSCA Title II

Planners

Course Date

Barbara (Blog

COEH Director

god R. Blu-

Date of Exam: February 5, 2007

Expiration Date: February 5, 2008

Continuing Education Director

Cal/OSHA Approval Number: CA-002-06 / CA-002-08

Fax: (510) 643-7291 Center for Occupational and Environmental Health Continuing Education Program UC Berkeley Mailcode 5120, 2223 Fulton Street, 2nd Floor, Berkeley, CA 94720-5120 Ph. (510) 643-7277 ASBESTECH 6825 Fair Oaks Blvd., Suite 103 Carmichael, California 95608 Tel.(916) 481-8902 Fax (916) 481-3975

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

07-465 Chico USD Loma Vista Elementary Unit A, North Bldg., Chico, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 50277

Date/Time Collected: 5/10/07 Date Received: 5/21/07 NVLAP # 101442 DOHS # 1153

Date Analyzed: 5/22/07

Sample No.

Color/Description

% Type Asbestos

Other Materials

ECG-07-465-

01A

White 12" floor tile, SE corner of room

1-5 CHRYSOTILE

Granular Mins.

16 near room 13

Yellow mastic

LABORATORY DIRECTOR: TOM CONLON

NONE DETECTED

Synthetics

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A), THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.

NVLAP

ANALYST: JIM JUNGLES

Jun John

50277

BULK ASBESTOS MATERIAL Analysis Request Form for Entek Consulting Group, Inc.

4200 ROCKLIN ROAD, STE. 7 ROCKLIN, CA 95677 (916) 632-6800 FAX (916) 632-6812

JOB I.D.: 07-465

CLIENT: Chico Unified School District

COLLECTED BY: William Esparza

DATE COLLECTED: 05/10/07

DATE SUBMITTED: 05/21/07

LAB SUBMITTED TO: Asbestech

SPECIAL INSTRUCTIONS:

ANALYSIS REQUESTED: PLM with Dispersion Staining

TURNAROUND TIME: 24 Hours

JOB SITE:

Loma Vista Elementary School

Unit A (North Building) 2404 Marigold Avenue, Chico, California 95926

SAMPLE#	MATERIAL DESCRIPTION/LOCATION
ECG-07-465-01A	12" Floor Tile and Mastic, SE Corner of Room 16, Near Room 13

C:\Entek\Clients\Chico USD\07-465 Chico 3 Year Inspections\Bulk Asbestos Request 05-10-07.wpd

DELIVERED BY: MAINING MANNEY DATE: 5-21-0)

RECEIVED BY: DATE: 5/21/7

ASBESTECH 6825 Fair Oaks Blvd., Suite 103 Carmichael, California 95608 Tel.(916) 481-8902 Fax (916) 481-3975

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

07-465 Chico USD Chico HS, Bldg. LH-800, MPR Chico, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 50276

Date/Time Collected: 5/11/07 Date Received: 5/21/07 NVLAP # 101442 DOHS # 1153

Date Analyzed: 5/22/07

Sample No.

Color/Description

% Type Asbestos

Other Materials

ECG-07-465-

02A

White linoleum on columns

LABORATORY DIRECTOR: TOM CONLON

NONE DETECTED

Vinyl Cellulose

Yellow mastic

NONE DETECTED

Synthetics

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)/(2)/(A), THE MCL IS 1 % SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.

NVLAP

ANALYST: JIM JUNGLE

es Jon Jalie

50276

BULK ASBESTOS MATERIAL Analysis Request Form for Entek Consulting Group, Inc.

4200 ROCKLIN ROAD, STE. 7 ROCKLIN, CA 95677 (916) 632-6800 FAX (916) 632-6812

JOB I.D.: 07-465

CLIENT: Chico Unified School District

COLLECTED BY: William Esparza

DATE COLLECTED: 05/11/07

DATE SUBMITTED: 05/21/07

LAB SUBMITTED TO: Asbestech

SPECIAL INSTRUCTIONS:

ANALYSIS REQUESTED; PLM with Dispersion Staining

TURNAROUND TIME: 24 Hours

JOB SITE:

Chico Senior High School

Building LH-800, Multi-Purpose Room

901 The Esplanade, Chico, California 95926

SAMPLE#	MATERIAL DESCRIPTION/LOCATION
ECG-07-465-02A	Linoleum on Columns

C:\Entek\Clients\Chico USD\07-465 Chico 3 Year Inspections\Bulk Asbestos Request 05-11-07.wpd

RECEIVED BY: MANISM WARMON DATE: 521-07

RECEIVED BY: DATE: 5/2/7 1/072

Page 1 of 1

RECORD OF FRIABLE AND NONFRIABLE ACM (FORM B)

Inspection Date(s) May 10, 2007

THREE-YEAR REINSPECTION

				CDS CODE 04-61424-0000000	
SCHOOL DISTRICT OFFICE				SCHOOL PHONE NUMBER (530) 898-3000	
ADDRESS 1163 E. Seventh Street	(NUMBER)	(STREET)	(CITY) Chico, CA	(ZIP) 95928	

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of <u>FORM C</u> (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

		СН	ECK O	NE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	вм	ASSUME	ED ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	DISTRICT OFFICE		Х		Х			
2.	PSYCHOLOGIST BUILDING DISTRICT MUST CERTIFY							
3.	UST BUILDING DISTRICT MUST CERTIFY							
4.								
5.								
6.								
7.								
8.								
9.								
10.								
11.								
12.								
13.								
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

THREE-YEAR REINSPECTION HOMOGENEOUS ACBM RECORDS

District: Chico Unified School District

School: District Office

Building: District Office

Inspector: William Esparza

Date of Inspection: May 10, 2007

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	Condition: Code & Comments	Friable Yes/No
H	PIPE WRAP DEBRIS	2	25-35%	25 S	BASEMENT CRAWL SPACE	(11)	COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. SAMPLE HMS-DO-07C COLLECTED ON 4-1-88.	>
F	PIPE WRAP STRAIGHT	8	80-85%	350 L	BASEMENT CRAWL SPACE	(11)	COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. (FORMALLY KNOWN AS HOMO MAT. #7.) SAMPLE HMS-DO-07A COLLECTED ON 4-1-88.	>
F	PIPE WRAP JOINT	o	10-15%	350 L	BASEMENT CRAWL SPACE	(11)	COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. (FORMALLY KNOWN AS HOMO MAT. #7.) SAMPLE HMS-DO-07B COLLECTED ON 4-1-88.	>

CONDITION CODE

	1 & Restricted (13) Non-Asbestos/Not Inspected
(2) Damaged(3) Significantly Damaged(25% or more)(5) Yes (If Yes, explain under comments)	ncapsulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-
(2) Damaged(3) Significantly Damagec(5) Yes (If Yes, explain under comments)	6) Repaired (7) Removed (8) Encapsulated 11) Inaccessible, no inspection data (12) Ott
(1) Good (4) No	(6) Repaired (11) Inaccess
General Condition: Change in Condition:	<u>Abated:</u> Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Zishandonis-year Reinspectionsichico Usdzoot/district OfficeNHMR.wpd

ENTEK CONSULTING GROUP, INC. ASSESSMENT OF TSI and/or FRIABLE MATERIAL

District: Chico Unified School District

Date: May 10, 2007

School: District Office

Inspector: William Esparza

Building & Location(s): Basement Crawl Space (Functional Area)

Sample#: HMS-DO-07C

% Asbestos- 25-35%

Homogeneous Mat. #7

Material description: Pipe Wrap Debris

Total amount of material this location: 25 S

Amount of friable material this location: 25 S

Damage	Local		Distributed	Х	Damaged	98 -99%
Type of Damage	Air Erosion	Х	Water	Х	Flaking	Х
	Deterioration	Х	Physical	Х	Delamination	

Probable cause(s) of damage: Unknown

POTENTIAL FOR DISTURBANCE		RESPONSE ACT	IONS	PREVENTIVE MEASURES			
	Н	M	L	Isolate/Restrict		Fix leaks	Х
Accessibility	Х			Repair/Cleanup	X	Prevent water contact	Х
Vibration			Х	Enclose		Do not drill, cut, sand, or grind	Х
Air Erosion		Х		Remove	Х	Do not affix signs	Х
Water		Х		Encapsulate		Avoid contact	Х
Occupancy			Х	O & M		·	

Assessment of Material Condition Significantly Damaged Not damaged Damaged (Fair) (Good) (Poor) Potential High High Mod Low High Mod Low Damage: Hazard 1 2 3 4 5 6 7 Ranking:

Comments & Observations:

Was instructed by Leroy Christopher not go into the basement crawl space. Possibly removed and could not locate.

ENTEK CONSULTING GROUP, INC. ASSESSMENT OF TSI and/or FRIABLE MATERIAL

District: Chico Unified School District Date: May 10, 2007

School: District Office Inspector: William Esparza

Building & Location(s): Basement Crawl Space

Sample#: HMS-DO-07A % Asbestos- 80-85% Homogeneous Mat. #8

Material description: Pipe Wrap Straight

Total amount of material this location: 350 L Amount of friable material this location: 350 L

Damage	Local		Distributed	х	Damaged	98%
Type of Damage	Air Erosion	Х	Water	Х	Flaking	Х
8	Deterioration	Х	Physical	Х	Delamination	

Probable cause(s) of damage: Unknown

POTENTIAL F	OR DISTURBANCE		NCE	RESPONSE ACTIONS		PREVENTIVE MEASURES		
	Н	М	L	Isolate/Restrict		Fix leaks		
Accessibility	х			Repair/Cleanup X		Prevent water contact		
Vibration			Х	Enclose		Do not drill, cut, sand, or grind	Х	
Air Erosion		Х		Remove X		Do not affix signs		
Water		Х		Encapsulate		Avoid contact		
Occupancy			Х	O & M				

Assessment of Material Condition Significantly Damaged Damaged Not damaged (Poor) (Fair) (Good) Potential High High Mod Low High Mod Low Damage: Hazard 1 2 3 7 4 5 6 Ranking:

Comments & Observations:

Was instructed by Leroy Christopher not go into the basement crawl space. Possibly removed and could not locate.

ENTEK CONSULTING GROUP, INC. ASSESSMENT OF TSI and/or FRIABLE MATERIAL

District: Chico Unified School District

Date: May 10, 2007

School: District Office

Inspector: William Esparza

Building & Location(s): Basement Crawl Space

Sample#: HMS-DO-07B

% Asbestos- 10-15%

Homogeneous Mat. #9

Material description: Pipe Wrap Joint

Total amount of material this location: 350 L

Amount of friable material this location: 350 L

Damage	Local		Distributed	Х	Damaged	98%
Type of Damage	Air Erosion	Х	Water	Х	Flaking	Х
Residence of the second se	Deterioration	Х	Physical	Х	Delamination	

Probable cause(s) of damage: Unknown


POTENTIAL F	POTENTIAL FOR DISTURBANCE		RESPONSE ACTIONS		PREVENTIVE MEASURES			
	Н	М	L	Isolate/Restrict		Fix leaks		
Accessibility	Х			Repair/Cleanup X		Prevent water contact		
Vibration			Х	Enclose		Do not drill, cut, sand, or grind	Х	
Air Erosion		Х		Remove X		Do not affix signs		
Water		Х		Encapsulate		Avoid contact	Х	
Occupancy			Х	O&M				

:	Assessmer Significantly Damaged (Poor)		nt of Material Condition Damaged (Fair)				Not da (Goo			
Potential Damage:	High		High	Mod	Low		High	Mod	Low	
Hazard Ranking:	1		2	3	4		5	6	7	

Comments & Observations:

Was instructed by Leroy Christopher not go into the basement crawl space. Possibly removed and could not locate.

Admin District Office Building



UST Building Psychologist Building

District Office 1163 E. Seventh Street Chico, CA 95928 Map Not To Scale Three-Year Reinspection Conducted By: William Esparza Entek Consulting Group, Inc. May 10, 2007 Conference Room Sustrict

RESILIENT TILE FLOORING 09658

AZROC

1. Product Name

Azrock Vinyl Composition Tile (VCT)

- Cortina Colors
- Cortina Complements
- Cortina SD
- Solids
- Classic Granite
- Classic Granite SR
- Thru-Quartz
- CortinaStone
- Plaza Marble
- StoneGlow

2, Manufacturer

Azrock

A Brand of Tarkett Commercial 1705 Oliver Street Houston, TX 77007 (713) 366-2689 Fax: (713) 869-5271 E-mail: AzTech@tarkett.cor1

www.tarkett.com

3. Product Description

BASIC USE

Azrock Vinyl Composition T le (VCT) is recommended for use in high traffic applications where a smooth surfaced, easily maintained, durable, long-wearing floor is required. Recommended areas of use are:

- · School offices, classroom; and corridors
- · Commercial office areas
- Hospital lobbies, patient 100ms and corridors
- Retail stores

COMPOSITION & MATERIALS

Azrock resilient floor tile is available in 1/8" (3.2 mm) nominal thicknesses. Selected Cortina Colors tile are also available in a 3/32" (2.4 mm) thickness. Color and pattern details are dispersed uniformly throughout the thickness of the product.

SIZES

- Nominal overall thickness: 1/8" (3.2 mm)
- Size All styles of VCT come in a 12" × 12" (305 × 305 mm)

- Area per carton 45 ft₂ (4.2 m₂)
- Weight per carton 62 lb (28 kg)

COLORS

- Cortina colors- 53 colors
- Cortina Complements- 7 colors
- · Solids- 16 colors
- Classic Granite- 9 colors
- Classic Granite SR- 9 colors
- Thru-Quartz- 15 colors
- CortinaStone- 14 colors
- Plaza Marble- 5 colors
- StoneGlow- 5 colors

LIMITATIONS

These products are unsuitable for concrete substrates where hydrostatic pressure or excessively alkaline conditions exist. Concrete floors containing curing agents, sealers or hardeners are not suitable. Do not install over gypsum type underlayment or patching compounds.

Unsuitable substrates or any other conditions that are obviously unsuited to good installation should not be considered acceptable, even if those conditions are not listed in the paragraph above.

4. Technical Data

APPLICABLE STANDARDS **ASTM International**

- ASTM D2047 Standard Test Method for Static Coefficient of Friction of Polish- Coated Floor Surfaces as Measured by the James Machine
- ASTM E648 Standard Test Method for Critical Radiant Flux of Floor Covering Systems Using a Radiant Heat Energy Source
- ASTM E662 Standard Test Method for Specific Optical Density of Smoke Generated by Solid Materials
- ASTM F150 Standard Test Method for Electrical Resistance of Conductive and Static Dissipative Resilient Flooring
- ASTM F710 Standard Practice for Preparing Concrete Floors to Receive Resilient Flooring
- ASTM F970 Standard Test Method for Static Load Limit
- ASTM F1066 Standard Specification for Vinyl Composition Floor Tile
- ASTM F1869 Standard Test Method for Measuring Moisture Vapor Emission Rate of Concrete

Subfloor Using Anhydrous Calcium Chloride

• ASTM FM1678 Standard Test Method for Using a Portable Articulated Strut Slip Tester (PAST)

APPROVALS

Consult manufacturer for current information on compliance with requirements of specific agencies and/or building code jurisdictions.

PHYSICAL/CHEMICAL PROPERTIES

- Product classification (ASTM) F1066) - Class 2, Through Pattern
- Static load limit (ASTM F970) ≥ 125psi (861 kPa)
- Static load limit (ASTM F970) (Cortina SD)- 75 psi (517kPa)
- Static coefficient of friction (ASTM) D2047)- 0.6
- Azrock VCT exceeds minimum requirement of 0.6 static coefficient of friction per ASTM D2047. Azrock VCT exceeds minimum ADA requirements of 0.6 (Slip Resistant 0.8) static coefficient of friction per ASTM F1678.

Although Azrock VCT meets the recommendations for a safe walking surface, tiles are always maintained with floor polish.

Contact the polish manufacturer for slip resistance qualities of the floor polish to be used.

Test reports and additional product information are available upon request.

FIRE PERFORMANCE

- Flooring Radiant Panel Test (ASTM) E648) - \geq 1.0 critical radiant flux
- Smoke Density Test (ASTM E662)
- Less than 450

5. Installation

PREPARATORY WORK

Refer to the latest edition of the Azrock Installation and Maintenance manual for complete information. Handle and store product according to Azrock recommendations.

Maintain minimum air temperature of 65 degrees F (18 degrees C) at flooring installation area for a minimum 2 days prior to, during and for minimum 24 hours after installation of flooring tile. Store flooring materials in area of application and allow 2 days for material to reach the ambient temperature of the installation area. Construct concrete floors in accordance with the American Concrete Institute (ACI) 302 1 R-96 Guide for Concrete Floor and Slab Construction. Floors must be finished and cured according to ACI with a minimum compressive strength of 3500 psi (24 Mpa).

Floors must be dry, clean and smooth. Any surface materials such as paint, wax, grease, oil, achesive residues, etc., must be removed. Floors must be free of any sealers, curing hardening or parting compounds that would adversely affect the adhesive used with the flooring. Installation of a moisture barrier, such as 1/8" (3.2mr1) Sealtight®, manufactured by W.R. Meadows Inc., or similar product, is recommended prior to placement of on-grade or below-grade slabs. Moisture vapor transmissior must not exceed 5 lb/1000 square ft/24 hours when tested according to ASTM F1869 (Anyhdrous Calcium Chloride Test). Surface pH of concrete slabs should be no greater than 9. As a general rule, a 4" (102 mm) thick slab will require a 3 month drying time before moisture tests are performed.

METHODS

Wood floors must be double construction with a minimum thickness of 1" (25.4mm). The top layer of wood should be American Plywood Association (APA) Underlayment Grade Plywood or other underlayment panel approved and warranted for use beneath resilient flooring.

Adhere flooring with Tarkett 100 Clear Thin Spread Adhesive. Apply adhesive with a notched trawel with notches 1/32'' deep \times 1/16'' wide \times 1/32'' apart.

Slip Resistant Tile installed in areas subject to temperature extremes and/or topical moisture should be installed with Tarkett 940 Polyurethane adhesive.

PRECAUTIONS

Gypsum type patching compounds and underlayments are no: recommended. Tarkett will not accept responsibility for flooring failures related to the use of gypsum type patching compounds and underlayments.

6. Availability & Cost AVAILABILITY

These products are marketed throughout the United States, Canada and many foreign countries. Contact manufacturer for information on local availability.

COST

Approximate installed cost per square ft (US \$):

- Cortina SD- \$5.45-\$6.30
- Cortina Colors- \$1.20-\$1.80 (1/8" gauge); \$1.15-\$1.60 (3/32" gauge)
- Cortina Complement- \$1.20-\$1.80
- Granite- \$1.60-\$2.25
- Granite SR- \$2.40-\$3.15
- Thru-Quartz- \$1,60-\$2,25
- Solids- \$2.20-\$3.00
- CortinaStone- \$1.80-\$2.35
- Plaza Marble- \$3.50-\$4.00
- Stone Glow- \$2.75-3.25

Variations may result from competitive bidding depending on local labor costs, job conditions, extent of floor preparation, etc. Budget installed cost information may be obtained from a local Azrock distributor or from the manufacturer.

7. Warranty

Azrock VCT is warranted to be free of manufacturing defects for 5 years from installation. Refer to Azrock Commercial Products Limited Warranty.

8. Maintenance

One of the main reasons for the popularity of Azrock VCT is the minimal effort required to keep the tiles clean and attractive. A new tile floor should not be washed until it has become tightly adhered to the subfloor. This will generally take a week or longer, depending on foom temperature and the temperature of the subfloor. In the meantime, sweep or vacuum the flooring to remove loose grit or debris and wipe clean with a damp mop. Spots of adhesive can be removed with a clean, white cloth dampened with mineral spirits. Use caution when handling flammable solvents.

Note- Stop dirt in the doorway. By doing so, time, work and money are saved. The use of non-staining walk-off mats at all heavy traffic entrances is recommended. Mats should wipe dirt and grit from shoes

Page 29 3

RESILIENT TILE FLOORING 09658

and allow particles to fall beneath the mat surface, preventing accumulated dirt from being tracked into the building. Frequency of maintenance will always vary depending on the traffic and use. Do not use abrasive cleaners. Use Tarkett Commercial maintenance products or their equivalent.

Initial Cleanup/Daily Care Sweep or vacuum to remove loose dirt. Allow treated mops to dry overnight before reusing. Wash floor with a neutral floor cleaner. If the floor was subjected to excess dirt and heavy traffic before initial mainenance., use a wax stripping solution to clean floor. Use a standard scrubbing machine or an automatic scrubber with a red polyester scrubbing pad. Rinse the floor with clean water and wet vacuum or mop dry. The floor must be thoroughly rinsed to remove all detergent.

Surface Treatment
Apply 3-5 coats of good quality,
acrylic floor polish. The use of a
sealer prior to application of floor
polish is optional. Floor polishes
should be applied and maintained
according to the instructions of the
manufacturer.

Slip Resistant Tile is maintained with application of floor polish and scrubbing procedures involving bristle brushes.

Spot Removal
Spills and spots should be cleaned
up while still fresh. Use a red
polyester pad moistened with
detergent.

Precautions

Do not use acetone or similar materials to clean floors. Furniture rests, cart wheels and tires should be made of soft, nonstaining rubber and should be large enough to fully dissipate the load. Use plywood panels to protect flooring from damage that may occur when moving heavy objects directly over flooring. The use of dolies may not be sufficient protection from heavy loads.

A detailed maintenance manual is available from Tarkett.

9. Technical Services

RESILIENT TILE FLOORING 09658

A staff of factory trained service personnel offers design assistance and technical support. For technical assistance, contact the Tarkett Technical Service Department.

10. Filing Systems

- Sweet's Catalog Files
- Additional product information is available from the manufacturer upon request.

Page 30/3

Mangold School

Etrus School

Admin office floor '07

Health office '07

Unit C

Mann	ington Commercial® Tile			
Specif cations	Vinyl Composition Tile (VCT)	Mannington Assurance'* Modular		
Cons ruction	Through Pattern	Slip Resistant Inlaid Tile		
Thick ness, nominal inches (mm)	0.125 (3.18)	0,055 (1.40)		
Overill Thickness, nominal inches (mm)	0.125 (3.18)	0,125 (3.18)		
Pack age/Count	carton/45	carton/16		
Average weight: b (kg) per carton b (kg) per tile	65 (29.50) 1.43 (0.65)	34.5 (15.6) 2.05 (0.93)		
Boxes Per Pallet	30	48		
Size, nominal, inches (mm)	12 x 12 (304.8 x 304.8)	18 x 18 (457.2 x 457.2)		
Static load limit F970, psi (kg/cm²)	125 (8.79)	750 (49.22)		
ASTIA Specification F-1066	Class 2	N/A		
Federal Specification SS-1-312B (1)	Type IV	N/A		
AST / Specification F-1303	N/A	Type II, Grade I Construction		
AST vi E-648 critical radiant flux, ≥ 0.4-5 w/cm²	Class I	Class I		
AST VI E-662 NBS smoke chamber test, smoke value 450 or less	Yes	Yes		
Recommended adhesive, type, spread	V-11, clear thin set, 250-300 sq ft/gal	MT-711 or V-85, Full		