

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/03/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Cohasset Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
TSI	PIPE WRAP CORNER	1	10-15%	5 L	ATTIC ABOVE ROOMS 900 (FKA 3), 901 (FKA 4), 902 (FKA 5), 903 (FKA 7), AND 904 (FKA 6)	(11) SAME	N
M	12" VFT	2	5-10%	3,000 S	ROOMS 1, 2, 900 (FKA 3), 3 (FKA 8), 905 (FKA 9), 906 (FKA 10), 907 (FKA 11 & 13), 910 (FKA 12), AND LIBRARY	(1) (5) RM 2 – CARPET COVERING VFT	N

Building: B - Portable Classroom 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	98	ASSUMED	1,000 S	PORTABLE CLASSROOM 4	(1) (4) LOCATION OF DRYWALL UNKNOWN	N
M	2' X 4' FCP	99	ASSUMED	900 S	PORTABLE CLASSROOM 4	(1) (4) LOCATION OF DRYWALL UNKNOWN	N
M	12" VFT	100	ASSUMED	165 S	PORTABLE CLASSROOM 4	(1) (4) SAME	N
						<b>NOTE:</b> THIS PORTABLE WAS MANUFACTURED IN 1986, WHICH MEANS THAT CERTIFICATION LETTERS CANNOT BE OBTAINED FOR THE BUILDING. ALL MATERIALS WILL BE ASSUMED UNTIL PROPER SAMPLING OF SUSPECT MATERIALS IS CARRIED OUT.	

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Cohasset Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
TSI	PIPE WRAP CORNER	1	10-15%	5 L	ATTIC ABOVE ROOMS 900 (FKA 3), 901 (FKA 4), 902 (FKA 5), 903 (FKA 7), AND 904 (FKA 6)	(11)	N
M	12" VFT	2	5-10%	3,000 S	ROOMS 1, 2, 900 (FKA 3), 3 (FKA 8), 905 (FKA 9), 906 (FKA 10), 907 (FKA 11 & 13), 910 (FKA 12), AND LIBRARY	(1) (4) RM 2 – CARPET COVERING VFT	N

Building: B - Portable Classroom 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	98	ASSUMED	1,000 S	PORTABLE CLASSROOM 4	(1) (4)	N
M	2' X 4' FCP	99	ASSUMED	900 S	PORTABLE CLASSROOM 4	(1) (4)	N
M	12" VFT	100	ASSUMED	165 S	PORTABLE CLASSROOM 4	(1) (4)	N
						<b>NOTE:</b> THIS PORTABLE WAS MANUFACTURED IN 1986, WHICH MEANS THAT CERTIFICATION LETTERS CANNOT BE OBTAINED FOR THE BUILDING. ALL MATERIALS WILL BE ASSUMED UNTIL PROPER SAMPLING OF SUSPECT MATERIALS IS CARRIED OUT.	

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Cohasset Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> L.F.	Location	Condition: Code & Comments	Friable Yes/No
TSI	PIPE WRAP CORNER	1	10-15%	5 L	ATTIC ABOVE ROOMS 900 (FKA 3), 901 (FKA 4), 902 (FKA 5), 903 (FKA 7), AND 904 (FKA 6)	(11)	N
M	12" VFT	2	5-10%	3,000 S	ROOMS 1, 2, 900 (FKA 3), 3 (FKA 8), 905 (FKA 9), 906 (FKA 10), 907 (FKA 11 & 13), 910 (FKA 12), AND LIBRARY	(1) (4) RM 2 - CARPET COVERING VFT	N

Building: B - Portable Classroom 4

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	98	ASSUMED	1,000 S	PORTABLE CLASSROOM 4	(1) (4)	N
M	2' X 4' FCP	99	ASSUMED	900 S	PORTABLE CLASSROOM 4	(1) (4)	N
M	12" VFT	100	ASSUMED	165 S	PORTABLE CLASSROOM 4	(1) (4)	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible; no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**NOTE:** THIS PORTABLE WAS MANUFACTURED IN 1986, WHICH MEANS THAT CERTIFICATION LETTERS CANNOT BE OBTAINED FOR THE BUILDING. ALL MATERIALS WILL BE ASSUMED UNTIL PROPER SAMPLING OF SUSPECT MATERIALS IS CARRIED OUT.

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**