

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District  
School: Parkview Elementary School

Inspector: Leroy Christophersen  
Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	85	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, AND OFFICE CORRIDOR	(1) (4)	N
M	12" VFT	86	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, AND OFFICE CORRIDOR	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	850 S	CLASSROOMS 3-6 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	87	ASSUMED	3,200 S	CLASSROOMS 3-6 AND WORKROOM	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	82	ASSUMED	800 S	MEN S & WOMEN S RESTROOMS	(1) (4)	N
M	12" VFT	86	ASSUMED	400 S	CLASSROOMS 7-10	(1) (4)	N
M	2' X 4' FCP	87	ASSUMED	3,600 S	CLASSROOMS 7-10	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	1-5%	1,100 S	BOY S & GIRL S RESTROOM WALLS AND CUSTODIAN ROOM	(1) (4)	N
M	DRYWALL	83	ASSUMED	300 S	BOY S & GIRL S RESTROOM CEILING	(5) (2) BOY'S CEILING NEEDS REPAIR	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	CEILING PLASTER	4	1-5%	50 S	STAFF ROOM	(1) (4)	N
M	12" ACT	6	NONE DETECTED	2,800 S	ENTIRE WING	(13) REPRESENTED BY SAMPLE HMS-PKV-06 COLLECTED ON 4-1-88.	N/A
M	TRANSITE PANELS	99	ASSUMED	300 S	BELOW WINDOWS	(1) (4)	N
M	LINOLEUM	100	ASSUMED	80 S	CLASSROOM 1	(12) COULD NOT FIND	N
M	9" VFT GREEN/WHITE	101	ASSUMED	150 S	OFFICE, HALL, AND STORAGE ROOM	(13) COULD NOT FIND THIS MATERIAL.	N
M	12" VFT	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	12	NONE DETECTED	4,500 S	CLASSROOMS 14-17 & LIBRARY	(13) SAMPLE HMS-PKV-12 COLLECTED ON 3-31-88.	N/A
M	9" VFT TAN	13	1-5%	5,000 S	CLASSROOMS 14-17 AND SER ROOM	(1) (4)	N
T	PIPE WRAP CORNER	15	1-5%	12 EACH	RESTROOM ATTIC	(11)	N
M	DRYWALL	76	TRACE IN SKIM COAT	3,000 S	ALL ROOMS	(1) (4)	N
M	12" ACT	97	ASSUMED	250 S	SER ROOM	(1) (4)	N
M	12" VFT	100	ASSUMED	250 S	LIBRARY	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	16	NONE DETECTED	640 S	CLASSROOMS 18-21	(13) SAMPLE HMS-PKV-16 WAS COLLECTED ON 4-1-88.	N/A
M	2' X 4' FCP S	17	NONE DETECTED	3,800 S	CLASSROOMS 18-21	(13) SAMPLE HMS-PKV-17 COLLECTED ON 4-1-88.	N/A
T	PIPE WRAP CORNER	18	5-10%	20 S	CLASSROOM 18	(11) ABOVE FCP S.	N

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	NONE DETECTED	1,200 S	KITCHEN	(13) REPRESENTED BY SAMPLES HMS-PKV-03A-F COLLECTED ON 4-1-88.	N/A
M	12" VFT RED	9	1-5%	540 S	KITCHEN (NORTH WEST CORNER)	(1) (4)	N
M	DRYWALL	11	ASSUMED	60 S	GIRL S & BOY S RESTROOM	(1) (6) <del>GIRLS RESTROOM HOLE IN WALL</del>	N
M	12" VFT	92	ASSUMED	1,800 S	MPR, KITCHEN, AND CLOSET ON EACH END OF STAGE	(1) (4)	N
M	9" VFT	101	ASSUMED	200 S	KITCHEN STORAGE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: Portable 11A & B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	12	ASSUMED	120 S	CLASSROOMS 11A & B	(1) (4)	N
M	2' X 4' FCP S	14	ASSUMED	900 S	CLASSROOMS 11A & B	(1) (4)	N

Building: Portables 12 & 13

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 12 & 13	THESE TWO PORTABLES WERE NOT IN OUR ORIGINAL INSPECTION. MANUFACTURES DATE UNREADABLE. BOTH HAVE 12" VFT & 2' X 4' FCP S. DISTRICT MUST CERTIFY IF MANUFACTURE DATES FOR THESE PORTABLES ARE PAST 10-12-88.	

Building: Portables 22-25

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 22-25	PORTABLES 22-25 REQUIRE CERTIFICATION. PORTABLE 22 MANUFACTURERS DATE 1995. PORTABLES 23-25 MANUFACTURERS DATE 1997.	

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District  
School: Parkview Elementary School

Inspector: Leroy Christophersen  
Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	85	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, AND OFFICE CORRIDOR	(1) (4)	N
M	12" VFT	86	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, AND OFFICE CORRIDOR	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	850 S	CLASSROOMS 3-6 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	87	ASSUMED	3,200 S	CLASSROOMS 3-6 AND WORKROOM	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	82	ASSUMED	800 S	MEN'S & WOMEN'S RESTROOMS	(1) (4)	N
M	12" VFT	86	ASSUMED	400 S	CLASSROOMS 7-10	(1) (4)	N
M	2' X 4' FCP	87	ASSUMED	3,600 S	CLASSROOMS 7-10	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	1-5%	1,100 S	BOY'S & GIRL'S RESTROOM WALLS AND CUSTODIAN ROOM	(1) (4)	N
M	DRYWALL	83	ASSUMED	300 S	BOY'S & GIRL'S RESTROOM CEILING	(1) (2) BOY'S CEILING NEEDS REPAIR	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	CEILING PLASTER	4	1-5%	50 S	STAFF ROOM	(1) (4)	N
M	12" ACT	6	NONE DETECTED	2,800 S	ENTIRE WING	(13) REPRESENTED BY SAMPLE HMS-PKV-06 COLLECTED ON 4-1-88.	N/A
M	TRANSITE PANELS	99	ASSUMED	300 S	BELOW WINDOWS	(1) (4)	N
M	LINOLEUM	100	ASSUMED	80 S	CLASSROOM 1	(12) COULD NOT FIND	N
M	9" VFT GREEN/WHITE	101	ASSUMED	150 S	OFFICE, HALL, AND STORAGE ROOM	(13) COULD NOT FIND THIS MATERIAL.	N
M	12" VFT	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	12	NONE DETECTED	4,500 S	CLASSROOMS 14-17 & LIBRARY	(13) SAMPLE HMS-PKV-12 COLLECTED ON 3-31-88.	N/A
M	9" VFT TAN	13	1-5%	5,000 S	CLASSROOMS 14-17 AND SER ROOM	(1) (4)	N
T	PIPE WRAP CORNER	15	1-5%	12 EACH	RESTROOM ATTIC	(11)	N
M	DRYWALL	76	TRACE IN SKIM COAT	3,000 S	ALL ROOMS	(1) (4)	N
M	12" ACT	97	ASSUMED	250 S	SER ROOM	(1) (4)	N
M	12" VFT	100	ASSUMED	250 S	LIBRARY	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	16	NONE DETECTED	640 S	CLASSROOMS 18-21	(13) SAMPLE HMS-PKV-16 WAS COLLECTED ON 4-1-88.	N/A
M	2' X 4' FCP'S	17	NONE DETECTED	3,800 S	CLASSROOMS 18-21	(13) SAMPLE HMS-PKV-17 COLLECTED ON 4-1-88.	N/A
T	PIPE WRAP CORNER	18	5-10%	20 S	CLASSROOM 18	(11) ABOVE FCP'S.	N

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	NONE DETECTED	1,200 S	KITCHEN	(13) REPRESENTED BY SAMPLES HMS-PKV-03A-F COLLECTED ON 4-1-88.	N/A
M	12" VFT RED	9	1-5%	540 S	KITCHEN (NORTH WEST CORNER)	(1) (4)	N
M	DRYWALL	11	ASSUMED	60 S	GIRL'S & BOY'S RESTROOM	(1) (4)	N
M	12" VFT	92	ASSUMED	1,800 S	MPR, KITCHEN, AND CLOSET ON EACH END OF STAGE	(1) (4)	N
M	9" VFT	101	ASSUMED	200 S	KITCHEN STORAGE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Parkview Elementary School

Building: Portable 11A & B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	12	ASSUMED	120 S	CLASSROOMS 11A & B	(1) (4)	N
M	2' X 4' FCP'S	14	ASSUMED	900 S	CLASSROOMS 11A & B	(1) (4)	N

Building: Portables 12 & 13

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 12 & 13	THESE TWO PORTABLES WERE NOT IN OUR ORIGINAL INSPECTION. MANUFACTURES DATE UNREADABLE. BOTH HAVE 12" VFT & 2' X 4' FCP'S. DISTRICT MUST CERTIFY IF MANUFACTURE DATES FOR THESE PORTABLES ARE PAST 10-12-88.	

Building: Portables 22-25

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 22-25	PORTABLES 22-25 REQUIRE CERTIFICATION. PORTABLE 22 MANUFACTURERS DATE 1995. PORTABLES 23-25 MANUFACTURERS DATE 1997.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**