District: Chico Unified School District School: Chico Senior High School

Abated:

Date of Inspection: Inspector: Building: A (1st Floor)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA & CLASSROOMS 110-111, AND 113-130	(13)	SAMPLE HMS-CHS-01 COLLECTED 3-28-88.	Y
М	12" VINYL FLOOR TILE (BEIGE) & ADHESIVE	2	TRACE	5,700 S	RECEPTION AREA & CLASSROOMS	(1) (4)		N
М	12" ACOUSTIC CEILING TILE (FISSURE PATTERN)	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, 120 AND CLASSROOMS 102-107	(13) (2)	SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88. DAMAGED WHERE VISIBLE	Y
Т	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (CLASSROOM 111)	(11)	INACCESSIBLE.	Y
Т	MESH WRAP	8	12-20%	½ L	DARK ROOM ATTIC (CLASSROOM 111)	(11)	INACCESSIBLE.	Y
М	TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, AND STAIRWELLS	(1) (4)	PANELS PAINTED WHITE 11/19/03.	N
М	DRYWALL & JOINT COMPOUND	166	ASSUMED POSITIVE	8,000 S	THROUGHOUT INTERIOR WALLS	(1) (4)		N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	700 S	THROUGHOUT INTERIOR	(1) (4)		N
S	STUCCO	251	ASSUMED POSITIVE	2,500 S	COVERED WALKWAYS	(1) (4)		N
М	CARPET ADHESIVE	501	ASSUMED POSITIVE	200 S	ADMIN AREA, PRINCIPAL'S OFFICE	(1) (4)		N

 $C:\label{lem:constant} $$C:\label{lem:constant} $$C:\label{lem:consta$ 

#### CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

## CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: A (2<sup>ND</sup> Floor)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (BEIGE) & ADHESIVE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4)	N
М	2' X 4' CEILING PANELS	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88.	Y
М	CEMENTITIOUS TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	COVERED WALKWAYS	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	167	ASSUMED POSITIVE	8,000 S	THROUGHOUT INTERIOR WALLS	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	700 S	CLASSROOMS & COVERED WALKWAYS	(1) (4)	N
S	STUCCO	251	ASSUMED POSITIVE	2,800 S	STAIRS & COVERED WALKWAYS	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS - 6 Month Survillance.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location		riable es/No
М	2' X 4' CEILING PANELS	13	NONE DETECTED	10, 000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON Y 3-28-88.	Υ
М	CEMENTITIOUS TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, AND STAIRWAYS	(1) (4) PANELS PAINTED WHITE 11/19/03. N	N
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	152	CERTIFIED ASBESTOS FREE	9,430 S	THROUGHOUT	(13) CERTIFICATION LETTER ON FILE. N	N
М	DRYWALL & JOINT COMPOUND	168	ASSUMED POSITIVE	7,500 S	THROUGHOUT	(1) (4) N	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	650 S	THROUGHOUT	(1) (4) N	N
S	STUCCO	251	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4) N	N
М	12" ACOUSTIC CEILING TILE (FISSURE PATTERN)	252	ASSUMED POSITIVE	800 S	CORRIDORS AT ROOMS 2 & 10, B-3	(1) (4) N	N
S	DRYWALL TEXTURE	502	ASSUMED POSITIVE	7, 500 S	THROUGHOUT	(1) (4) N	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico H

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	EXTERIOR OF BUILDING	(1) (4) PANELS PAINTED WHITE 11/19/03.	N
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	150	CERTIFIED ASBESTOS FREE	9,513 S	CLASSROOMS 1-11	(13) LETTER IN FILE AS OF 6/2005.	N
М	DRYWALL & JOINT COMPOUND	169	ASSUMED POSITIVE	7,500 S	THROUGHOUT	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	650 S	THROUGHOUT	(1) (4)	N
S	STUCCO	251	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N
М	12" ACOUSTIC CEILING TILE (FISSURE PATTERN)	252	ASSUMED POSITIVE	800 S	CORRIDORS AT ROOMS C1, C3, C4 AND C10	(1) (4)	Y

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS - 6 Month Survillance.wpd

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	38	1-5%	300 S	CORRIDOR BETWEEN D AND BAND ROOM OFFICE	(1) (4) TROWELED ON CEILING.	N
М	12" VINYL FLOOR TILE (OFF WHITE) & ADHESIVE	150	CERTIFIED ASBESTOS FREE	1,200 S	MUSIC WING HALL AND BAND ROOM D1	(13) CERTIFICATION LETTER ON FILE AS OF 6/2005.	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	CLASSROOMS D1-D5	(1) (4)	N
М	12" ACOUSTIC CEILING TILE (1/8" HOLE PATTERN)	255	ASSUMED POSITIVE	3,500 S	CLASSROOMS D1-D5 AND RESTROOMS	(1) (4)	Y
М	SHEET VINYL FLOORING (GRAY MARBLED) & ADHESIVE	256	ASSUMED POSITIVE	3,000 S	CLASSROOMS D1-D5	(1) (4)	N
М	DRYWALL	257	ASSUMED POSITIVE	3,000 S	CLASSROOMS D1, D2, & D3	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico H

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: D (Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACOUSTIC CEILING TILE (FISSURE PATTERN)	258	ASSUMED POSITIVE	600 S	CORRIDOR BETWEEN D, BAND ROOM D1 AND CHORAL ROOM D2	(1) (4)	Y
М	CEMENTITIOUS TRANSITE PIPE	259	ASSUMED POSITIVE	10 L	STORAGE AT WATER HEATER	(1) (4)	N
М	12" VINYL FLOOR TILE (DARK GRAY) & ADHESIVE	260	ASSUMED POSITIVE	1,800 S	CHORAL ROOM D2	(1) (4)	Z
S	PLASTER	601	ASSUMED POSITIVE	5000 S	COVERED WALKWAY	(1)	N
М	2"X2" CERAMIC FLOOR TILES	602	ASSUMED POSITIVE	300 S	MENS AND WOMEN'S RESTROOM	(1)	N
М	4"X4" CERAMIC WALL TILE	603	ASSUMED POSITIVE	300 S	MENS AND WOMEN'S RESTROOM	(1)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico H

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: L

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code	e & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	17	NONE DETECTED	11,155 S	ALL ROOMS	( - /	PLE HMS-CHS-17 COLLECTED ON 8-88.	Y
Т	MUD JOINTS	19	5-10%	20 JOINTS	LIBRARY ATTIC	(11) NOT	ACCESSIBLE	Y
М	12" VINYL FLOOR TILE (BEIGE MOTTLED) & ADHESIVE	151	CERTIFIED ASBESTOS FREE	850 S	LIBRARY ENTRANCE/OFFICE	` '	TIFICATION LETTER ON FILE AS OF 005.	N
М	DRYWALL & JOINT COMPOUND	170	ASSUMED POSITIVE	10,000 S	THROUGHOUT	(1) (4) BEHI	IND TAG BOARD	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	800 S	THROUGHOUT	(1) (4)		N
М	CARPET (BROWN) & ADHESIVE	264	ASSUMED POSITIVE	5,000 S	LIBRARY	(1) (4)		N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS\Chico HS - 6 Month Survillance.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District
School: Chico Senior High School

Inspector: Building: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	on: Code & Comments	Friable Yes/No
Т	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(12)	UNABLE TO LOCATE	Y
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	59	NONE DETECTED	4,500 S	CLASSROOMS 1-5	(13)	SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	Y
Т	MUD JOINTS	60	5-10%	12 L	CLASSROOM 1	(12)	UNABLE TO LOCATE	Y
М	KILN BRICK (TAN)	151	NONE DETECTED	10.5 S	INSIDE OLDER TRANSITE PANELS ENCASED KILN	(13)	SAMPLE HMS-R1303-01A COLLECTED ON 4-13-04.	N
М	KILN BRICK (WHITE)	152	NONE DETECTED	10.5 S	LARGER OLDER TRANSITE PANEL ENCASED KILN	(13)	SAMPLE HMS-R1303-02A COLLECTED ON 4-13-04.	N
М	KILN BRICK (WHITE)	153	NONE DETECTED	10.5 S	METAL ENCASED CRESS ELECTRIC KILN MODEL A-22-H	(13)	SAMPLE HMS-R1303-03A COLLECTED ON 4-13-04.	N
М	KILN BRICK	154	NONE DETECTED	10.5 S	SMALL KILN APPROXIMATELY 2' HIGH BY 14" SQUARE WITH B-19 ON SIDE	(13)	SAMPLE HMS-R1303-04A COLLECTED ON 4-13-04.	N
М	KILN BRICK	155	NONE DETECTED	10.5 S	3' SQUARE KILN	(13)	SAMPLE HMS-R1303-05A COLLECTED ON 4-13-04.	N
S	STUCCO	156	<1% CHRYSOTILE	220 S	EXTERIOR WALL AT SOUTH SIDE OF CERAMICS LAB ROOM 505	(1) (4)	SAMPLE HMS-R1303-06A COLLECTED ON 4-13-04.	N
М	VINYL COVERED TAGBOARD	157	NONE DETECTED	800 S	CERAMICS LAB ROOM 505D	(13)	SAMPLE HMS-R1303-07A COLLECTED ON 4-13-04.	N
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	400 S	THROUGHOUT	(1) (4)		N
М	12" X 12" VINYL FLOOR TILE (GRAY) AND MASTIC	503	ASSUMED POSITIVE	200 S	STUDIO 999	(1) (4)		N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS - 6 Month Survillance.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Senior High School

Building: S

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS	22	NONE DETECTED	8,000 S	ROOMS 1-7	(13) SAMPLE HMS-CHS-22 COLLECTED ON 3-28-88.	Y
Т	MUD JOINTS	23	5-10%	40 JOINTS	ROOMS 1-7	(12) UNABLE TO LOCATE	Y
М	9" VINYL FLOOR TILE (BEIGE MARBLED) & ADHESIVE	24	1-5%	8,100 S	SCIENCE LAB/STORAGE	(1) (5) MISSING TILES	N
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	171	ASSUMED POSITIVE	8,000 S	ALL ROOMS EXCEPT SCIENCE LAB/STORAGE	(1) (4)	N
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	500 S	THROUGHOUT	(1) (4)	N
М	SCIENCE TABLE TOPS	600	ASSUMED POSITIVE	UNDETERMINED	ROOMS 1-7	(1)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS - 6 Month Survillance.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

Building: G (Gym) School: Chico Senior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88. ADDITIONAL SAMPLES HMS-93103- 03A-C COLLECTED ON 7-8-93.	N
Т	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM AND BOILER ROOM CRAWL SPACES	(10) ISOLATED & RESTRICTED (11) INACCESSIBLE	Υ
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	150 S	COACH OFFICE (GIRLS & BOYS)	(1) (4)	Ν
М	12" VINYL FLOOR TILE (RED, WHITE, AND BLACK) & ADHESIVE	264	ASSUMED POSITIVE	500 S	COACH OFFICE (GIRLS & BOYS)	(1) (4)	N
М	DRYWALL AND JOINT COMPOUND	604	ASSUMED POSITIVE	1000 S	LOCKER ROOM ENTRANCE	(1)	N
S	DRYWALL TEXTURE	605	ASSUMED POSITIVE	1000 S	LOCKER ROOM ENTRANCE	(1)	Y

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico HS - 6 Month Survillance.wpd

### **CONDITION CODE**

**General Condition:** (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (5) Yes (If Yes, explain under comments) (4) No

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated:

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous:

### CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: IT

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	500 S	THROUGHOUT	(1) (4)	N
М	DRYWALL	257	ASSUMED POSITIVE	8,000 S	ROOMS 1, 2, 4, & 5	(1) (4) (7)	N
М	12" VINYL FLOOR TILE (LIGHT GRAY MOTTLED) & ADHESIVE	261	ASSUMED POSITIVE	4,500 S	ROOMS 1, 4, & 5	(1) (4)	N
М	2'X4' CEILING PANELS (SOLID PATTERN)	270	ASSUMED POSITIVE	4,500 S	THROUGHOUT, EXCEPT WOOD SHOP	(1) (4)	Y
М	12" X 12" ACOUSTICAL CEILING TILE	505	ASSUMED POSITIVE	3,000 S	WOOD SHOP	(1)	Y
М	CMU BRICK	606	ASSUMED POSITIVE	5000 S	THROUGHOUT	(1)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS\Chico H

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

## CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District School: Chico Senior High School Date of Inspection: Inspector:

Building: AG-1100

1			l l		•	
Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
WALL PLASTER	46	1-5%	950 S	CLASSROOM 2	(1) (4)	N
WALL PLASTER	160	NONE DETECTED	150 S	SOUTH WEST CORNER AREA BY DOOR OF TOILET ROOM OF CLASSROOM 1	(13) SAMPLE HMS-R1303-15A COLLECTED ON 4-13-04.	N
STUCCO	161	NONE DETECTED	1,000 S	EXTERIOR SOUTH ENTRY DOOR AND EAST WALL BY COKE MACHINE	(13) SAMPLES HMS-R1303-16A & B COLLECTED ON 4-13-04.	N
LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)	162	NONE DETECTED	100 S	CLASSROOM 3	(13) SAMPLE HMS-R1303-17A COLLECTED ON 4-13-04.	N
GLOSS LIKE FLOOR FINISH (BROWN COLORED)	163	NONE DETECTED	300 S	HALLWAY BY CLASSROOM 2	(13) SAMPLE HMS-R1303-13A COLLECTED ON 4-13-04.	N
GLOSS LIKE FLOOR FINISH (GREEN COLORED)	164	NONE DETECTED	50 S	TOILET ROOM OFF CLASSROOM 1	(13) SAMPLE HMS-R1303-14A COLLECTED ON 4-13-04.	N
12" X 12" MOTTLED VINYL FLOOR TILE (TAN)	506	ASSUMED POSITIVE	2,300 S	AG 1-2	(1) (4)	N
VINYL BASE COVE (TAN) ADHESIVE	507	ASSUMED POSITIVE	250 L	AG 1-2	(1) (4)	N
SHEET VINYL FLOORING (GRAY)	508	ASSUMED POSITIVE	100 S	TOILET 987A AND RESTROOM	(1) (4)	N
	WALL PLASTER  WALL PLASTER  STUCCO  LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)  GLOSS LIKE FLOOR FINISH (BROWN COLORED)  GLOSS LIKE FLOOR FINISH (GREEN COLORED)  12" X 12" MOTTLED VINYL FLOOR TILE (TAN)  VINYL BASE COVE (TAN) ADHESIVE  SHEET VINYL	WALL PLASTER 46  WALL PLASTER 160  STUCCO 161  LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)  GLOSS LIKE FLOOR FINISH (BROWN COLORED)  GLOSS LIKE FLOOR FINISH (GREEN COLORED)  12" X 12" MOTTLED VINYL FLOOR TILE (TAN)  VINYL BASE COVE (TAN) ADHESIVE  SHEET VINYL 508	WALL PLASTER  WALL PLASTER  WALL PLASTER  160  NONE DETECTED  STUCCO  161  NONE DETECTED  LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)  GLOSS LIKE FLOOR FINISH (BROWN COLORED)  GLOSS LIKE FLOOR FINISH (GREEN COLORED)  12" X 12" MOTTLED VINYL FLOOR TILE (TAN)  VINYL BASE COVE (TAN) ADHESIVE  SHEET VINYL  508  ASSUMED POSITIVE	WALL PLASTER         46         1-5%         950 S           WALL PLASTER         160         NONE DETECTED         150 S           STUCCO         161         NONE DETECTED         1,000 S           LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)         162         NONE DETECTED         100 S           GLOSS LIKE FLOOR FINISH (BROWN COLORED)         163         NONE DETECTED         300 S         S           GLOSS LIKE FLOOR FINISH (GREEN COLORED)         164         NONE DETECTED         50 S         S           12" X 12" MOTTLED VINYL FLOOR TILE (TAN)         506         ASSUMED POSITIVE         2,300 S         NONE DETECTED         250 L           VINYL BASE COVE (TAN) ADHESIVE         507         ASSUMED ASSUMED         250 L         NONE DETECTED         250 L           SHEET VINYL         508         ASSUMED         100 S         100 S	WALL PLASTER         46         1-5%         950 S         CLASSROOM 2           WALL PLASTER         160         NONE DETECTED         150 S         SOUTH WEST CORNER AREA BY DOOR OF TOILET ROOM OF CLASSROOM 1           STUCCO         161         NONE DETECTED         1,000 S         EXTERIOR SOUTH ENTRY DOOR AND EAST WALL BY COKE MACHINE           LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)         162         NONE DETECTED         100 S         CLASSROOM 3           GLOSS LIKE FLOOR FINISH (BROWN COLORED)         163         NONE DETECTED         300 S         HALLWAY BY CLASSROOM 2           GLOSS LIKE FLOOR FINISH (GREEN COLORED)         164         NONE DETECTED         50 S         TOILET ROOM OFF CLASSROOM 1           12° X 12° MOTTLED VINYL FLOOR TILE (TAN)         506         ASSUMED POSITIVE         2,300 S         AG 1-2           VINYL BASE COVE (TAN) ADHESIVE         507         ASSUMED POSITIVE         250 L AG 1-2           SHEET VINYL         508         ASSUMED         100 S         TOILET 987A AND RESTROOM	WALL PLASTER         46         1-5%         950 S         CLASSROOM 2         (1) (4)           WALL PLASTER         160         NONE DETECTED         150 S         SOUTH WEST CORNER AREA BY DOOR OF TOILET ROOM OF CLASSROOM 1         (13)         SAMPLE HMS-R1303-15A COLLECTED ON 4-13-04.           STUCCO         161         NONE DETECTED         1,000 S         EXTERIOR SOUTH ENTRY DOOR AND EAST WALL BY COKE MACHINE         (13)         SAMPLES HMS-R1303-16A & B COLLECTED ON 4-13-04.           LINOLEUM LIKE COUNTER TOP WITH ASPHALT LIKE BACKING (GREEN)         NONE DETECTED         100 S         CLASSROOM 3         (13)         SAMPLE HMS-R1303-17A COLLECTED ON 4-13-04.           GLOSS LIKE FLOOR FINISH (GREEN)         163         NONE DETECTED         300 S         HALLWAY BY CLASSROOM 2         (13)         SAMPLE HMS-R1303-13A COLLECTED ON 4-13-04.           GLOSS LIKE FLOOR FINISH (GREEN COLORED)         164         NONE DETECTED         50 S         TOILET ROOM OFF CLASSROOM 1         (13)         SAMPLE HMS-R1303-14A COLLECTED ON 4-13-04.           GLOSS LIKE FLOOR FINISH (GREEN COLORED)         164         NONE DETECTED         50 S         TOILET ROOM OFF CLASSROOM 1         (13)         SAMPLE HMS-R1303-14A COLLECTED ON 4-13-04.           12" X 12" MOTTLED (TAN)         506         ASSUMED         2,300 S         AG 1-2         (1) (4)           VINYL BASE COVE (TAN)

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico HS \Chico HS - 6 Month Survillance.wpd

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TACE AMOUNTS OF ASBESTOS