MPR AND STAFF DINNING

EACHI TV DESTROOMS

NURSE OFFICE

NURSE OFFICE, CONFERENCE ROOM AND

District: Chico Unified School District

(DARK GRAY) & ADHESIVE

12" VINYL FLOOR TILE

(BLUE MOTTLED) &

DRYWALL TEXTURE

12" VINYL FLOOR TILE

(GRAY/BLUE) &

ADHESIVE

ADHESIVE

School: Chico Junior High School

Material Class

S

Μ

Μ

М

S

Μ

CONDITION CODE

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

ASSUMED

POSITIVE

ASSUMED

ASSUMED

POSITIVE

108

109

110

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Change in Condition: (4) No (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: (6) Repaired Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

5,570 S

1,400 S

200 S

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
CEILING PLASTER	8	1-5%	6,500 S	TEACHER'S DINING ROOM, MPR AND REST OF THE WING	(1) (4)	Ν
DRYWALL & JOINT COMPOUND	106	ASSUMED POSITIVE	5,000 S	THROUGHOUT UNIT - ALL WALLS, KITCHEN CEILING AND FACULTY RESTROOMS	(1) (4)	Ν
LINOLEUM (NON-SLIP) (DARK GRAY) &	107	ASSUMED POSITIVE	2,200 S	KITCHEN, KITCHEN OFFICE AND JANITOR'S CLOSET	(1) (4)	Ν

(1)(4)

(1) (4)

(1) (4)

Date of Inspection:

Building: (FKA P) MPR

Inspector:

Ν

Ν

Ν

District: Chico Unified School District

School: Chico Junior High School

Building: (FKA P) MPR

(Continued)

Inspector:

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	SHEET VINYL FLOORING - (GRAY/ WHITE PEBBLED)	111	ASSUMED POSITIVE	50 S	NURSE RESTROOMS	(1) (4)	Ν
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	700 L	THROUGHOUT UNIT	(1) (4)	Ν
М	CARPET ADHESIVE	252	ASSUMED POSITIVE	500 S	NURSE OFFICE & CONFERENCE ROOM	(1) (4)	Ν
S	STUCCO	254	ASSUMED POSITIVE	1,200 S	COVERED WALKWAY	(1) (4)	Ν
м	SINK UNDERCOATING	500	ASSUMED POSITIVE	5 S	STAFF DINING ROOM	(1)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 200, 202, 204, 206 & 208 (FKA O)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
s	CEILING PLASTER	8	1-5%	500 S	TITLE ONE OFFICE	(1) (4) MINOR CRACKS IN THE MIDDLE AREA.	Ν
М	CEMENTITIOUS	96		640 S	EXTERIOR OF UNIT	(1) (4)	Ν
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	 (1) (4) (11) TITLE ONE OFFICE COVERED WITH CARPET. 	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	99	ASSUMED POSITIVE	4,000 S	THROUGHOUT CLASSROOM WING	(1) (4)	Y
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOM WING	(1) (4)	Ν
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL	255	ASSUMED POSITIVE	800 S	CLASSROOMS 202-208 AT LOWER WALLS	 (1) APPEARS TO BE PAINTED WOOD PANELS. (12) FURTHER INVESTIGATION REQUIRED 	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not InspectedCONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 200, 202, 204, 206 & 208 (FKA O) (Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	EPOXY FLOORING (SALT AND PEPPER)	501	ASSUMED POSITIVE	500 S	TITLE 1 OFFICE	(1) (4)	Ν
М	CARPET ADHESIVE	502	ASSUMED POSITIVE	200 S	RESTROOMS	(1) (4)	Ν
М	DRYWALL AND JOINT COMPOUND	503	ASSUMED POSITIVE	1,500 S	RESTROOMS	(1) (4)	Ν
S	KNOCKDOWN TEXTURE	504	ASSUMED POSITIVE	1, 500 S	RESTROOMS	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more) Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted (6) Repaired (7) Removed (8) Encapsulated Abated: Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 300, 302, 304 & 306 (FKA N)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VINYL FLOOR TILE (RED) & ADHESIVE	2	1-5%	70 S	JANITOR'S CLOSET (FKA ROOM 310)	(1) (4)	N
S	CEILING PLASTER	8	1-5%	200 S	JANITOR'S CLOSET (FKA ROOM 310)	(1) (4)	N
м	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	2,000 S	CLASSROOMS 300, 302	(1) (4)	N
М	2' X 4' CEILING PANELS - FISSURE PATTERN	99	ASSUMED POSITIVE	4,000 S	THROUGHOUT CLASSROOMS AND SCIENCE PREP	(1) (4)	Y
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOMS & JANITOR CLOSET	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd


CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good Change in Condition: (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected (4) No (7) Removed (8) Encapsulated Abated: (6) Repaired Miscellaneous:

(9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS



District: Chico Unified School District

School: Chico Junior High School

Building: N (Classrooms 300, 302, 304 & 306) (Continued)

						()	<u>oonanaoa)</u>
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAYS	(1) (4)	N
м	DRYWALL	255	ASSUMED POSITIVE	2,900 S	CLASSROOMS 300-306, SCIENCE PREP AND GIRL'S RESTROOM	(1) (4)	N
м	EPOXY FLOORING (SALT AND PEPPER)	505	ASSUMED POSITIVE	200 S	GIRL'S RESTROOM	(1)(4)	N
М	ADHESIVE ASSOCIATED WITH VINYL BASE COVE	506	ASSUMED POSITIVE	250 L	CLASSROOMS 304-306 AND SCIENCE PREP	(1) (4)	N
s	KNOCKDOWN TEXTURE	507	ASSUMED POSITIVE	2,900	CLASSROOMS 304-306, SCIENCE PREP AND GIRL'S RESTROOM	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous: (1) Good

(6) Repaired

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments)
(13) Non-Asbestos/Not Inspected
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 400, 402, 404, 406 & 408 (FKA M)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	112	ASSUMED POSITIVE	175 S	PSYCHOLOGIST OFFICE & STAFF RESTROOM	(1) (4)	Ν
М	TRANSITE PANELS	113	ASSUMED POSITIVE	640 S	EXTERIOR	(1) (4)	N
м	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	114	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	(1) (4)	Ν
М	2' X 4' CEILING PANELS (PINHOLE/GASH PATTERN)	115	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	(1) (4)	Y
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOMS	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 400, 402, 404, 406 & 408 (FKA M) (Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CARPET ADHESIVE	252	ASSUMED POSITIVE	450 S	PSYCHOLOGIST	(1) (4)	Ν
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	Ν
М	DRYWALL AND JOINT COMPOUND	255	ASSUMED POSITIVE	1,500 S	CLASSROOMS 400-408 AT LOWER NORTH WALLS, STAFF AND BOYS RESTROOMS	(1) (4)	N
М	EPOXY FLOORING (SALT AND PEPPER)	508	ASSUMED POSITIVE	400 S	STAFF AND BOYS RESTROOMS	(1) (4)	N
S	KNOCKDOWN TEXTURE	509	ASSUMED POSITIVE	500 S	STAFF AND BOYS RESTROOMS	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 500, 502, 504 & 506 (FKA L)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
м	9" VINYL FLOOR TILE (RED) & ADHESIVE	2	1-5%	70 S	MIGRANT EDUCATION OFFICE	(1) (4)	Ν
S	CEILING PLASTER	8	1-5%	100 S	MIGRANT EDUCATION OFFICE'S	(1) (4)	Ν
т	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	CLASSROOM 502	(1) (4) VISIBLE IN STORAGE MISSING 12" CEILING TILES	Y
т	PIPE WRAP STRAIGHT	95	ASSUMED POSITIVE	UNDETERMINED	CLASSROOM 506	(11) UNABLE TO LOCATE MATERIAL	Y
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	640 S	EXTERIOR OF UNIT	(1) (4)	Ν
М	12" VINYL FLOOR TILE (LIGHT GRAY /BEIGE) & ADHESIVE	98	ASSUMED POSITIVE	975 S	CLASSROOM 500	(1) (4)	N
м	2' X 4' CEILING PANELS (FISSURE PATTERN)	116	ASSUMED POSITIVE	975 S	CLASSROOM 500	(1) (4)	Y
М	ADHESIVE ASSOCIATED WITH RED VINYL BASE COVE	509	ASSUMED POSITIVE	25 L	MIGRANT'S EDUCATION OFFICE	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

 General Condition:
 (1) Good
 (2) Damaged
 (3) Significantly Damaged (25% or more)

 Change in Condition:
 (4) No
 (5) Yes (If Yes, explain under comments)
 (13) Non-Asbestos/Not Inspected

 Abated:
 (6) Repaired
 (7) Removed
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

 Miscellaneous:
 (11) Inaccessible, no inspection data
 (12) Other (Explain under comments)
 (13) Non-Asbestos/Not Inspected

 CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 500, 502, 504 & 506 (FKA L) (Continued)

							oontinucu)
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	100 L	CLASSROOM 500	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAYS	(1) (4)	N
М	DRYWALL AND JOINT COMPOUND	255	ASSUMED POSITIVE	3,000 S	ROOM 500 ATT LOWER NORTH WALLS ROOMS 502-506 AND GIRL'S AND STAFF RESTROOM	(1) (4)	N
М	12" ACOUSTIC CEILING TILE	256	ASSUMED POSITIVE	50 S	ROOM 502 STORAGE 2	(1) (4)	N
NS	PLASTER	257	ASSUMED POSITIVE	300 S	ROOM 502 STORAGES 1 & 2	(1) (4)	N
S	KNOCKDOWN TEXTURE	510	ASSUMED POSITIVE	2,000 S	ROOMS 502-506 AND GIRL'S AND STAFF RESTROOMS	(1) (4)	N
М	EPOXY FLOORING (SALT AND PEPPER)	511	ASSUMED POSITIVE	3,000 S	ROOMS 502-506 AND GIRLS AND STAFF RESTROOMS	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) GoodChange in Condition:(4) NoAbated:(6) RepairedMiscellaneous:(11) Inaccess

(1) Good
(2) Damaged (3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(13) Non-Asbestos/Not Inspected
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

(1) Good

(4) No

School: Chico Junior High School

Building: Maintenance (FKA J)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CARPET ADHESIVE	512	ASSUMED POSITIVE	25 S	MAINTENANCE	(1)	Ν
М	2' X 4' DROP-IN CEILING PANEL (PINHOLE/GASH)	513	ASSUMED POSITIVE	100 S	MAINTENANCE	(1)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition: Change in Condition: (2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: Miscellaneous:

(7) Removed (8) Encapsulated (6) Repaired

(9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

Date of Inspection:

Inspector:

School: Chico Junior High School

Building: Classrooms 501, 503 & 505 (FKA H & I Classroom 501 A&B, 503, 505)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" ACOUSTIC CEILING TILE	17	NONE DETECTED	4,300 S	WOOD SHOP, DURST THEATER, MUSIC CLASSROOM, & PRACTICE CLASSROOMS	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988. DURST THEATER & MUSIC CLASSROOM ARE SAME AREA	Y
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	100 S	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	Ν
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	2,200 S	COMPUTER ROOM, MATERIAL STORAGE, STORAGE, & STAFF OFFICE, DURST THEATER, OFFICES, MUSIC CLASSROOM, AND PRACTICE CLASSROOMS	(1) (4) DURST THEATER & MUSIC CLASSROOM ARE SAME AREA	Ν
S	CEILING PLASTER	117	ASSUMED POSITIVE	700 S	OFFICES, STORAGE ROOMS, AND WOOD SHOP CLASSROOM	(1) (4)	Ν
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	200 S	CLASSROOM	(1) (4)	Ν
s	STUCCO	254	ASSUMED POSITIVE	1,500 S	COVERED WALKWAY	(1) (4)	Ν
М	12" X 12" VINYL FLOOR TILE (GRAY)	513	ASSUMED POSITIVE	120 S	OFFICE	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:	(1) Good	(2) Damaged	d (3) Significantly Damaged (25% or more)
Change in Condition:	(4) No	(5) Yes (If Yes,	es, explain under comments) (13) Non-Asbestos/Not Inspected
Abated:	(6) Repaired	(7) Removed	d (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous:	(11) Inaccessibl	e, no inspection	on data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
CONSULT ORIGINAL	AND SUPPLEMI	ENTARY INSPE	PECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

School: Chico Junior High School

Building: Main Office Building (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	2,500 S	LIBRARY	(1) (4)	N
М	12" VINYL FLOOR TILE (GRAY) & ADHESIVE	97	ASSUMED POSITIVE	600 S	ADMINISTRATION OFFICES, HALLWAY, AND LIBRARY	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	101	ASSUMED POSITIVE	14,100 S	THROUGHOUT UNIT AND LIBRARY	(1) (4) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000.	Ν
S	DRYWALL TEXTURE	118	ASSUMED POSITIVE	14,100 S	THROUGHOUT UNIT	(1) (4)	Ν
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	800 S	THROUGHOUT UNIT	(1) (4)	Ν
М	12" VINYL FLOOR TILE (DARK GRAY) & ADHESIVE	251	ASSUMED POSITIVE	100 S	ROOM 211	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

 CONDITION CODE

 General Condition:
 (1) Good
 (2) Damaged
 (3) Significantly Damaged (25% or more)

 Change in Condition:
 (4) No
 (5) Yes (If Yes, explain under comments)
 (13) Non-Asbestos/Not Inspected

 Abated:
 (6) Repaired
 (7) Removed
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

 Miscellaneous:
 (11) Inaccessible, no inspection data
 (12) Other (Explain under comments)
 (13) Non-Asbestos/Not Inspected

 CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

% Asb. Ft²/L.F. Condition: Code & Comments Friable Material Material Homo Location Class Mat. # Yes / No М CARPET ADHESIVE 252 ASSUMED 4,000 S **OFFICES & LIBRARY** (1) (4) Ν POSITIVE Μ 12" VINYL FLOOR TILE 253 ASSUMED 700 S HALLWAY (1)(4)Ν (LIGHT GRAY) & POSITIVE ADHESIVE Μ SHEET VINYL FLOORING ASSUMED 30 S CONFERENCE ROOM RESTROOM (1) 514 Ν (WHITE/BLUE PEBBLED) POSITIVE Μ 2' X 2' CARPET ASSUMED 320 S LIBRARY 515 (1) Ν SQUARES(TAN/BROWN) POSITIVE AND ADHESIVE ASSUMED Μ 2' X 2' VINYL FLOOR TILE 516 750 S LIBRARY AND LIBRARIANS OFFICE (1) Ν POSITIVE (GRAY)

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted (6) Repaired (7) Removed (8) Encapsulated Abated: Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

Inspector:

Building: Main Office Building (FKA A) (Continued)

District: Chico Unified School District

Date of Inspection:

Inspector:

School: Chico Junior High School

Building: Classrooms 201, 203, 205, 207, 209 & 211 (FKA B)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	700 S	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	N
м	2' X 4' CEILING PANELS - (PINHOLE/GASH PATTERN)	99	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VINYL FLOOR TILE (LIGHT GRAY) & ADHESIVE	102	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	Ν
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	720 S	THROUGHOUT CLASSROOMS	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL	255	ASSUMED POSITIVE	2,000 S	CLASSROOMS AT LOWER NORTH WALLS	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS\6 Month Surveillance.wpd
CONDITION CODE

General Condition:

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: Abated: (4) No(5) Yes (If Yes,(6) Repaired(7) Removed

(1) Good

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Building: Classrooms 301, 303, 305, 307, 309 & 311 (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	700 S	EXTERIOR OF UNIT	(1) (4)	Ν
М	2' X 4' CEILING PANELS - (PINHOLE/GASH PATTERN)	99	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	Ν
М	12" VINYL FLOOR TILE (LIGHT GRAY MOTTLED) & ADHESIVE	103	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	Ν
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	720 S	THROUGHOUT CLASSROOMS	(1) (4)	Ν
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	Ν
М	PRESSED WOOD	517	ASSUMED POSITIVE	2,000 S	CLASSROOMS AT LOWER NORTH WALLS	(1)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Change in Condition: (4) No (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

School: Chico Junior High School

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Classrooms 401, 403, 405, 407 & 409 (FKA D)

Material Material Homo. % Asb. Ft²/L.F. Location Condition: Code & Comments Friable Yes / No Class Mat. # TRANSITE PANELS ASSUMED EXTERIOR OF UNIT Ν Μ 96 700 S (1)(4)POSITIVE 2' X 4' CEILING PANELS 99 THROUGHOUT CLASSROOMS RENOVATED DURING THE SUMMER Ν Μ ASSUMED 4.800 S (1)(4)(PINHOLE/GASH POSITIVE OF 2000. PATTERN) М 12" VINYL FLOOR TILE 103 ASSUMED 4,800 S THROUGHOUT CLASSROOMS (1)(4)RENOVATED DURING THE SUMMER Ν POSITIVE (LIGHT GRAY MOTTLED) OF 2000. & ADHESIVE COVE BASE ADHESIVE ASSUMED М 250 650 S THROUGHOUT CLASSROOMS (1)(4)Ν POSITIVE STUCCO ASSUMED S 254 250 S COVERED WALKWAY (1)(4)Ν POSITIVE DRYWALL 255 1.800 S CLASSROOMS AT LOWER NORTH WALLS AND Μ ASSUMED (1)(4)Ν POSITIVE CUSTODIAL CLOSET SHEET VINYL FLOORING Μ 516 ASSUMED 130 S CUSTODIAL CLOSET (1) Ν (GRAY/BLUE PEBBLED) POSITIVE

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Gymnasium (FKA E)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" CEILING TILE	119	ASSUMED POSITIVE	5,000 S	GYMNASIUM	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	2,200 S	CORRIDOR	(1) (4)	Ν
s	TEXTURE ON CONCRETE & PLASTER WALLS	300	ASSUMED POSITIVE	1,800 S	COVERED WALKWAY	(1) (4)	Ν
М	DRYWALL & JOINT COMPOUND	301	ASSUMED POSITIVE	400 S	RESTROOMS	(1) (4)	Ν
S	TEXTURE ON DRYWALL	302	ASSUMED POSITIVE	400 S	RESTROOMS	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition	on:	(1) Goo	d	(2) D	amaged	(3) Signifi	cantly Da	maged	l (25%	or mo	ore)			
Change in Cond	lition:	(4) No		(5) Yo	es (If Yes	s, explain un	der comm	nents)	(1:	3) No	n-Asbes	tos/Not Insp	pected	
Abated:	(6) Rep	paired	(7)	Removed	(8) En	capsulated	(9)	Enclos	sed	(10) l	solated a	& Restricted	ł	
<u>Miscellaneous:</u>	(11) Ir	naccessik	ole, n	io inspecti	on data	(12) Other	(Explain	under c	comm	ents)	(13)	Non-Asbes	stos/Not Insp	ected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Locker Rooms (FKA F-PE Locker Rooms)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
Μ	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	5	1-5%	UNDETERMINED	CLASSROOM 18 STORAGE	(12) GIRL'S LOCKER ROOM	N
т	PIPE WRAP	105	ASSUMED POSITIVE	UNDETERMINED	IN CEILING PIPE CHASE	(10)	Y
М	12" X 12" VINYL FLOOR TILE	217	ASSUMED POSITIVE	50 S	OFFICE OF GIRL'S LOCKER ROOM	(1)	Ν
S	STUCCO	254	ASSUMED POSITIVE	800 S	COVERED WALKWAY	(1) (4)	Ν
S	PLASTER	260	ASSUMED POSITIVE	5,000 S	THROUGHOUT UNIT	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

School: Chico Junior High School

Building: Main Corridor (FKA Q)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	PLASTER	8	1-5%	10,000 S	CEILINGS & WALLS	(1) (4)	Ν
М	12" VINYL FLOOR TILE	97		500 S	THROUGHOUT CORRIDOR AT BORDERS	(1) (4)	Ν
м	12" VINYL FLOOR TILE (LIGHT GRAY) & ADHESIVE	253	ASSUMED POSITIVE	3,000 S	THROUGHOUT CORRIDOR	(1) (4)	Ν
М	COVE BASE ADHESIVE	261	ASSUMED POSITIVE	1,000 S	THROUGHOUT CORRIDOR	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Chico JHS\Chico JHS-6 Month Surveillance.wpd

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: