THREE-YEAR REINSPECTION

				CDS CODE 04-61424-6057129
SCHOOL Bidwell Junior High Sc	hool			SCHOOL PHONE NUMBER (530) 891-3080
ADDRESS 2376 North Avenue	(NUMBER)	(STREET)	(CITY) Chico	(ZIP) 95926

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of <u>FORM C</u> (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

	(630. 700.00).	CHECK (ONE		CHECK ONE			
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			ACBM		ASSUMED ACBM	
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1	Building 100	Х	Х	Χ		Х		Х
2.	Building 200 (AKA 600)		Х	Χ		Х		Х
3.	Building 300			Χ		Х		Х
4.	Building 400 (AKA 700)		Х	Χ		Х		Х
5.	Building 500		Х	Χ		Х		Х
6.	Building 800			Χ				Х
7.	Building 900		Х	Χ		Х		Х
8.	Maintenance Building No Suspect ACBM							
9.	Metal Storage No Suspect ACBM							
10.	Green House No Suspect ACBM							
11.	2 C-Trains No Suspect ACBM							
12.								
13.								
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

District: Chico Unified School District Inspector: Michael B. Galang

Building: 100 School: Bidwell Junior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	CEILING PLASTER	6	1-5 %	UNDETERMINED	ALL ROOMS EXCEPT KITCHEN	(1) (4)	N
Т	PIPEWRAP STRAIGHT	8	30-35%	UNDETERMINED	CHAIR STORE ROOM	(1) (4)	N
М	FAN VENT INSULATION	94	ASSUMED	UNDETERMINED	FAN ROOMS	(12) COULD NOT FIND THIS ROOM .	N
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS EXCEPT NORTH CHAIR STORE	(1) (4)	N
М	TRANSITE PIPE	99	ASSUMED	UNDETERMINED	KITCHEN AND BOILER ROOMS 1 & 2	(1) (4)	N
М	2 X 4 FCP'S	102	ASSUMED1	UNDETERMINED	ROOM 108	(1)	N
М	DRYWALL	103	ASSUMED	UNDETERMINED	KITCHEN	(1)	N
М	12" VFT	104	ASSUMED	UNDETERMINED	MULTI-PURPOSE ROOM, ROOMS 105, 106,	(1)	N

CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted (6) Repaired

Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

(11

Date of Inspection: 5/31/01

District: Chico Unified School District Inspector: Michael B. Galang

School: Bidwell Junior High School

Building: 200 (AKA 600)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOM 208 NEAR THE SINK	(11)	N
М	PLASTER	5	1-5 %	UNDETERMINED	ALL ROOMS, CLOSET (C), ROOM 204, HALLWAY, ROOM 250, AND GIRLS RESTROOM	(1) (4) WATER STAINS ARE PRESENT. SOME AREAS HAVE 1' X 1' PENETRATIONS WHERE SKY LIGHTS ARE GOING TO BE	N
М	DRYWALL	90	ASSUMED	UNDETERMINED	ROOM 250 & RESTROOM	(1)	N
М	12" VFT	93	ASSUMED	UNDETERMINED	ROOM 208	(1)	N
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS, HALLWAY 200, ROOM 250, & GIRLS RESTROOM	(1) (4)	N
М	TRANSITE PANEL	98	ASSUMED	UNDETERMINED	METAL SHOP	(1) (4)	N
М	12" ACT	105	ASSUMED	UNDETERMINED	ROOMS 206, 207, & 209	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

Milosofia no odo.

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

(11

Date of Inspection: 5/31/01

District: Chico Unified School District

Inspector: Michael B. Galang

School: Bidwell Junior High School

Building: 300

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	CEILING PLASTER	6	1-5%	UNDETERMINED	ALL CLASSROOMS AND HALLWAY 300	(1) (4)	N
М	2 X 4 FCP'S	106	ASSUMED	UNDETERMINED	ROOMS 308 & 309	(1)	N
М	9" VFT	300	ASSUMED	UNDETERMINED	ALL CLASSROOMS, HALLWAY 300, AND GIRLS RESTROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Miscellaneous:

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

(11)

Date of Inspection: 5/31/01

District: Chico Unified School District

Inspector: Michael B. Galang

School: Bidwell Junior High School

Building: 400 (AKA 700)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOMS 408 & 409	(11) COULD NOT FIND THE JOINTS DURING THE TIME OF INSPECTION.	N/A
Т	PIPE WRAP	14	ASSUMED	UNDETERMINED	PE BOILER ROOM & TUNNEL	(1) (4)	N
Т	TANK WRAP	15	ASSUMED	UNDETERMINED	PE BOILER ROOM	(1) (4)	N
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL CLASSROOMS	(1) (4)	N
М	TRANSITE PANELS	98	ASSUMED	UNDETERMINED	PANELS IS BOTH LOCKER ROOMS	(1) (4)	N
М	2 X 4 FCP'S	101	ASSUMED	UNDETERMINED	ROOMS 408, 408A, & 409	(1)	N
М	TRANSITE PIPE	107	ASSUMED	UNDETERMINED	CLOSET OF ROOM 405	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

Date of Inspection: 5/31/01

District: Chico Unified School District Inspector: Michael B. Galang

Building: 500 School: Bidwell Junior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS	(2) CRACKED TILE IN ROOM 502.	Z
М	DRYWALL	100	1%	UNDETERMINED	ALL ROOMS	(1) (4)	N
М	12" ACT	108	ASSUMED	UNDETERMINED	ROOMS 501, 502, OFFICE, AND PRACTICE ROOMS	(1)	N
Т	DUCT INSULATION	109	90-95%	UNDETERMINED	DUCT WORK-CEILING AND WALLS	(11) COULD FIND DURING THE TIME OF INSPECTION.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: (6) Repaired

Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

Date of Inspection: 5/31/01

District: Chico Unified School District

Inspector: Michael B. Galang

School: Bidwell Junior High School

Building: 800

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Y / N
М	9" VFT	95	ASSUMED	UNDETERMINED	LIBRARY	(1) (4)	N
М	12" ACT	109	ASSUMED	UNDETERMINED	LIBRARY, OFFICES, & AUDIO VISUAL	(1)	N
М	PLASTER	110	ASSUMED	UNDETERMINED	THROUGHOUT THE UNIT	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

Date of Inspection: 5/31/01

District: Chico Unified School District

Inspector: Michael B. Galang

School: Bidwell Junior High School

Building: 900

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	PIPE WRAP STRAIGHT	17	15-20%	UNDETERMINED	GYM & STOREROOM	(1) (4)	N
Т	PIPE WRAP CORNER	18	5-10%	UNDETERMINED	GYM, BOILER ROOM, & STOREROOM	(1) (4)	N
М	12" ACT	111	ASSUMED	UNDETERMINED	GYM	(1) SOME TILES HAVE BEEN REMOVED. THE MASTIC IS SHOWING	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

C:\Clients\ChicoUSD\2001Reinsp\R0329\BidwellJHS\HMR

Date of Inspection: 5/31/01