

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection:

District: Chico Unified School District

Inspector:

School:

Citrus Elementary School
Building: Unit D - Classrooms 13-16 & Library

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VINYL FLOOR TILE (OFF WHITE WITH BROWN STREAKS) & ADHESIVE	1	1-5%	3,800 S	CLASSROOMS 13-16 AND WORK ROOM	(11) BENEATH CARPET IN WORK ROOM.	N
M	2 X 4 CEILING PANELS FISSURE PATTERN	2	ASSUMED POSITIVE	5,000 S	13, 14, 15, 16 & LIBRARY	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	3	ASSUMED POSITIVE	6,000 S	13, 14, 15, 16, LIBRARY AND WORK ROOM	(11) BEHIND TAGBOARD.	N
M	12" ACOUSTIC CEILING TILE FISSURE PATTERN	4	ASSUMED POSITIVE	200 S	WORK ROOM	(1) (4)	N
S	PLASTER	5	ASSUMED POSITIVE	800 S	RESTROOMS (2)	(1) (4)	N
M	VENT DUCT CONNECTOR	6	35-40%	UNDETERMINED	RESTROOM ATTIC	(11)	N
M	CARPET ADHESIVE	251	ASSUMED POSITIVE	1,500 S	LIBRARY & WORK ROOM	(1) (4)	N
S	STUCCO	260	ASSUMED POSITIVE	2,000 S	EXTERIOR WALLS	(1) (4)	N
M	COVE BASE ADHESIVE	261	ASSUMED POSITIVE	600 S	THROUGHOUT UNIT D	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Citrus ES\Citrus 6 Month Surveillance.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(14) Non AHERA/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

HOMOGENEOUS ACBM RECORDS

SIX MONTH SURVEILLANCE

Date of Inspection:

District: Chico Unified School District

Inspector:

School:

Citrus Elementary School
Building: A - Classrooms 1-8

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 CEILING PANELS FISSURE PATTERN	2	ASSUMED POSITIVE	6,400 S	CORRIDORS AND ALL CLASSROOMS	(1) (4)	N
S	PLASTER	5	ASSUMED POSITIVE	8,000 S	THROUGHOUT	(1) (4)	N
M	12" VINYL FLOOR TILE(TURQUOISE MOTTLED WITH SALMON, RED, & GREEN ACCENT TILES) & ADHESIVE	10	ASSUMED POSITIVE	1,200 S	CORRIDORS AND COPY ROOM	(1) (4)	N
M	12" VINYL FLOOR TILE GRAY	11	ASSUMED POSITIVE	UNDETERMINED	HEALTH ROOM	(11) LETTER ON FILE. COULD NOT LOCATE.	N
T	PIPEWRAP STRAIGHT	12	40-50%	UNDETERMINED	BASEMENT & STORAGE	(11) ASSUMED POSITIVE TO EXIST IN WALL CAVITIES. MATERIAL IS INACCESSIBLE, UNABLE TO INSPECT SO NO ASSESSMENT MADE.	Y
M	12" VFT (TAN WITH BROWN STREAKS)	12	ASSUMED POSITIVE	800 S	READING ROOM CLASSROOM AND CLASSROOMS 1-8	(1)	N
M	VINYL COVE BASE/ADHESIVE (LIGHT BROWN)	13	ASSUMED POSITIVE	600 L	CLASSROOMS 1-8, 1A, 2A, 3A,4A, 5A, 6A, 7A, & 8A	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(14) Non AHERA/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

HOMOGENEOUS ACBM RECORDS

SIX MONTH SURVEILLANCE

Date of Inspection:

District: Chico Unified School District

Inspector:

School:

Citrus Elementary School
Building: C (Kitchen/MPR)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACOUSTIC CEILING TILE 1/8" HOLE PATTERN WITH BROWN MASTIC	4	ASSUMED POSITIVE	2,400 S	MPR	(1) (4) (12) SOME MISSING TILES 30 SQUARE FEET.	N
S	PLASTER	5	ASSUMED POSITIVE	800 S	KITCHEN, STAGE FAN ROOM	(1) (4)	N
M	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	7	1-5%	1,800 S	MPR	(11) COVERED WITH 12" VINYL FLOOR TILE TAN.	N
T	PIPEWRAP	9	ASSUMED POSITIVE	UNDETERMINED	STAGE FAN ROOMS (2)	(11) ASSUMED POSITIVE TO EXIST IN WALL CAVITIES. MATERIAL IS INACCESSIBLE, UNABLE TO INSPECT SO NO ASSESSMENT MADE.	Y
M	12" VINYL FLOOR TILE (TAN) & ADHESIVE	150	ASSUMED POSITIVE	2,000 S	MPR / KITCHEN	(1) (4)	N
M	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	500 L	THROUGHOUT	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Citrus ES\Citrus 6 Month Surveillance.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(14) Non AHERA/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS