Date of Inspection:

Chico Unified School District

District:

School: Corporate Yard

Building: A

Inspector:

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	9" VINYL FLOOR TILE & ADHESIVE	2	1-5%	980 S	LOCKERS & ELECTRICIAN OFFICE	(1)	FORMERLY MECHANICS OFFICE & MAINTENANCE OFFICE	N
М	12" VINYL FLOOR TILE (BEIGE) & ADHESIVE	4	TRACE	60 S	UPSTAIRS RESTROOM	(1) (4)	SAMPLE HMS-COP-04 COLLECTED IN 1988.	N
М	12" VINYL FLOOR TILE (YELLOW) & ADHESIVE	6	TRACE	200 S	TRANSPORTATION OFFICE, ROLLING CHAIR WEAR-OUT	(2) (4)	SAMPLE HMS-COP-06 COLLECTED IN 1988.	N
М	12" ACOUSTIC CEILING TILE - 1/8" HOLE PATTERN	7	NONE DETECTED	680 S	DRIVERS LOUNGE & TRANSPORTATION OFFICE	(13)	SAMPLE HMS-COP-07 COLLECTED IN 1988.	N/A
М	12" VINYL FLOOR TILE (GREY/BLUE) & ADHESIVE	8	ASSUMED POSITIVE	260 S	TRANSPORTATION OFFICE	(1) (4)		N
S	DRYWALL TEXTURE	9	ASSUMED POSITIVE	200 S	TRANSPORTATION OFFICE	(1) (4)		N
М	9" VINYL FLOOR TILE (PINK) & ADHESIVE	62	ASSUMED POSITIVE	500 S	KEY SMITH SHOP	(1) (4)		N
М	DRYWALL	77	NONE DETECTED	5,000 S	ALL ROOMS	(13)	SAMPLE HMS-CUSD-CORP-77A  COLLECTE D ON 5-20- 92.	N/A
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	78	ASSUMED POSITIVE	100 S	DRIVERS ROOM AT TRANSPORTATION OFFICE	(1) (4)	COVERED BY CARPET.	N
М	GLAZING COMPOUND	79	ASSUMED POSITIVE	50 L	GROUND SHED WINDOWS	(1) (4)		N
М	12" X 12" VINYL FLOOR TILE (WHITE)	400	ASSUMED POSITIVE	150 S	BREAK ROOM	(1)(4)		N

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Chico Unified School District

Date of Inspection:

Inspector:

School: Corporate Yard

Building: E - Paint Shop

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	75	1-5% IN SKIM COAT	2,000 S	PAINT SHOP - ALL AREAS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\6 Month Surveillance\Corp Yard - 6 Month.wpd

District:

#### CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Chico Unified School District

Date of Inspection:

Inspector:

School: Corporate Yard

Building: Ground Shed

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	76	NONE DETECTED	500 S	ALL ROOMS	(13)	N/A

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\6 Month Surveillance\Corp Yard - 6 Month.wpd

District:

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

Chico Unified School District

Inspector:

School: Corporate Yard

Building: Building 15 - M & O Office

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" x 12" WHITE MOTTLED VINYL FLOOR TILE	401	ASSUMED POSITIVE	200 S	OFFICE	(1)	N
М	ADHESIVE ASSOCIATED WITH BLUE CARPET	402	ASSUMED POSITIVE	250 S	OFFICE	(1)	N
М	2' X 4' FIBERGLASS DROP-IN CEILING PANELS	403	ASSUMED POSITIVE	350 S	OFFICE	(1)	N
М	ADHESIVE ASSOCIATED WITH 4" VINYL BASE COVE	404	ASSUMED POSITIVE	300 S	OFFICE	(1)	N
М	2' X 4' (PINHOLE) DROP- IN CEILING PANELS	405	ASSUMED POSITIVE	250 S	OFFICE	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\6 Month Surveillance\Corp Yard - 6 Month.wpd

District:

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Chico Unified School District

Date of Inspection:

Inspector:

School: Corporate Yard

Building: Bathrooms - 17

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	SHEET VINYL FLOORING	406	ASSUMED POSITIVE	400 S	RESTROOMS	(1) LESS THAN 1 SQUARE FOOT IS DAMAGED	N
М	2' X 4' (FISSURE/ PINHOLE) DROP-IN CEILING PANELS	407	ASSUMED POSITIVE	400 S	RESTROOMS	(2) SEVERAL PANELS ARE IN DAMAGED CONDITION	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\6 Month Surveillance\Corp Yard - 6 Month.wpd

#### CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

District:

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected