Date of Inspection:

District:

Chico Unified School District Inspector:

School:

Shasta Elementary School Building: B - Classrooms 3, 6, 7, & 909-911

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|--------------------------------|-----------------|---------------------|----------|--|---|-------------------|
| М | 2' X 4' CEILING PANELS | 1 | NONE DETECTED | 4,500 S | LIBRARY (922) AND CLASSROOMS 3, 6, AND 7 | (13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTE D IN 1988. | N/A |
| М | 12" VINYL FLOOR TILE BEIGE | 2 | TRACE | 2,500 S | ENTIRE WING | (1) (4) | N |
| М | DRYWALL | 80 | ASSUMED POSITIVE | 1,500 S | ENTIRE WING | (11) COVERED WITH TAGBOARD. | N |
| М | CEMENTITIOUS TRANSITE PANEL | 99 | ASSUMED POSITIVE | 100 S | OUTSIDE BUILDING ABOVE DOORS AT COVERED WALKWAYS | (1) (4) | N |
| М | COVE BASE ADHESIVE (BLACK) | 150 | ASSUMED POSITIVE | 500 L | LIBRARY, CLASSROOMS 3, 6 & 7 | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 5,000 S | LIBRARY, CLASSROOMS 3, 6 & 7 | (1) (4) | N |
| М | HVAC SEAM TAPE | 153 | ASSUMED POSITIVE | 20 L | CUSTODIAN ROOM 910 | (1) | N |

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Shasta ES\Shasta 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

| CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS | |
|--|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date of Inspection:

District:

Chico Unified School District

Inspector:

School:

Shasta Elementary School Building: C - Classrooms 4, 5, & 8-10

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|---|-----------------|---------------------|----------|---|--|-------------------|
| М | 2 X 4 CEILING PANELS FISSURE PATTERN | 1 | NONE DETECTED | 7,000 S | OFFICE (915) AND CLASSROOMS 4, 5, 8, 9,10, AND BREAK ROOM 913 | (13) SAMPLE HMS-SHA-01 COLLECTED IN 1988. | N/A |
| М | 12" VINYL FLOOR TILE(CREAM) & ADHESIVE | 2 | TRACE | 600 S | OFFICE (915), PRINCIPAL OFFICE, AND CLASSROOM 4 | (1) (4) (11) CARPET OVER TILE IN PRINCIPAL OFFICE. (12) CERAMIC FLOOR TILE INSTALLED IN OFFICE 915 WALKWAY | N |
| S | PLASTER | 86 | ASSUMED POSITIVE | 500 S | MEN'S (912) & WOMEN'S (914) RESTROOM CEILINGS, MEN'S (917) & WOMEN'S (919) | (1) (4) | N |
| М | CEMENTITIOUS TRANSITE PANELS | 99 | ASSUMED POSITIVE | 200 S | ABOVE DOORS AT COVERED WALKWAYS | (1) (4) | N |
| М | DRYWALL | 112 | ASSUMED POSITIVE | 5,000 S | THROUGHOUT OFFICES & CLASSROOMS | (11) COVERED WITH TAGBOARD IN ALL CLASSROOMS - NOT INSPECTED | N |
| М | COVE BASE ADHESIVE | 150 | ASSUMED POSITIVE | 700 L | THROUGHOUT OFFICES & CLASSROOMS | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 5,000 S | THROUGHOUT OFFICES & CLASSROOMS | (1) (4) | N |
| М | 12" VINYL FLOOR TILE (LIGHT BROWN) & ADHESIVE | 154 | ASSUMED POSITIVE | 150 S | CLASSROOM 9 | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District

Inspector:

School:

Shasta Elementary Building: D - Portables 13, 13A, & 14

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|---|-----------------|---------------------|----------|---------------------------|---|-------------------|
| М | 2' X 4' CEILING PANELS FIBERGLASS | 60 | NON- SUSPECT | 2,200 S | PORTABLES 13, 13A, AND 14 | (13) | N/A |
| М | 12" VINYL FLOOR TILE (WHITE WITH GRAY STREAKS) & ADHESIVE | 70 | ASSUMED POSITIVE | 2,300 S | PORTABLES 13, 13A, AND 14 | (11) ASSUMED POSITIVE TO EXIST BENEATH CARPET | N |
| М | COVE BASE ADHESIVE (GRAY/BROWN) | 150 | ASSUMED POSITIVE | 325 L | PORTABLES 13, 13A, AND 14 | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 1,650 S | PORTABLES 13, 13A, AND 14 | (1) (4) | N |
| | | | | | | ROOM 14 - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1083.1 & 2 ROOM 13 - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1084 # 3 & # 2 ROOM 13A - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1084 # 1 | |

 ${\tt Z:\Clients\Chico\ USD\16-4066\ 3\ Year\ Reinspections\Sites\Shasta\ ES\Shasta\ 6\ month.wpd}$

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

| CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS |
|--|
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Shasta Elementary School
Building: E - Classroom 15

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|---|-----------------|---------------------|----------|--------------|--|-------------------|
| М | 12" VINYL FLOOR TILE (TAN) & ADHESIVE | 109 | ASSUMED POSITIVE | 253 S | CLASSROOM 15 | (1) (4) MINOR CRACKING | N |
| М | 2' X 4' CEILING PANELS FISSURE PATTERN | 110 | ASSUMED POSITIVE | 900 S | CLASSROOM 15 | (1) (4) | N |
| М | DRYWALL | 111 | ASSUMED POSITIVE | 900 S | CLASSROOM 15 | (11) DRYWALL BEHIND TAGBOARD. | N |
| М | COVE BASE ADHESIVE (BLACK) | 150 | ASSUMED POSITIVE | 80 L | CLASSROOM 15 | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 375 S | CLASSROOM 15 | (1) (4) | N |
| | | | | | | BUILT BY HUFFMAN - AUG. 1987 - NO SERIAL # | |

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Shasta ES\Shasta 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Shasta Elementary School
Building: F - Classroom 16

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|--|-----------------|---------------------|----------|--------------|---|-------------------|
| М | 12" VINYL FLOOR TILE (TAN) & ADHESIVE | 109 | ASSUMED POSITIVE | 253 S | CLASSROOM 16 | (1) (4) | N |
| М | 2' X 4' CEILING PANELS | 110 | ASSUMED POSITIVE | 900 S | CLASSROOM 16 | (1) (4) | N |
| М | DRYWALL | 111 | ASSUMED POSITIVE | 900 S | CLASSROOM 16 | (11) DRYWALL BEHIND TAGBOARD. | N |
| М | COVE BASE ADHESIVE (BLACK) | 150 | ASSUMED POSITIVE | 120 L | CLASSROOM 16 | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 900 S | CLASSROOM 16 | (1) (4) | N |
| | | | | | | BUILT BY: KRUSEMARK - JULY 1988 SERIAL # 8751-16 B & C | |

 ${\tt Z:\Clients\Chico\ USD\16-4066\ 3\ Year\ Reinspections\Sites\Shasta\ ES\Shasta\ 6\ month.wpd}$

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Shasta Elementary School
Building: G - Classroom 17

| Material Class | Material | Homo. Mat. # | % Asb. | Ft²/L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|-------------------|--|-----------------|---------------------|----------|--------------|---|-------------------|
| М | 12" VINYL FLOOR TILE (TAN) & ADHESIVE | 109 | ASSUMED POSITIVE | 253 S | CLASSROOM 17 | (1) (4) | N |
| М | 2' X 4' CEILING PANELS | 110 | ASSUMED POSITIVE | 900 S | CLASSROOM 17 | (1) (4) | N |
| М | DRYWALL | 111 | ASSUMED POSITIVE | 900 S | CLASSROOM 17 | (11) DRYWALL BEHIND TAGBOARD | N |
| М | COVE BASE ADHESIVE (BLACK) | 152 | ASSUMED POSITIVE | 120 L | CLASSROOM 17 | (1) (4) | N |
| М | CARPET ADHESIVE | 151 | ASSUMED POSITIVE | 900 L | CLASSROOM 17 | (1) (4) | N |
| | | | | | | UNKNOWN MANUFACTURER - UNKNOWN BUILD DATE SERIAL # 8888.10 A & B | |

 ${\tt Z:\Clients\Chico\ USD\16-4066\ 3\ Year\ Reinspections\Sites\Shasta\ ES\Shasta\ 6\ month.wpd}$

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected