Hooker Oak Elementary	

RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

Inspection Date(s): August 1, 2013

THREE-YEAR REINSPECTION

		IIINEE-TEAN	REINSFECTION	1	
				CDS CODE 04-61424-6003008	
SCHOOL Hooker Oak Elementary	School			SCHOOL PHONE NUMBER (530) 891-3119	
ADDRESS 1238 Arbutus Avenue	(NUMBER)	(STREET)	(CITY) Chico, CA	(ZIP) 95926	

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of <u>FORM C</u> (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

		CHECK ONE				CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	ВМ	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	C-TRAIN NO SUSPECT ACBM							
2.	UNIT A - CLASSROOMS 1-5	Х		Х				Х
3.	UNIT B - CLASSROOMS 6-10	Х		Х				Х
4.	UNIT C - CLASSROOMS 13-17	X		Х		Х		X
5.	UNIT D - PORTABLE LIBRARY & PORTABLE 18			Х				Х
6.	UNIT E - MPR	Х		Х		Х		Х
7.	BOILER ROOM (925)		Х		Х			
8.	UNIT F - PORTABLES 20-22			Х				Х
9.	UNIT G - ROOM 19 DISTRICT MUST CERTIFY							
10.								
11.								
12.								
13.								
14.								
15.								
16.								
17.								

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary School

Building: Unit A - Classrooms 1-5

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (GREEN) & ADHESIVE	101	ASSUMED POSITIVE	2,200 S	HALLWAY	(1) (4)	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	110	ASSUMED POSITIVE	4,500 S	CLASSROOMS 1-5	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	111	ASSUMED POSITIVE	3,500 S	HALLWAY, CLASSROOMS AT WALLS	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	112	ASSUMED POSITIVE	4,500 S	CLASSROOMS 1-5	(1) (4)	N
М	MAUVE COVE BASE & ADHESIVE	113	ASSUMED POSITIVE	600 LF	CLASSROOMS 1-5	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	114	ASSUMED POSITIVE	420 LF	HALLWAY	(1) (4)	N
М	CARPET ADHESIVE	151	ASSUMED POSITIVE	600 SF	CLASSROOMS 1, 2 & 4	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary School

Building: Unit B - Classrooms 6-10

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS FISSURE PATTERN	107	ASSUMED POSITIVE	4,500 S	CLASSROOMS 6-10	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	108	ASSUMED POSITIVE	2,500 S	HALLWAY & STAFF ROOM (906) AND CLASSROOMS AT WALLS	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	109	ASSUMED POSITIVE	4,500 S	CLASSROOMS 6-10	(1) (4)	N
М	12" VINYL FLOOR TILE (GREEN) & ADHESIVE	115	ASSUMED POSITIVE	2,500 S	HALLWAY AND STAFF ROOM (906)	(1) (4)	N
М	MAUVE COVE BASE ADHESIVE	116	ASSUMED POSITIVE	600 S	CLASSROOMS 6-10	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	117	ASSUMED POSITIVE	480 S	HALLWAY AND STAFF ROOM (906)	(1) (4)	N
М	CARPET ADHESIVE	251	ASSUMED POSITIVE	600 S	STAFF ROOM (906), CLASSROOM 7	(1) (4)	N
М	WINDOW GLAZING PUTTY	255	ASSUMED POSITIVE	200 S	INTERIOR AT HALLWAY	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary School

Building: Unit C - Classrooms 13-17

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	14	NONE DETECTED	1,200 S	CLASSROOM 17 (LIBRARY)	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
М	9" VINYL FLOOR TILE)BRIGHT GREEN) & ADHESIVE	97	ASSUMED POSITIVE	400 S	SINK ROOM (914)	(1) (4)	N
М	12" ACOUSTIC CEILING TILE 1/8" HOLE PATTERN	98	ASSUMED POSITIVE	2,880 S	CLASSROOMS 13-16, SINK ROOM (914), AND RESTROOM (915 & 916)	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	99	ASSUMED POSITIVE	1,200 S	CLASSROOM 17 (LIBRARY)	(1) (4)	N
М	BROWN COVE BASE ADHESIVE	118	ASSUMED POSITIVE	125 LF	CLASSROOM 17 (LIBRARY)	(1) (4)	N
М	YELLOW COVE BASE ADHESIVE	119	ASSUMED POSITIVE	90 LF	COMPUTER ROOM (912 & 913)	(1) (4)	N
М	BLACK COVE BASE ADHESIVE	120	ASSUMED POSITIVE	460 LF	CLASSROOMS 13-16	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary Building: Unit D - Portable Library & Portable 18

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments Friab Yes/I	
М	2' X 4' CEILING PANELS FIBERGLASS	104	NON- SUSPECT	900 S	LIBRARY PORTABLE	(13) MANUFACTURE DATE OF PORTABLE N/A LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION.	/A
М	2' X 4' ACOUSTIC CEILING TILE FISSURE PATTERN	105	ASSUMED POSITIVE	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. N MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	106	ASSUMED POSITIVE	240 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. N MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	300 L	PORTABLE CLASSROOM 18	(1) (4) N	٧
М	CARPET ADHESIVE	251	ASSUMED POSITIVE	1,440 S	PORTABLE CLASSROOM 18 & LIBRARY PORTABLE	(1) (4) N	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector: Blake Howes

School: Hooker Oak Elementary School Building: Unit E - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	350 S	MPR (NORTH WALL) (921), WORK ROOM (932)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
Т	BOILER LINER	8	50-55%	210 S	BOILER ROOM (925)	(1) (4) 2 BOILERS. SAMPLE HMS-HKR-08 COLLECTED ON 3-29-88.	Y
М	SHEET VINYL FLOORING & ADHESIVE	17	5-10%	250 S	ADMINISTRATION OFFICE (919)	(1) (4)	N
М	12" VINYL FLOOR TILE (GREEN/ WHITE) & ADHESIVE	93	ASSUMED POSITIVE	2,500 S	MPR (921) AND HALLWAY	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	96	ASSUMED POSITIVE	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
М	9" VINYL FLOOR TILE (RED) & ADHESIVE	100	ASSUMED POSITIVE	50 S	ADMINISTRATION STORAGE (918)	(1) (4)	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	121	ASSUMED POSITIVE	8,400 S	CLASSROOMS 11 & 12, HALLWAY, AND MPR (921)	(1) (4)	N
М	MAUVE COVE BASE ADHESIVE	122	ASSUMED POSITIVE	180 LF	CLASSROOMS 11 & 12	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	123	ASSUMED POSITIVE	700 LF	MPR (921) AND HALLWAY	(1) (4)	N
М	DRYWALL	124	NONE DETECTED	3,500 S	MPR (921) AND PRINCIPALS OFFICE	(13) SAMPLE CUSD HO-001-004 COLLECTED ON 8-16-06.	N/A

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (5) Yes (If Yes, explain under comments) (4) No

Abated: (7) Removed (8) Encapsulated (6) Repaired (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary School

Building: Unit E - MPR

(Continued)

Date of Inspection: August 1, 2013

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	WINDOW GLAZING PUTTY	255	ASSUMED POSITIVE	100 S	CLASSROOMS 11 & 12 AT NORTH SIDE	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	500 S	BASEMENT	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 1, 2013

District: Chico Unified School District

Inspector: Blake Howes

School: Hooker Oak Elementary

Building: Unit F - Portables 20-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (WHITE) & ADHESIVE	101	ASSUMED POSITIVE	2,700 S	PORTABLES CLASSROOMS 20-22	(1) (4)	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION.	N
М	2' X 4' CEILING PANELS FIBERGLASS	102	NON- SUSPECT	2,700 S	PORTABLES CLASSROOMS 20-22	(13)	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION.	N/A
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	300 L	PORTABLE CLASSROOMS 20-22	(1)		N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

ENTEK CONSULTING GROUP, INC. ASSESSMENT OF TSI and/or FRIABLE MATERIAL

District: Chico Unified School District Date: August 1, 2013

School: Hooker Oak Elementary School Inspector: Blake Howes

Building & Location(s): Unit E - MPR, Boiler Room (925)

HMS-HKR-08 % Asbestos-50-55% Homogeneous Mat. #8

Material description: Boiler Liner

Total amount of material this location: 210 S Amount of friable material this location: 210 S

Damage	Local	Distributed	Damaged	0%
Type of Damage	Air Erosion	Water	Flaking	
	Deterioration	Physical	Delamination	

Probable cause(s) of damage: Physical Damage

POTENTIAL FOR	POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES	
	Н	М	L	Isolate/Restrict		Fix leaks	
Accessibility			Х	Repair/Cleanup		Prevent water contact	
Vibration			Х	Enclose		Do not drill, cut, sand, or grind	
Air Erosion			Х	Remove	Х	Do not affix signs	
Water			Х	Encapsulate		Avoid contact	Х
Occupancy			Х	O & M	Х		

Assessment of Material Condition Significantly Damaged Damaged Not damaged (Poor) (Good) (Fair) Potential Damage: High High Mod High Mod Low Low Hazard Ranking: 2 3 4 5 6

Comments & Observations:

Hooker Oak Elementary School N 21 20 UNIT G 911 Library 11/12 ARBUTUS AVE. 16 13 91 14 928 6.5 927 9 stage below Stage 922 E TIMU 907 UNIT E 991 Mimetein A 2 903 919 916 917 UNIT A Telephone - 920 Water 3 AVE. Make Howe 3-Year AHERA Reinspection Chico Unified School District Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Conducted by Blake Howes Hooker Oak Elementary School Rocklin, California 95677 August 1, 2013 1238 Arbutus Avenue Map Not To Scale Project 13-2751 Chico, CA 95926

SIX-MONTH SURVEILLANCE	

District: Chico Unified School District

Inspector:

School: Hooker Oak Elementary School

Building: Unit A - Classrooms 1-5

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (GREEN) & ADHESIVE	101	ASSUMED POSITIVE	2,200 S	HALLWAY	(1) (4)	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	110	ASSUMED POSITIVE	4,500 S	CLASSROOMS 1-5	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	111	ASSUMED POSITIVE	3,500 S	HALLWAY, CLASSROOMS AT WALLS	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	112	ASSUMED POSITIVE	4,500 S	CLASSROOMS 1-5	(1) (4)	N
М	MAUVE COVE BASE & ADHESIVE	113	ASSUMED POSITIVE	600 LF	CLASSROOMS 1-5	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	114	ASSUMED POSITIVE	420 LF	HALLWAY	(1) (4)	N
М	CARPET ADHESIVE	151	ASSUMED POSITIVE	600 SF	CLASSROOMS 1, 2 & 4	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector:

School: Hooker Oak Elementary School

Building: Unit B - Classrooms 6-10

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS FISSURE PATTERN	107	ASSUMED POSITIVE	4,500 S	CLASSROOMS 6-10	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	108	ASSUMED POSITIVE	2,500 S	HALLWAY & STAFF ROOM (906) AND CLASSROOMS AT WALLS	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	109	ASSUMED POSITIVE	4,500 S	CLASSROOMS 6-10	(1) (4)	N
М	12" VINYL FLOOR TILE (GREEN) & ADHESIVE	115	ASSUMED POSITIVE	2,500 S	HALLWAY AND STAFF ROOM (906)	(1) (4)	N
М	MAUVE COVE BASE ADHESIVE	116	ASSUMED POSITIVE	600 S	CLASSROOMS 6-10	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	117	ASSUMED POSITIVE	480 S	HALLWAY AND STAFF ROOM (906)	(1) (4)	N
М	CARPET ADHESIVE	251	ASSUMED POSITIVE	600 S	STAFF ROOM (906), CLASSROOM 7	(1) (4)	N
М	WINDOW GLAZING PUTTY	255	ASSUMED POSITIVE	200 S	INTERIOR AT HALLWAY	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Hooker Oak Elementary School Building: Unit C - Classrooms 13-17

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	14	NONE DETECTED	1,200 S	CLASSROOM 17 (LIBRARY)	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
М	9" VINYL FLOOR TILE)BRIGHT GREEN) & ADHESIVE	97	ASSUMED POSITIVE	400 S	SINK ROOM (914)	(1) (4)	N
М	12" ACOUSTIC CEILING TILE 1/8" HOLE PATTERN	98	ASSUMED POSITIVE	2,880 S	CLASSROOMS 13-16, SINK ROOM (914), AND RESTROOM (915 & 916)	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	99	ASSUMED POSITIVE	1,200 S	CLASSROOM 17 (LIBRARY)	(1) (4)	N
М	BROWN COVE BASE ADHESIVE	118	ASSUMED POSITIVE	125 LF	CLASSROOM 17 (LIBRARY)	(1) (4)	N
М	YELLOW COVE BASE ADHESIVE	119	ASSUMED POSITIVE	90 LF	COMPUTER ROOM (912 & 913)	(1) (4)	N
М	BLACK COVE BASE ADHESIVE	120	ASSUMED POSITIVE	460 LF	CLASSROOMS 13-16	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

(2) Damaged (3) Significantly Damaged (25% or more) General Condition: (1) Good

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector:

School: Hooker Oak Elementary Building: Unit D - Portable Library & Portable 18

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments Friable Yes/N
М	2' X 4' CEILING PANELS FIBERGLASS	104	NON- SUSPECT	900 S	LIBRARY PORTABLE	(13) MANUFACTURE DATE OF PORTABLE N/A LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION.
М	2' X 4' ACOUSTIC CEILING TILE FISSURE PATTERN	105	ASSUMED POSITIVE	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. N MANUFACTURE DATE OF PORTABLE 18 IS 8/86.
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	106	ASSUMED POSITIVE	240 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. NANUFACTURE DATE OF PORTABLE 18 IS 8/86.
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	300 L	PORTABLE CLASSROOM 18	(1) (4) N
М	CARPET ADHESIVE	251	ASSUMED POSITIVE	1,440 S	PORTABLE CLASSROOM 18 & LIBRARY PORTABLE	(1) (4) N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Hooker Oak Elementary School Building: Unit E - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	350 S	MPR (NORTH WALL) (921), WORK ROOM (932)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
Т	BOILER LINER	8	50-55%	210 S	BOILER ROOM (925)	(1) (4) 2 BOILERS. SAMPLE HMS-HKR-08 COLLECTED ON 3-29-88.	Y
М	SHEET VINYL FLOORING & ADHESIVE	17	5-10%	250 S	ADMINISTRATION OFFICE (919)	(1) (4)	N
М	12" VINYL FLOOR TILE (GREEN/ WHITE) & ADHESIVE	93	ASSUMED POSITIVE	2,500 S	MPR (921) AND HALLWAY	(1) (4)	N
М	12" VINYL FLOOR TILE (SALMON) & ADHESIVE	96	ASSUMED POSITIVE	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
М	9" VINYL FLOOR TILE (RED) & ADHESIVE	100	ASSUMED POSITIVE	50 S	ADMINISTRATION STORAGE (918)	(1) (4)	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	121	ASSUMED POSITIVE	8,400 S	CLASSROOMS 11 & 12, HALLWAY, AND MPR (921)	(1) (4)	N
М	MAUVE COVE BASE ADHESIVE	122	ASSUMED POSITIVE	180 LF	CLASSROOMS 11 & 12	(1) (4)	N
М	GREEN COVE BASE ADHESIVE	123	ASSUMED POSITIVE	700 LF	MPR (921) AND HALLWAY	(1) (4)	N
М	DRYWALL	124	NONE DETECTED	3,500 S	MPR (921) AND PRINCIPALS OFFICE	(13) SAMPLE CUSD HO-001-004 COLLECTED ON 8-16-06.	N/A

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (5) Yes (If Yes, explain under comments) (4) No

Abated: (7) Removed (8) Encapsulated (6) Repaired (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector:

School: Hooker Oak Elementary School

Building: Unit E - MPR

(Continued)

Date of Inspection:

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	WINDOW GLAZING PUTTY	255	ASSUMED POSITIVE	100 S	CLASSROOMS 11 & 12 AT NORTH SIDE	(1) (4)	N
S	STUCCO	300	ASSUMED POSITIVE	500 S	BASEMENT	(1) (4)	N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Hooker Oak Elementary

Building: Unit F - Portables 20-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	Condition: Code & Comments	
М	12" VINYL FLOOR TILE (WHITE) & ADHESIVE	101	ASSUMED POSITIVE	2,700 S	PORTABLES CLASSROOMS 20-22	(1) (4)	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION.	N
М	2' X 4' CEILING PANELS FIBERGLASS	102	NON- SUSPECT	2,700 S	PORTABLES CLASSROOMS 20-22	(13)	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION.	N/A
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	300 L	PORTABLE CLASSROOMS 20-22	(1)		N

Z:\Clients\Chico USD\13-2751 3 Year Reinspections\Sites\Hooker Oak ES\HookerOak 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS