District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: P - (aka MPR) (FKA - BLDG. A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	TEACHER'S DINING ROOM, MPR, AND REST OF THE WING	(1) (4)	N
М	DRYWALL	106	ASSUMED	UNDETERMINED	THROUGHOUT UNIT - ALL WALLS AND KITCHEN CEILING	(1) (4)	N
М	NON-SLIP LINOLEUM DARK GRAY	107	ASSUMED	2,200 S	KITCHEN AND KITCHEN OFFICE	(1) (4)	N
М	12" VFT BLUE	108	ASSUMED	5,570 S	MPR AND STAFF DINNING	(1) (4)	N
S	TEXTURE	109	ASSUMED	1,400 S	NURSE OFFICE AND CONFERENCE ROOM	(1) (4)	N
М	12" VFT GRAY	110	ASSUMED	200 S	NURSE OFFICE	(1) (4)	N
М	LINOLEUM - GRAY	111	ASSUMED	25 S	NURSE RESTROOM	(1) (4)	N
М	4" BASE COVE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1)	N
М	CARPET ADHESIVE	252	ASSUMED	UNDETERMINED	NURSE OFFICE & CONFERENCE ROOM	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: O - (aka Classrooms 200, 202, 204, 206 & 208) (FKA - BLDG. C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	300 S	TITLE ONE OFFICE AND RESTROOMS	(1) (4) MINOR CRACKS IN THE MIDDLE AREA.	N
М	TRANSITE PANELS	96	ASSUMED	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	4,000 S	ALL CLASSROOMS	(1) (4) (11) TITLE ONE OFFICE COVERED WITH CARPET.	N
М	2' X 4' FCP FISSURE PATTERN	99	ASSUMED	4,000 S	THROUGHOUT CLASSROOM WING	(1) (4)	Ν
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOM WING	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS 202-208 AT LOWER WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School Building: N - (aka Classrooms 300, 302, 304, & 306) (FKA - BLDG. D)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	70 S	JANITOR'S CLOSET (ROOM 310)	(1) (4)	N
S	CEILING PLASTER	8	1-5%	300 S	JANITOR'S CLOSET (ROOM 310) AND GIRL'S RESTROOM	(1) (4)	N
М	TRANSITE PANELS	96	ASSUMED	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	4,000 S	CLASSROOMS 300, 302, 304, 306, & 308	(1) (4)	N
М	2' X 4' FCP - FISSURE PATTERN	99	ASSUMED	4,000 S	THROUGHOUT CLASSROOMS	(1) (4)	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS & JANITOR CLOSET	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAYS	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS 300-306 AT LOWER NORTH WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u>
Abated:
(4) No
(5) Yes (If Yes, explain under comments)
(13) Non-Asbestos/Not Inspected
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: M - (aka Classrooms 400, 402, 404, 406 & 408) (FKA - BLDG. E)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	112	ASSUMED	175 S	PSYCHOLOGIST OFFICE & STAFF RESTROOM	(1) (4)	N
М	TRANSITE PANELS	113	ASSUMED	640 S	EXTERIOR	(1) (4)	N
М	12" VFT CREAM	114	ASSUMED	4,000 S	ALL CLASSROOMS	(1) (4) (11) CLASSROOM 402 AND PSYCHOLOGIST OFFICE ARE COVERED WITH CARPET.	N
М	2' X 4' FCP FISSURE PATTERN	115	ASSUMED	4,000 S	ALL CLASSROOMS	(1) (4)	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1)	N
М	CARPET ADHESIVE	252	ASSUMED	UNDETERMINED	CLASSROOM 402 & PSYCHOLOGIST	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS 400-408 AT LOWER NORTH WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u>
Abated:

(4) No
(5) Yes (If Yes, explain under comments)
(13) Non-Asbestos/Not Inspected
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School Building: L - (aka Classrooms 500, 502, 504 & 506) (FKA - BLDG. F)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	70 S	MIGRANT EDUCATION OFFICE	(1) (4)	N
S	CEILING PLASTER	8	1-5%	175 S	MIGRANT EDUCATION OFFICE'S & GIRL'S RESTROOM	(1) (4)	N
Т	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	CLASSROOM 502	(11)	Y
Т	PIPE WRAP STRAIGHT	95	ASSUMED	UNDETERMINED	CLASSROOM 506	(11)	Y
М	TRANSITE PANELS	96	ASSUMED	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT LIGHT GRAY	98	ASSUMED	4,000 S	CLASSROOMS 500, 502, 504, & 506	(1) (4)	N
М	2' X 4' FCP - FISSURE PATTERN	116	ASSUMED	4,000 S	ALL CLASSROOMS	(1) (4)	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	ALL CLASSROOMS	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAYS	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	ALL CLASSROOMS AT LOWER NORTH WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School Building: J - (aka Maintenance) (FKA - BLDG. G)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
Т	BOILER REFRACTORY	100	ASSUMED	UNDETERMINED	TWO BOILER UNITS	(1) (4)	Y

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School Building: H & I - (aka Room 501, 503 & 505) (FKA - BLDG. H&N)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" ACT	17	NONE DETECTED	UNDETERMINED	WOOD SHOP, DURST THEATER, MUSIC CLASSROOM, & PRACTICE CLASSROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988.	N/A
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, STORAGE, & STAFF OFFICE, DURST THEATER, OFFICES, MUSIC CLASSROOM, AND PRACTICE CLASSROOMS 1-5	(1) (4)	N
S	CEILING PLASTER	117	ASSUMED	700 S	OFFICES, STORAGE ROOMS, AND WOODSHOP CLASSROOM	(1) (4)	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	CLASSROOM	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: A - (aka Main Office Bldg.) (FKA - BLDG. J)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	LIBRARY	(1) (4)	N
М	12" VFT GRAY	97	ASSUMED	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, AND LIBRARY	(1) (4)	N
М	DRYWALL	101	ASSUMED	UNDETERMINED	THROUGHOUT UNIT AND LIBRARY	(1) (4) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000.	N
S	TEXTURE	118	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) (4)	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1)	N
М	12" VFT DARK GRAY	251	ASSUMED	100 S	ROOM 908	(1)	N
М	CARPET ADHESIVE	252	ASSUMED	UNDETERMINED	OFFICES & LIBRARY	(1)	N
М	12" VFT LIGHT GRAY	253	ASSUMED	UNDETERMINED	HALLWAY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: B - (aka Classrooms 201-211) (FKA - BLDG. K)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	700 S	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	N
М	2' X 4' FCP - FISSURE	99	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VFT LIGHT GRAY	102	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	4" BASE COVE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS AT LOWER NORTH WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: C - (aka Classrooms 301-311) (FKA - BLDG. L)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	700 S	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP - FISSURE PATTERN	99	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VFT LIGHT GREY	103	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS AT LOWER NORTH WALLS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: D - (aka Classrooms 401, 403, 405, 407 & 409)(FKA - BLDG. M)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	n: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	700 S	EXTERIOR OF UNIT	(1) (4)		N
М	2' X 4' FCP FISSURE PATTERN	99	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4)	RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VFT LIGHT GREY	103	ASSUMED	4,800 S	THROUGHOUT CLASSROOMS	(1) (4)	RENOVATED DURING THE SUMMER OF 2000.	N
М	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1)		N
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)		N
М	DRYWALL	255	ASSUMED	UNDETERMINED	CLASSROOMS AT LOWER NORTH WALLS	(1)		N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u>
Abated:

(4) No
(5) Yes (If Yes, explain under comments)
(13) Non-Asbestos/Not Inspected
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: E - (aka Gymnasium) (FKA - BLDG. O)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" CEILING TILE	119	ASSUMED	5,000 S	GYM	(1) (4)	N
S	STUCCO	254	ASSUMED	UNDETERMINED	CORRIDOR	(1)	N
S	TEXTURE ON CONCRETE & PLASTER WALLS	300	ASSUMED	UNDETERMINED	RESTROOMS	(1)	Z
М	DRYWALL	301	ASSUMED	UNDETERMINED	RESTROOMS	(1)	N
S	TEXTURE ON DRYWALL	302	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: F - (aka PE Locker Rooms) (FKA - BLDG. P)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT GREEN	5	1-5%	UNDETERMINED	CLASSROOM 18 STORAGE	(11) COULD NOT FIND DURING TIME OF INSPECTION.	N
Т	PIPE WRAP	105	ASSUMED	UNDETERMINED	IN CEILING PIPE CHASE	(10)	Y
S	STUCCO	254	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
S	PLASTER	260	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Junior High School

Building: Q (Main Corridor)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	PLASTER	8	1-5%	UNDETERMINED	CEILINGS & WALLS	(1)	N
М	12" VFT GRAY	97	ASSUMED	UNDETERMINED	THROUGHOUT CORRIDOR	(1)	N
М	12" VFT LIGHT GRAY	253	ASSUMED	UNDETERMINED	THROUGHOUT CORRIDOR	(1)	N
М	6" COVE BASE ADHESIVE	261	ASSUMED	UNDETERMINED	THROUGHOUT CORRIDOR	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\ChicoJHS\Chico JHS-HMR.wpd