

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Citrus Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT TAN		1-5%	UNDETERMINED	CLASSROOMS 13-16 & STAFF ROOM	(1) (4)	N
M	9" VFT		1-5%	UNDETERMINED	WORKROOM OF LIBRARY	(1) (4) CARPET OVER TILE.	N
M	9" VFT		1-5%	UNDETERMINED	SPEECH ROOM	(1) (4) CARPET OVER TILE.	N
M	VENT DUCT CONNECTOR		35-40%	UNDETERMINED	RESTROOM ATTIC	(11)	N

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PIPEWRAP STRAIGHT		40-50%	UNDETERMINED	BASEMENT & STORAGE	(7) REMOVED IN THE ACCESS AREAS. THE REST OF THE BUILDING UNDETERMINED AMOUNT.	N/A

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected  
 (14) Non AHERA/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Citrus Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	MPR (GREEN)	(11) CANNOT LOCATE	N
M	DUCT VENT CONNECTOR		35-40%	UNDETERMINED	MPR-STAGE OFFICE	(7)	N/A
T	PIPEWRAP JOINT		ASSUMED	12 L	KITCHEN STORAGE	(7) JOINTS REMOVED - STRAIGHT RUNS STILL THERE. SAME 11/12/04	N/A
T	PIPEWRAP		ASSUMED	UNDETERMINED	STAGE FAN ROOMS	(1) (4)	N
M	12" VFT TAN	150	ASSUMED	1,900 S	MPR	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected  
(14) Non AHERA/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Citrus Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT TAN		1-5%	UNDETERMINED	CLASSROOMS 13-16 & STAFF ROOM	(1) (4)	N
M	9" VFT		1-5%	UNDETERMINED	WORKROOM OF LIBRARY	(1) (4) CARPET OVER TILE.	N
M	9" VFT		1-5%	UNDETERMINED	SPEECH ROOM	(1) (4) CARPET OVER TILE.	N
M	VENT DUCT CONNECTOR		35-40%	UNDETERMINED	RESTROOM ATTIC	(11)	N

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PIPEWRAP STRAIGHT		40-50%	UNDETERMINED	BASEMENT & STORAGE	(7) REMOVED IN THE ACCESS AREAS. THE REST OF THE BUILDING UNDETERMINED AMOUNT.	N/A

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected  
 (14) Non AHERA/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/28/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Citrus Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	MPR (GREEN)	(11) CANNOT LOCATE	N
M	DUCT VENT CONNECTOR		35-40%	UNDETERMINED	MPR-STAGE OFFICE	(7)	N/A
T	PIPEWRAP JOINT		ASSUMED	12 L	KITCHEN STORAGE	(7) JOINTS REMOVED - STRAIGHT RUNS STILL THERE. SAME 11/12/04	N/A
T	PIPEWRAP		ASSUMED	UNDETERMINED	STAGE FAN ROOMS	(1) (4)	N
M	12" VFT TAN	150	ASSUMED	1,900 S	MPR	(1) (4)	N
M	12" VFT	150	NON ASBESTOS	UNDETERMINED	NURSE'S OFFICE	INSTALLED 12/2006 - MANNINGTON NON-ASBESTOS PER MANUFACTURER	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected  
 (14) Non AHERA/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**