

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 9, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Country Day School (FKA Fairview High School)

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BEIGE	10	1-5%	1,920 S	CLASSROOM 1 AND ADMINISTRATION OFFICES	(1) (4)	N
M	DRYWALL	75	TRACE	1,400 S	OFFICE WALLS, RESTROOMS, AND CUSTODIAN ROOM	(1) (4)	N
M	12" ACT - FISSURE PATTERN	101	ASSUMED	1,920 S	CLASSROOM 1 AND ADMINISTRATION OFFICES	(1) (4)	N
M	6" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT BUILDING	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 9, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Country Day School (FKA Fairview High School)

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BEIGE	10	1-5%	4,300 S	ALL CLASSROOMS & COUNSELING OFFICES	(1) (4)	N
M	DRYWALL	98	ASSUMED	UNDETERMINED	CLASSROOMS AND CUSTODIAN ROOM	(1) (4)	N
M	DRYWALL	98	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS CEILING	(1) (4)	N
M	12" ACT - FISSURE PATTERN	101	ASSUMED	4,220 S	ALL CLASSROOMS	(1) (4)	N
M	2 X 4 FCP - FISSURE PATTERN	102	ASSUMED	50 S	CLASSROOM 2	(1) (4)	N
S	TEXTURE (KNOCK DOWN)	265	ASSUMED	100 S	CLASSROOM 3 STORAGE	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 9, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Country Day School (FKA Fairview High School)

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP (PLASTIC)	96	NOT SUSPECT	2,400 S	ALL CLASSROOMS 6, 7, 8 & 10	(13)	N
M	9" VFT	97	ASSUMED	2,400 S	ALL CLASSROOMS	(11) ALL COVERED WITH CARPET (2) (11) CLASSROOM 9 HAS MINOR CRACKS AND A FEW BROKEN TILES.	N
M	2 X 4 FCP - FISSURE PATTERN	102	ASSUMED	600 S	CLASSROOM 9 ONLY	(1) (4)	N
M	CARPET ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT BUILDING	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 9, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Chico Country Day School (FKA Fairview High School)

Building: G - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	5	1-5%	2,600 S	MPR	(1) (4) MINOR WATER STAINS.	N
M	9" VFT GREEN	6	1-5%	2,800 S	MPR, KITCHEN, FOOD STORAGE, AND ENTRANCE	(1)	N
T	BOILER INSULATION	7	75-80%	150 S	BOILER ROOM	(11)	Y
T	MUD PIPE JOINT	8	35-40%	32 EACH	BOILER ROOM	(1) (4)	Y
M	TRANSITE PIPE FLUE	99	ASSUMED	2 EACH 25 L	BOILER ROOM	(1) (4)	N
M	12" VFT RED	100	ASSUMED	150 S	KITCHEN	(1) (4)	N
M	4" COVE BASE ADHESIVE	250	ASSUMED	UNDETERMINED	THROUGHOUT BUILDING	(1)	N
S	STUCCO	260	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS