Date of Inspection: <u>02/11/2009</u>

District: Chico Unified School District

School: Loma Vista Elementary School

Inspector: Mike Fender

Building: Unit A (FKA North)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
т	PIPEWRAP STRAIGHT	4	70-75%	300 L	ATTIC	(11) SAMPLE HMS-LVS-04C COLLECTED ON 3/30/88.	Y
М	2' X 4' FCP	8	NONE DETECTED	7,900 S	MAIN OFFICE-914, SHOP-926, BOY'S RESTROOM-917, GIRL'S RESTROOM-918, AND CLASSROOMS 5-15	(13) SAMPLE HMS-LVS-01-6 COLLECTED ON 3/30/88.	N/A
М	12" VFT OFF WHITE	9	10-15%	8,000 S	KITCHEN, GYM-11, CLASSROOMS 14 & 15, AND RESTROOM-922	(1) (4) SAMPLE HMS-LVS-02-6 COLLECTED ON 3/30/88.	N
М	12" ACT	11	NONE DETECTED	2,481 S	CLASSROOM AREA 16	(13)	N/A
т	MUD JOINTS	12	<1%	11 JOINTS	BOILER ROOM-927	(1) (6) SAMPLE HMS-LVS-05-6 COLLECTED ON 3/30/88.	Y
М	12" VFT WHITE/BLUE SPECKS	96	1-5% Chrysotile	2,481 S	CLASSROOM AREA 16 AND GYM-11	<ul><li>(1) (4) Entek sample ECG-07-465-01A.</li><li>Mastic reported non-dectected</li></ul>	N
т	BOILER LINER	97	10-15%	200 S	BOILER ROOM-927	(1) (4) SAMPLE HMS-LVS-06-6 COLLECTED ON 3/30/88.	Y

## CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: \_\_02/11/2009

# District: Chico Unified School District

School: Loma Vista Elementary School

Inspector: Mike Fender

Building: Unit A (FKA North) (Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DUCT BOX	98	ASSUMED	50 L	BOILER ROOM-927	(1) (4)	Ν
М	TRANSITE PANELS	99	ASSUMED	2,000 S	ABOVE ALL DOORS AND IN BOILER ROOM-927	(1) (4)	Ν
М	12" VFT CREAM	151	ASSUMED	1,200 S	CUSTODIAL CLOSET-915 AND CLASSROOMS 5-9	(1) (4)	Ν
М	12" VFT LIGHT BLUE	152	ASSUMED	50 S	CLASSROOM 9	(1) (4)	Ν
М	12" VFT LIGHT BLUE	153	ASSUMED	175 S	CLASSROOM 5	(7)	N/A
М	WHITE DUCT TAPE	155	ASSUMED	100 L	BOILER UNIT EXTERIOR-927	(1) (4)	Ν
М	VIBRATION DAMPENER	157	ASSUMED	20 L	BOILER ROOM-927	(1)	Y
М	12" VFT PINK	158	ASSUMED	400 S	CLASSROOM 5	(1)	Ν

## CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: <u>02/11/2009</u>

# District: Chico Unified School District

Inspector: Mike Fender

School: Loma Vista Elementary School

Buildings: Units A & B (FKA North & South)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	95	1-5 SKIM COAT	UNDETERMINED	ALL NON-PLASTER WALLS & CEILINGS	(1) (4)	Ν

School: Loma Vista Elementary School

Building: SED Portable Classroom

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	93	Certified Non-Asbestos	960 S	SED PORTABLE CLASSROOM	<ul> <li>(11) DRYWALL IS ASSUMED TO EXIST BEHIND</li> <li>TAGBOARD.</li> <li>(13) Letter on file</li> </ul>	N
М	2' X 4' FCP'S FIBERGLASS	94	NON- SUSPECT	900 S	SED PORTABLE CLASSROOM	(1) (4)	N

# CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: \_\_02/11/2009

# District: Chico Unified School District

School: Loma Vista Elementary School

Inspector: Mike Fender

Building: Unit B (FKA South)

Material Class	Material	Homo Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT CREAM/PINK	1	1-5%	4,100 S	HALLWAY, ORTHOPEDICS, ORTHOPEDICS CLASSROOM, PHYSICAL THERAPY-2, AND THERAPY OFFICE-900	(1) (4)	Ν
М	12" ACT	2	NONE DETECTED	7,000 S	PSYCH INTEGRATION OFFICE, HALLWAY, PRINCIPAL'S OFFICE-908, ORTHOPEDICS, ORTHOPEDICS CLASSROOM, AND PHYSICAL THERAPY-2	(13)	N/A
s	HARD PLASTER	3	1-5%	1,400 S	MEN'S & WOMEN'S RESTROOMS AND CUSTODIAN ROOM-910	(1) (4)	Ν
S	HARD PLASTER	5	1-5%	UNDETERMINED	MEN'S & WOMEN'S RESTROOMS	<ul> <li>(1) (4)</li> <li>(7) REMOVED IN CUSTODIAL ROOM, STORAGE, AND NURSE'S OFFICE.</li> </ul>	N N/A
М	12" VFT WHITE WITH BLUE	155	ASSUMED	200 S	OFFICE	(1) (4) BOILER ROOM WAS CONVERTED INTO A OFFICE IN JULY, 2001.	Ν
М	GYPSUM BOARD	156	ASSUMED	450 S	OFFICE	(1) (4) BOILER ROOM WAS CONVERTED INTO A OFFICE IN JULY, 2001.	N
М	DRYWALL & JOINT COMPOUND	159	ASSUMED	UNDETERMINED	THROUGHOUT INTERIOR WALLS IN OFFICES AND CORRIDOR	(1)	Ν

## CONDITION CODE

 General Condition:
 (1) Good
 (2) Damaged
 (3) Significantly Damaged (25% or more)

 Change in Condition:
 (4) No
 (5) Yes (If Yes, explain under comments)

 Abated:
 (6) Repaired
 (7) Removed
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

 Miscellaneous:
 (11) Inaccessible, no inspection data
 (12) Other (Explain under comments)
 (13) Non-Asbestos/Not Inspected