



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Leroy Christophersen

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B084994
Date Received: 05/05/06
Date Analyzed: 05/09/06
Date Printed: 05/09/06
First Reported: 05/09/06

Job ID/Site: Marigold Elementary - Staff Room Remodel - PO# 050289

FASI Job ID: 2921-94

Date(s) Collected: 05/04/2006

Total Samples Submitted: 1

Total Samples Analyzed: 1

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
0001	10519258						
Layer: Beige Tile				ND			
Layer: Yellow Mastic				ND			
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921-94



Forensic Analytical

Analysis Request Form

Client Name & Address: Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		P.O. #: 050289 Date: 5/4/06
Contact: Kip Hansen		Turn Around Time: ___ hr / 12hr / 24hr / 48hr / ext: ___
Phone #: (530) 895-4179	Fax #: (530) 891-3190	Due Date: 5/9/06 Due Time: ___:___ am/pm
Site: Marigold Elementary		<input checked="" type="checkbox"/> PLM: <input checked="" type="checkbox"/> Standard / <input type="checkbox"/> Point Count <input type="checkbox"/> PCM: NIOSH 7400
Job: Staff Room Re Model		<input type="checkbox"/> TEM Air: <input type="checkbox"/> AHERA / <input type="checkbox"/> Yamate2 / <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> TEM Bulk: <input type="checkbox"/> Quantitative / <input type="checkbox"/> Qualitative / <input type="checkbox"/> Chatfield <input type="checkbox"/> TEM Water: <input type="checkbox"/> Potable / <input type="checkbox"/> Non-Potable / <input type="checkbox"/> Wt % <input type="checkbox"/> TEM Microvac <input type="checkbox"/> Special Project:
Comments: Please test sample tile & mastic for asbestos.		<input type="checkbox"/> Metals Analysis: Method _____ Matrix: _____ Analytes: _____

Sample ID	Date/Time	Sample Location/Description	FOR AIR SAMPLES ONLY				Sample Area or Air Volume
			Type	Time On/Off	Avg. LPM	Total Time	
0001	5/4/06 8:30AM	Staff Room Floor Tile/Mastic	A				
			P				
			C				
			A				
			P				
			C				
			A				
			P				
			C				
			A				
			P				
			C				
			A				
			P				
			C				

Sampled by: Kip Hansen Date: 5/4/06 Time: 8:30AM

Shipped via: FedEx Airborne UPS US Mail Courier Drop Off Other:

Relinquished by:	Relinquished by:	Relinquished by:
Date / Time:	Date / Time:	Date / Time:
Received by: <u>[Signature]</u>	Received by:	Received by:
Date / Time: <u>5/5/06</u>	Date / Time:	Date / Time:
Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 1010

May 4, 2006

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Marigold Elementary School

To Whom It May Concern:

Please test the enclosed sample from the Staff Room at Marigold Elementary School for asbestos. We would like a 48-hour turnaround on the samples. Please fax the results as soon as they are available. Our fax number is 530-891-3190.

Site Sampled:	Marigold Elementary School
Location:	Staff Room
Date Sampled:	May 4, 2006
Number of Samples:	One - #0001

Thank you for your prompt response to this request.

Sincerely,



Kip Hansen
Maintenance/Operations Manager

Enclosure (1)

dlg

BK 5/5/06

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit: C,E,F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(1)	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4)	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1) (4)	N
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(1)	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(12) UNABLE TO LOCATE THE MATERIAL.	N
M	PLASTER	101	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4)	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	ASSUMED	305 S	STAFF LOUNGE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(11) LOCKED	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 15-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES 18A-22	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES 18A-22	(11) MAY BE BEHIND TACK BOARD	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES 18A-22	(1) (4)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/05/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	ASSUMED	180 S	PORTABLES 23 & 24	(1) (4)	N
M	TAGBOARD	103	ASSUMED	960 S	PORTABLES 23 & 24	(1) (4)	N
M	2' X 4' FCP'S (FIBERGLASS)	104	ASSUMED	900 S	PORTABLES 23 & 24	(1) (4)	N
M	CARPET	105	ASSUMED	780 S	PORTABLES 23 & 24	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit: C,E,F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(1)	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4)	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1) (4)	N
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(1)	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(12) UNABLE TO LOCATE THE MATERIAL.	N
M	PLASTER	101	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4)	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	ASSUMED	305 S	STAFF LOUNGE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(11) LOCKED	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 15-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES 18A-22	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES 18A-22	(11) MAY BE BEHIND TACK BOARD	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES 18A-22	(1) (4)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	ASSUMED	180 S	PORTABLES 23 & 24	(1) (4)	N
M	TAGBOARD	103	ASSUMED	960 S	PORTABLES 23 & 24	(1) (4)	N
M	2' X 4' FCP'S (FIBERGLASS)	104	ASSUMED	900 S	PORTABLES 23 & 24	(1) (4)	N
M	CARPET	105	ASSUMED	780 S	PORTABLES 23 & 24	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS