

**ENTEK CONSULTING GROUP, INC.
ASSESSMENT OF TSI and/or FRIABLE MATERIAL**

District: Chico Unified School District

Date: June 29, 2010

School: Marigold Elementary School

Inspector: Jack DeLay

Building & Location(s): Unit E - Restrooms - Boiler Room

HMS-MAR-10

% Asbestos - 60-65%

Homogeneous Mat. #10

Material description: Pipe Wrap Straight

Total amount of material this location: 150 L

Amount of friable material this location: 150 L

Damage	Local		Distributed		Damaged	0%
Type of Damage	Air Erosion		Water		Flaking	
	Deterioration		Physical		Delamination	

Probable cause(s) of damage:

POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES	
	H	M	L	Isolate/Restrict		Fix leaks
Accessibility	X			Repair/Cleanup		Prevent water contact X
Vibration			X	Enclose		Do not drill, cut, sand, or grind X
Air Erosion			X	Remove	X	Do not affix signs
Water			X	Encapsulate		Avoid contact X
Occupancy			X	O & M	X	

Assessment of Material Condition

Significantly Damaged
(Poor)

Damaged
(Fair)

Not damaged
(Good)

Potential Damage:

High

High

Mod

Low

High

Mod

Low

Hazard Ranking:

1

2

3

4

5

6

7

						X		
--	--	--	--	--	--	---	--	--

Comments & Observations: