

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit A - Rooms 1 & 2

| Material Class | Material                    | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location                      | Condition: Code & Comments                  | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|-------------------------------|---|----------------|
| M              | 9" VFT WHITE                | 2            | 1-5%    | 2,800 S               | CLASSROOMS 1 & 2              | (1) (4) SAMPLE MAR-02 COLLECTED ON 3-30-88. | N              |
| M              | 2' X 4' FCP FISSURE PATTERN | 94           | ASSUMED | 1,800 S               | CLASSROOMS 1 & 2              | (1) (4)                                     | N              |
| M              | TRANSITE PANELS             | 99           | ASSUMED | 300 S                 | ABOVE GLASS PANELS (EXTERIOR) | (1) (4)                                     | N              |
| M              | DRYWALL & JOINT COMPOUND    | 105          | ASSUMED | 600 S                 | CLASSROOMS 1 & 2              | (1) (4)                                     | N              |
| M              | 4" COVE BASE ADHESIVE       | 250          | ASSUMED | 170 L                 | CLASSROOMS 1 & 2              | (1)   | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit B - MPR

| Material Class | Material                    | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location  | Condition: Code & Comments  | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|---|---|----------------|
| M              | 9" VFT CREAM                | 2            | 1-5%    | 3,160 S               | KITCHEN (909), ADMIN OFFICE, MULTI PURPOSE ROOM (905), STORAGE, PIP ROOM (908), AND HEALTH OFFICE (903) | (1) (4)<br>(11) PRINCIPAL OFFICE AND PIP ROOM (908) COVERED WITH CARPET.<br><br>ADMIN OFFICE (NORTH HALF ONLY) COVERED WITH 12" VFT BLUE. | N              |
| M              | COLD BOX CEILING            | 6            | 30-35%  | 20 S                  | COLD BOX  | (1) (4) SAMPLE MAR-06 COLLECTED ON 3-30-88.   | N              |
| S              | PLASTER                     | 75           | ASSUMED | 1,000 S               | KITCHEN (909) AND RESTROOMS (907 & 907A)  | (1) (4)   | N              |
| M              | 12" ACT FISSURE PATTERN     | 90           | ASSUMED | 2,500 S               | MULTI-PURPOSE ROOM (905)  | (1) (4)   | N              |
| M              | 2' X 4' FCP FISSURE PATTERN | 91           | ASSUMED | 5,000 S               | PRINCIPALS OFFICE, OFFICE, PIP ROOM (908), CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE (903)           | (1) (4)   | N              |
| M              | 12" VFT BLUE                | 106          | ASSUMED | 240 S                 | ADMIN OFFICE  | (1) (4)   | N              |
| M              | 4" COVE BASE ADHESIVE       | 250          | ASSUMED | 600 L                 | MPR AND KITCHEN   | (1)   | N              |
| M              | CARPET ADHESIVE             | 251          | ASSUMED | 100 S                 | PRINCIPAL'S OFFICE  | (1)   | N              |
| S              | STUCCO                      | 260          | ASSUMED | 1000 S                | COVERED WALKWAY   | (1)   | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit C - Rooms 3-5

| Material Class | Material                        | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location        | Condition: Code & Comments                  | Friable Yes/No |
|----------------|---------------------------------|--------------|---------|-----------------------|-----------------|---|----------------|
| M              | 9" VFT BROWN                    | 8            | 1-5%    | 5,728 S               | CLASSROOMS 3-5  | (1) (4) SAMPLE MAR-08 COLLECTED ON 3-30-88. | N              |
| M              | 12" ACT<br>1/8" HOLE<br>PATTERN | 98           | ASSUMED | 5,728 S               | CLASSROOMS 3-5  | (1) (4)                                     | N              |
| M              | 4" COVE BASE<br>ADHESIVE        | 250          | ASSUMED | 300 L                 | CLASSROOMS 3-5  | (1)   | N              |
| S              | STUCCO                          | 260          | ASSUMED | 1,000 S               | COVERED WALKWAY | (1)   | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit D - Rooms 6A & 6B

| Material Class | Material                 | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location           | Condition: Code & Comments  | Friable Yes/No |
|----------------|--------------------------|--------------|---------|-----------------------|--------------------|-----------------------------|----------------|
| M              | 12" VFT                  | 95           | ASSUMED | 240 S                 | CLASSROOMS 6A & 6B | (1) (4)                     | N              |
| M              | 2' X 4' FCP              | 96           | ASSUMED | 1,800 S               | CLASSROOMS 6A & 6B | (1) (4)                     | N              |
| M              | DRYWALL & JOINT COMPOUND | 107          | ASSUMED | 2,500 S               | CLASSROOMS 6A & 6B | (11) COVERED WITH TAGBOARD. | N              |
| M              | 4" COVE BASE ADHESIVE    | 250          | ASSUMED | 100 L                 | CLASSROOMS 6A & 6B | (1)                         | N              |
| M              | CARPET ADHESIVE          | 251          | ASSUMED | 240 S                 | CLASSROOMS 6A & 6B | (1)                         | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit E - Restrooms

| Material Class | Material                | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location                                    | Condition: Code & Comments                                       | Friable Yes/No |
|----------------|-------------------------|--------------|---------|-----------------------|---|--|----------------|
| T              | PIPE WRAP STRAIGHT      | 10           | 60-65%  | 150 L                 | BOILER ROOM                                 | (1) (4) SAMPLE MAR-10 COLLECTED ON 3-30-88.                      | Y              |
| M              | 12" ACT FISSURE PATTERN | 97           | ASSUMED | 850 S                 | GIRL'S & BOY'S RESTROOMS                    | (2) (4) MINOR WATER DAMAGE ON ACT'S IN BOY'S & GIRL'S RESTROOMS. | N              |
| M              | TRANSITE PANELS         | 99           | ASSUMED | 50 S                  | MAIN BOILER ROOM AT BOILERS                 | (11)   | N              |
| S              | PLASTER                 | 101          | ASSUMED | 600 S                 | BOY'S & GIRL'S RESTROOMS AND CUSTODIAL ROOM | (1) (4)  | N              |
| T              | BOILER INSULATION       | 108          | ASSUMED | 2 EACH                | BOILER ROOM                                 | (1) (4)  | Y              |
| S              | STUCCO                  | 260          | ASSUMED | 1,000 S               | COVERED WALKWAY                             | (1)  | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit F - Rooms 7-9

| Material Class | Material                  | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location        | Condition: Code & Comments | Friable Yes/No |
|----------------|---------------------------|--------------|---------|-----------------------|-----------------|----------------------------|----------------|
| M              | 9" VFT BROWN              | 8            | 1-5%    | 5,728 S               | CLASSROOMS 7-9  | (1)                        | N              |
| M              | 12" ACT 1/8" HOLE PATTERN | 98           | ASSUMED | 5,728 S               | CLASSROOMS 7-9  | (1) (4)                    | N              |
| M              | 4" COVE BASE ADHESIVE     | 250          | ASSUMED | 300 L                 | CLASSROOMS 7-9  | (1)                        | N              |
| S              | STUCCO                    | 260          | ASSUMED | 1,500 S               | COVERED WALKWAY | (1)                        | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit G - Room 10

| Material Class | Material                 | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location     | Condition: Code & Comments      | Friable Yes/No |
|----------------|--------------------------|--------------|---------|-----------------------|--------------|---------------------------------|----------------|
| M              | 2' X 4' FCP FIBERGLASS   | 96           | ASSUMED | 1,800 S               | CLASSROOM 10 | (1) (4)                         | N              |
| M              | DRYWALL & JOINT COMPOUND | 109          | ASSUMED | 1,700 S               | CLASSROOM 10 | (11) (4) COVERED WITH TAGBOARD. | N              |
| M              | 4" COVE BASE ADHESIVE    | 250          | ASSUMED | 100 L                 | CLASSROOM 10 | (1)                             | N              |
| M              | CARPET ADHESIVE          | 251          | ASSUMED | 800 S                 | CLASSROOM 10 | (1)                             | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit H - Rooms 11-14

| Material Class | Material                    | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location   | Condition: Code & Comments   | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|--|--|----------------|
| M              | 9" VFT                      | 2            | 1-5%    | 4,500 S               | CLASSROOMS 11-14 AND MIDDLE RESTROOM                   | (1) (4) MIDDLE RESTROOM.<br>(4) (11) ASSUMED TO EXIST UNDER CARPET IN CLASSROOMS 11, 13, & 14. | N              |
| M              | 2' X 4' FCP FISSURE PATTERN | 92           | ASSUMED | 4,500 S               | ALL ROOMS  | (1) (4)  | N              |
| M              | 12" VFT                     | 93           | ASSUMED | 900 S                 | ROOM 12 - LIBRARY                                      | (11) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE. | N              |
| M              | TRANSITE PANELS             | 99           | ASSUMED | 300 S                 | ABOVE WINDOWS  | (1) (4) APPROXIMATELY 18 PANELS.   | N              |
| M              | 12" VFT GREEN               | 151          | ASSUMED | 305 S                 | STAFF LOUNGE (920)                                     | (1) (4)  | N              |
| S              | PLASTER                     | 152          | ASSUMED | 2,000 SF              | RESTROOMS (918 & 919) AND STAFF LOUNGE (920)           | (1) (4)  | N              |
| M              | DRYWALL & JOINT COMPOUND    | 153          | ASSUMED | 2,500 SF              | CLASSROOMS 11-14                                       | (1) (4)  | N              |
| M              | 4" COVE BASE ADHESIVE       | 250          | ASSUMED | 1,000 L               | STAFF LOUNGE (920), CLASSROOMS, LIBRARY & COMPUTER LAB | (1)  | N              |
| M              | CARPET ADHESIVE             | 251          | ASSUMED | 4,000 S               | CLASSROOMS, LIBRARY & COMPUTER LAB                     | (1)  | N              |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit J - Rooms 19-23

| Material Class | Material                    | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location                                    | Condition: Code & Comments   | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|---|--|----------------|
| M              | 12" VFT CREAM               | 80           | ASSUMED | 2,400 S               | PORTABLES 19-23                             | (1) (4)  | N              |
| M              | DRYWALL                     | 81           | ASSUMED | 10,000 S              | PORTABLES 19 - 23 AND RESTROOMS (923 & 924) | (11) (4) COVERED WITH TAGBOARD IN CLASSROOMS   | N              |
| M              | 2' X 4' FCP FISSURE PATTERN | 89           | ASSUMED | 8,000 S               | PORTABLES 19-23                             | (1) (4)  | N              |
| M              | LINOLEUM TAN                | 100          | ASSUMED | 500 S                 | RESTROOMS (923 & 924)                       | (1) (4)  | N              |
| M              | 4" COVE BASE ADHESIVE       | 250          | ASSUMED | 500 L                 | CLASSROOMS 19-23                            | (1)  | N              |
| M              | CARPET ADHESIVE             | 251          | ASSUMED | 3,600 S               | CLASSROOMS 19-23                            | (1)  | N              |
|                |                             |              |         |                       |   | NOTE: BUILT BY - KRUSEMARK - JULY 1988<br>ROOM 19 - SERIAL # 8751-9A, B & C<br>ROOM 20 - SERIAL # 8888-4A, B & C<br>ROOM 21 - SERIAL # 8888-5 A, B & C<br>ROOM 22 - SERIAL # 8888-6A, B & C<br>ROOM 23 - SERIAL # 8888-7A, B & C<br>THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988. |                |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit K - Room 18

| Material Class | Material              | Homo. Mat. # | % Asb.  | Ft <sup>2</sup> /L.F. | Location    | Condition: Code & Comments   | Friable Yes/No |
|----------------|-----------------------|--------------|---------|-----------------------|-------------|--|----------------|
| M              | 12" VFT               | 80           | ASSUMED | 2,400 S               | PORTABLE 18 | (1) (4)  | N              |
| M              | DRYWALL               | 81           | ASSUMED | 10,000 S              | PORTABLE 18 | (1) (4)  | N              |
| M              | 2' X 4' FCP           | 89           | ASSUMED | 8,000 S               | PORTABLE 18 | (1) (4)  | N              |
| M              | 4" COVE BASE ADHESIVE | 250          | ASSUMED | 100 L                 | PORTABLE 18 | (1) (4)  | N              |
|                |                       |              |         |                       |             | NOTE:<br>BUILT BY: DESIGNED MOBILE SYSTEMS IND. INC. 6-97<br>SERIAL # 20-310-1 & 2<br>THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS<br>ON ANY PORTABLES MANUFACTURED AFTER<br>OCTOBER 12, 1988. |                |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 29, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Marigold Elementary School

Building: Unit L - Portables 24 & 25 (FKA - Portables 23 & 24)

| Material Class | Material                           | Homo. Mat. # | % Asb.      | Ft <sup>2</sup> /L.F. | Location                       | Condition: Code & Comments   | Friable Yes/No |
|----------------|------------------------------------|--------------|-------------|-----------------------|--------------------------------|--|----------------|
| M              | 12" VFT BLUE                       | 102          | ASSUMED     | 360 S                 | PORTABLES 24 & 25              | (1) (4)  | N              |
| M              | DRYWALL & JOINT COMPOUND           | 103          | ASSUMED     | 960 S                 | PORTABLES 24 & 25              | (11) COVERED WITH TAGBOARD.  | N              |
| M              | 2' X 4' FCP'S (FIBERGLASS)         | 104          | NON-SUSPECT | 900 S                 | PORTABLES 24 & 25              | (13)   | N              |
| M              | VINYL SHEET FLOORING BLUE SPECKLED | 200          | ASSUMED     | 84 S                  | RESTROOMS AT PORTABLES 24 & 25 | (1)  | N              |
| M              | 4" COVE BASE ADHESIVE              | 250          | ASSUMED     | 200 L                 | PORTABLES 24 & 25              | (1)  | N              |
| M              | CARPET ADHESIVE                    | 251          | ASSUMED     | 1,800 S               | PORTABLES 24 & 25              | (1)  | N              |
|                |                                    |              |             |                       |                                | NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988. |                |

Z:\AHERA Inspections - Scanned\Chico USD\2010\Marigold.Elem\Marigold.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**