

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit A - Rooms 1-2 & 900-902

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	CEILING PLASTER	4	1-5%	50 S	STAFF ROOM	(1) (4)	N
M	12" ACT 1/8" HOLE PAT.	6	NONE DETECTED	2,800 S	ENTIRE WING	(13) REPRESENTED BY SAMPLE HMS-PKV-06 COLLECTED ON 4-1-88.	N/A
M	TRANSITE PANELS	99	ASSUMED	70 S	BELOW WINDOWS	(1) (4)	N
M	LINOLEUM	100	ASSUMED	80 S	CLASSROOM 1	(12) COULD NOT LOCATE THIS MATERIAL.	N
M	9" VFT GREEN/WHITE	101	ASSUMED	150 S	OFFICE, HALL, AND STORAGE ROOM	(12) COULD NOT LOCATE THIS MATERIAL.	N
M	12" VFT WHITE/BLUE	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2	(1) (4)	N
M	12" VFT OLIVE	103	ASSUMED	70 S	STORAGE	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	100 L	CLASSROOMS 1 & 2	(1)	N
S	STUCCO	200	ASSUMED	1,000 S	COVERED WALKWAYS	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit B - Portable 11A & 11B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT CREAM	12	ASSUMED	120 S	CLASSROOMS 11A & 11B	(1) (4)	N
M	2' X 4' CEILING PANEL - FISSURE PAT.	14	ASSUMED	900 S	CLASSROOMS 11A & 11B	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	60 L	CLASSROOMS 11A & 11B	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	180 S	CLASSROOMS 11A & 11B	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

Z:\AHERA Inspections - Scanned\Chico USD\Parkview ES\3-Year Reinspections\2010\ParkView.HMR.wpd

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit E - Rooms 18-21

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	17	NONE DETECTED	3,800 S	CLASSROOMS 18-21	(13) SAMPLE HMS-PKV-17 COLLECTED ON 4-1-88.	N/A
T	PIPE WRAP CORNER	18	5-10%	20 S	CLASSROOM 18	(11) ABOVE FCP'S. SAMPLE HMS-PKV-18 COLLECTED ON 4-1-88.	Y
M	12" VFT WHITE/BLUE	16	ASSUMED	640 S	CLASSROOMS 18-21	(1) (4)	N
M	4' COVE BASE ADHESIVE	150	ASSUMED	120 L	CLASSROOMS 18-21	(1)	N
S	STUCCO	200	ASSUMED	1,500 S	COVERED WALKWAYS	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit F - Rooms 14-17 & 905-908

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' CEILING PANEL - FISSURE PAT.	12	NONE DETECTED	4,500 S	CLASSROOMS 14-17 & LIBRARY	(13) SAMPLE HMS-PKV-12 COLLECTED ON 3-31-88.	N/A
M	9" VFT CREAM	13	1-5%	5,000 S	CLASSROOMS 14-17 AND SER ROOM (906)	(1) (4)	N
T	PIPE WRAP CORNER	15	1-5%	12 EACH	RESTROOM ATTIC	(11) ATTIC DOOR IS LOCKED. MATERIAL IS INACCESSIBLE - NO ASSESSMENT IS FEASIBLE	Y
M	DRYWALL	76	TRACE IN SKIM COAT	3,000 S	ALL ROOMS	(1) (4) CLASSROOMS & LIBRARY HAVE TAG BOARD WALLS	N
M	12" ACT - FISSURE PAT.	97	ASSUMED	250 S	SER ROOM (906)	(1) (4)	N
M	12" VFT GREY	100	ASSUMED	250 S	LIBRARY	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	400 L	CLASSROOMS 14-17, LIBRARY, & ROOM 906	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	900 S	LIBRARY	(1)	N
S	STUCCO	200	ASSUMED	1,500 S	COVERED WALKWAYS	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit G - Rooms 910-914

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	85	ASSUMED	700 S	OFFICE CORRIDOR	(1) (4)	N
M	12" VFT WHITE/BLUE	86	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, OFFICE CORRIDOR, NURSE, AND STAFF LOUNGE	(1) (4) (11) COVERED WITH CARPET IN SPEECH ROOM.	N
M	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N
M	12" VFT BLUE	104	ASSUMED	200 S	ADMINISTRATION OFFICE	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	500 L	SPEECH (910), OFFICES 911-914, & NURSE	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	800 S	OFFICE CORRIDOR	(1)	N
M	6" COVE BASE ADHESIVE	152	ASSUMED	100 L	OFFICES 911, 912, & 914	(1)	N
S	STUCCO	200	ASSUMED	1,500 S	COVERED WALKWAYS	(1)	N
M	SHEET VINYL FLOORING (CREAM)	250	ASSUMED	25 S	NURSE RESTROOM (912A)	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit H - Rooms 7-10

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	82	ASSUMED	800 S	MEN'S & WOMEN'S RESTROOMS	(1) (4)	N
M	12" VFT WHITE/BLUE	86	ASSUMED	1,000 S	CLASSROOMS 7-10	(1) (4)	N
M	2' X 4' CEILING PANEL - FISSURE PAT.	87	ASSUMED	2,600 S	CLASSROOMS 7-10	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	400 S	BELOW EXTERIOR WINDOWS	(1) (4)	N
M	12" ACT - 1/8" HOLE PAT.	105	ASSUMED	400 S	CLASSROOMS 7-10	(1) (4)	N
M	SHEET VINYL FLOORING CREAM	106	ASSUMED	200 S	MEN'S & WOMEN'S RESTROOMS	(1) (4)	N
M	4" COVE BASE ADHESIVE	250	ASSUMED	400 L	CLASSROOMS 7-10	(1)	N
M	CARPET ADHESIVE	251	ASSUMED	2,800 S	CLASSROOMS 7-10	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit I - Rooms 914-918

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	1-5%	1,100 S	BOY'S & GIRL'S RESTROOM WALLS AND CUSTODIAN ROOM	(1) (4) (2) (4) MINOR DAMAGE IN THE CUSTODIAL ROOM.	N
M	DRYWALL	83	ASSUMED	300 S	BOY'S & GIRL'S RESTROOM CEILING	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

Z:\AHERA Inspections - Scanned\Chico USD\Parkview ES\3-Year Reinspections\2010\ParkView.HMR.wpd

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit J - Rooms 3-6

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT WHITE/BLUE	86	ASSUMED	1,000 S	CLASSROOMS 3-6 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	87	ASSUMED	3,200 S	CLASSROOMS 3-6	(1) (4) (7) REMOVED FROM WORKROOM.	N N/A
M	TRANSITE PANELS	99	ASSUMED	400 S	BELOW WINDOWS	(1) (4)	N
M	12" ACT	107	ASSUMED	400 S	CLASSROOMS 3-6	(1)	N
M	DRYWALL	108	ASSUMED	1,200 S	COPY ROOM AND CUSTODIAL ROOM	(1)	N
M	4" COVE BASE ADHESIVE	250	ASSUMED	400 L	CLASSROOMS 3-6 & WORKROOM	(1)	N
M	CARPET ADHESIVE	251	ASSUMED	2,800 S	CLASSROOMS 3-6	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: July 6, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Parkview Elementary School

Building: Unit K- Rooms 921-925

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	NONE DETECTED	1,200 S	KITCHEN	(13) REPRESENTED BY SAMPLES HMS-PKV-03A-F COLLECTED ON 4-1-88.	N/A
M	12" VFT RED	9	1-5%	540 S	KITCHEN (NORTH WEST CORNER)	(1) (4)	N
M	DRYWALL	11	ASSUMED	60 S	GIRL'S & BOY'S RESTROOM CEILINGS	(1) (4)	N
M	12" VFT WHITE/BLUE	92	ASSUMED	1,800 S	MPR, KITCHEN, AND CLOSET ON EACH END OF STAGE	(1) (4)	N
M	9" VFT BEIGE	101	ASSUMED	200 S	KITCHEN STORAGE	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	UNDETERMINED	MPR, KITCHEN	(1)	N
S	STUCCO	200	ASSUMED	500 S	COVERED WALKWAYS	(1)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**