Date of Inspection: <u>12/27/07</u>

District: Chico Unified School District

School: Rosedale Elementary School

Inspector: Leroy Christophersen

Building: Unit A (FKA D)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT GREEN	3	5-10%	3,200 S	MPR (905), KITCHEN 908, KITCHEN STORAGE 909A, AND STORAGE ROOM 909B	(1)	Ν
М	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE 909	(7)	N/A
М	12" VFT	93	ASSUMED	3,000 S	CORRIDOR	(1) (4)(7) OFFICES AND MULTI-PURPOSE ROOM	N N/A
М	12" VFT GREY	107	ASSUMED	400 S	ADMINISTRATION OFFICES 900-903, 906, 907 & 909	(1) INSTALLED DURING THE MODERNIZATION.	Ν
М	12" ACT	108	ASSUMED	400 S	ADMINISTRATION OFFICES 900-903, 906, 907 & 909	(1) INSTALLED DURING THE MODERNIZATION.	N
М	LINOLEUM	109	ASSUMED	100 S	RESTROOM 904	(1)	N

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

CONDITION CODE

Date of Inspection: <u>12/27/07</u>

School: Rosedale Elementary School

Inspector: Leroy Christophersen

Building: Unit A (FKA D) (Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	110	NONE DETECTED	UNDETERMINED	MPR (905) /KITCHEN 908	(13) SAMPLE ROS01 COLLECTED ON FEBRUARY 22, 2006.	N/A
т	3" O.D. PIPE RUNS	111	ASSUMED	20 L	KITCHEN WATER HEATER CLOSET	(1)	Y
т	3" O.D. PIPE FITTINGS	112	ASSUMED	3 EACH	KITCHEN WATER HEATER CLOSET	(1)	Y
М	6" COVE BASE	113	ASSUMED	200 L	CORRIDOR	(1)	Ν

School: Rosedale Elementary School

Building: Unit B (FKA E)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	94	ASSUMED	2,000 S	CLASSROOMS K-1, & K-2	(1) (4) Water spots.	Ν
М	12" VFT CREAM	95	ASSUMED	2,000 S	CLASSROOMS K-1, & K-2	(1) (4)	Ν
М	12" ACT	114	ASSUMED	160 S	2 CLASSROOMS K-1, & K-2	(1)	Ν
М	LINOLEUM	115	ASSUMED	120 S	4 RESTROOMS IN EACH K-1, & K-2	(1)	Ν

CONDITION CODE General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments) Change in Condition:(4) No (6) Repaired (7) Removed (8) Encapsulated Abated: (9) Enclosed (10) Isolated & Restricted Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Date of Inspection: <u>12/27/07</u>

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Rosedale Elementary School

Building: Unit C (FKA F) - Portable 3

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S FIBERGLASS	103	NON- SUSPECT	1,200 S	PORTABLE CLASSROOM 3	(1) (4)	Ν
М	LINOLEUM CREAM	116	ASSUMED	200 S	PORTABLE CLASSROOM 3	(1)	Ν

School: Rosedale Elementary School

Building: Unit D (FKA F) - Portable 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	103	ASSUMED	1,200 S	PORTABLE CLASSROOM 4	(1) (4)	Ν
М	LINOLEUM CREAM	117	ASSUMED	200 S	PORTABLE CLASSROOM 4	(1)	Ν

 CONDITION CODE

 General Condition:(1) Good
 (2) Damaged
 (3) Significantly Damaged (25% or more)

 <u>Change in Condition:</u>(4) No
 (5) Yes (If Yes, explain under comments)

 <u>Abated:</u>
 (6) Repaired
 (7) Removed
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

 <u>Miscellaneous:</u>
 (11) Inaccessible, no inspection data
 (12) Other (Explain under comments)
 (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/27/07

Inspector: Leroy Christophersen

School: Rosedale Elementary School

District: Chico Unified School District

Building: Unit E - Portables 5 & 5B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLE CLASSROOMS 5 & 5A - RSP & READ RECOVERY	(1) (4)	Ν
М	12" VFT CREAM	118	ASSUMED	360 S	PORTABLE CLASSROOMS 5 & 5A	(1)	Ν

School: Rosedale Elementary School

Building: Unit F (FKA I)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	18	NONE DETECTED	1,600 S	CLASSROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS (916 & 917)	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S	106	ASSUMED	1,600 S	CLASSROOMS 6, 7, & 8	(1) (4)	Ν

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments) Change in Condition:(4) No (6) Repaired (7) Removed (8) Encapsulated Abated: (9) Enclosed (10) Isolated & Restricted Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

CONDITION CODE

Date of Inspection: <u>12/27/07</u>

District: Chico Unified School District

School: Rosedale Elementary School

Inspector: Leroy Christophersen

Building: Unit G (FKA H)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT WHITE	18	NONE DETECTED	2,000 S	CLASSROOMS 9-12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS (918 & 919)	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S FIBERGLASS	105	NON- SUSPECT	2,000 S	CLASSROOMS 9-12	(1) (4)	N

School: Rosedale Elementary School

Building: Unit H (FKA G)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13-18	(1) (4)	Ν
М	2' X 4' FCP'S	91	None Detected	6,500 S	CLASSROOMS 13-18 AND LIBRARY (920)	(13) CUSD sample PSI-RS9 dated 3/22/08	Ν
М	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS (921 & 923) AND TV/PARENT AREA (920)	(2) Holes in wall board	Ν
М	12" ACT	102	ASSUMED	250 S	TV/PARENT AREA (920)	(1) (4)	Ν
М	12" VFT GREY	119	ASSUMED	1,200 S	LIBRARY/TV PARENT AREA (920)	(1)	N

CONDITION CODE

<u>General Condition:</u>(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/27/07

Inspector: Leroy Christophersen

Building: Unit I (FKA B)

District: Chico Unified School District

School: Rosedale Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
м	DRYWALL	97	ASSUMED	400 S	BOTH RESTROOMS (924 & 925) AND WORK ROOM (926)	(1) (4)	N
м	12" VFT CREAM	98	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM (926)	(1) (4)	N
м	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM (926)	(1) (4)(7) REMOVED FROM WORK ROOM.	N N/A
м	12" ACT - WALLS	120	ASSUMED	200 S	CLASSROOMS 19-23	(1)	N
м	12" ACT - CEILING	121	ASSUMED	900 S	CLASSROOMS 19-23	(1)	N
М	COVE BASE	122	ASSUMED	600 L	CLASSROOMS 19-23	(1)	N

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments) Change in Condition:(4) No (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

CONDITION CODE

Date of Inspection: <u>12/27/07</u>

District: Chico Unified School District

School: Rosedale Elementary School

Inspector: Leroy Christophersen

Building: Unit J (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	100	ASSUMED	1,900 S	BOTH RESTROOMS (928 & 930)	(1) (4)	Ν
S	PLASTER	123	ASSUMED	1,200 S	CUSTODIAL ROOM AND BOILER ROOM (927 & 929)	(1)	N

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: <u>12/27/07</u>

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Rosedale Elementary School

Building: Unit K (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4)	Ν
М	DRYWALL	97	ASSUMED	300 S	READING OFFICE (FKA LOUNGE) (931)	(1) (4)	Ν
М	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24-28	(1) (4)	Ν
М	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24-28	(1) (4)(7) REMOVED FROM RESOURCE ROOM.	N N/A
М	12" ACT - WALLS	124	ASSUMED	200 S	CLASSROOMS 24-28	(1)	N
М	12" ACT - CEILINGS	125	ASSUMED	900 S	CLASSROOMS 24-28	(1)	N
М	COVE BASE	126	ASSUMED	600 S	CLASSROOMS 24-28	(1)	N

CONDITION CODE

General Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Change in Condition:(4) No(5) Yes (If Yes, explain under comments)Abated:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected