

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit A - Classroom 1

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|-------------|----------------------------------|----------------|
| M | DRYWALL | 93 | ASSUMED | 1,250 S | CLASSROOM 1 | (4) (11) EXISTS BEHIND TAGBOARD. | N |
| M | 2' X 4' FCP FISSURE PATTERN | 99 | ASSUMED | 960 S | CLASSROOM 1 | (1) (4) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 120 L | CLASSROOM 1 | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 850 S | CLASSROOM 1 | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit B - Classrooms 2-5

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|---------------------------|--------------|---------|-----------------------|-----------------------------------|----------------------------|----------------|
| S | PLASTER | 3 | 1-5% | 400 S | SPEECH ROOMS | (1) (4) | N |
| M | 9" VFT GREEN | 14 | 1-5% | 4,000 S | CLASSROOMS 2-5 AND SPEECH ROOMS | (1) (4) | N |
| M | TRANSITE PANELS | 83 | ASSUMED | 25 PANELS | UNDER WINDOWS THROUGHOUT BUILDING | (1) (4) | N |
| M | 12" ACT 1/8" HOLE PATTERN | 17 | ASSUMED | 4,000 S | CLASSROOMS 2-5 AND SPEECH ROOMS | (1) (4) | N |
| M | 4" COVE BASE BLACK | 157 | ASSUMED | 600 LF | CLASSROOMS 2-5 AND SPEECH ROOMS | (1) (4) | N |
| M | 9" VFT GRAY | 158 | ASSUMED | 400 S | SPEECH ROOMS | (1) (4) | N |
| M | STUCCO | 255 | ASSUMED | 200 S | COVERED WALKWAY AT EAST END | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

J

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit C - Library

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|--------------------------|--------------|---------|-----------------------|--|----------------------------|----------------|
| M | 12" ACT | 97 | ASSUMED | 600 S | LIBRARY (902), AND ANNEX (902A) | (1) (4) | N |
| M | DRYWALL / JOINT COMPOUND | 260 | ASSUMED | 1,500 S | LIBRARY (902) & ANNEX (902A) AT WALLS & CEILINGS | (1) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 400 L | LIBRARY (902), AND ANNEX (902A) | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 1,150 S | LIBRARY (902), AND ANNEX (902A) | (1) (4) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit D - Restroom Bldg.

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|--------------------------|--------------|---------|-----------------------|--|--|----------------|
| M | PLASTER | 3 | 1-5% | 1,500 S | CUSTODIAN CLOSET (904), BOY'S (907) & GIRL'S (905) RESTROOMS | (1) (4) | N |
| T | MUD JOINT | 12 | 60-65% | 30 L | BOILER ROOM (906) | (1) (4) | Y |
| M | DRYWALL & JOINT COMPOUND | 150 | N/A | N/A | BOY'S (907) & GIRL'S (905) RESTROOMS | (12) MATERIAL MISIDENTIFIED - RESTROOM WALLS & CEILINGS ARE PLASTER, SQUARE FOOTAGE ADDED TO HOMOGENEOUS MATERIAL #3 | N/A |
| T | BOILER TSI | 156 | ASSUMED | 1 EACH | BOILER ROOM (906) | (1) (4) | Y |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit E - Classrooms 6 & 7

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------|--------------|---------|-----------------------|------------------|------------------------------|----------------|
| M | DRYWALL | 93 | ASSUMED | 1,700 SF | CLASSROOMS 6 & 7 | (11) EXISTS BEHIND TAGBOARD. | N |
| M | 12" VFT | 94 | ASSUMED | 120 S | CLASSROOM 6 | (1) (4) | N |
| M | 2' X 4' FCP | 99 | ASSUMED | 960 S | CLASSROOMS 6 & 7 | (1) (4) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 175 L | CLASSROOMS 6 & 7 | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 900 S | CLASSROOMS 6 & 7 | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit F - Classrooms 8 - 11

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|---------------------------|--------------|---------|-----------------------|--|----------------------------|----------------|
| S | PLASTER | 3 | 1-5% | 400 S | PIP ROOM (909) AND NURSES ROOM | (1) (4) | N |
| M | 9" VFT GREEN | 14 | 1-5% | 4,000 S | CLASSROOMS 8-11 | (1) (4) | N |
| M | TRANSITE PANELS | 83 | ASSUMED | 25 PANELS | UNDER WINDOWS THROUGHOUT BUILDING | (1) (4) | N |
| M | 12" ACT 1/8" HOLE PATTERN | 97 | ASSUMED | 4,000 S | CLASSROOMS 8-11 | (1) (4) | N |
| M | LINOLEUM | 100 | ASSUMED | 50 S | RESTROOM (908) | (12) UNABLE TO LOCATE. | N |
| M | 9" VFT GRAY | 170 | ASSUMED | 400 S | PIP ROOM (909) AND NURSES ROOM | (1) (4) | N |
| M | 4" COVE BASE BLACK | 171 | ASSUMED | 480 LF | CLASSROOMS 8-11 | (1) (4) | N |
| S | STUCCO | 255 | ASSUMED | 300 S | COVERED WALKWAY @ EAST END OF BUILDING | (1) | N |
| M | 4" COVE BASE BROWN | 265 | ASSUMED | 40 L | NURSE ROOM | (1) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit G - MPR

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-------------------------|--------------|---------|-----------------------|--|---|----------------|
| S | PLASTER | 3 | 1-5% | 1,200 S | KITCHEN (912), KITCHEN STORAGE (910), AND MPR CHAIR STORAGE | (1) (4) | N |
| T | PIPE WRAP | 8 | 15-20% | 13 L | MECHANICAL ROOM (911) | (2) (4) UNCAPPED ENDS. | Y |
| M | TRANSITE PIPE FLUE | 98 | ASSUMED | 20 L | HOT WATER ROOM | (1) (4) THIS MATERIAL IS LOCATED IN THE MECHANICAL ROOM (911) | N |
| M | LINOLEUM WHITE | 152 | ASSUMED | 50 S | KITCHEN RESTROOM | (1) (4) | N |
| M | DRYWALL | 153 | ASSUMED | UNDETERMINED | OFFICES AND MPR (913) CEILINGS | (1) (4) | N |
| M | 12" VFT WHITE / BLUE | 154 | ASSUMED | 3,500 S | OFFICE HALLWAY (914-916) & MPR (913) | (1) (4) | N |
| M | 12" ACT FISSURE PATTERN | 155 | ASSUMED | 2,000 S | OFFICE HALLWAY CEILING, ALL THREE OFFICES (914-916), AND MPR (913) | (1) (4) | N |
| M | LINOLEUM TAN | 159 | ASSUMED | 500 S | KITCHEN (912) | (1) (4) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 400 L | OFFICES (914-916), AND MPR (913) | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit G - MPR

(Continued)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|---------------------------|--------------|---------|-----------------------|--------------------------|----------------------------|----------------|
| M | SHEET VINYL FLOORING GRAY | 268 | ASSUMED | 40 S | RESTROOM AT OFFICE (914) | (1) | N |
| M | 6" COVE BASE ADHESIVE | 270 | ASSUMED | 200 L | OFFICE HALLWAY | (1) | N |
| S | WALL TEXTURE | 295 | ASSUMED | 700 S | OFFICES (914-916) | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit H - Classrooms 13-16

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|--|--|----------------|
| M | TRANSITE PANELS | 83 | ASSUMED | 4,500 S | STAFF ROOM (917) & CLASSROOMS 13-16 | (1) (4) | N |
| M | 12" VFT BLUE / WHITE | 94 | ASSUMED | 720 S | STAFF ROOM (917) & CLASSROOMS 13-16 | (1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE. | N |
| M | 2' X 4' FCP FISSURE PATTERN | 150 | ASSUMED | 3,600 S | STAFF ROOM (917) & CLASSROOMS 13-16 | (1) (4) | N |
| M | LINOLEUM BLUE & WHITE | 151 | ASSUMED | 100 S | MEN'S (918) & WOMEN'S (918A) RESTROOMS | (1) (4) | N |
| M | 12" ACT 1/8" HOLE PATTERN | 160 | ASSUMED | 600 S | CLASSROOMS 13-16 | (1) (4) | N |
| M | 4" COVE BASE GRAY | 161 | ASSUMED | 480 S | CLASSROOMS 13-16 | (1) (4) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 2,400 S | CLASSROOMS 13-16 | (1) | N |
| M | DRYWALL / JOINT COMPOUND | 300 | ASSUMED | 550 S | MEN'S (917) & WOMEN'S (918A) RESTROOMS | (1) | N |
| S | DRYWALL TEXTURE | 301 | ASSUMED | 150 S | MEN'S (917) & WOMEN'S (918A) RESTROOMS | (1) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

- General Condition:** (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit I - Classrooms 12 & 17

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|--------------------|--------------------------------------|----------------|
| M | 2' X 4' FCP FISSURE PATTERN | 95 | ASSUMED | 1,920 S | CLASSROOMS 12 & 17 | (1) (4) | N |
| M | 12" VFT WHITE | 110 | ASSUMED | 250 S | CLASSROOM 12 | (1) (4) | N |
| M | 12" VFT WHITE | 162 | ASSUMED | 480 S | CLASSROOMS 12 & 17 | (1) (4) | N |
| M | DRYWALL | 163 | ASSUMED | 1,000 S | CLASSROOMS 12 & 17 | (11) DRYWALL EXISTS BEHIND TAGBOARD. | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 160 L | CLASSROOMS 12 & 17 | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 1,440 S | CLASSROOMS 12 & 17 | (1) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit J - Restrooms Bldg.

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|---|--------------|---------|-----------------------|--|--|----------------|
| S | WALL PLASTER | 4 | ASSUMED | 1,000 S | GIRL'S (922) & BOY'S (919) RESTROOM & CUSTODIAN CLOSET (920) | (1) (4) MINOR CRACKS. | N |
| T | HARD PACKED TSI FLUE ENCASED WITH METAL | 98 | ASSUMED | 12 L | BOILER ROOM (921) | (11) THIS MATERIAL IS ENCASE IN METAL JACKET AND NOT ABLE TO BE ASSESSED | Y |
| M | DRYWALL | 164 | ASSUMED | 1,000 LF | BOY'S (919) & GIRL'S (922) RESTROOMS | (1) (4) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit K - Classrooms 18-21

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|---|--|----------------|
| S | PLASTER | 4 | ASSUMED | 6,000 S | CEILING AT CLASSROOMS 18-21, CUSTODIAN (924) (FORMERLY KNOWN AS RESTROOM 924) | (1) | N |
| M | TRANSITE PANELS | 83 | ASSUMED | 16 PANELS | UNDER WINDOWS THROUGHOUT BUILDING | (1) (4) | N |
| M | 12" VFT BLUE / WHITE | 94 | ASSUMED | 720 S | WORKROOM (923) & CLASSROOMS 18-21 | (1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE. | N |
| M | LINOLEUM | 100 | ASSUMED | 50 S | RESTROOM (924) | (12) COULD NOT LOCATE. | N |
| M | 2' X 4' FCP FISSURE PATTERN | 150 | ASSUMED | 3,600 S | CLASSROOMS 18-21 | (1) (4) | N |
| M | 12" ACT 1/8" HOLE PATTERN | 165 | ASSUMED | 800 S | CLASSROOMS 18-21 AND WORKROOM (923) | (1) (4) | N |
| M | 4" COVE BASE GRAY | 166 | ASSUMED | 480 LF | CLASSROOMS 18-21 - WORK ROOM (923) | (1) (4) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 5,000 S | CLASSROOMS 18-21 | (1) | N |
| M | 12" ACT FISSURE PATTERN | 289 | ASSUMED | 240 S | WORK ROOM (923) | (1) | N |

Z:\AHERA Inspections - Scanned\Chico USD\Sierra View ES\3-Year Reinspections\2010\Sierra View.HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit L - Classrooms 22 & 23

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|---------------------------------------|---|----------------|
| M | LINOLEUM | 102 | ASSUMED | 200 S | RESTROOMS (926A & B AND 927A & B) | (12) COULD NOT LOCATE - THERE IS OLD CERAMIC FLOOR TILE CURRENTLY INSTALLED | N |
| M | 12" VFT WHITE / BLUE | 105 | ASSUMED | 1,200 S | CLASSROOMS 22 & 23 AND WORKROOM (925) | (1) (4) | N |
| M | 2' X 4' FCP FISSURE PATTERN | 106 | ASSUMED | 2,400 S | CLASSROOMS 22 & 23 AND WORKROOM (925) | (1) (4) | N |
| M | DRYWALL / JOINT COMPOUND | 150 | ASSUMED | 200 S | RESTROOMS (926 A&B), (927 A&B) | (1) | N |
| M | 12" ACT 1/8" HOLE PATTERN | 165 | ASSUMED | 64 S | RESTROOMS (926 A&B), (927 A&B) | (1) | N |
| M | 4" COVE BASE GRAY | 167 | ASSUMED | 280 L | CLASSROOMS 22 & 23 | (1) (4) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 800 S | CLASSROOMS 22 & 23 | (1) | N |
| S | STUCCO | 255 | ASSUMED | 400 S | COVERED WALKWAY AT CLASSROOM ENTRIES | (1) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit M - Portables 24-26

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------------------|--------------|---------|-----------------------|---|--|----------------|
| M | 12" VFT LIGHT GRAY | 86 | ASSUMED | 720 S | PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS) | (1) (4) SOME CRACKS IN CLASSROOM 25 & 26. | N |
| M | DRYWALL | 87 | ASSUMED | 1,400 S | BOY'S (928) & GIRL'S (929) RESTROOMS, & PORTABLE CLASSROOMS 24-26 | (1) (4) DRYWALL IS ASSUMED TO EXIST BEHIND THE TAGBOARD IN PORTABLES 24-26. | N |
| M | LINOLEUM YELLOW | 88 | ASSUMED | 600 S | GIRL'S RESTROOM (929) | (1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26. | N |
| M | 2' X 4' FCP FISSURE PATTERN | 89 | ASSUMED | 3,000 S | PORTABLE CLASSROOMS 24-26 | (1) (4) | N |
| M | LINOLEUM WHITE | 168 | ASSUMED | 600 S | BOY'S RESTROOM (928) | (1) (4) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 250 L | PORTABLE CLASSROOMS 24-26 | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 2,000 S | PORTABLE CLASSROOMS 24-26 | (1) | N |
| | | | | | | ROOM 24 - SERIAL # 8888.13 A, B & C ROOM 25 - SERIAL # 8888.14 A, B & C ROOM 26 - SERIAL # 8888.15 A, B & C RESTROOM SERIAL # 8888.16 B | |

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Sierra View Elementary School

Building: Unit N - Portable 27

| Material Class | Material | Homo . Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|------------------------|---------------|-------------|-----------------------|--------------|--|----------------|
| M | DRYWALL | 84 | ASSUMED | 900 S | CLASSROOM 27 | (11) BEHIND TAGBOARD COVERING | N |
| M | 2' X 4' FCP FIBERGLASS | 85 | NON-SUSPECT | 900 S | CLASSROOM 27 | (13) | N |
| M | 12" VFT GRAY | 169 | ASSUMED | 180 S | CLASSROOM 27 | (1) (4) | N |
| M | 4" COVE BASE ADHESIVE | 250 | ASSUMED | 120 L | CLASSROOM 27 | (1) | N |
| M | CARPET ADHESIVE | 251 | ASSUMED | 850 S | CLASSROOM 27 | (1) | N |
| | | | | | | ROOM 27 - DESIGNED MOBILE SYSTEMS IND. - 4/99 SERIAL # 20-551#1 & #2 | |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS