

Homogeneous Materials Record

School Dist: **Chico USD**

School: **BIDWELL JUNIOR HIGH**

Date Inspected: **04/15/92**

BUILDING: **300**

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
CEILING PLAST	6	ALL RMS but N. Wing	01-05	16500 S	N
9" VFTs	95	ALL ROOMS	99-99 ASSUMED	16490 S	N
TRANSITE PIPE	99	CLOSET OF RM 405	99-99 ASSUMED	12 L	N
WALL PLASTER	100	ALL ROOMS	00-00	3500 S	N

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

Homogeneous Materials Record

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **400**

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
PW JNTs	14	PE BLR RM & TUNNEL	99-99 ASSUMED	50 J	N
TANK WRAP	15	PE BLR RM	99-99 ASSUMED	150 S	N
TRANS PANELS	98	LOCKER RMS	99-99 ASSUMED	1000 S	N
WALL PLASTER	100	COACHES OFFICES	00-00	1500 S	N

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/15/92

School: BIDWELL JUNIOR HIGH

BUILDING: 500

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
A DUCT INS	0	ON DUCT IN WALL & CL	90-95	0 S	N
9" vftS	95	All Rooms	99-99 ASSUMED	3420 S	N

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **600**

Material	Homog. Mat. #	Locations	% Asb	Footage Y or N	Friable?
MUD JNT	1	RM 208 NEAR SINK	01-05	2 J	N
12" VFTs	93	RM 9	99-99 ASSUMED	1100 S	N
9" VFTs	95	OFFICE AREA	99-99 ASSUMED	360 S	N
9" VFTs	95	RM 8	99-99 ASSUMED	960 S	N
ASB WLD CURTN	96	METAL SHOP	99-99 ASSUMED	40 S	N
TRANS PANELS	98	METAL SHOP	99-99 ASSUMED	400 S	N
FCP	101	RM 8 AND 9	00-00	2296 S	N

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 700

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
MUD JNTs	1	409	01-05	4 S	N
MUD JNTs	1	RM 408	01-05	4 S	N
9" VFTs	95	ALL CLS RMS	99-99 ASSUMED	5220 S	N
FCP	101	ALL CLASSROOMS	00-00	5220 S	N
WALL PLASTER	104	RESTROOMS / OFFICE	00-00	700 S	N

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 800

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
9" VFTs	95	LIBRARY	99-99 ASSUMED	3000 S	N

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **900**

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
PW STR	17	BLR RM	15-20	100 L	N
PW STR	17	GYM	15-20	400 L	N
PW STR	17	STR RM	15-20	50 L	N
PW JNTs	18	BLR RM	05-19	10 L	N
PW JNTs	18	GYM	05-19	15 J	N
PW JNTs	18	STR RM	05-19	5 L	N

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/15/92

School: BIDWELL JUNIOR HIGH

BUILDING: PORTABLES

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
CERTIFIED	0	8 PORTABLES	00-00	0

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

HOMOGENEOUS MATERIAL RECORDS

DISTRICT Chico SCHOOL Bidwell Jr. High

ADDRESS _____

BLDG.	MAT. CLASS.	MATERIAL	HOMOG. MAT. #	SAMPLE NUMBER	LOCATION	ASBESTOS %	FOOTAGE FT ² or LF	FRIABLE	
								YES	NO
100	surf	PLASTER ceiling	06	06B	All Rooms except Kitchen Area	1-S	3496#		X
100	misc	9" VEST	95	NS	All Rooms except Storage Areas	Assumed	3000#		X
100	surf	Hard wall PLASTER	100	100A-C	Transformer Rm, Chair Storage, Dining Rm Kitchen (walls & ceiling), Boy's Admin	0	10,000# →		X
100	T&E	PW STR	08	08B	Chair Storage Rm	30-35	25 lf		X
100	T&E	PW CNR	10	10B	Under Kitchen Dishwasher	0	12 INTS		X
100	T&E	PW STR	11	11B	Under Kitchen Dishwasher	0	15 lf	X	
100	T&E	PW CNR	13	13B	Kitchen BIR Rm	Assumed	~20 INTS		X
100	T&E	BIR Ceiling	12	12B	Kitchen BIR Rm	60-65	125#		X
100	misc	TRANSIT PIPE	99	NS	Kitchen BIR Rm	Assumed	10' of 8"		X
100	T&E	FAN UNIT	94	NS	Fan Rooms	Assumed	100#		X

DISTRICT Chico SCHOOL Bidwell Sr. High

ADDRESS

[illegible]

DISTRICT Chico SCHOOL Bidwell Jr. High

DISTRICT Chico SCHOOL Bidwell Jr. High

[illegible]

300	Surf	Hard wood PLASTER	100	100A-C	Rms 405 storage, 406 storage, cust Rm Restrooms	0	3500 # ↓	X
300	misc	Drywall	90	NS	Rm 250, Restrooms, Teachers Rm,	Assumed	3000 #	X
300	misc	9" UFT	95	NS	Rm 250, Hallways, Restrooms, Teachers Rm All classrooms	Assumed	16490 # ↓	X
300	Surf Surf	Ceiling PLASTER	06	06B	Rm 250, Hallways, Restrooms, Teachers Rm, All classrooms Except 105, 106 and 107	1-5 1-5	16,500 ↓	X
300	misc	Transite pipe	99	NS	Closet of Rm 405	Assumed	12' att"	X

DISTRICT Chico SCHOOL B'dwell Jr. High

ADDRESS

[illegible]

DISTRICT Chico SCHOOL Bidwell Jr. High

ADDRESS

[illegible]

DISTRICT Chico SCHOOL Bidwell Jr. High

[illegible]

DISTRICT Chico SCHOOL Bidwell Jr. High

[illegible]

DISTRICT	SCHOOL
Chicago	Bidwell Jr. High

Bidwell Jr. High

[illegible]

DISTRICT Chico
SCHOOL Bidwell Sr. High

Bidwell St. High

[illegible]

HMS, INC.
HAZARD MANAGEMENT SERVICES, INC.

CHICO UNIFIED SCHOOL DISTRICT
BIDWELL JUNIOR HIGH SCHOOL
AHERA THREE-YEAR REINSPECTION SUMMARY
APRIL, 1992

Attached you will find a computer print-out of your original "Homogeneous Materials Record Sheets". You will find these sheets easier to read than the original copies. If additional samples were collected at this site, the results are listed at the end of the new "homogeneous" sheets. A comment on drywall sampling and lab accreditation sheets are added as appropriate.

At this site all previously or currently identified asbestos-containing materials were in good condition, i.e., non-friable.

We have given you a new index to insert into your management plan to account for new sections VIII and IX. We have added section VIII in which you should include results of your six-month inspections. We have also included a sheet on drywall sampling with recommendations on handling drywall. We also want to remind you that new buildings or portables must either be inspected or exempted by letter by your architect or builder.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: BIDWELL JUNIOR HIGH

BUILDING: 100

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST	6	ALL RMS EXCEPT KIT	01-05	3496 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Not found in MPR either.					
PW STR	8	CHAIR STRG & FAN RM	30-35	50 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
BLR LINING	12	KITCHEN BLR RM	60-65	125 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW CNR	13	KITCHEN BLR RM	01-99 (ASSUMED)	20 J	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
FAN UNIT INS	94	FAN ROOMS	01-99 (ASSUMED)	100 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Caution should be used when storing items next to pipewrap. Do not damage pipewrap.					
9" vfts	95	ALL RMS EXCEPT STRRM	01-99 (ASSUMED)	3000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **100**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
TRANSITE PIPE	99	KITCHEN BLR RM	01-99	10 L	1-4
3 Year Inspection Notes:			(ASSUMED)		
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: BIDWELL JUNIOR HIGH

BUILDING: 200

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
PLASTER	5	ALL ROOMS	01-05	17600 S	1-4

3 Year Inspection Notes:

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments:

9" VFTS	95	ALL ROOMS	01-99 (ASSUMED)	13560 S	1-4
---------	----	-----------	--------------------	---------	-----

3 Year Inspection Notes:

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments:

Codes:

General Condition:	(1) Good	(2) Damaged	(3) Sig. Damaged
Change in Condition:	(N or 4) No	(Y) Yes	(Please explain)
Abated:	(R) Repaired	(M) Removed	(E) Enclsd
	(I) Isolated and Restricted		

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: 300

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST	6	ALL RMS but N. WING	01-05	16500 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Small amount of damage seen where ceiling fixture has been removed from south hallway.					
DRYWALL	90	RM 250	01-99 (ASSUMED)	3000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Samples #90A,B,C collected to determine whether this drywall is asbestos or not.					
DRYWALL	90	TEACHERS RM	01-99 (ASSUMED)	0 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Samples #90A,B, and C represent this material.					
9" VFTs	95	ALL ROOMS	01-99 (ASSUMED)	16490 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
TRANSITE PIPE	99	CLOSET OF RM 405	01-99 (ASSUMED)	12 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: 400

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
PW JNTs	14	PE BLR RM & TUNNEL	01-99 (ASSUMED)	50 J	1-4
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					
<hr/>					
TANK WRAP	15	PE BLR RM	01-99 (ASSUMED)	150 S	1-4
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					
<hr/>					
TRANS PANELS	98	LOCKER RMS	01-99 (ASSUMED)	1000 S	1-4
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: 500

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
A DUCT INS	0	ON DUCT IN WALL & CL	90-95	0 S	0-
3 Year Inspection Notes: Condition of Material: NO SURVEILLANCE DATA Change in Condition? NO Abated? NO Comments: Could not find access to duct.					

9" VFTs	95	ALL ROOMS	01-99 (ASSUMED)	3420 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

DRYWALL	100	ALL RMS	01-01	4000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:
General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **600**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
MUD JNT	1	RM 208 NEAR SINK	01-05	2 J	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Above FCPs.					
12" VFTs	93	RM 9	01-99 (ASSUMED)	1100 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	95	OFFICE AREA	01-99 (ASSUMED)	360 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	95	RM 8	01-99 (ASSUMED)	960 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
ASB WLD CURTN	96	METAL SHOP	01-99 (ASSUMED)	40 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Small hole in fabric.					
TRANS PANELS	98	METAL SHOP	01-99 (ASSUMED)	400 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
 Change in Condition: (N or 4) No (Y) Yes (Please explain)
 Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**

School: **BIDWELL JUNIOR HIGH**

Date Inspected: **04/15/92**

BUILDING: 600

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: 700

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
MUD JNTs	1	409	01-05	4 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
MUD JNTs	1	RM 408	01-05	4 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	95	ALL CLS RMS	01-99 (ASSUMED)	5220 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: BIDWELL JUNIOR HIGH

BUILDING: 800

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	95	LIBRARY	01-99	3000 S	1-4
3 Year Inspection Notes:			(ASSUMED)		
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: 900

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
PW STR	17	BLR RM	15-20	100 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW STR	17	GYM	15-20	400 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW STR	17	STR RM	15-20	50 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW JNTs	18	BLR RM	05-19	10 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW JNTs	18	GYM	05-19	15 J	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW JNTs	18	STR RM	05-19	5 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: **900**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **BIDWELL JUNIOR HIGH**

BUILDING: PORTABLES

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

SUMMARY OF FRIABLE AND NON-FRIABLE ACBM BY BUILDING

CS CODE

04 61242 6057129

SCHOOL

BIDWELL JUNIOR HIGH SCHOOL

SCHOOL PHONE NUMBER

(916) 891-3080

ADDRESS

(Number)

(Street)

(City)

(Zip Code)

2376 NORTH AVE.

CHICO

95926

NUMBER OF BUILDINGS

12

LINE	BUILDING NAME (Indicate Address if Different From Above)	CHECK ONE				
		ACBM		ASSUMED ACBM		
		NONE	FRIABLE	NON-FRIABLE	FRIABLE	NON-FRIABLE
1.	100			X		X
2.	200			X		X
3.	300			X		X
4.	400					X
5.	500			X		X
6.	600			X		X
7.	700			X		X
8.	800					X
9.	900			X		
10.	MAINTENANCE SHED	X				
11.	GREEN HOUSE	X				
12.	METAL STORAGE SHED	X				
13.	PORTABLES (2)	X				
14.						
15.						
16.						
17.						
18.						
19.						
20.						

SIX-MONTH SURVEILLANCE

Page 1 of 3

DISTRICT Chico Unified School District DATE December 21, 1992SCHOOL Bidwell Junior High INSPECTOR Michael Fender *MF*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
-------	-----------------	----------------------	----------	----------------------------

100	Ceil Plas	1-5	All rooms except kitchen	1-4
100	9" VFT	Assumed	All rooms except store	1-4
100	PW Str	30-35	Chair Store Room	1-4 (door locked)
100	PW Cnr	Assumed	Kitchen B/R Room	1-4
100	B/R Lin	60-65	Kitchen B/R Room	1-4
100	Tran pipe	Assumed	Kitchen B/R Room	1-4
100	Fan Vent Insul	Assumed	Fan Rooms	1-4
200	9" VFT	Assumed	All Rooms	1-4
200	Plaster	1-5	All Rooms	1-4
300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4
300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 3

DISTRICT Chico Unified School District DATE December 21, 1992SCHOOL Bidwell Junior High INSPECTOR Michael Fender *MF*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
300	Ceil Plas	1-5	Rm 250, halls, rr, teach	1-4
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4 (room 105A - small holes)
300	Tran pipe	Assumed	Closet of Room 405	1-4
400	Tran panl	Assumed	Panels in both locker rooms	1-4
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4
400	Tank Wrap	Assumed	PE Boiler room	4-6
500	Drywall	1	All rooms	1-4
500	9" VFT	Assumed	All rooms	1-4
500	Duct Insl	90-95	Duct work - ceil. & walls	1-4-10
600	Tran panl	Assumed	Metal Shop	1-4
600	9" VFT	Assumed	Room 8 and office	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 3 of 3

DISTRICT Chico Unified School District DATE December 21, 1992SCHOOL Bidwell Junior High INSPECTOR Michael Fender *MF*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
600	Asb. Curt	Assumed	Metal Shop	7
600	Mud Jnts	1-5	Rm 208 near sink (Rm 9)	1-4
600	12" VFT	Assumed	Room 9	1-4
700	9" VFT	Assumed	All Classrooms	1-4
700	Mud Jnts	1-5	Rooms 408 & 409	1-4
800	9" VFT	Assumed	Library	1-4
900	PW Str	15-20	Gym, B/R, Storeroom	1-4
900	PW Cnr	5-10	Gym, B/R, Storeroom	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

ASBESTECH

6801 FAIR OAKS BLVD., SUITE H
CARMICHAEL, CA 95608
(916) 481-8902

Hazard Management Services
P.O. Box 7548
Citrus Heights, CA 95621

Chico U.S.D.

ASBESTOS ANALYSIS REPORT

LAB JOB NO. 3512

DATE RECEIVED

3/11/89

SAMPLE NO.

COLOR/DESCRIPTION

% TYPE ASBESTOS

N.V.L.A.B. LAB #142

EPA LAB #9247

DATE REPORTED

3/13/89

% TYPE OTHER

BID-JR-100A

White drywall Music bldg
Choral room ceiling

NONE DETECTED

85 Gypsum Binder
15 Cellulose

100B

~~White drywall Music bldg~~
choral Rm wall practice Rm

(in topping)

60 Calcite Binder
30 Gypsum
9 Cellulose

100C

White drywall Music bldg
choral Rm wall practice Rm

NONE DETECTED

85 Gypsum
15 Cellulose

ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING EPA METHOD #600/4820. SAMPLES THAT CONTAIN LESS THAN 1% ASBESTOS ARE NOT CONSIDERED HAZARDOUS BY EPA. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITH THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED BY CLIENT TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.B. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH AND T.O. CONLON ACCEPT TECHNICAL RESPONSIBILITY FOR THIS TEST REPORT AND DATE OF ISSUE.



SIGNED

T. O. Conlon



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177335
Date Received: 04/21/92

Lab Number: 19220548
Sample Number: HMS-CUSD-BJR-90A
P.O. Num:
Job ID: Chico Unified School District
Site: ~~Chico Unified High~~

Date Collected: 04/15/92

Location: Teacher's room at door jam Unit 300, drywall.

Gross Description: White fibrous plaster with paint, fibrous backing
and a trace of skim coat.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Non-Det. %

Chrysotile
Amosite

Non-Det. %

Non-Det. %

%

%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

15-20 %

Cellulose
Fibrous Glass
Talc

10-15 %

1-5 %

Trace %

%

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 800/827-FASL Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177335
Date Received: 04/21/92

Lab Number: 19220549

Date Collected: 04/15/92

Sample Number: HMS-CUSD-BJR-90B

P.O. Num:

Job ID: Chico Unified School District

Site: Bidwell Junior High

Location: Room 250 north wall at door jam, drywall.

Gross Description: White fibrous powder with a trace of skim coat and fibrous backing.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %
Non-Det. %

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose 10-15
Fibrous Glass 1-5

15-20 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85 %

Janis Teichman
Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177335
Date Received: 04/21/92

Lab Number: 19220550

Date Collected: 04/15/92

Sample Number: HMS-CUSD-BJR-90C

P.O. Num:

Job ID: Chico Unified School District

Site: Bidwell Junior High

Location: Room 250 south wall in west corner, floor level, drywall.

Gross Description: White fibrous powder with paint and fibrous backing.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %

Non-Det. %

%

%

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose

10-15

%

Fibrous Glass

1-5

%

%

%

15-20 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 800/827-FASL Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684