

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-15-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit A (FKA H)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	1,250 S	CLASSROOM 1	(11) EXISTS BEHIND TAGBOARD.	N
M	2' X 4' FCP	99	ASSUMED	960 S	CLASSROOM 1	(1) (4) 4	N

School: Sierra View Elementary School

Building: Unit B (FKA F)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOMS	(1) (4) 4	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5 AND SPEECH ROOMS	(1) MODERNIZATION PROJECT 1997 NEEDS REPAIR IN ROOM 295 BY DOORS 6	N
M	TRANSITE PANELS	83	ASSUMED	25 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) 4	N
M	12" ACT	17	ASSUMED	4,000 S	CLASSROOMS 2-5 AND SPEECH ROOMS	(1) (4) 4	N
M	4" COVE BASE BLACK	157	ASSUMED	600 LF	CLASSROOMS 2-5 AND SPEECH ROOMS	(1) (4) 4	N
M	9" VFT GREY	158	ASSUMED	400 S	SPEECH ROOMS	(1) (4) MODERNIZATION PROJECT 1997 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit C (FKA H)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	97	ASSUMED	600 S	LIBRARY (902)	(1) (4) 4	N

School: Sierra View Elementary School

Building: Unit D (FKA E)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET (904)	(1) (4) 4	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM (906)	(1) (4) 4	Y
M	DRYWALL & JOINT COMPOUND	150	ASSUMED	1,000 S	BOY'S (907) & GIRL'S (905) RESTROOMS	(1) (4) 4	N
T	BOILER TSI	156	ASSUMED	1 EACH	BOILER ROOM (906)	(1) (4) 4	Y

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hat

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit E (FKA H)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	1,700 SF	CLASSROOMS 6 & 7	(11) EXISTS BEHIND TAGBOARD.	N
M	12" VFT	94	NON ASBESTOS	120 S	CLASSROOM 6	(1) (4) MODERNIZATION PROJECT 1997 MANUFACTURER LETTER ON FILE	N
M	2' X 4' FCP	99	ASSUMED	960 S	CLASSROOM 6 & 7	(1) (4) <u>4</u>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit F (FKA G)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	PIP ROOM (909) AND NURSES ROOM	(1) (4) 4	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11	(1) ROOM 9 NEEDS REPAIR BY DOOR (7) (5) REMOVED IN PIP ROOM. 4	N N/A
M	TRANSITE PANELS	83	ASSUMED	25 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) 4	N
M	12" ACT	97	ASSUMED	4,000 S	CLASSROOMS 8-11	(1) (4) (2) RM 10 4" COVE REAR DOOR CHIPPED, VCT WATER STAINS 1.5.6	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM (908)	(1) UNABLE TO LOCATE. 4	N
M	9" VFT GREY	170	ASSUMED	400 S	PIP ROOM (909) AND NURSES ROOM	(1) (5) NEEDS REPAIR BY FRONT DOOR 4	N
M	4" COVE BASE BLACK	171	ASSUMED	480 LF	CLASSROOMS 8-11	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit G (FKA D)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN (912), KITCHEN STORAGE (910), AND MPR CHAIR STORAGE	(1) (5) (2) SMALLHOLE NEAR EXTINGUISHER (2) UNDER PHONE 4	N
T	PIPE WRAP	8	15-20%	13 L	HOT WATER ROOM (911)	(2) (4) UNCAPPED ENDS. 1	Y
M	TRANSITE PIPE FLUE	98	ASSUMED	20 L	HOT WATER ROOM	(1) (4) 4	Y
M	LINOLEUM WHITE	152	ASSUMED	50 S	KITCHEN RESTROOM	(1) (4) 4	N
M	DRYWALL	153	ASSUMED	UNDETERMINED	OFFICES AND MPR (913) CEILINGS	(1) (4) 4	N
M	12" VFT WHITE/BLUE	154	None Detected	3,500 S	OFFICE HALLWAY & MPR (913)	(13) CUSD Sample SV01 on 6/1/07	N
M	12" ACT	155	ASSUMED	2,000 S	OFFICE HALLWAY CEILING, ALL THREE OFFICES (914-916), AND MPR (913)	(1) (4) (2) ACT LOOSE OUTSIDE ROOM 913 AND 923 4	N
M	LINOLEUM TAN	159	ASSUMED	500 S	KITCHEN (912)	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit H (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM (917) & CLASSROOMS 13-16	(1) (4) 4	N
M	12" VFT BLUE/WHITE	94	None Detected	720 S	STAFF ROOM (917) & CLASSROOMS 13-16	(13) CUSD Sample SV01 on 6/1/07	N
M	2' X 4' FCP	150	ASSUMED	3,600 S	STAFF ROOM (917) & CLASSROOMS 13-16	(1) (4) 7 (917)	N
M	LINOLEUM	151	ASSUMED	100 S	MEN'S (918) & WOMEN'S (918A) RESTROOMS	(1) (4) 4	N
M	12" ACT	160	ASSUMED	600 S	CLASSROOMS 13-16	(1) (4) 4 (6) LOOSE TILES ROOM 14	N
M	4" COVE BASE GREY	161	ASSUMED	480 S	CLASSROOMS 13-16	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-16-14

Inspector: Daniel Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit I (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	95	ASSUMED	1,920 S	CLASSROOMS 12 & 17	(1) (4) 4	N
M	12" VFT WHITE	110	NON ASBESTOS	250 S	CLASSROOM 12	(1) (4) MODERNIZATION 1997 MANUFACTURER LETTER ON FILE	N
M	12" VFT	162	NON ASBESTOS	480 S	CLASSROOMS 12 & 17	(1) (4) MODERNIZATION 1997 MANUFACTURER LETTER ON FILE	N
M	DRYWALL	163	ASSUMED	1,000 S	CLASSROOMS 12 & 17	(11) DRYWALL EXISTS BEHIND TAGBOARD.	N

School: Sierra View Elementary School

Building: Unit J (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S (922) & BOY'S (919) RESTROOM & CUSTODIAN CLOSET (920)	(1) (5) BAD AREA OVER BOYS OUTER DOOR 6	N
T	HARD PACKED TSI FLUE ENCASED WITH METAL	98	ASSUMED	12 L	BOILER ROOM (921)	(1) (4) 4	Y
M	DRYWALL	164	NON ASBESTOS	1,000 LF	BOY'S (919) & GIRL'S (922) RESTROOMS	(7) Replaced per CUSD Records	N

CONDITION CODE

General Condition: (1) Good (2) **1** Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 10-16-14

Inspector: David Hunt

District: Chico Unified School District

School: Sierra View Elementary School

Building: Unit K (FKA B)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) 4	N
M	12" VFT BLUE/WHITE	94	None Detected	720 S	WORKROOM (923) & CLASSROOMS 18-21	(13) CUSD Sample SV01 on 6/1/07	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM (916) HEALTH ROOM	(1) 4	N
M	2' X 4' FCP	150	ASSUMED	3,600 S	CLASSROOMS 18-21	(1) (2) RMS 18, 19, 20 4	N
M	12" ACT	165	ASSUMED	800 S	CLASSROOMS 18-21 AND WORKROOM (923)	(1) (4) 4	N
M	4" COVE BASE GREY	166	ASSUMED	480 LF	CLASSROOMS 18-21	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-16-14

District: Chico Unified School District

Inspector: Daniel Hunt

School: Sierra View Elementary School

Building: Unit L (FKA I)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	CERAMIC TILE	102	ASSUMED	200 S	RESTROOMS (926A & B AND 927A & B)	(1) (4) 4	N
M	12" VFT WHITE/BLUE	105	None Detected	1,200 S	CLASSROOMS 22 & 23 AND WORKROOM (925)	(13) CUSD sample S01 on 6/1/07	N
M	2' X 4' FCP	106	ASSUMED	2,400 S	CLASSROOMS 22 & 23 AND WORKROOM (925)	(1) (4) 4	N
M	4" COVE BASE GREY	167	ASSUMED	280 L	CLASSROOMS 22 & 23	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection: 10-16-14

District: Chico Unified School District

Inspector: Daniel Hunt

School: Sierra View Elementary School

Building: Unit M - Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	None Detected	720 S	PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS)	(1) (4) SOME CRACKS IN CLASSROOM 25 & 26. (13) CUSD sample 3/22/05 MODERNIZATION 1997	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S (928) & GIRL'S (929) RESTROOMS, & PORTABLE CLASSROOMS 24-26	(1) (4) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26. 4	N
M	LINOLEUM YELLOW	88	ASSUMED	600 S	GIRL'S RESTROOM (929)	(1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26. 4	N
M	2' X 4' FCP	89	ASSUMED	3,000 S	PORTABLE CLASSROOMS 24-26	(1) (4) THESE UNITS WERE MANUFACTURED IN 8-89. 4	N
M	LINOLEUM WHITE	168	ASSUMED	600 S	BOY'S RESTROOM (928)	(1) (4) 2	N

School: Sierra View Elementary School

Building: Unit N - Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	CLASSROOM 27	(1) (4) 9 walls covered w/VTB	N
M	2' X 4' FCP FIBERGLASS	85	NON-SUSPECT	900 S	CLASSROOM 27	(13)	N
M	12" VFT GREY	169	NON ASBESTOS	180 S	CLASSROOM 27	(1) (4) MODERNIZATION 1997 MANUFACTURER LETTER ON FILE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS