

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

Inspector: Daniel Hunt

District: Chico Unified School District

School: Marigold Elementary School

Building: Unit A - Rooms 1 & 2 (FKA 3)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT WHITE	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4) 4 SAMPLE MAR-02 COLLECTED ON 3-30-88.	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4) 4	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE & BELOW GLASS PANELS (EXTERIOR)	(1) (4) 4	N
M	DRYWALL & JOINT COMPOUND	105	ASSUMED	600 S	CLASSROOMS 1 & 2	(1) (4) 114	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

Inspector: Daniel Hunt

District: Chico Unified School District

School: Marigold Elementary School

Building: Unit B - MPR (FKA 5)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN (909), ADMIN OFFICE, MULTI PURPOSE ROOM (905), STORAGE, PIP ROOM (908), AND HEALTH OFFICE (903)	(2) (11) 1,4 ADMIN OFFICE (NORTH HALF ONLY) COVERED WITH 12" VFT BLUE.	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(1) (4) SAMPLE MAR-06 COLLECTED ON 3-30-88.	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN (909) AND RESTROOMS (907 & 907A)	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM (905)	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM (908), CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE (903)	(1) (4)	N
M	12" VFT BLUE	106	NON ASBESTOS	240 S	ADMIN OFFICE	(1) MODERNIZATION PROJECT 1996 LETTER FROM ARMSTRONG (MFG) ON FILE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec - 2011

District: Chico Unified School District

Inspector: Daniel Hunt

School: Marigold Elementary School

Building: Unit E - Restrooms (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP STRAIGHT	10	60-65%	150 L	BOILER ROOM	(1) (4) 4 SAMPLE MAR-10 COLLECTED ON 3-30-88.	Y
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(2) 4 MINOR WATER DAMAGE ON ACT'S IN BOY'S & GIRL'S RESTROOMS.	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(11) 4	N
S	PLASTER	101	NON ASBESTOS	600 S	BOY'S & GIRL'S RESTROOMS AND CUSTODIAL ROOM	(2) (6) BOYS RESTROOM DAMAGED NEAR DOOR CUSD SAMPLE 7/7/08 MAR01,03-05	N
T	BOILER INSULATION	108	ASSUMED	2 EACH	BOILER ROOM	(1) 4	Y

School: Marigold Elementary School

Building: Unit F - Rooms 7-9 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 7-9	(1) MODERNIZATION 1996 4	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 7-9	(1) (4) 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec 2011

Inspector: Daniel Hunt

District: Chico Unified School District

School: Marigold Elementary School

Building: Unit C - Rooms 3-5 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5	(1) (6) SAMPLE MAR-08 COLLECTED ON 3-30-88.	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5	(1) (4)	N

School: Marigold Elementary School

Building: Unit D - Rooms 6A & 6B (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	95	NON ASBESTOS	240 S	CLASSROOMS 6A & 6B	(1) (4) MODERNIZATION 1996 MANUFACTURER LETTER ON FILE 4	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A & 6B	(1) (4) 4	N
M	DRYWALL & JOINT COMPOUND	107	ASSUMED	2,500 S	CLASSROOMS 6A & 6B	(11) COVERED WITH TAGBOARD. 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec-2011

District: Chico Unified School District

Inspector: Daniel Host

School: Marigold Elementary School

Building: Unit H (FKA 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	CLASSROOMS 11-14 AND MIDDLE RESTROOM	(1) (4) MIDDLE RESTROOM. (11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	NON ASBESTOS	4,500 S	ALL ROOMS	(1) (4) CUSD SAMPLE COLLECTED 7/7/08	N
M	12" VFT	93	NON ASBESTOS	900 S	ROOM 12 - LIBRARY	(11) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE IN 1996 - NEW CARPET 9/09	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	NON ASBESTOS	305 S	STAFF LOUNGE (920)	(7) MODERNIZATION 1996 REMOVED AND REPLACED WITH 12" VFT GREEN.	N/A
M	12" VFT GREEN	151	NON ASBESTOS	305 S	STAFF LOUNGE (920)	(1) MODERNIZATION 1996 MANUFACTURER LETTER ON FILE	N
S	PLASTER	152	ASSUMED	2,000 SF	RESTROOMS (918 & 919) AND STAFF LOUNGE (920)	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	153	ASSUMED	2,500 SF	CLASSROOMS 11-14	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Ex under comments) (13) Non-Asbestos/Not Inspected

SIX MONTH SURVEILLANCE
HOMOGENEOUS ASBESTOS RECORDS

Date of Inspection: Dec. 2011

District: Chico Unified School District

Inspector: Daniel Hunt

School: Marigold Elementary School

Building: Unit G - Room 10 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP FIBERGLASS	96	Certified Non-Asbestos	1,800 S	CLASSROOM 10	(13) Letters on file	N
M	DRYWALL & JOINT COMPOUND	109	Certified Non-Asbestos	1,700 S	CLASSROOM 10	(13) Letters on file COVERED WITH TAGBOARD	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

District: Chico Unified School District

Inspector: Daniel Hunt

School: Marigold Elementary School

Building: Unit L - Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	Certified Non-Asbestos	180 S	PORTABLES 23 & 24	(1) (4) (13) Letter on file	N
M	DRYWALL & JOINT COMPOUND	103	Certified Non-Asbestos	960 S	PORTABLES 23 & 24	(11) COVERED WITH TAGBOARD. (13) Letter on file	N
M	2' X 4' FCP'S (FIBERGLASS)	104	Certified Non-Asbestos	900 S	PORTABLES 23 & 24	(1) (4) (13) Letter on file	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

District: Chico Unified School District

Inspector: _____

School: Marigold Elementary School

Building: Unit K - Room 18 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	Certified Non-Asbestos	2,400 S	PORTABLE 18A	(1)(4) MODERNIZATION IN 1996 (13) Letter on file	N
M	DRYWALL	81	Certified Non-Asbestos	10,000 S	PORTABLE 18A	(1) (4) (13) Letter on file	N
M	2' X 4' FCP	89	Certified Non-Asbestos	8,000 S	PORTABLE 18A	(1) (4) (13) Letter on file	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

CONSULTANT ANAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

District: Chico Unified School District

Inspector: Daniel Host

School: Marigold Elementary School

Building: Unit I - Rooms 15-17 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
						NOTE: ROOMS 15-17 WERE NOT INCLUDED IN THE ORIGINAL INSPECTION PERFORMED BY HMS, INC. IN 1988. (13) Letters on file	

School: Marigold Elementary School

Building: Unit J - Rooms 19-23 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	Certified Non-Asbestos	2,400 S	PORTABLES 18B-22	(1)(4) MODERNIZATION 1996 (13) Letter on file	N
M	DRYWALL	81	Certified Non-Asbestos	10,000 S	PORTABLES 18B-22 AND RESTROOMS (923 & 924)	(11) COVERED WITH TAGBOARD IN CLASSROOMS 18B-22. (13) Letter on file	N
M	2' X 4' FCP	89	Certified Non-Asbestos	8,000 S	PORTABLES 18B-22	(1)(4) (13) Letter on file	N
M	LINOLEUM	100	Certified Non-Asbestos	500 S	RESTROOMS (923 & 924)	(1)(4) (13) Letter on file	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected