

# SIX-MONTH SURVEILLANCE

DISTRICT CHICO UNIFIED SCHOOL DISTRICT

DATE 12/19/89

SCHOOL Fairview High School

INSPECTOR Robert Peters

*Robert Peters*

BLDG. HOMOG. ASBESTOS MAT. MATERIAL LOCATION CONDITION: CODE & COMMENTS

A	9" VFT	1 - 5	Rooms 1 & 2 (Beige)	(1) Good
B	9" VFT	1 - 5	Rooms 4, 5, 3, 2	(1) Good
MPR	Mud Jnt	65 - 70	Kitchen	(1) Good
MPR	9" VFT	1 - 5	MPR (Green)	(1) Good
MPR	9" VFT	1 - 5	Food storage, ARS office	(1) Good
MPR	9" VFT	1 - 5	S-Storage & food storage	(1) Good
MPR	Ceiling plaster	1 - 5	MPR	(5) Water damaged
MPR	Boiler insulation	75 - 80	Boiler room	(1) Good
MPR	Transite pipe	Assumed	Boiler room	(1) Good
MPR	Mud Jnt	35 - 40	Boiler room	(1) Good

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (DAMAGED 2 & OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES [IF YES, EXPLAIN UNDER COMMENTS]  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED