

PROJECT SP 1-A

ADDENDUM

SCHOOL FAIRVIEW CONT. HIGH SCHOOL

Signature
11-15-90

DATE

APPLICATION NO. 1

SITE SUMMARY
GRADES SERVED AT THIS SCHOOL

BLDG	UNIT DESCRIPTION	CONSTRUCTED APPLICATION NO.	TOTAL AREA	NON-CHARGEABLE		OVER 30	SPEC. EDS.	T/S	LAB/S
				LEASE	NON-CONFORM				
	MULTI-USE	14259	4,202.78			X		—	
A	PORTABLES (2)(CLASSRMS)	31606	2,080.36			X		1	
B	PORTABLES (5)(CLASSRMS) (TOILETS & ADMIN.)	31114	5,207.99			X		4	
C	PORTABLES (CLASSRMS)	28178	4,251.84			X		5	
	DIST. RELOCATABLES	54216 6/90	960.00			X			
							TOTAL	10	
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									
<hr/>									

PREPARED BY: THOMSON & HENDRICKS /ARCHITECTS & PLANNERS/ (916) 342-5669 234 WEST THIRD STREET CHICO, CALIF. 95928

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE Dec. 4, 1990

SCHOOL Fairview High School INSPECTOR Robert Peters *RP*

BLDG. HOMOC. ASBESTOS LOCATION CONDITION: CODE & COMMENTS
 MAT.# MATERIAL

A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good (4)
MPR	Mud Jnt	65-70	Kitchen	(5) (7)
MPR	9" VFT	1-5	MPR (Green)	(1) (5) (2) 27 kitchen tiles
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good (4)
MPR	Ceill plas	1-5	MPR	(4)
MPR	Boil Insl	75-80	Boiler Room	(1) Good (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) Good (4)
MPR	Mud Jnt	35-40	Boiler Room	(5) (2) 1 Jnt has small tear

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 5, 1990

SCHOOL Fairview High School INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good
MPR	Mud Jnt	65-70	Kitchen	(1) Good
MPR	9" VFT	1-5	MPR (Green)	(1) Good
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good
MPR	Ceill plas	1-5	MPR	(5) Water Damaged
MPR	Boil Insl	75-80	Boiler Room	(1) Good
MPR	Tran pipe	Assumed	Boiler Room	(1) Good
MPR	Mud Jnt	35-40	Boiler Room	(1) Good

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)