

CLEANING/REPAIR REPORT - AHERA

40 CFR 763.91(c) (INITIAL CLEANING) Unless the building has been cleaned using equivalent methods within the previous 6 months, all areas of a school building where friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM are present shall be cleaned at least once after the completion of the inspection ... and before the initiation of any response action, other than O & M activities or repair, according to the following procedures:

(i) HEPA-vacuum or steam-clean all carpets. (ii) HEPA-vacuum or wet-clean all other horizontal surfaces. (iii) Dispose of all debris, filters, mopheads, and cloths in sealed, leak-tight containers.

CLEANING

REPAIR

Date of cleaning/repair: 1/15/91

Person performing the cleaning/repair: Mike Fender

Location of cleaning/repair: Fairview High School boiler room workorder #29041

Method of cleaning/repair: wettable cloth, HEPA vacuum



Signature, Title of Authorizing Person

40 CFR 763.91(c)(2) (ADDITIONAL CLEANING) The accredited management planner shall make a written recommendation to the local education agency whether additional cleaning is needed, and if so, the method and frequency of such cleaning.

Date of cleaning/repair:

Person performing the cleaning/repair:

Location of cleaning/repair:

Method of cleaning/repair:

Signature, Title of Authorizing Person

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1991

SCHOOL Fairview High School INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good (4)
MPR	Mud Jnt	65-70	Kitchen	(5) (7)
MPR	9" VFT	1-5	MPR (Green)	(6) (4)
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good (4)
MPR	Cell plas	1-5	MPR	(4)
MPR	Boil Insl	75-80	Boiler Room	(1) Good (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) Good (4)
MPR	Mud Jnt	35-40	Boiler Room	(6) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 5, 1991

SCHOOL Fairview High School INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good (4)
MPR	Mud Jnt	65-70	Kitchen	(5) (7)
MPR	9" VFT	1-5	MPR (Green)	(5) - (6) 27 kitchen tiles
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good (4)
MPR	Ceill plas	1-5	MPR	(4)
MPR	Boil Insl	75-80	Boiler Room	(1) Good (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) Good (4)
MPR	Mud Jnt	35-40	Boiler Room	(5) (6)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)