

DISTRICT Chico Unified School District DATE August 12, 1999

SCHOOL Fair View High School INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) (4)
MPR	Mud Jnt	65-70	Kitchen	(7)
MPR	9" VFT	1-5	MPR (Green)	(1) (4)
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) (4)
MPR	Ceill plas	1-5	MPR	(2) (4)
MPR	Boil Insl	75-80	Boiler Room	(1) (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) (4)
MPR	Mud Jnt	35-40	Boiler Room	(1) (4)
C	9" VFTs	1-5	All Classrooms	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE 2/23/99

SCHOOL Fairview High School

INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) (4)
MPR	Mud Jnt	65-70	Kitchen	(7)
MPR	9" VFT	1-5	MPR (Green)	(1) (4)
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) (4)
MPR	Ceill plas	1-5	MPR	(2) (4)
MPR	Boil Insl	75-80	Boiler Room	(1) (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) (4)
MPR	Mud Jnt	35-40	Boiler Room	(1) (4)
C	9" VFTs	1-5	All Classrooms	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

