

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Fairview High School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BEIGE	10	1-5%	1,920 S	ROOMS 1 & 2	(1) (4) SAME 11/24/03	N
M	DRYWALL	75	TRACE	1,400 S	OFFICE WALLS, RESTROOMS, & CUSTODIAN ROOM	(1) (4) SAME 11/24/03	N

School: Fairview High School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	10	1-5%	4,300 S	ALL CLASSROOMS & COUNSELING OFFICES	(1) (4) SAME 11/24/03	N
M	DRYWALL	98	ASSUMED	600 S	BOYS & GIRL'S RESTROOMS	(1) SAME 11/24/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Fairview High School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP (PLASTIC)	96	ASSUMED	2,400 S	ALL CLASSROOMS	(1) SAME 11/24/03	N
M	9" VFT	97	ASSUMED	2,400 S	ALL CLASSROOMS	(1) SAME 11/24/03	N

School: Fairview High School

Building: Green House (Shop)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	TRACE	600 S	GREEN HOUSE	(1) (4) SAME 11/24/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Fairview High School

Building: MPR

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	5	1-5%	2,600 S	MPR	(1) (4) MINOR WATER STAINS. (5) (6) 11/6/02 (1) (5) PAINTED PER 5/12/03 INSPECTION	N
M	9" VFT GREEN	6	1-5%	2,800 S	MPR, KITCHEN, FOOD STORAGE, ENTRANCE	(1) (4) SAME 11/24/03	N
T	BOILER INSULATION	7	75-80%	150 S	BOILER ROOM	(1) (4) APPEARS TO BE IN GOOD SHAPE. SAME 11/24/03	N
T	MUD JOINT	8	35-40%	32 EACH	BOILER ROOM	(1) (4) SAME 11/24/03	N
M	TRANSITE PIPE	99	ASSUMED	25 L	BOILER ROOM	(1) (4) SAME 11/24/03	N

School: Fairview High School

Building: Portables 12, 15, & 16

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 12, 15, AND 16	(12) MANUFACTURES DATE 1989. DISTRICT CERTIFICATION REQUIRED.	

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Fairview High School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BEIGE	10	1-5%	1,920 S	ROOMS 1 & 2	(1) (4) SAME 5/12/2003	N
M	DRYWALL	75	TRACE	1,400 S	OFFICE WALLS, RESTROOMS, & CUSTODIAN ROOM	(1) (4) SAME 5/12/2003	N

School: Fairview High School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	10	1-5%	4,300 S	ALL CLASSROOMS & COUNSELING OFFICES	(1) (4) SAME 5/12/2003	N
M	DRYWALL	98	ASSUMED	600 S	BOYS & GIRL'S RESTROOMS	(1) SAME 5/12/2003	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Fairview High School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP (PLASTIC)	96	ASSUMED	2,400 S	ALL CLASSROOMS	(1) SAME 5/12/2003	N
M	9" VFT	97	ASSUMED	2,400 S	ALL CLASSROOMS	(1) SAME 5/12/2003	N

School: Fairview High School

Building: Green House (Shop)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	TRACE	600 S	GREEN HOUSE	(1) (4) SAME 5/12/2003	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Fairview High School

Building: MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	5	1-5%	2,600 S	MPR	(1) (4) MINOR WATER STAINS. (5) (6) 11/6/02 (1) (5) PAINTED PER 5/12/03 INSPECTION	N
M	9" VFT GREEN	6	1-5%	2,800 S	MPR, KITCHEN, FOOD STORAGE, ENTRANCE	(1) (4) SAME 5/12/2003	N
T	BOILER INSULATION	7	75-80%	150 S	BOILER ROOM	(1) (4) APPEARS TO BE IN GOOD SHAPE. SAME 5/12/2003	N
T	MUD JOINT	8	35-40%	32 EACH	BOILER ROOM	(1) (4) } SAME 5/12/2003	N
M	TRANSITE PIPE	99	ASSUMED	25 L	BOILER ROOM	(1) (4) } SAME 5/12/2003	N

School: Fairview High School

Building: Portables 12, 15, & 16

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 12, 15, AND 16	(12) MANUFACTURES DATE 1989. DISTRICT CERTIFICATION REQUIRED.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS