

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 01/27/2009

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Chapman Elementary School

Building: Unit A (FKA G)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------|--------------|----------------|-----------------------|-------------------------|--|----------------|
| T | MUD JOINT | 1 | 1-5% | UNDETERMINED | THROUGHOUT | (11) SAMPLE HMS-CPM-03 COLLECTED ON 4/9/88. | Y |
| M | TRANSITE PANELS | 2 | ASSUMED | UNDETERMINED | THROUGHOUT | (1) | N |
| M | 12" VFT CREAM | 3 | None Detectedb | 400 S | CLASSROOMS 1, 2, 6, & 7 | (13) CUSD sample taken 12/26/07 chp01-chp 04 | N |

School: Chapman Elementary School

Building: Unit D (FKA F)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------|--------------|---------|-----------------------|------------------------------|----------------------------|----------------|
| M | 9" VFT | 4 | 1-5% | UNDETERMINED | THROUGHOUT EXCEPT IN LIBRARY | (1) (4) | N/A |
| M | 9" VFT | 5 | 1-5% | UNDETERMINED | THROUGHOUT EXCEPT IN LIBRARY | (1) (4) | N/A |
| M | TRANSITE PANELS | 6 | ASSUMED | 400 S | EXTERIOR | (1) (4) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 01/27/2009

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Chapman Elementary School

Building: Unit E (FKA C)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------|--------------|---------------|-----------------------|------------------|--|----------------|
| M | TRANSITE PANELS | 7 | ASSUMED | 400 S | EXTERIOR | (1) (4) | N |
| M | 12" VFT CREAM | 8 | None Detected | 3,600 S | CLASSROOMS 15-18 | (13) CUSD sample 12/26/07 chp 01-04 MODERNIZATION 1989 | N |

School: Chapman Elementary School

Building: Unit F (FKA A)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|---------------|--------------|---------------|-----------------------|----------------------------|---|----------------|
| M | 9" VFT BROWN | 9 | 10-15% | UNDETERMINED | KITCHEN | (1) 17 TILES MISSING | N |
| M | 12" VFT CREAM | 10 | None Detected | 3,600 S | MPR, CORRIDOR, AND OFFICES | (13) CUSD sample on 12/26/07 chp 01-04 MODERNIZATION 1989 | N |
| M | 12" ACT | 11 | NON ASBESTOS | 3,600 S | MPR, CORRIDOR, AND OFFICES | (13) CUSD SAMPLE COLLECTED ON 7/8/08 | N |
| S | PLASTER | 12 | NONE DETECTED | UNDETERMINED | KITCHEN | (11) CUSD SAMPLE Chp01COLLECTED 2/22/06 | N/A |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 01/27/2009

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Chapman Elementary School

Building: Unit H (FKA B)

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|-----------------|--------------|---------------|-----------------------|------------------|--|----------------|
| M | TRANSITE PANELS | 13 | ASSUMED | 400 S | EXTERIOR | (1) (4) | N |
| M | 12" VFT cream | 14 | None Detected | 3,600 S | CLASSROOMS 19-22 | (13) CUSD sample on 12/26/07 chp 01- chp 04 MODERNIZATION 1989 | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS