



BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928	PHONE: 916-891-3194 FAX: 916-891-3190	DATE: 4-17-96
	Circle the Method and Turn Around Time hr/12hr/24hr/48hr/Ext →	Results Needed: Fri. 4-19-96 by NOON FAX
	PLM: Standard / Point Count	Gravimetry Prep
	TEM: QUAL. / QUANT. / WATER	
CONTACT: Ron Jones	P.O.# 96-4623	JOB #
SITE: Chico Jr. High - Gym - Roof	AA/Flame AA/Furnace ICP	
METALS:		

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
CJH-GYM-7	4-17-96	SE corner of Gym Roof
		Note: The roofing is stacked the way it came off, with white on top.
		plastic
		Please open carefully to keep intact
		analyse by layer

Sampled by: Ron Jones RJ	Date: 4-17-96 Time: 8:30 AM
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928	PHONE: 916-891-3194 FAX: 916-891-3190	DATE: 3-14-96
	Circle the Method and Turn Around Time 24 ☐ hr/12hr/24hr/48hr/Ext	Results Needed:
	☒ PLM Standard / Point Count	
	☐ Gravimetry Prep	
CONTACT: Ron Jones		TEM: QUAL. / QUANT. / WATER
P.O.# 96-4122	JOB #	AA/Flame AA/Furnace ICP
SITE: Chico Jr High Gym Roof		METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
CJH GYM-1	3-13-96	SE Corner of lower roof/ Roofing Material
CJH Gym-2	3-13-96	SW Corner of lower roof/ roofing Material
CJH Gym-3	3-13-96	NE corner of lower roof/ roofing material
CJH Gym-4	3-13-96	N Side of lower roof/ roofing material
CJH Gym-5	3-13-96	NW Corner of lower Roof/ roofing material
CJH Gym-6	3-13-96	West end of roof top section/ roofing material
		Please analyse each layer separately from the roof
		samples if possible. See Christina / <i>Prior Positive</i>

Sampled by: Ron Jones	Date: 3-13-96 Time: 2:15 pm
Relinquished by: Ron Jones	Received By: FED-EX Chico
Date/Time: 3-14-96 4:00 pm	Date/Time: Sealed Condition (circle one) YES / NO
Relinquished by:	Received By:
Date/Time:	Date/Time: Sealed Condition (circle one) YES / NO



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: 916-891-3194 FAX: 916-891-3190	DATE: 3-14-96
		Circle the Method and Turn Around Time 24 <u> </u> hr/12hr/24hr/48hr/Ext	Results Needed:
		AA Standard / Point Count	
		CONTACT: Ron Jones	
P.O.# 96-4122	JOB #	AA/Flame AA/Furnace ICP	
SITE: Chico Jr High Gym Roof		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
CJH GYM-1	3-13-96	SE Corner of lower roof/ Roofing Material
CJH Gym-2	3-13-96	SW Corner of lower roof/ roofing Material
CJH Gym-3	3-13-96	NE corner of lower roof/ roofing material
CJH Gym-4	3-13-96	N Side of lower roof/ roofing material
CJH Gym-5	3-13-96	NW Corner of lower Roof/ roofing material
CJH Gym-6	3-13-96	West end of roof top section/ roofing material
		Please analyse each layer separately from the roof
		samples if possible. See Christina / Prior Positive

Sampled by: Ron Jones		Date: 3-13-96	Time: 2:15 pm
Relinquished by: Ron Jones		Received By: FED-EX Chico	
Date/Time: 3-14-96 4:00 pm		Date/Time: <i>h 3/15/96</i>	
		Sealed Condition (circle one) YES / NO	
Relinquished by:		Received By:	
Date/Time:		Date/Time:	
		Sealed Condition (circle one) YES / NO	

FORENSIC ANALYTICAL

Page 1 of 2FAX TRANSMISSION
Summary of Results
Polarized Light MicroscopyTo: Chico Unified School DistrictDate/Time: 3/18/96Project :
Report #: 251588Attn: RonSender: K. Wentz

If you do not receive all pages, please contact Sender at (510) 887-8828

C: Chrysotile
A: AmositeCr: Crocidolite
ND: No Asbestos detected
P : Preliminary; subject to review

Sample Number	Asbestos %	Asb. Type(s)	Notes
CJH-GYM-1	Trace	C	
CJH-GYM-2	Trace	C	
CJH-GYM-3	Trace	C	
CJH-GYM-4	Trace	C	
CJH-GYM-5	Trace	C	
CJH-GYM-6	Trace	C	

FAXED TO: _____

A hard copy report will follow in the mail. Thank you.

Supervisor Approval: KL

FORENSIC ANALYTICAL SPECIALTIES INC. - ASBESTOS ANALYSIS LABORATORY REQUEST FORM

BULK SAMPLES

3777 Depot Rd: Suite 408

Hayward, Ca. 94545 (415) 887-8828

Page 1 of 6

HAZARD MANAGEMENT SERVICES, INC

Client Number _____
Report Number _____
Received By _____
Date Rec'd _____

Bill To:
P.O. Box 7012, Modesto, Ca 95355
Billing Address:

District or Business
School Chico Junior High
OR
Bldg _____

3-28-88

Reported Results _____
Date/Time/By _____

Collected by: _____
Date _____
LAB Request: % Asbestos By PLM

Sent to Lab by: _____

date

FAI Lab#	Sample #HMS-	I - 1 page No	MATERIALS/LOCATION	% Asbestos
	CJH-01		M: VET- 9" - White & Backing L: Kitchen Office	1-5%
	CJH-02		M: VET- 9" - Red & Backing L: Kitchen Office	1-5%
	CJH-03		M: VET- 9" - Green & Backing L: Kitchen	Trace
	CJH-04A		M: Hard Plaster L: Kitchen Office	<1%
	CJH-04B		M: Hard Plaster L: Kitchen Snack Bar	<1%
	CJH-04C		M: Hard Plaster L: Kitchen Wall	<1%
	CJH-04D		M: Hard Plaster L: MPR Wall	<1%
	CJH-05		M: VET- 9" - Dark Green & Backing L: Snack Bar	1-5%
	CJH-06		M: TSI - Mudded Joint L: Water heater room	1-5%
	CJH-07		M: TSI - Pl. l. Straight L: Water heater room	<1%

BULK SAMPLES

3777 Depot Rd: Suite 408

Hayward, Ca. 94543 (415) 887-8828

Page 2 of 6

Client Number		Report Number		District or Business	
Received By		Date Rec'd		School <u>Chico Junior High</u>	
Reported Results		Date/Time/By		OR	
Sample #HMS-		I - 1 page No		Bldg	
FAS Lab#		MATERIALS/LOCATION		3-28-88 date	
CJH-08A		M: Plaster Ceiling L: Teachers Lunch room		Trace	
CJH-08B		M: Plaster Ceiling L: Cafeteria		1-5	
CJH-08C		M: Plaster Ceiling L: Hallway		1-5	
CJH-09		M: Ceiling Material L: Refrigerator room		1-5	
CJH-10A		M: TSI - PV Straight L: MPR Fan room - (south side fan room)		25-30	
CJH-10B		M: TSI - Matted PW corner L: MPR - Fan room - (south side fan room)		45-50	
CJH-12		M: VET-9" - red & white - (replacement tile) L: Hallway -		1-5	
CJH-13		M: VET-12" - red - L: Hallway -		TRACE	
CJH-14		M: VET-9" - beige L: Teachers lounge		1-5	
CJH-15		M: VET-9" - red & black - (original) L: Hallway		1-5	

HAZARD MANAGEMENT SERVICES, INC.

Client Number Report Number

Bill To:

P.O. Box 7012, Modesto, Ca 95355

District or Business

Received By Date Rec'd

Billing Address:

School Chico Junior High

OR

Bldg

Reported Results Date/Time/By

Collected by:

Date

Sent to Lab by:

3-28-88

LAB Request: % Asbestos By PLM

FAI Lab#	Sample #HMS-	I - 1 page No	MATERIALS/LOCATION	% Asbestos
	CJH-08D		M: Plaster Ceiling L: Book Room	1-5
	CJH-04E		M: Wall Plaster L: Book room	<1%
	CJH-11A		M: PW straight L: Hot water tank closet - off book room	50-55
	CJH-11B		M: PW Corner L: Hot water tank closet - off book room	50-55
	CJH-08E		M: Plaster Ceiling L: Hallway - out side of Counseling office	1-5
	CJH-04F		M: Plaster Wall L: Counselors Office	<1%
	CJH-04G		M: Plaster Wall L: Hallway - outside of Principals Office	<1%
	CJH-08F		M: Plaster Ceiling L: Hallway - outside of Book room	1-5
	CJH-16		M: Tank wrap L: Hot water closet - off of book room	40-50
	CJH-17		M: Acoustic ceiling tile L: room # 211	<1

HAZARD MANAGEMENT SERVICES, INC.

Client Number Report Number

Bill To:

Received By Date Rec'd

P.O. Box 7012, Modesto, Ca 95355

Billing Address:

District or Business

School Chico Junior High

OR

Bldg

3-28-88

Reported Results Date/Time/By

Collected by:

Date

Sent to Lab by:

date

LAB Request: % Asbestos By PLM

FAS Lab#	Sample #HMS-	I page No	MATERIALS/LOCATION	% Asbestos
	CJH-18		M: VFT-9"-Green & white & backing L: room # 211	1-5
	CJH-19		M: VFT-9"-Dark Brown & backing L: room # 201	5-10
	CJH-20		M: VFT-9"-Light brown & backing L: room # 201	5-10
	CJH-21		M: acoustic ceiling tile L: room # 201	<1
	CJH-22		M: VFT-9"-rust & backing L: room # 202	5-10
	CJH-23		M: VFT-9"-Tan - & Backing L: room # 409	5-10
	CJH-24		M: VFT-9"-Light Gray & Backing L: room # 308	1-5
	CJH-25		M: Linoleum - beige L: room # 500	<1
	CJH-26A		M: TSI - Muddled joint L: room # 502 - storage room	40-50
	CJH-26B		M: TSI - Muddled joint L: room # 502 - storage room	80-85

BULK SAMPLES

3777 Depot Rd: Suite 408 Hayward, Ca. 94545 (415) 887-8828 Page 5 of 6

Client Number		Report Number		District or Business	
Received By		Date Rec'd		School <u>Chico Junior High</u>	
Reported Results		Date/Time/By		OR	
Collected by:		Date		Bldg	
LAB Request: % Asbestos By PLM		Sent to Lab by:		3-28-88	
HAZARD MANAGEMENT SERVICES, INC.		Bill To:		date	
P.O. Box 7012, Modesto, Ca 95355		Billing Address:			

FAI Lab#	Sample #HMS-	I - 1 page No	MATERIALS/LOCATION	% Asbestos
	CJH-27		M: VET-9" - Chocolate & backing L: Room # 504	5-10
	CJH-28		M: Ceiling Panel L: Portable - Blind room # 600	< 1
	CJH-29A		M: TSI - PW straight (10") diameter L: Boiler room	60-70
	CJH-29B		M: Muddled Joint (10") diameter L: Boiler room	60-70
	CJH-30		M: Tank wrap L: Boiler room	60-70
	CJH-29C		M: PW straight L: Boiler room	55-60
	CJH-31		M: PW straight (3") diameter L: Boiler room	35-40
	CJH-04H		M: Plaster wall L: Music room office	< 1%
	CJH-32		M: Sheet rock with plaster wall L: Wall at end of hallway between gym & ballroom	< 1
	CJH-33A		M: TSI - PW straight L: Locker room Boiler room	60-70

BULK SAMPLES

3777 Depot Rd: Suite 408

Hayward, Ca. 94545 (415) 887-8828

Page 6 of 6

HAZARD MANAGEMENT SERVICES, INC

Client Number Report Number

Bill To:

P.O. Box 7012, Modesto, Ca 95355

Received By Date Rec'd

Billing Address:

District or Business

School Chico Junior High

OR

Bldg

3-28-88

Reported Results Date/Time/By

Collected by:

Date

Sent to Lab by:

date

LAB Request: % Asbestos By PLM

FAI Lab#	Sample #HMS-	I - I page No	MATERIALS/LOCATION	% Asbestos
	CJH-34		M: TSI - PW Straight L: Locker room boiler room	45-50
	CJH-35A		M: TSI - PW Straight L: Locker room boiler room	60-70
	CJH-35C		M: TSI - Locker room PW Straight L: Locker room boiler room	50-60
	CJH-35A		M: TSI - Muddled joint L: Locker room boiler room	60-70
	CJH-35B		M: TSI - Muddled joints L: Locker room boiler room	60-70
	CJH-35C		M: TSI - Muddled joints L: Locker room boiler room	60-70
	CJH-36		M: TSI - Tank wrap L: Unit P - Boiler room	20-30
			M: L:	
			M: L:	
			M: L:	

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT W	1-5	Kitchen office	(1) (4)
A	9" VFT R	1-5	Kitchen office	(1) (4)
A	9" VFT	1-5	Main Hallway	(7)
A	9" VFT	1-5	MPR (Green)	(1) (4)
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) (4)
A	9" VFT	1-5	Fan rooms (Green)	(1) (4)
A	Mud Jnts	1-5	Water Tank room	(1) (4)
A	Ceill Plas	1-5	Teacher's Lounge	(1) (5) Roof & Ceiling Repaired
A	Ceill Plas	1-5	MPR	(1) (5) Roof & Ceiling Repaired
A	Ceill Plas	1-5	Rest of Wing	(1) (5) Roof & Ceiling Repaired
A	Ceill Mat.	1-5	Refrigerator room	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 7

DISTRICT Chico Unified School District DATE July 5, 1996SCHOOL Chico Junior High INSPECTOR Rob Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	25-50	South & North Fan Rooms	(1) (4)
A	Mud Jnt	50-55	South & North Fan Rooms	(1) (4)
A	9" VFT	1-5	Teacher's Lounge	(1) (4)
A	Tank Wrap	40-45	Hot water closet	(11)
A	PW Str	Assumed	Stage area	(7)
A	Light cords	Assumed	Stage lighting	(7)
B	Ceill plas	1-5	Hallway & Upper wall	(1) (5) Roof & Ceiling Repaired
B	9" VFT R	1-5	Hallway	(7)
B	12" VFT R	1-5	Hallway	(7)
C	9" VFT R	1-5	Chapter One Office	(7)
C	Ceill Plas	1-5	Room 11	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996SCHOOL Chico Junior High INSPECTOR Rob Peters 2.7

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
C	9" VFT Br	5-10	Rms 200,202,204,206,208	(7)	
C	9" VFT Br	5-10	Rm 202	(7)	
D	9" VFT R	1-5	Rm 10 - Janitor storage	(1) (4)	
D	Ceill Plas	1-5	Rm 11	(1) (4)	
D	9" VFT Gr	1-5	Rms 300,302,304,306,308	(7)	
E	9" VFT Rd	1-5	Janitor's Storage	(1) (4)	
E	Ceill Plas	1-5	Rm 8	(1) (4)	
E	9" VFT	5-10	Rms 400,402,404,406,408	(7)	
F	9" VFT Rd	1-5	Room 1	(1) (4)	
F	Ceill Plas	1-5	Room 2	(1) (4)	
F	9" VFT Br	5-10	Rms 500,502,504,506	(7)	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters V.P.

BLDG.	HOMOG.	ASBESTOS MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45		Room 502	(11)
F	9" VFT BR	5-10		Room 504	(7)
F	PW Str	Assumed		Room 506	(11)
G	PW Str	55-70		Boiler Room	(7)
G	8" Str	60-70		Boiler Room	(7)
G	Tank Wrap	60-70		Boiler Room	(7)
G	4" Str	35-40		Boiler Room	(7)
G	4" Str	35-40		Shop Storage	(7)
H	Ceil Plas	1-5		Wood shop offices	(7)
H	9" VFT	1-5		Wood shop office & classrms	(7)
J	9" VFT Rd	1-5		Admin. offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 5 of 7

DISTRICT Chico Unified School District DATE July 5, 1996SCHOOL Chico Junior High INSPECTOR Rob Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
J	9" VFT Rd	1-5	Hallway and Library	(7)	
J	Ceill Plas	1-5	All rooms in wing	(1) (4)	
J	PW Str	25-50	Work room closet	(1) (4)	
J	PW Cnr	50-55	Work room closet	(1) (4)	
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) (4)	
L	9" VFT Br	5-10	301,303,305,307,309	(1) (4)	
M	9" VFT Tn	5-10	401,403,405,407,409	(1) (4)	
N	Ceill Plas	1-5	Office area	(1) (4)	
N	Ceill Plas	1-5	Storage	(1) (4)	
N	9" VFT Bg	1-5	Choral Room	(7)	
N	9" VFT Bg	1-5	Offices	(7)	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 6 of 7

DISTRICT Chico Unified School DistrictDATE July 5, 1996SCHOOL Chico Junior HighINSPECTOR Rob PetersR.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
N	9" VFT Br	5-10	Rm 503, Practice rooms	(7)
N	PW Str	25-50	Under raised floor	(7)
O	9" VFT Gn	1-5	RRs	(1) (4)
O	PW Str	60-70	Inside metal cabinets	(7)
O	PW Crn	60-70	Inside metal cabinets	(7)
P	9" VFT Gn	1-5	Room 18 storage	(11)
P	PW Str	50-70	Boiler Room	(7)
P	PW Str 5"	45-50	Boiler Room	(7)
P	PW Str 5"	45-50	Men & Women's locker rooms	(7)
P	Tank Wrap	20-30	Boiler Room	(7)
P	PW Str Cn	Assumed	Crawlspce between locker rooms	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 1 of 7

DISTRICT Chico Unified School District DATE January 8, 1996

SCHOOL Chico Junior High INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS
MAT.# MATERIAL

LOCATION

CONDITION: CODE & COMMENTS

A	9" VFT W	1-5	Kitchen office	(1) (4)
A	9" VFT R	1-5	Kitchen office	(1) (4)
A	9" VFT	1-5	Main Hallway	(7)
A	9" VFT	1-5	MPR (Green)	(1) (4)
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) (4)
A	9" VFT	1-5	Fan rooms (Green)	(1) (4)
A	Mud Jnts	1-5	Water Tank room	(1) (4)
A	Ceill Plas	1-5	Teacher's Lounge	1-4 Roof & Ceiling Repaired
A	Ceill Plas	1-5	MPR	1-4 Roof & Ceiling Repaired
A	Ceill Plas	1-5	Rest of Wing	1-4 Roof & Ceiling Repaired
A	Ceill Mat.	1-5	Refrigerator room	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 7

DISTRICT Chico Unified School District

DATE January 8, 1996

SCHOOL Chico Junior High

INSPECTOR Ron Jones

BLDG. HOMOG. ASBESTOS
MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

A	PW Str	25-50	South & North Fan Rooms	(1) (4)
A	Mud Jnt	50-55	South & North Fan Rooms	(1) (4)
A	9" VFT	1-5	Teacher's Lounge	(1) (4)
A	Tank Wrap	40-45	Hot water closet	(11)
A	PW Str	Assumed	Stage area	(7)
A	Light cords	Assumed	Stage lighting	(7)
B	Ceill plas	1-5	Hallway & Upper wall	1-4 Roof & Ceiling Repaired
B	9" VFT R	1-5	Hallway	(7)
B	12" VFT R	1-5	Hallway	(7)
C	9" VFT R	1-5	Chapter One Office	(7)
C	Ceill Plas	1-5	Room 11	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 3 of 7

DISTRICT Chico Unified School District DATE January 8, 1996SCHOOL Chico Junior High INSPECTOR Ron Jones 

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
C	9" VFT Br	5-10	Rms 200, 202, 204, 206, 208	(7)
C	9" VFT Br	5-10	Rm 202	(7)
D	9" VFT R	1-5	Rm 10 - Janitor storage	(1) (4)
D	Ceill Plas	1-5	Rm 11	(1) (4)
D	9" VFT Gr	1-5	Rms 300, 302, 304, 306, 308	(7)
E	9" VFT Rd	1-5	Janitor's Storage	(1) (4)
E	Ceill Plas	1-5	Rm 8	(1) (4)
E	9" VFT	5-10	Rms 400, 402, 404, 406, 408	(7)
F	9" VFT Rd	1-5	Room 1	(1) (4)
F	Ceill Plas	1-5	Room 2	(1) (4)
F	9" VFT Br	5-10	Rms 500, 502, 504, 506	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 4 of 7

DISTRICT Chico Unified School District DATE January 8, 1996SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45	Room 502	(11)
F	9" VFT BR	5-10	Room 504	(7)
F	PW Str	Assumed	Room 506	(11)
G	PW Str	55-70	Boiler Room	(7)
G	8" Str	60-70	Boiler Room	(7)
G	Tank Wrap	60-70	Boiler Room	(7)
G	4" Str	35-40	Boiler Room	(7)
G	4" Str	35-40	Shop Storage	(7)
H	Ceill Plas	1-5	Wood shop offices	(7)
H	9" VFT	1-5	Wood shop office & classrms	(7)
J	9" VFT Rd	1-5	Admin. offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 5 of 7

DISTRICT Chico Unified School District DATE January 8, 1996SCHOOL Chico Junior High INSPECTOR Ron Jones

HOMOG. ASBESTOS

BLDG. MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

J	9" VFT Rd	1-5	Hallway and Library	(7)
J	Ceill Plas	1-5	All rooms in wing	(1) (4)
J	PW Str	25-50	Work room closet	(1) (4)
J	PW Cnr	50-55	Work room closet	(1) (4)
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) (4)
L	9" VFT Br	5-10	301,303,305,307,309	(1) (4)
M	9" VFT Tn	5-10	401,403,405,407,409	(1) (4)
N	Ceill Plas	1-5	Office area	(1) (4)
N	Ceill Plas	1-5	Storage	(1) (4)
N	9" VFT Bg	1-5	Choral Room	(7)
N	9" VFT Bg	1-5	Offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 6 of 7

DISTRICT Chico Unified School DistrictDATE January 8, 1996SCHOOL Chico Junior HighINSPECTOR Ron Jones

HOMOG. ASBESTOS

MAT.# MATERIAL

LOCATION

CONDITION: CODE & COMMENTS

N	9" VFT Br	5-10	Rm 503, Practice rooms	(7)
N	PW Str	25-50	Under raised floor	(7)
O	9" VFT Gn	1-5	RRs	(1) (4)
O	PW Str	60-70	Inside metal cabinets	(7)
O	PW Crn	60-70	Inside metal cabinets	(7)
P	9" VFT Gn	1-5	Room 18 storage	(11)
P	PW Str	50-70	Boiler Room	(7)
P	PW Str 5"	45-50	Boiler Room	(7)
P	PW Str 5"	45-50	Men & Women's locker rooms	(7)
P	Tank Wrap	20-30	Boiler Room	(7)
P	PW Str Cn	Assumed	Crawlspace between locker rooms	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 1 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
A	9" VFT W	1-5	Kitchen office	(1) (4)	
A	9" VFT R	1-5	Kitchen office	(1) (4)	
A	9" VFT	1-5	Main Hallway	(7)	
A	9" VFT	1-5	MPR (Green)	(1) (4)	
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) (4)	
A	9" VFT	1-5	Fan rooms (Green)	(1) (4)	
A	Mud Jnts	1-5	Water Tank room	(1) (4)	
A	Ceil Plas	1-5	Teacher's Lounge	(1) (5) Roof & Ceiling Repaired	
A	Ceil Plas	1-5	MPR	(1) (5) Roof & Ceiling Repaired	
A	Ceil Plas	1-5	Rest of Wing	(1) (5) Roof & Ceiling Repaired	
A	Ceil Mat.	1-5	Refrigerator room	(1) (4)	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	25-50	South & North Fan Rooms	(1) (4)
A	Mud Jnt	50-55	South & North Fan Rooms	(1) (4)
A	9" VFT	1-5	Teacher's Lounge	(1) (4)
A	Tank Wrap	40-45	Hot water closet	(11)
A	PW Str	Assumed	Stage area	(7)
A	Light cords	Assumed	Stage lighting	(7)
B	Ceill plas	1-5	Hallway & Upper wall	(1) (5) Roof & Ceiling Repaired
B	9" VFT R	1-5	Hallway	(7)
B	12" VFT R	1-5	Hallway	(7)
C	9" VFT R	1-5	Chapter One Office	(7)
C	Ceill Plas	1-5	Room 11	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 3 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
C	9" VFT Br	5-10	Rms 200,202,204,206,208	(7)
C	9" VFT Br	5-10	Rm 202	(7)
D	9" VFT R	1-5	Rm 10 - Janitor storage	(1) (4)
D	Ceill Plas	1-5	Rm 11	(1) (4)
D	9" VFT Gr	1-5	Rms 300,302,304,306,308	(7)
E	9" VFT Rd	1-5	Janitor's Storage	(1) (4)
E	Ceill Plas	1-5	Rm 8	(1) (4)
E	9" VFT	5-10	Rms 400,402,404,406,408	(7)
F	9" VFT Rd	1-5	Room 1	(1) (4)
F	Ceill Plas	1-5	Room 2	(1) (4)
F	9" VFT Br	5-10	Rms 500,502,504,506	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 4 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45		Room 502	(11)
F	9" VFT BR	5-10		Room 504	(7)
F	PW Str	Assumed		Room 506	(11)
G	PW Str	55-70		Boiler Room	(7)
G	8" Str	60-70		Boiler Room	(7)
G	Tank Wrap	60-70		Boiler Room	(7)
G	4" Str	35-40		Boiler Room	(7)
G	4" Str	35-40		Shop Storage	(7)
H	Ceil Plas	1-5		Wood shop offices	(7)
H	9" VFT	1-5		Wood shop office & classrms	(7)
J	9" VFT Rd	1-5		Admin. offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 5 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
J	9" VFT Rd	1-5	Hallway and Library	(7)
J	Ceill Plas	1-5	All rooms in wing	(1) (4)
J	PW Str	25-50	Work room closet	(1) (4)
J	PW Cnr	50-55	Work room closet	(1) (4)
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) (4)
L	9" VFT Br	5-10	301,303,305,307,309	(1) (4)
M	9" VFT Tn	5-10	401,403,405,407,409	(1) (4)
N	Ceill Plas	1-5	Office area	(1) (4)
N	Ceill Plas	1-5	Storage	(1) (4)
N	9" VFT Bg	1-5	Choral Room	(7)
N	9" VFT Bg	1-5	Offices	(7)

CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 6 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
N	9" VFT Br	5-10	Rm 503, Practice rooms	(7)
N	PW Str	25-50	Under raised floor	(7)
O	9" VFT Gn	1-5	RRs	(1) (4)
O	PW Str	60-70	Inside metal cabinets	(7)
O	PW Crn	60-70	Inside metal cabinets	(7)
P	9" VFT Gn	1-5	Room 18 storage	(11)
P	PW Str	50-70	Boiler Room	(7)
P	PW Str 5"	45-50	Boiler Room	(7)
P	PW Str 5"	45-50	Men & Women's locker rooms	(7)
P	Tank Wrap	20-30	Boiler Room	(7)
P	PW Str Cn	Assumed	Crawlspace between locker rooms	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 7 of 7

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Junior High INSPECTOR Rob Peters

BLDG. HOMOG. ASBESTOS
MAT.# MATERIAL

LOCATION

CONDITION: CODE & COMMENTS

Main Hall Tunl	PW Str	Assumed	Pipe tunnel from front to back	(7)
P	Pipewrap	Assumed	In Ceiling Pipe Chase	10
K, L, M	Pipewrap	Assumed	Enclosed under Cabinets	10

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)