



Forensic Analytical

OCT 18 1999

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

San Francisco • Los Angeles • Minneapolis / St. Paul

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

FAEI Job ID: 2921-19

Job ID / Site: Chico Jr. High

| Sample Number | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|

## UNIT A-1

19960533

ND

Layer: Black Tar

ND

Layer: Black Felt

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (65%)  
Comment: Collected on 10/7/99

## UNIT A-2

19960534

ND

Layer: Black Felt

ND

Layer: Black Tar

ND

Layer: Black Felt

ND

Layer: Black Tar

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (65%)  
Comment: Collected on 10/7/99

## UNIT A-3

19960535

ND

Layer: Black Tar

ND

Layer: Black Felt

ND

Layer: Black Tar

ND

Layer: Black Felt

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (65%)  
Comment: Collected on 10/7/99

## UNIT J-1

19960536

ND

Layer: Black Semi-Fibrous Tar

ND

Layer: Black Felt

ND

Layer: Black Felt

ND

Layer: Black Tar

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (45%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

FAJI Job ID: 2921-19

Job ID / Site: Chico Jr. High

| Sample Number     | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|-------------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
| UNIT J-2          | 19960537   |               |                  |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (55%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| J-3               | 19960538 |  |    |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (55%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| UNIT J-4          | 19960539 |  |    |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (55%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

FASI Job ID: 2921-19

Job ID / Site: Chico Jr. High

| Sample Number | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|

## UNIT J-5

19960540

Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt

ND  
ND  
ND  
ND  
ND  
ND

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (55%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99

## J-6

19960541

Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt

ND  
ND  
ND  
ND  
ND  
ND  
ND  
ND

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (55%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99

## UNIT K-1

19960542

Layer: Black Tar  
Layer: Black Felt  
Layer: Black Tar  
Layer: Black Felt

ND  
ND  
ND  
ND

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (55%)  
Comment: Collected on 10/7/99



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

FASI Job ID: 2921-19

Job ID / Site: Chico Jr. High

| Sample Number     | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|-------------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
| UNIT K-2          | 19960543   |               |                  |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| UNIT K-3          | 19960544 |  |    |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| UNIT L-1          | 19960545 |  |    |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| UNIT L-2          | 19960546 |  |    |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (40%) Fibrous Glass (ND)  
Comment: Collected on 10/7/99



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

## Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

Job ID / Site: Chico Jr. High

FAJI Job ID: 2921-19

| Sample Number                                 | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type      | Percent in Layer    | Asbestos Type | Percent in Layer |
|-----------------------------------------------|------------|---------------|------------------|--------------------|---------------------|---------------|------------------|
| UNIT L-3                                      |            |               |                  |                    |                     |               |                  |
|                                               | 19960547   |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Total Composite Values of Fibrous Components: |            | Asbestos:(ND) |                  | Cellulose (Trace%) | Fibrous Glass (45%) |               |                  |
| Comment: Collected on 10/7/99                 |            |               |                  |                    |                     |               |                  |
| UNIT B-1                                      |            |               |                  |                    |                     |               |                  |
|                                               | 19960548   |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Total Composite Values of Fibrous Components: |            | Asbestos:(ND) |                  | Cellulose (Trace%) | Fibrous Glass (45%) |               |                  |
| Comment: Collected on 10/7/99                 |            |               |                  |                    |                     |               |                  |
| UNIT B-2                                      |            |               |                  |                    |                     |               |                  |
|                                               | 19960549   |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Layer: Black Tar                              |            |               | ND               |                    |                     |               |                  |
| Layer: Black Felt                             |            |               | ND               |                    |                     |               |                  |
| Total Composite Values of Fibrous Components: |            | Asbestos:(ND) |                  | Cellulose (Trace%) | Fibrous Glass (45%) |               |                  |
| Comment: Collected on 10/7/99                 |            |               |                  |                    |                     |               |                  |



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

## Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

Job ID / Site: Chico Jr. High

FASI Job ID: 2921-19

| Sample Number | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
|---------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|

UNIT B-3 19960550

|                   |    |
|-------------------|----|
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
Comment: Collected on 10/7/99

UNIT B-4 19960551

|                   |    |
|-------------------|----|
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (10%) Fibrous Glass (40%)  
Comment: Collected on 10/7/99

UNIT M-1 19960552

|                   |    |
|-------------------|----|
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |
| Layer: Black Tar  | ND |
| Layer: Black Felt | ND |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
Comment: Collected on 10/7/99



Forensic Analytical

San Francisco • Los Angeles • Minneapolis / St. Paul

## Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Ron Jones2455 Carmichael Drive  
Chico, CA 95928Client ID: 2921  
Report Number: B014302  
Date Received: 10/08/99  
Date Analyzed: 10/11/99  
Date Reported: 10/11/99

Job ID / Site: Chico Jr. High

FASI Job ID: 2921-19

| Sample Number     | Lab Number | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer | Asbestos Type | Percent in Layer |
|-------------------|------------|---------------|------------------|---------------|------------------|---------------|------------------|
| UNIT M-2          | 19960553   |               |                  |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |
| Layer: Black Tar  |            |               | ND               |               |                  |               |                  |
| Layer: Black Felt |            |               | ND               |               |                  |               |                  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
 Comment: Collected on 10/7/99

|                   |          |  |    |  |  |  |  |
|-------------------|----------|--|----|--|--|--|--|
| UNIT M-3          | 19960554 |  |    |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |
| Layer: Black Tar  |          |  | ND |  |  |  |  |
| Layer: Black Felt |          |  | ND |  |  |  |  |

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)  
 Comment: Collected on 10/7/99

Mark Floyd, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Forensic Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on this report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from the client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

FO# 00-208/

# 2921-18

CHICO JR. HIGH.

10/7/79

UNIT A.

- (1.) STAFF ROOM ROOF.
- (2.) STAFF ROOM ROOF
- (3.) STAFF ROOM ROOF.

UNIT J.

- (1.) PRINC. OFFICE LOWER ROOF.
- (2.) U.P. OFFICE LOWER ROOF.
- (3.) COUN. OFFICE LOWER ROOF.
- (4.) HALLWAY UPPER ROOF.
- (5.) OFFICE ENTRANCE UPPER ROOF.
- (6.) ATTENDANCE OFFICE UPPER ROOF.

UNIT K.

- (1.) EAST END HALLWAY LOWER ROOF.
- (2.) MIDDLE OF HALLWAY LOWER ROOF.
- (3.) WEST END OF HALLWAY LOWER ROOF.

UNIT L.

- (1.) EAST END HALLWAY LOWER ROOF.
- (2.) MIDDLE OF HALLWAY LOWER ROOF.
- (3.) WEST END OF HALLWAY LOWER ROOF.



CHICO JR. HIGH.

10/7/99

UNIT 13

- (1) NORTH END SOUTH OF 500 WING.
- (2) BETWEEN 400-300 WING
- (3) BETWEEN 300-200 WING.
- (4) SOUTH END OVER MAIN DOORS

UNIT 17

- (1) EAST END HALLWAY LOWER ROOF
- (2) MIDDLE OF HALLWAY LOWER ROOF
- (3) WEST END OF HALLWAY LOWER ROOF.

SITE: CHICO JR HIGH

INSPECTOR: ROB PETERS

DATE: 10/7/99.

TIME: 8:03 AM.

P.O. # 00-2081

*Rob Peters*  
10/8/99

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Chico Junior High INSPECTOR Robert Peters

| BLDG. | HOMOG.     |     | ASBESTOS<br>MATERIAL | LOCATION                 | CONDITION: CODE & COMMENTS                                                              |
|-------|------------|-----|----------------------|--------------------------|-----------------------------------------------------------------------------------------|
|       | MAT.#      |     |                      |                          |                                                                                         |
| A     | 9" VFT W   | 1-5 |                      | Kitchen office           | (1) (4)                                                                                 |
| A     | 9" VFT R   | 1-5 |                      | Kitchen office           | (1) (4)                                                                                 |
| A     | 9" VFT     | 1-5 |                      | Main Hallway             | (7)                                                                                     |
| A     | 9" VFT     | 1-5 |                      | MPR (Green)              | (1) (4)                                                                                 |
| A     | 9" VFT     | 1-5 |                      | Teacher's Lounge (Green) | (1) (4)                                                                                 |
| A     | 9" VFT     | 1-5 |                      | Fan rooms (Green)        | (1) (4)                                                                                 |
| A     | Mud Jnts   | 1-5 |                      | Water Tank room          | (1) (4)                                                                                 |
| A     | Ceill Plas | 1-5 |                      | Teacher's Lounge         | (5) Water stained less than<br>25% & Ceiling Repaired. Roof<br>Repaired 8/98 1-4 (8/99) |
| A     | Ceill Plas | 1-5 |                      | MPR                      | (1) (5) Roof & Ceiling Repaired.<br>Roof Repaired 8/98 1-4 (8/99)                       |
| A     | Ceill Plas | 1-5 |                      | Rest of Wing             | (1) (5) Roof & Ceiling Repaired<br>1-4 (8/99)                                           |
| A     | Ceill Mat. | 1-5 |                      | Refrigerator room        | (1) (4)                                                                                 |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Chico Junior High INSPECTOR Robert Peters

| BLDG.        | HOMOG.<br>MAT.#     | ASBESTOS<br>MATERIAL | LOCATION                      | CONDITION: CODE & COMMENTS |
|--------------|---------------------|----------------------|-------------------------------|----------------------------|
| A            | PW Str              | 25-50                | South & North Fan Rooms       | (7) Removed 9/98           |
| A            | Mud Jnt             | 50-55                | South & North Fan Rooms       | (7) Removed 9/98           |
| A            | 9" VFT              | 1-5                  | Teacher's Lounge              | (1) (4)                    |
| A            | Tank Wrap           | 40-45                | Hot water closet              | (11)                       |
| A            | PW Str              | Assumed              | Stage area                    | (7)                        |
| A            | Light<br>cords      | Assumed              | Stage lighting                | (7)                        |
| B            | Ceill plas          | 1-5                  | Hallway & Upper wall          | (1) (4)                    |
| B            | 9" VFT R            | 1-5                  | Hallway                       | (7)                        |
| B            | 12" VFT R           | 1-5                  | Hallway                       | (7)                        |
| <del>C</del> | <del>9" VFT R</del> | <del>1-5</del>       | <del>Chapter One Office</del> | <del>(7)</del>             |
| C            | Ceill Plas          | 1-5                  | Room 11                       | (1) (4)                    |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School DistrictDATE August 11, 1999SCHOOL Chico Junior HighINSPECTOR Robert Peters

| BLDG. | HOMOG.<br>MAT.# | ASBESTOS<br>MATERIAL | LOCATION                           | CONDITION: CODE & COMMENTS |  |
|-------|-----------------|----------------------|------------------------------------|----------------------------|--|
|       |                 |                      |                                    |                            |  |
| C     | 9" VFT Br       | 5-10                 | Rms 200,202,204,206,208            | (7)                        |  |
| C     | 9" VFT Br       | 5-10                 | Rm 202                             | (7)                        |  |
| D     | 9" VFT R        | 1-5                  | Rm 10 - Janitor storage            | (1) (4)                    |  |
| D     | Ceill Plas      | 1-5                  | Rm 11                              | (1) (4)                    |  |
| D     | 9" VFT Gr       | 1-5                  | Rms 300,302,304,306,308            | (7)                        |  |
| E     | 9" VFT Rd       | 1-5                  | Janitor's Storage                  | (1) (4)                    |  |
| E     | Ceill Plas      | 1-5                  | Rm 8                               | (1) (4)                    |  |
| -E    | 9" VFT          | 5-10                 | <del>Rms 400,402,404,406,408</del> | <del>(7)</del>             |  |
| F     | 9" VFT Rd       | 1-5                  | Room 1                             | (1) (4)                    |  |
| F     | Ceill Plas      | 1-5                  | Room 2                             | (1) (4)                    |  |
| F     | 9" VFT Br       | 5-10                 | Rms 500,502,504,506                | (7)                        |  |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Chico Junior High INSPECTOR Robert Peters

| BLDG. | HOMOG.<br>MAT.# | ASBESTOS<br>MATERIAL | LOCATION                    | CONDITION: CODE & COMMENTS |
|-------|-----------------|----------------------|-----------------------------|----------------------------|
| F     | PW Str          | 40-45                | Room 502                    | (11)                       |
| F     | 9" VFT BR       | 5-10                 | Room 504                    | (7)                        |
| F     | PW Str          | Assumed              | Room 506                    | (11)                       |
| G     | PW Str          | 55-70                | Boiler Room                 | (7)                        |
| G     | 8" Str          | 60-70                | Boiler Room                 | (7)                        |
| G     | Tank Wrap       | 60-70                | Boiler Room                 | (7)                        |
| G     | 4" Str          | 35-40                | Boiler Room                 | (7)                        |
| G     | 4" Str          | 35-40                | Shop Storage                | (7)                        |
| H     | Ceill Plas      | 1-5                  | Wood shop offices           | (7)                        |
| H     | 9" VFT          | 1-5                  | Wood shop office & classrms | (7)                        |
| J     | 9" VFT Rd       | 1-5                  | Admin. offices              | (7)                        |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Chico Junior High INSPECTOR Robert Peters

| BLDG.        | HOMOG.<br>MAT.#      | ASBESTOS<br>MATERIAL | LOCATION                       | CONDITION: CODE & COMMENTS |  |
|--------------|----------------------|----------------------|--------------------------------|----------------------------|--|
|              |                      |                      |                                |                            |  |
| J            | 9" VFT Rd            | 1-5                  | Hallway and Library            | (7)                        |  |
| J            | Ceill Plas           | 1-5                  | All rooms in wing              | (1) (4)                    |  |
| J            | PW Str               | 25-50                | Work room closet               | (1) (4)                    |  |
| J            | PW Cnr               | 50-55                | Work room closet               | (1) (4)                    |  |
| K            | 9" VFT Gn            | 1-5                  | Rms 201,203,205,207,209        | (1) (4)                    |  |
| <del>L</del> | <del>9" VFT Bx</del> | <del>5-10</del>      | <del>301,303,305,307,309</del> | <del>(1) (4)</del>         |  |
| M            | 9" VFT Tn            | 5-10                 | 401,403,405,407,409            | (1) (4)                    |  |
| N            | Ceill Plas           | 1-5                  | Office area                    | (1) (4)                    |  |
| N            | Ceill Plas           | 1-5                  | Storage                        | (1) (4)                    |  |
| N            | 9" VFT Bg            | 1-5                  | Choral Room                    | (7)                        |  |
| N            | 9" VFT Bg            | 1-5                  | Offices                        | (7)                        |  |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School DistrictDATE August 11, 1999SCHOOL Chico Junior HighINSPECTOR Robert Peters

| HOMOG. |           | ASBESTOS |  | LOCATION                      | CONDITION: CODE & COMMENTS |
|--------|-----------|----------|--|-------------------------------|----------------------------|
| BLDG.  | MAT.#     | MATERIAL |  |                               |                            |
| N      | 9" VFT Br | 5-10     |  | Rm 503, Practice rooms        | (7)                        |
| N      | PW Str    | 25-50    |  | Under raised floor            | (7)                        |
| O      | 9" VFT Gn | 1-5      |  | RRs                           | (1) (4)                    |
| O      | PW Str    | 60-70    |  | Inside metal cabinets         | (7)                        |
| O      | PW Crn    | 60-70    |  | Inside metal cabinets         | (7)                        |
| P      | 9" VFT Gn | 1-5      |  | Room 18 storage               | (11)                       |
| P      | PW Str    | 50-70    |  | Boiler Room                   | (7)                        |
| P      | PW Str 5" | 45-50    |  | Boiler Room                   | (7)                        |
| P      | PW Str 5" | 45-50    |  | Men & Women's locker rooms    | (7)                        |
| P      | Tank Wrap | 20-30    |  | Boiler Room                   | (7)                        |
| P      | PW Str Cn | Assumed  |  | Crawlspc between locker rooms | (7)                        |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Chico Junior High INSPECTOR Robert Peters

| BLDG.          | HOMOG.   |          | MATERIAL | LOCATION                       | CONDITION: CODE & COMMENTS |  |
|----------------|----------|----------|----------|--------------------------------|----------------------------|--|
|                | MAT.#    | ASBESTOS |          |                                |                            |  |
| Main Hall Tunl | PW Str   | Assumed  |          | Pipe tunnel from front to back | (7)                        |  |
| P              | Pipewrap | Assumed  |          | In Ceiling Pipe Chase          | 10                         |  |
| K, L, M        | Pipewrap | Assumed  |          | Enclosed under Cabinets        | 10                         |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |
|                |          |          |          |                                |                            |  |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



DISTRICT Chico Unified School District

DATE 3/22/99.

SCHOOL Chico Junior High

INSPECTOR Rob Peters

| BLDG. | HOMOG.<br>MAT.# | ASBESTOS<br>MATERIAL | LOCATION                 | CONDITION: CODE & COMMENTS                                             |
|-------|-----------------|----------------------|--------------------------|------------------------------------------------------------------------|
| A     | 9" VFT W        | 1-5                  | Kitchen office           | (1) (4)                                                                |
| A     | 9" VFT R        | 1-5                  | Kitchen office           | (1) (4)                                                                |
| A     | 9" VFT          | 1-5                  | Main Hallway             | (7)                                                                    |
| A     | 9" VFT          | 1-5                  | MPR (Green)              | (1) (4)                                                                |
| A     | 9" VFT          | 1-5                  | Teacher's Lounge (Green) | (1) (4)                                                                |
| A     | 9" VFT          | 1-5                  | Fan rooms (Green)        | (1) (4)                                                                |
| A     | Mud Jnts        | 1-5                  | Water Tank room          | (1) (4)                                                                |
| A     | Ceill Plas      | 1-5                  | Teacher's Lounge         | (5) Water stained less than 25% & Ceiling Repaired. Roof Repaired 8/98 |
| A     | Ceill Plas      | 1-5                  | MPR                      | (1) (5) Roof & Ceiling Repaired. Roof Repaired 8/98.                   |
| A     | Ceill Plas      | 1-5                  | Rest of Wing             | (1) (5) Roof & Ceiling Repaired                                        |
| A     | Ceill Mat.      | 1-5                  | Refrigerator room        | (1) (4)                                                                |

## CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

HOMOG. ASBESTOS  
MAT.# MATERIAL

LOCATION

CONDITION: CODE &amp; COMMENTS

|    |             |         |                         |                                     |
|----|-------------|---------|-------------------------|-------------------------------------|
| A  | PW Str      | 25-50   | South & North Fan Rooms | (7) Removed 9/98                    |
| A  | Mud Jnt     | 50-55   | South & North Fan Rooms | (7) Removed 9/98                    |
| A  | 9" VFT      | 1-5     | Teacher's Lounge        | (1) (4)                             |
| A  | Tank Wrap   | 40-45   | Hot water closet        | (11)                                |
| A  | PW Str      | Assumed | Stage area              | (7)                                 |
| A  | Light cords | Assumed | Stage lighting          | (7)                                 |
| B  | Ceill plas  | 1-5     | Hallway & Upper wall    | (1) (5) Roof & Ceiling Repaired (4) |
| B  | 9" VFT R    | 1-5     | Hallway                 | (7)                                 |
| B  | 12" VFT R   | 1-5     | Hallway                 | (7)                                 |
| -C | 9" VFT R    | 1-5     | Chapter One Office      | (7)                                 |
| C  | Ceill Plas  | 1-5     | Room 11                 | (1) (4)                             |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED &amp; RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

HOMOG. ASBESTOS  
MAT.# MATERIAL

LOCATION

CONDITION: CODE &amp; COMMENTS

|              |                   |                 |                                    |                |
|--------------|-------------------|-----------------|------------------------------------|----------------|
| C            | 9" VFT Br         | 5-10            | Rms 200,202,204,206,208            | (7)            |
| C            | 9" VFT Br         | 5-10            | Rm 202                             | (7)            |
| D            | 9" VFT R          | 1-5             | Rm 10 - Janitor storage            | (1) (4)        |
| D            | Ceill Plas        | 1-5             | Rm 11                              | (1) (4)        |
| D            | 9" VFT Gr         | 1-5             | Rms 300,302,304,306,308            | (7)            |
| E            | 9" VFT Rd         | 1-5             | Janitor's Storage                  | (1) (4)        |
| E            | Ceill Plas        | 1-5             | Rm 8                               | (1) (4)        |
| <del>E</del> | <del>9" VFT</del> | <del>5-10</del> | <del>Rms 400,402,404,406,408</del> | <del>(7)</del> |
| F            | 9" VFT Rd         | 1-5             | Room 1                             | (1) (4)        |
| F            | Ceill Plas        | 1-5             | Room 2                             | (1) (4)        |
| F            | 9" VFT Br         | 5-10            | Rms 500,502,504,506                | (7)            |

## CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

BLDG. HOMOG. ASBESTOS  
MAT.# MATERIAL

LOCATION

CONDITION: CODE &amp; COMMENTS

|   |            |         |                             |      |
|---|------------|---------|-----------------------------|------|
| F | PW Str     | 40-45   | Room 502                    | (11) |
| F | 9" VFT BR  | 5-10    | Room 504                    | (7)  |
| F | PW Str     | Assumed | Room 506                    | (11) |
| G | PW Str     | 55-70   | Boiler Room                 | (7)  |
| G | 8" Str     | 60-70   | Boiler Room                 | (7)  |
| G | Tank Wrap  | 60-70   | Boiler Room                 | (7)  |
| G | 4" Str     | 35-40   | Boiler Room                 | (7)  |
| G | 4" Str     | 35-40   | Shop Storage                | (7)  |
| H | Ceill Plas | 1-5     | Wood shop offices           | (7)  |
| H | 9" VFT     | 1-5     | Wood shop office & classrms | (7)  |
| J | 9" VFT Rd  | 1-5     | Admin. offices              | (7)  |

## CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

| BLDG.        | HOMOG.<br>MAT.#      | ASBESTOS<br>MATERIAL | LOCATION                       | CONDITION: CODE & COMMENTS |
|--------------|----------------------|----------------------|--------------------------------|----------------------------|
| J            | 9" VFT Rd            | 1-5                  | Hallway and Library            | (7)                        |
| J            | Ceill Plas           | 1-5                  | All rooms in wing              | (1) (4)                    |
| J            | PW Str               | 25-50                | Work room closet               | (1) (4)                    |
| J            | PW Cnr               | 50-55                | Work room closet               | (1) (4)                    |
| K            | 9" VFT Gn            | 1-5                  | Rms 201,203,205,207,209        | (1) (4)                    |
| <del>H</del> | <del>9" VFT Br</del> | <del>5-10</del>      | <del>301,303,305,307,309</del> | <del>(1) (4)</del>         |
| M            | 9" VFT Tn            | 5-10                 | 401,403,405,407,409            | (1) (4)                    |
| N            | Ceill Plas           | 1-5                  | Office area                    | (1) (4)                    |
| N            | Ceill Plas           | 1-5                  | Storage                        | (1) (4)                    |
| N            | 9" VFT Bg            | 1-5                  | Choral Room                    | (7)                        |
| N            | 9" VFT Bg            | 1-5                  | Offices                        | (7)                        |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

BLDG. HOMOG. ASBESTOS  
MAT.# MATERIAL

LOCATION

CONDITION: CODE &amp; COMMENTS

|   |           |         |                                 |         |
|---|-----------|---------|---------------------------------|---------|
| N | 9" VFT Br | 5-10    | Rm 503, Practice rooms          | (7)     |
| N | PW Str    | 25-50   | Under raised floor              | (7)     |
| O | 9" VFT Gn | 1-5     | RRs                             | (1) (4) |
| O | PW Str    | 60-70   | Inside metal cabinets           | (7)     |
| O | PW Crn    | 60-70   | Inside metal cabinets           | (7)     |
| P | 9" VFT Gn | 1-5     | Room 18 storage                 | (11)    |
| P | PW Str    | 50-70   | Boiler Room                     | (7)     |
| P | PW Str 5" | 45-50   | Boiler Room                     | (7)     |
| P | PW Str 5" | 45-50   | Men & Women's locker rooms      | (7)     |
| P | Tank Wrap | 20-30   | Boiler Room                     | (7)     |
| P | PW Str Cn | Assumed | Crawlspace between locker rooms | (7)     |

## CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-22-99

SCHOOL Chico Junior High

INSPECTOR Rob Peters

BLDG. HOMOG. ASBESTOS  
MAT.# MATERIAL

LOCATION

CONDITION: CODE &amp; COMMENTS

|                      |          |         |                                   |     |
|----------------------|----------|---------|-----------------------------------|-----|
| Main<br>Hall<br>Tunl | PW Str   | Assumed | Pipe tunnel from front to<br>back | (7) |
| P                    | Pipewrap | Assumed | In Ceiling Pipe Chase             | 10  |
| K,L,M                | Pipewrap | Assumed | Enclosed under Cabinets           | 10  |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |
|                      |          |         |                                   |     |

## CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)