

**ENTEK CONSULTING GROUP, INC.  
ASSESSMENT OF TSI and/or FRIABLE MATERIAL**

District: Chico Unified School District

Date: July 14, 2010

School: Chico Senior High School

Inspector: Jack DeLay

Building & Location(s): LH - 942-Teacher's Lounge Restrooms

ECG- % Asbestos-5-10%

Homogeneous Mat. #102

Material description: Mud Joints

Total amount of material this location: 4 Joints

Amount of friable material this location: 4 Joints

Damage	Local		Distributed		Damaged	0%
Type of Damage	Air Erosion		Water		Flaking	
	Deterioration		Physical		Delamination	

Probable cause(s) of damage: Physical Damage

POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES	
	H	M	L			
				Isolate/Restrict		Fix leaks
Accessibility	X			Repair/Cleanup		Prevent water contact
Vibration			X	Enclose	X	Do not drill, cut, sand, or grind X
Air Erosion			X	Remove	X	Do not affix signs
Water			X	Encapsulate		Avoid contact X
Occupancy		X		O & M	X	

**Assessment of Material Condition**

Significantly Damaged (Poor)

Damaged (Fair)

Not damaged (Good)




Potential Damage: High

High Mod Low

High Mod Low

Hazard Ranking:

1 2 3 4 5 6 7

						X		
--	--	--	--	--	--	---	--	--

Comments & Observations: