

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/24/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: A

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|------------------|--------------|---------------|-----------------------|---|---|----------------|
| M | 9" VFT | 2 | 1-5% | 980 S | MECHANICS OFFICE & MAINTENANCE OFFICE | (2) DAMAGED UNDER CHAIR AT DESK. | N |
| M | 12" VFT BEIGE | 4 | TRACE | 60 S | UPSTAIRS RESTROOM | (1) (4) SAMPLE HMS-COP-04 COLLECTED IN 1988. | N |
| M | 12" VFT YELLOW | 6 | TRACE | 200 S | TRANSPORTATION OFFICE, ROLLING CHAIR WEAR-OUT | (2) SAMPLE HMS-COP-06 COLLECTED IN 1988. | N |
| M | 12" ACT | 7 | NONE DETECTED | 680 S | DRIVERS LOUNGE & TRANSPORTATION OFFICE | (13) SAMPLE HMS-COP-07 COLLECTED IN 1988. | N/A |
| M | 12" VFT GREY | 8 | ASSUMED | 260 S | TRANSPORTATION OFFICE | (1) | N |
| S | TEXTURE | 9 | ASSUMED | 200 S | TRANSPORTATION OFFICE | (1) | N |
| M | 9" VFT PINK | 62 | ASSUMED | 500 S | KEY SMITH SHOP | (1) (4) | N |
| M | DRYWALL | 77 | NONE DETECTED | 5,000 S | ALL ROOMS | (13) SAMPLE HMS-CUSD-CORP-77A COLLECTED ON 5-20-92. | N/A |
| M | 12" VFT CREAM | 78 | ASSUMED | 100 S | DRIVERS LOUNGE | (1) (4) | N |
| M | GLAZING COMPOUND | 79 | ASSUMED | 50 L | GROUND SHED WINDOWS | (1) (4) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/24/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: E - Paint Shop

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|----------|--------------|-------------------|-----------------------|------------------------|----------------------------|----------------|
| M | DRYWALL | 75 | 1-5% IN SKIM COAT | 2,000 S | PAINT SHOP - ALL AREAS | (1) (4) | N |

School: Corporate Yard

Building: D - Poison Storage

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|----------|--------------|---------------|-----------------------|-----------|----------------------------|----------------|
| M | DRYWALL | 76 | NONE DETECTED | 500 S | ALL ROOMS | (13) | N/A |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 07/18/2008

District: Chico Unified School District
School: Corporate Yard

Inspector: Leroy Christophersen
Building: A

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|------------------|--------------|---------------|-----------------------|---|---|----------------|
| M | 9" VFT | 2 | 1-5% | 980 S | MECHANICS OFFICE & MAINTENANCE OFFICE | (2) DAMAGED UNDER CHAIR AT DESK. | N |
| M | 12" VFT BEIGE | 4 | TRACE | 60 S | UPSTAIRS RESTROOM | (1) (4) SAMPLE HMS-COP-04 COLLECTED IN 1988. | N |
| M | 12" VFT YELLOW | 6 | TRACE | 200 S | TRANSPORTATION OFFICE, ROLLING CHAIR WEAR-OUT | (2) SAMPLE HMS-COP-06 COLLECTED IN 1988. | N |
| M | 12" ACT | 7 | NONE DETECTED | 680 S | DRIVERS LOUNGE & TRANSPORTATION OFFICE | (13) SAMPLE HMS-COP-07 COLLECTED IN 1988. | N/A |
| M | 12" VFT GREY | 8 | ASSUMED | 260 S | TRANSPORTATION OFFICE | (1) | N |
| S | TEXTURE | 9 | ASSUMED | 200 S | TRANSPORTATION OFFICE | (1) | N |
| M | 9" VFT PINK | 62 | ASSUMED | 500 S | KEY SMITH SHOP | (1) (4) | N |
| M | DRYWALL | 77 | NONE DETECTED | 5,000 S | ALL ROOMS | (13) SAMPLE HMS-CUSD-CORP-77A COLLECTED ON 5-20-92. | N/A |
| M | 12" VFT CREAM | 78 | ASSUMED | 100 S | DRIVERS LOUNGE | (1) (4) | N |
| M | GLAZING COMPOUND | 79 | ASSUMED | 50 L | GROUND SHED WINDOWS | (1) (4) | N |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/18/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: E - Paint Shop

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|----------|--------------|-------------------|-----------------------|------------------------|----------------------------|----------------|
| M | DRYWALL | 75 | 1-5% IN SKIM COAT | 2,000 S | PAINT SHOP - ALL AREAS | (1) (4) | N |

School: Corporate Yard

Building: D - Poison Storage

| Material Class | Material | Homo. Mat. # | % Asb. | Ft ² /L.F. | Location | Condition: Code & Comments | Friable Yes/No |
|----------------|----------|--------------|---------------|-----------------------|-----------|----------------------------|----------------|
| M | DRYWALL | 76 | NONE DETECTED | 500 S | ALL ROOMS | (13) | N/A |

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS