

**ENTEK CONSULTING GROUP, INC.
ASSESSMENT OF TSI and/or FRIABLE MATERIAL**

District: Chico Unified School District

Date: July 12, 2010

School: Fair View High School

Inspector: Jack DeLay

Building & Location(s): Unit F - MPR - Kitchen, Water Heater Room, MPR Storage, & Custodial Room

ECG-

% Asbestos-Assumed

Homogeneous Mat. #7

Material description: Mud Joints

Total amount of material this location: 20 Joints

Amount of friable material this location: 20 Joints

Damage	Local		Distributed		Damaged	0%
Type of Damage	Air Erosion		Water		Flaking	
	Deterioration		Physical		Delamination	

Probable cause(s) of damage:

POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES	
	H	M	L			
				Isolate/Restrict	X	Fix leaks
Accessibility		X		Repair/Cleanup		Prevent water contact X
Vibration			X	Enclose		Do not drill, cut, sand, or grind X
Air Erosion			X	Remove	X	Do not affix signs
Water			X	Encapsulate		Avoid contact X
Occupancy		X		O & M	X	

Assessment of Material Condition

Significantly Damaged
(Poor)

Damaged
(Fair)

Not damaged
(Good)

Potential Damage:

High

High

Mod

Low

High

Mod

Low

Hazard Ranking:

1

2

3

4

5

6

7

								X
--	--	--	--	--	--	--	--	---

Comments & Observations: