

SIX-MONTH SURVEILLANCE

DISTRICT CHICO UNIFIED SCHOOL DISTRICT DATE 12/28/89
 SCHOOL Loma Vista Elementary School INSPECTOR GRAVES

BLDG.	HOMOG. MAT.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1 - 5%	Hall, Rooms 15,17,14,11	1 - 4
2	Hard plaster	1 - 5%	Rm 13 RR, Rm 16 RR	1 - 4
2	Soft plaster	1 - 5%	Rm 13 Rr, Rm 8 Men's RR and Rm 7	1 - 4
2	Soft plaster	1 - 5%	Rm 6 Women's RR, Rm 16	1 - 4
2	PW Str & Debris	55 - 65%	Attic	2 - 4
2	PW Str	70 - 75%	Boiler room	1 - 4
2	PW Cnr	5 - 10%	Boiler room	1 - 4
6	12" VFT	10 - 15%	MPR, washroom, kitchen, classrooms and open areas, special purpose	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (DAMAGED 2 * OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES [IF YES, EXPLAIN UNDER COMMENTS]
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

SIX-MONTH SURVEILLANCE

DISTRICT CHICO UNIFIED SCHOOL DISTRICT DATE 12/28/89
 SCHOOL Loma Vista Elementary School INSPECTOR Paul B. Graves

BLDG. HOMOG. ASBESTOS MAT. LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS MAT.	LOCATION	CONDITION: CODE & COMMENTS
6	Mud Jnts	Assumed	B/R room	2 - 4
6	PW Str	70 - 75%	Attic	1 - 4
6	Transite panels	Assumed	Above all doors and B/R	1 - 4
6	Duct	Assumed	B/R room	1 - 4
6	Conc boxes	Assumed	B/R room	1 - 4
6	Boiler liner	10 - 15%	Boiler room	1 - 4

CONDITION CODES
 GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (DAMAGED 2 * OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES [IF YES, EXPLAIN UNDER COMMENTS]
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED