

BUTTE
COUNTY
OFFICE OF
EDUCATION

JERRY McGUIRE
SUPERINTENDENT

Kirby White
Maintenance & Operations
Facilities Planner
(916) 538-2084


Board of
Education

Brenda J. Brimhall
Frank Gladen
Bessie Hironimus
Erwin M. Howlett
James F. Lindsey
Brent Moore
Betty Vassar

Business Services
1859 Bird Street
Oroville, CA 95965
(916) 538-7227
FAX: (916) 538-7218
An Equal Opportunity
Employer

MEMORANDUM

To: ~~Sally Bonavito~~
Marigold Portable, Room 10

From: Kirby L. White 

Date: December 2, 1994

Subject: 6 Month AHERA Surveillance Report

Please find attached the most recent 6 month AHERA surveillance report for your site. Please include this in the rear most section of your AHERA Inspection and Management Plan.

Thank you for your assistance and have a happy holiday season !!

jm
AA11945

cc: AHERA Master File

BUTTE COUNTY OFFICE OF EDUCATION INSPECTOR: *Von Smith*
 MARI GOLD PORTABLE ROOM 10 DATE OF INSPECTION: *11-10-94*
 2446 MARI GOLD AVENUE CHICO CA. *12-13-94*

LOCATION	MATERIAL	MATERIAL CLASSIFICATION	HOMOGENEOUS MATERIAL #	PERCENTAGE ASBESTOS ASSUMED	AMOUNT Sq. Ft./LI Ft. 990 SQ. FT.	CONDITION: CODE & COMMENT	FRIABLE YES NO
THROUGHOUT	12" VINYL FLOOR TILE	MISC	99			(UNDER CARPETING) /	✓

CONDITION CODE:
 General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or More)
 Change in Condition: (4) No (5) Yes, (if Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection due (12) Other (explain under comments)


NT

BUTTE
COUNTY
OFFICE OF
EDUCATION

JERRY McGUIRE
SUPERINTENDENT

MEMORANDUM

To: Corin Meester
Marigold Portable - Room 10

From: Kirby L. White 

Date: May 19, 1994

Subject: 6 Month AHERA Surveillance Report

Please find attached the most recent 6 month AHERA surveillance report for your site. Please include this in the rear-most section of your AHERA inspection and management plan.

Thank you for your assistance.

jm
AA21934

Attachment

cc: AHERA Master File

Kirby White
Maintenance & Operations
Facilities Planner
(916) 538-2084

Board of
Education

Brenda J. Brimhall
Frank Gladen
Bessie Hironimus
Erwin M. Howlett
James F. Lindsey
Brent Moore
Betty Vassar

Business Services
1859 Bird Street
Oroville, CA 95965
(916) 538-7227
FAX: (916) 538-7218
*An Equal Opportunity
Employer*

BUTTE COUNTY OFFICE OF EDUCATION INSPECTOR: TOP Smith
 MARIGOLD PORTABLE ROOM 10 DATE OF INSPECTION: 5-18-04
 2446 MARIGOLD AVENUE CHICO CA.

LOCATION	MATERIAL	MATERIAL CLASSIFICATION	HOMOGENEOUS MATERIAL #	PERCENTAGE ASBESTOS ASSUMED	AMOUNT Sq. Ft./Li. Ft. 960 SQ. FT.	CONDITION: CODE & COMMENT	FRIABLE YES NO
THROUGHOUT	12" VINYL FLOOR TILE	MISC	99			(UNDER CARPETING) /	1

CONDITION CODE:
 General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or More)
 Change in Condition: (4) No (5) Yes, (if Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection of (12) Other (explain under comments)

Chico Unified School District
1163 East Seventh Street
Chico, CA 95928-5999
(916) 891-3210

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

SECTION I (to be completed by contractor)

Date: 1/21/94
Contractor organization: Thomson Telephone Service
Address: 317 Yolo Street, Orland, CA 95963
Description of work to be performed: Connect new telephone lines @ phone terminal
Location(s) of work: Loma Vista & Marigold Schools

SECTION II (to be completed by school district)

Type, amount and location of ACBM in work area:

FLOOR TILE 10-158

PW PANEL 70-758

TRANSIRE PANELS.

It is the explicit condition of the performance of this work that no asbestos be disturbed.

P.P.
Paul Grimes Date: 1/27/93
LEA Designee
(school district)

(Worker/Contractor Signature) Date:

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84 (d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school building are provided information regarding the locations of ACBM (asbestos containing building materials) and suspected ACBM assumed to be ACM (asbestos containing material).

DATE:

CONTRACTOR ORGANIZATION:

CONTRACTOR ADDRESS:

DESCRIPTION OF WORK TO BE PERFORMED:

LOCATION(S) OF WORK:

TYPE, AMOUNT, AND LOCATION OF ACBM IN WORK AREA:

IT IS THE EXPLICIT CONDITION OF THE PERFORMANCE OF THIS WORK THAT NO ASBESTOS BE DISTURBED.

LEA DESIGNEE:
 KIRBY L. WHITE
 BUTTE COUNTY OFFICE OF EDUCATION
 DIRECTOR OF MAINTENANCE & OPERATIONS/FACILITIES PLANNER
 (916) 538-2084

WORKER/CONTRACTOR SIGNATURE: DATE:

WORKER/CONTRACTOR SIGNATURE: DATE:

WORKER/CONTRACTOR SIGNATURE: DATE:

WORKER/CONTRACTOR SIGNATURE: DATE:

Loma
Vista

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

Date: 7 February 1994

Contractor Organization: Jesse Heating and Air Conditioning Inc.

Contractor Address: 3025 Southgate Lane
Chico, CA 95926

Contractor Phone: 891-4926

Description of work to be performed:
Remove approximately 85 linear feet of 18" x 60" fiberglass duct board and replace with sheet metal lined duct work.

Location(s) of work:
Loma Vista School, 2404 Marigold Avenue, Chico-Above room 10 and in the attic space above the MPR.

Type, amount, and location of ACBM in work area:
TSI (Thermal System Insulation) Pipe Wrap (straight), 300 linear feet, Boiler Room

TSI (Thermal System Insulation) Mudded joints, 11 joints; Boiler room.

Miscellaneous (transite Panels); 2000 sq. ft.; above all doors in Boiler room.

Miscellaneous (duct connectors) 50 linear ft.; Boiler room.

TSI (thermal system insulation) Boiler Liner; boiler room.

It is the explicit condition of the performance of this work that no asbestos be disturbed.

John L. White 2/7/94
Kirby L. White; Butte County Office of Education Dir. of Maintenance & Operations/Facilities Planner LEA Designee
1859 Bird Street, Oroville CA 95965
Phone 916 (538-2084)

Martin Anderson
Worker/Contractor Signature

3/24/94
Date

[Signature]
Worker/Contractor Signature

3-27-94

Post-It™ brand fax transmittal memo 7671		# of pages	1
To	PAUL GRAVES	From	Kirby White
Co.	CVSD	Co.	PROC
Dept.	MOTH	Phone #	538-2084
Fax #			

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 20, 1994

SCHOOL Loma Vista Elementary INSPECTOR Ron Jones *RJ*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1-5	Hall, Rms 15,17,14,11	1-4
2	Hard plas	1-5	Rm 13 RR, Rm 16 RR	1-4
2	Soft plas	1-5	Rm 13 RR, Rm 8 Men's RR, Rm7	1-4
2	Soft plas	1-5	Rm 3 RR	2-4 RR has plaster chipping on SO. wall <5%
2	PW Str & Debris	55-65	Attic	2-4
2	PW Str	70-75	Boiler Room	(1) (4)
2	PW Cnr	5-10	Boiler Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 20, 1994

SCHOOL Loma Vista Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
6	12" Vft	10-15	MPR, RR, Kitchen, Classrooms, open areas, special purpose	1-4
6	Mud Jnts	Assumed	B/R room	1-4 1 Jnt P.W. around valve
6	PW Str	70-75	Attic	1-4
6	Tran panl	Assumed	Above all doors and B/R	1-4
6	Duct box	Assumed	B/R room	1-4
6	Boil linr	10-15	Boiler room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 1, 1994
 SCHOOL Loma Vista Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1-5	Hall, Rms 15, 17, 14, 11	1-4
2	Hard plas	1-5	Rm 13 RR, Rm 16 RR	1-4
2	Soft plas	1-5	Rm 13 RR, Rm 8 Men's RR, Rm7	1-4
2	Soft plas	1-5	Rm 3 RR	2-4 RR has plaster chipping on SO. wall <5%
2	PW Str & Debris	55-65	Attic	2-4
2	PW Str	70-75	Boiler Room	(1) (4)
2	PW Cnr	5-10	Boiler Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 1, 1994

SCHOOL Loma Vista Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
6	12" Vft	10-15	MPR, RR, Kitchen, Classrooms, open areas, special purpose	1-4
6	Mud Jnts	Assumed	B/R room	1-4 1 Jnt P.W. around valve
6	PW Str	70-75	Attic	1-4
6	Tran panl	Assumed	Above all doors and B/R	1-4
6	Duct box	Assumed	B/R room	1-4
6	Boil linr	10-15	Boiler room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)