

# ASBESTOS TRAINING PERSONNEL RECORD

BARNES

Joseph

~~W~~

~~B~~

A

Custodian

Last Name

First Name

M.I.

Job Title

Employee Number

I received two hours of awareness training concerning asbestos on this date.

5-20-96

Date

Joseph Barnes

Signed by Employee

This training is described in EPA Final Rule and Notice 40 CFR Part 763, Section 763.92 dated October 30, 1987.

This form may be copied or reproduced as needed.


ap:0:\maint\asbestos.frm1

5/1/96

**BUTTE  
COUNTY**  
**OFFICE OF  
EDUCATION**

**JERRY McGUIRE**  
SUPERINTENDENT

MEMORANDUM

To: Site Supervisor  
From: Kirby L. White   
Date: 8 January 1996  
Subject: AHERA 6 Month Surveillance

Kirby L. White  
Maintenance/Operations  
Facilities Planner  
916-538-2084  
FAX 916-538-7218

E-mail:  
kwhite@ben.  
bcoe.butte.k12.ca.us  
Board of  
Education

*Brenda J. Brtnhall  
Frank Gladen  
Bessie Hironimus  
Erwin M. Howlett  
L. Charles Larsen  
James F. Lindsey  
Betty Vassar*

Business Services  
1859 Bird Street  
Oroville, CA 95965  
(916) 538-7227  
FAX: (916) 538-7218  
*An Equal Opportunity  
Employer*

Please find attached the AHERA 6 month surveillance form for your site. Review this surveillance and retain it in your site AHERA files.

Should you have any questions, please do not hesitate to contact me. Thank you.

jm  
MO76956.doc

cc: AHERA Master File

Attachment

BUTTE COUNTY OFFICE OF EDUCATION INSPECTOR: [Signature]  
 MARIGOLD PORTABLE ROOM 10 DATE OF INSPECTION: 12/26/94  
 2446 MARIGOLD AVENUE CHICO CA.

LOCATION	MATERIAL	MATERIAL CLASSIFICATION	HOMOGENEOUS MATERIAL #	PERCENTAGE ASBESTOS ASSUMED	AMOUNT Sq. Ft./Ll. Fl. 990 Sq. Ft.	CONDITION: CODE & COMMENT	FRIABLE YES NO
THROUGHOUT	12" VINYL FLOOR TILE	MISC	99			(UNDER CARPETING)	YES NO

CONDITION CODE:  
 General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or More)  
 Change In Condition: (4) No (5) Yes, (if Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (explain under comments)

NT

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Loma Vista Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1-5	Hall, Rms 15,17,14,11,12	1-4
2	Hard plas	1-5	Rm 13 RR, Rm 16 RR, Rm 6 Women's RR, Rms 7,8,14, Boiler Room	1-4
2	Soft plas	1-5	Rm 13 RR, Rm 8 Men's RR, Rm 7,16,17	1-4
2	Soft plas	1-5	Rm 3 RR	2-4 RR has plaster chipping on So. wall <5%
2	PW Str & Debris	55-65	Attic	5-6
2	PW Str	70-75	Boiler Room	1-4
2	PW Cnr	5-10	Boiler Room	1-4
All	Drywall	1-5 skim coat	All Non-plaster Walls and Ceilings	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Loma Vista Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
6	12" VFT	10-15	MPR, RR, Kitchen, Classrooms, open areas, special purpose	1-4
6	Mud Jnts	Assumed	B/R room	1-4 1 Jnt P.W. around valve
6	PW STR	70-75	Attic	11
6	Tran panl	Assumed	Above all doors and B/R	1-4
6	Duct box	Assumed	B/R room	1-4
6	Boil linr	10-15	Boiler room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

c:\mydocu-1\wpdocu-1\asbestos\loma796.sur

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 12, 1996  
 SCHOOL Loma Vista Elementary INSPECTOR Ron Jones *RJ*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1-5	Hall, Rms 15,17,14,11,12	1-4
2	Hard plas	1-5	Rm 13 RR, Rm 16 RR, Rm 6 Women's RR, Rms 7,8,14, Boiler Room	1-4
2	Soft plas	1-5	Rm 13 RR, Rm 8 Men's RR, Rm 7,16,17	1-4
2	Soft plas	1-5	Rm 3 RR	2-4 RR has plaster chipping on so. wall <5%
2	PW Str & Debris	55-65	Attic	2-4
2	PW Str	70-75	Boiler Room	1-4
2	PW Cnr	5-10	Boiler Room	1-4
All	Drywall	1-5 skim coat	All Non-plaster Walls and Ceilings	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE January 12, 1996

SCHOOL Loma Vista Elementary INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
6	12" Vft	10-15	MPR, RR, Kitchen, Classrooms, open areas, special purpose	1-4
6	Mud Jnts	Assumed	B/R room	1-4 1 Jnt P.W. around valve
6	PW Str	70-75	Attic	11
6	Tran panl	Assumed	Above all doors and B/R	1-4
6	Duct box	Assumed	B/R room	1-4
6	Boil linr	10-15	Boiler room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Loma Vista Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
2	9" VFT	1-5	Hall, Rms 15,17,14,11,12	1-4
2	Hard plas	1-5	Rm 13 RR, Rm 16 RR, Rm 6 Women's RR, Rms 7,8,14, Boiler Room	1-4
2	Soft plas	1-5	Rm 13 RR, Rm 8 Men's RR, Rm 7,16,17	1-4
2	Soft plas	1-5	Rm 3 RR	2-4 RR has plaster chipping on so. wall <5%
2	PW Str & Debris	55-65	Attic	5-6
2	PW Str	70-75	Boiler Room	1-4
2	PW Cnr	5-10	Boiler Room	1-4
All	Drywall	1-5 skim coat	All Non-plaster Walls and Ceilings	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Loma Vista Elementary INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
6	12" VFT	10-15	MPR, RR, Kitchen, Classrooms, open areas, special purpose	1-4
6	Mud Jnts	Assumed	B/R room	1-4 1 Jnt P.W. around valve
6	PW Str	70-75	Attic	11
6	Tran panl	Assumed	Above all doors and B/R	1-4
6	Duct box	Assumed	B/R room	1-4
6	Boil linr	10-15	Boiler room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)