

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit A - Rooms 1 & 2 (FKA 3)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT WHITE	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4) SAMPLE MAR-02 COLLECTED ON 3-30-88.	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE & BELOW GLASS PANELS (EXTERIOR)	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	105	ASSUMED	600 S	CLASSROOMS 1 & 2	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit B - MPR (FKA 5)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN (909), ADMIN OFFICE, MULTI PURPOSE ROOM (905), STORAGE, PIP ROOM (908), AND HEALTH OFFICE (903)	(2) (11) PRINCIPAL OFFICE AND PIP ROOM (908) COVERED WITH CARPET.  ADMIN OFFICE (NORTH HALF ONLY) COVERED WITH 12" VFT BLUE.	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(1) (4) SAMPLE MAR-06 COLLECTED ON 3-30-88.	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN (909) AND RESTROOMS (907 & 907A)	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM (905)	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM (908), CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE (903)	(1) (4)	N
M	12" VFT BLUE	106	NON ASBESTOS	240 S	ADMIN OFFICE	(1) MODERNIZATION PROJECT 1996 LETTER FROM ARMSTRONG (MFG) ON FILE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit C - Rooms 3-5 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5	(1) (6) SAMPLE MAR-08 COLLECTED ON 3-30-88.	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5	(1) (4)	N

School: Marigold Elementary School

Building: Unit D - Rooms 6A & 6B (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	95	NON ASBESTOS	240 S	CLASSROOMS 6A & 6B	(1) (4) MODERNIZATION 1996 MANUFACTURER LETTER ON FILE	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	107	ASSUMED	2,500 S	CLASSROOMS 6A & 6B	(11) COVERED WITH TAGBOARD.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit E - Restrooms (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP STRAIGHT	10	60-65%	150 L	BOILER ROOM	(1) (4) SAMPLE MAR-10 COLLECTED ON 3-30-88.	Y
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(2) MINOR WATER DAMAGE ON ACT'S IN BOY'S & GIRL'S RESTROOMS.	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(11)	N
S	PLASTER	101	NON ASBESTOS	600 S	BOY'S & GIRL'S RESTROOMS AND CUSTODIAL ROOM	(2) BOYS RESTROOM DAMAGED NEAR DOOR CUSD SAMPLE 7/7/08 MAR01,03-05	N
T	BOILER INSULATION	108	ASSUMED	2 EACH	BOILER ROOM	(1)	Y

School: Marigold Elementary School

Building: Unit F - Rooms 7-9 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 7-9	(1) MODERNIZATION 1996	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 7-9	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit G - Room 10 (FKA 1)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP FIBERGLASS	96	Certified Non-Asbestos	1,800 S	CLASSROOM 10	(13) Letters on file	N
M	DRYWALL & JOINT COMPOUND	109	Certified Non-Asbestos	1,700 S	CLASSROOM 10	(13) Letters on file COVERED WITH TAGBOARD	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit H (FKA 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	CLASSROOMS 11-14 AND MIDDLE RESTROOM	(1) (4) MIDDLE RESTROOM. (11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	NON ASBESTOS	4,500 S	ALL ROOMS	(1) (4) CUSD SAMPLE COLLECTED 7/7/08	N
M	12" VFT	93	NON ASBESTOS	900 S	ROOM 12 - LIBRARY	(11) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE IN 1996	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	NON ASBESTOS	305 S	STAFF LOUNGE (920)	(7) MODERNIZATION 1996 REMOVED AND REPLACED WITH 12" VFT GREEN.	N/A
M	12" VFT GREEN	151	NON ASBESTOS	305 S	STAFF LOUNGE (920)	(1) MODERNIZATION 1996 MANUFACTURER LETTER ON FILE	N
S	PLASTER	152	ASSUMED	2,000 SF	RESTROOMS (918 & 919) AND STAFF LOUNGE (920)	(1)	N
M	DRYWALL & JOINT COMPOUND	153	ASSUMED	2,500 SF	CLASSROOMS 11-14	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit I - Rooms 15-17 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
						<b>NOTE: ROOMS 15-17 WERE NOT INCLUDED IN THE ORIGINAL INSPECTION PERFORMED BY HMS, INC. IN 1988.</b> <b>(13) Letters on file</b>	

School: Marigold Elementary School

Building: Unit J - Rooms 19-23 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	Certified Non-Asbestos	2,400 S	PORTABLES 18B-22	(1)(4) MODERNIZATION 1996 (13) Letter on file	N
M	DRYWALL	81	Certified Non-Asbestos	10,000 S	PORTABLES 18B-22 AND RESTROOMS (923 & 924)	(11) COVERED WITH TAGBOARD IN CLASSROOMS 18B-22. (13) Letter on file	N
M	2' X 4' FCP	89	Certified Non-Asbestos	8,000 S	PORTABLES 18B-22	(1)(4) (13) Letter on file	N
M	LINOLEUM	100	Certified Non-Asbestos	500 S	RESTROOMS (923 & 924)	(1)(4) (13) Letter on file	N
						<b>NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.</b>	

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit K - Room 18 (FKA Portables 18A-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	Certified Non-Asbestos	2,400 S	PORTABLE 18A	(1)(4) MODERNIZATION IN 1996 (13) Letter on file	N
M	DRYWALL	81	Certified Non-Asbestos	10,000 S	PORTABLE 18A	(1) (4) (13) Letter on file	N
M	2' X 4' FCP	89	Certified Non-Asbestos	8,000 S	PORTABLE 18A	(1) (4) (13) Letter on file	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**



**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 02/11/2009

District: Chico Unified School District

Inspector: Mike Fender

School: Marigold Elementary School

Building: Unit L - Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	Certified Non-Asbestos	180 S	PORTABLES 23 & 24	(1) (4) (13) Letter on file	N
M	DRYWALL & JOINT COMPOUND	103	Certified Non-Asbestos	960 S	PORTABLES 23 & 24	(11) COVERED WITH TAGBOARD. (13) Letter on file	N
M	2' X 4' FCP'S (FIBERGLASS)	104	Certified Non-Asbestos	900 S	PORTABLES 23 & 24	(1) (4) (13) Letter on file	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**