



PRECISION I
MICRO-ANALYSIS C N

SPECIALISTS IN ASBESTOS-RELATED ANALYSIS

Bulk Sample Analysis (PLM) Report

Report # 93274009

Ron Jones
Chico Unified School District
2455 Carmichael Drive
Chico, CA 95969-

Date Collected:09/29/93
Date Received:10/01/93
Date Analyzed:10/01/93

Phone:(916)891-3095

Job Information:
P.O. #94-1868/Marigold School

Sample Number	Sample Location	Sample Description	Analytical Results
N/A Lab # 93-112343	Window ledge in Room 4 at Marigold School (Janet Akane's room)	Brown dirt and fibers on brown paper towel	No asbestos detected 5-10% Cellulose fibers

OFFICIAL NOTICE: After 45 days, samples are disposed of at a licensed waste disposal site unless client requests their return, identifying samples by our laboratory identification #'s. Charges for sample returns are a \$5.00 retrieval fee plus \$2.00 per sample to cover costs of retrieval, handling, and shipping.

Total Number of Samples: 1

Supervisor [Signature]

Analyst [Signature] Page 1 of 1

Note: The test result findings are made to the methodologies and parameters described on the reverse of this page.

Chico Unified School District
1163 East Seventh Street
Chico, CA 95928-5999
(916) 891-3210

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

SECTION I (to be completed by contractor)

Date: 1/21/94
Contractor organization: Thomson Telephone Service
Address: 317 Yolo Street, Orland, CA 95963
Description of work to be performed: Connect new telephone lines @ phone terminal
Location(s) of work: Loma Vista & Marigold Schools

SECTION II (to be completed by school district)

Type, amount and location of ACBM in work area:

FLOOR TILE 10-158
PW ATTIC 70-758
TRANSIT PANELS.

It is the explicit condition of the performance of this work that no asbestos be disturbed.

P.P.
Paul Brewer Date: 1/27/93
LEA Designee
(school district)

(Worker/Contractor Signature) Date:

**BUTTE
COUNTY**
**OFFICE OF
EDUCATION**

JERRY McGUIRE
SUPERINTENDENT

Kirby White
Maintenance & Operations
Facilities Planner
(916) 538-2084

Board of
Education

*Brenda J. Brimhall
Frank Gladen
Bessie Hironimus
Erwin M. Howlett
James F. Lindsey
Brent Moore
Betty Vassar*

Business Services
1859 Bird Street
Oroville, CA 95965
(916) 538-7227
FAX: (916) 538-7218
*An Equal Opportunity
Employer*

MEMORANDUM

To: Jim Howell
Marigold School

From: Kirby L. White (W)

Date: November 18, 1993

Subject: 6 Month AHERA Surveillance Report

Please find attached the most recent 6 month AHERA surveillance report for your site. Include this in the rear-most section of your AHERA inspection and management plan.

Thank you for your assistance and have a happy Thanksgiving.

jm
AA10934

cc: AHERA Master File

Attachment

BUTTE COUNTY OFFICE OF EDUCATION INSPECTOR: *[Signature]*
 MARIGOLD PORTABLE ROOM 10 DATE OF INSPECTION: 6-18-93
 2446 MARIGOLD AVENUE CHICO CA.

LOCATION	MATERIAL	MATERIAL CLASSIFICATION	HOMOGENEOUS MATERIAL #	PERCENTAGE ASBESTOS ASSUMED	AMOUNT Sq. Ft./ LI Ft. 900 SQ. FT.	CONDITION: CODE & COMMENT	FRIABLE YES NO
THROUGHOUT	12" VINYL FLOOR TILE	MISC	90			(UNDER CARPETING)	YES NO

CONDITION CODE:
 General Condition:
 Change in Condition:
 Abated:
 Miscellaneous:

(1) Good
 (4) No
 (6) Repaired
 (11) Inaccessible, no inspection data

(2) Damaged
 (5) Yes, (if Yes, explain under comments)
 (7) Removed
 (12) Other (explain under comments)

(3) Significantly Damaged (25% or More)
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

BUTTE
COUNTY
OFFICE OF
EDUCATION

JERRY McGUIRE
SUPERINTENDENT

Kirby L. White
Maintenance/Operations
Facilities Planner
(916) 538-2084

Board of
Education

Brenda J. Brimhall
Frank Gladen
Bessie Hironimus
Erwin M. Howlett
James F. Lindsey
Brent Moore
Betty Vassar

Business Services
1859 Bird Street
Oroville, CA 95965
(916) 538-7227
FAX: (916) 538-7218
*An Equal Opportunity
Employer*

MEMORANDUM

To: Parents, PTA, Teachers, Staff

From: Kirby L. White *(w)*
Director Maintenance & Operations/Facilities Planner
B.C.O.E. AHERA LEA Designee

Date: September 1, 1993

Subject: Site Asbestos Inspections and Management Plans to comply
with the Asbestos Hazard Emergency Response Act (AHERA).

Pursuant to the EPA's Asbestos Hazard Emergency Response Act (AHERA), all Butte County Office of Education facilities have been inspected for asbestos containing materials and management plans for the control of asbestos have been developed. The management plan includes the inspections, response actions, post response actions activities, periodic re-inspections, and operations and maintenance activities.

Also included are the names of the inspector, the management planner, forms in the management plan required by the Office of Local Assistance and the documentation of all significant events including any fiber release episodes. All data relating to asbestos activities will be entered into the plan within 30 days of the event.

A copy of the entire plan is available in the county office and at the office of the designee. Individual plans are available at the principal's office at each site. Annual notifications will be made in fall of each year.

The management plan(s) will be available for review during regular business hours. A nominal duplicating fee may be charged for those who wish to obtain copies of the plans.

The last periodic (six-month) surveillance was performed during May and June of this year and another is scheduled for early November. These inspections are included in the management plan(s).

jm
AA1934

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 28, 1993

SCHOOL Marigold Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1		Tran panl	Both boilers in Main B/R	1-4
1		9" VFT	Room 12 & rest of wing	1-4
1		PW Str	B/R Room	1-4
3		9" VFT	Room 17 & rest of unit	1-4
3		Tran panl	Above glass panels	1-4
4		9" VFT	Lib/staff & classrooms	1-4 Carpeted
5		9" VFT	Kit, MPR, AV store	1-4
5		Cold box ceiling	Cold Box	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 13, 1993

SCHOOL Marigold Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS
 MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1	Tran panl	Assumed		Both boilers in Main B/R	1-4
1	9" VFT	1-5%		Room 12 & rest of wing	1-4
1	PW Str	60-65%		B/R Room	1-4
3	9" VFT	1-5%		Room 17 & rest of unit	1-4
3	Tran panl	Assumed		Above glass panels	1-4
4	9" VFT	1-5%		Lib/staff & classrooms	1-4 Carpeted
5	9" VFT	1-5%		Kit, MPR, AV store	1-4
5	Cold box ceiling	30-35%		Cold Box	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)