

BUTTE
COUNTY
OFFICE OF
EDUCATION

JERRY McGUIRE
SUPERINTENDENT

Kirby L. White
Maintenance
Operations/Facilities
Supervisor
530-532-5600
FAX 530-538-5759
email:
kwhite@edison.
bcoe.butte.k12.ca.us

Board of
Education


Bessie Hronimus
Barbara Johnson
Charles Larsen
Brenda J. McLaughlin
Robert W. Purvis
Pat Matthews Spear
Betty Vassar

Administrative Services
1859 Bird Street
Oroville, CA 95965
(530) 538-7227
FAX: (530) 538-7218

Equal Opportunity
Employer

MEMORANDUM

TO: Marigold Portable Room 10
Corin Meester (Please distribute to the correct person at the site.)

FROM: Kirby L. White 

DATE: November 17, 2000

SUBJECT: AHERA Six - Month Surveillance

Please find attached the most recent AHERA Six-Month Surveillance for your site. The inspections were completed in November. Please review it and keep it in your site AHERA (Asbestos) file that is at or on your site.

Should you have any questions, please do not hesitate to contact me. Thank you.

ss
MO36001

cc: AHERA Site Files

Attachments



BUTTE COUNTY OFFICE OF EDUCATION
MARIGOLD PORTABLE ROOM 10
 2446 Marigold Avenue Chico
 original inspection 5/89

Inspector: *L. Smith*
 Date: *11-13-00*

LOCATION	MATERIAL	MATERIAL CLASSIFICATION	HOMOGENEOUS MATERIAL #	PERCENTAGE ASBESTOS	AMOUNT Sq. Ft./L.Ft.	CONDITION: CODE & COMMENT	FRIABLE YES NO
Throughout	12" vinyl floor tile	Misc		99 assumed	960 sq. ft.	(under carpeting) / -- 4	L

Condition Code:
 General Condition (1) Good
 Change in Condition (4) No
 Abated: (6) Repaired
 Miscellaneous: (11) Inaccessible

(2) Damaged (3) Significantly Damaged (25% or more)
 (5) Yes, (if yes explain under comments)
 (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (12) Other (explain under comments)

DISTRICT Chico Unified School District DATE 8/10/00

SCHOOL Marigold Elementary INSPECTOR Robert Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1	Tran panl	Assumed	Both boilers in Main B/R	1-4
1	9" VFT	1-5%	Room 12 & rest of wing	1-4
1	PW Str	60-65%	B/R Room	1-4
3	9" VFT	1-5%	Room 17 & rest of unit	1-4
3	Tran panl	Assumed	Above glass panels	1-4
4	Tran panl	Assumed	Above windows	1-4
4	9" VFT	1-5%	Lib/staff & classrooms	1-4 Carpeted
5	9" VFT	1-5%	Kit, MPR, AV store, Fac. RR	1-4
5	Cold box ceiling	30-35%	Cold Box	1-4
5	Plaster	Assumed	Kitchen & Restroom	1-4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 8/10/00

SCHOOL Marigold Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
All	Drywall	1-5 skim coat	All Non-Plaster Walls and Ceilings	1-4
Port	12" VFTs	Assumed	All Non-Certified Portables	1-4
Port	Linoleum	Assumed	Restroom Portables	1-4 X REPAIR COVING.
Port	Drywall	Assumed	All Non-Certified Portables (behind tagboard)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Marigold Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1	Tran panl	Assumed	Both boilers in Main B/R	1-4
1	9" VFT	1-5%	Room 12 & rest of wing	1-4
1	PW Str	60-65%	B/R Room	1-4
3	9" VFT	1-5%	Room 17 & rest of unit	1-4
3	Tran panl	Assumed	Above glass panels	1-4
4	Tran panl	Assumed	Above windows	1-4
4	9" VFT	1-5%	Lib/staff & classrooms	1-4 Carpeted
5	9" VFT	1-5%	Kit, MPR, AV store, Fac. RR	1-4
5	Cold box ceiling	30-35%	Cold Box	1-4
5	Plaster	Assumed	Kitchen & Restroom	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Marigold Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
All	Drywall	1-5 skim coat	All Non-Plaster Walls and Ceilings	1-4
Port	12" VFTs	Assumed	All Non-Certified Portables	1-4
Port	Linoleum	Assumed	Restroom Portables	1-4
Port	Drywall	Assumed	All Non-Certified Portables (behind tagboard)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)