

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Marigold Elementary School

Building: 1

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4) ←	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4) Same	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) →	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1)	N
M	12" ACT	97	ASSUMED	850 S	GIRLS & BOYS RESTROOMS	(2) MINOR WATER DAMAGE ON ACT'S IN BOYS & GIRLS RESTROOMS. (2) (5) (2) (4) 12/27/01 PEELING	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) Same →	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(1) (4)	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Marigold Elementary School

Building: 3

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1)(4) SAME 11/24/03	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(2)(5) BROKEN 11/24/03	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1)(4) SAME 11/24/03	N

School: Marigold Elementary School

Building: 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14. (7) 12" VFT REPLACED & 9" VFT IN THE LIBRARY. SAME 11/24/03	N/A N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(2)(5) BROKEN 11/24/03	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1)(12) 9" VFT WAS REPLACED WITH 12" VFT.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1)(4) APPROXIMATELY 18 PANELS. SAME 11/24/03	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Marigold Elementary School

Building: 5

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, & STORAGE	(1) (4) SAME 11/24/03	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(2) (5) PEELING 11/24/03	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN & RESTROOMS	(1) (4) 3 4 Tiles SAME 11/24/03	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI PURPOSE ROOM	(1) (4) SAME 11/24/03	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), & HO ROOM	(2) (5) BROKEN	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-24-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Marigold Elementary School

Building: Portables

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES	(1) (4)	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES	(2) (5) BROKEN 11/24/03	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(2) (5) 11/24/03	N
					<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;">                     Letters on File For 89 &amp; 90 Portables                 </div>	(12) THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Marigold Elementary School

Building: 1

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4) ←	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4) Same	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) ↓	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1)	N
M	12" ACT	97	ASSUMED	850 S	GIRLS & BOYS RESTROOMS	(2) MINOR WATER DAMAGE ON ACT'S IN BOYS & GIRLS RESTROOMS. (2) (4) 12/27/01	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) Same ↓	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Marigold Elementary School

Building: 3

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) <i>Same</i>	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1) (4)	N

School: Marigold Elementary School

Building: 4

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14. (7) 12" VFT REPLACED & 9" VFT IN THE LIBRARY.	N/A N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4) <i>Same</i>	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) 9" VFT WAS REPLACED WITH 12" VFT.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N

**CONDITION CODE**

**General Condition:** (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
**Change in Condition:** (4) No (5) Yes (If Yes, explain under comments)  
**Abated:** (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
**Miscellaneous:** (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Marigold Elementary School

Building: 5

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, & STORAGE	(1) (4) ←	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(1) (4) Same	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN & RESTROOMS	(1) (4) 3 4 Tiles	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI PURPOSE ROOM	(1)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), & HO ROOM	(1) →	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Marigold Elementary School

Building: Portables

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES	(1) (4)	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES	(1)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
					<div style="border: 1px solid black; padding: 5px; width: fit-content;">                     Letters on File For 89 &amp; 90 Portables                 </div>	(12) THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**





**Forensic Analytical**  
Analytical Report

**Preliminary FAX**

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist  
Ron Ferers

2455 Carmichael Drive  
Chico, CA 95928

**Client ID:** 2921  
**Report Number:** B047991  
**Date Received:** 02/28/03  
**Date Analyzed:** 03/03/03  
**Date Printed:** 03/03/03

**Job ID / Site:** Marigold Elementary

**FASI Job ID:** 2921-59

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
#1	10216857						
		Layer: White Drywall	ND				
		Layer: Beige Skimcoat/Joint Compound	Chrysotile	2%			
		Layer: Paint	ND				

Total Composite Values of Fibrous Components: **Asbestos:(Trace)**  
Cellulose (10%)    Fibrous Glass (5%)

#2	10216858						
		Layer: White Drywall	ND				
		Layer: Beige Skimcoat/Joint Compound	Chrysotile	2%			
		Layer: Paint	ND				

Total Composite Values of Fibrous Components: **Asbestos:(Trace)**  
Cellulose (10%)    Fibrous Glass (5%)

*cc: Mary  
Kip  
Bob  
Rob  
Bender (3)  
Jill*

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written consent from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

**COPY**



BULK SAMPLE REQUEST FORM

<b>CLIENT NAME &amp; ADDRESS:</b>  2921 -59 Chlco Unified School District 2455 Carmichael Drive Chico, CA 95928	<b>PHONE:</b> (916) 891- <b>FAX:</b> (916) 891-3190	<b>DATE:</b> 2/27/03
	Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	
	<b>PLM:</b> Standard / Point Count	<b>Results Needed:</b>  Gravimetry Prep
	<b>TEM:</b> QUAL. / QUANT. / WATER AA/Flame AA/Furnace ICP <b>METALS:</b>	
<b>CONTACT:</b> ROB PETERS		
<b>P.O.#</b>	<b>JOB #</b>	
<b>SITE:</b> MARIGOLD BLVD.		

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
# 1	2/27/03	UNIT 1 RESTROOM SKYLIGHT WELL
# 2	2/27/03	UNIT 1 RESTROOM SKYLIGHT WELL

<b>Sampled by:</b> ROB PETERS	<b>Date:</b> 2/27 <b>Time:</b> 10:15 AM
<b>Relinquished by:</b> <b>Date/Time:</b>	<b>Received By:</b> [Signature] 2/28/03 10:30 Fed ex <b>Date/Time:</b> <b>Sealed Condition (circle one) YES / NO</b>
<b>Relinquished by:</b> <b>Date/Time:</b>	<b>Received By:</b> <b>Date/Time:</b> <b>Sealed Condition (circle one) YES / NO</b>

Maintenance and Operations  
2455 Carmichael Drive  
Chico, CA 95928  
Phone: (530) 891-3195  
Fax: (530) 891-3190

# Chico Unified School District

February 27, 2003

Forensic Analytical Specialties, Inc.  
3777 Depot Road, Suite 409  
Hayward, CA 94545

Re: Marigold Elementary School

To Whom It May Concern:

Please test the enclosed samples from the Marigold Elementary School Unit #1 Restroom Skylight Well for asbestos. We would like a 24-hour turn around on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Marigold Elementary School  
Location: Unit 1 Restroom Skylight Well  
Date Sampled: February 27, 2003  
Number of Samples: Two (2)

Sample Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters  
Maintenance/Operations Supervisor

RP:dlg  
Enclosure

*John J. Fed -  
2/28/03 10:30pm*