

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit: C,E,F

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (2) ROOM 8 DOORWAY TILES CRUSHED	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4) NEED MORE SIGNAGE	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1) (4)	N
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(2) (4) MINOR WATER DAMAGE ON ACT'S IN BOY'S & GIRL'S RESTROOMS.	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(12) UNABLE TO LOCATE THE MATERIAL.	N
M	PLASTER	101	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(1) (4) (11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4)	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	ASSUMED	305 S	STAFF LOUNGE	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(2) (6) CEILING CRACK I CORNER	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 15-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES 18A-22	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES 18A-22	(1) (4)	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES 18A-22	(1) (4)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/08/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	ASSUMED	180 S	PORTABLES 23 & 24	(1) (4)	N
M	TAGBOARD	103	ASSUMED	960 S	PORTABLES 23 & 24	(1) (4)	N
M	2' X 4' FCP'S (FIBERGLASS)	104	ASSUMED	900 S	PORTABLES 23 & 24	(1) (4)	N
M	CARPET	105	ASSUMED	780 S	PORTABLES 23 & 24	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit: C,E,F

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(5) (6) <del>ROOM 8 DOORWAY TILES CRUSHED</del>	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4) NEED MORE SIGNAGE	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1) (4)	N
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(5) (6) <del>MINOR WATER DAMAGE ON ACT'S IN BOY'S &amp; GIRL'S RESTROOMS.</del>	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(12) UNABLE TO LOCATE THE MATERIAL.	N
M	PLASTER	101	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**



**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(1) (4) (11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4)	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	ASSUMED	305 S	STAFF LOUNGE	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(11) LOCKED	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 15-22

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES 18A-22	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES 18A-22	(1) (4)	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES 18A-22	(1) (4)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BLUE	102	ASSUMED	180 S	PORTABLES 23 & 24	(1) (4)	N
M	TAGBOARD	103	ASSUMED	960 S	PORTABLES 23 & 24	(1) (4)	N
M	2' X 4' FCP'S (FIBERGLASS)	104	ASSUMED	900 S	PORTABLES 23 & 24	(1) (4)	N
M	CARPET	105	ASSUMED	780 S	PORTABLES 23 & 24	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit: C,E,F

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	8	1-5%	5,728 S	CLASSROOMS 3-5 & 7-9	(5) (6) ROOM & DOORWAY TILES CRUSHED	N
T	PIPE WRAP STRAIGHT	10	60-65%	150 S	BOILER ROOM	(1) (4) NEED MORE SIGNAGE	N
M	12" VFT	95	ASSUMED	160 S	CLASSROOMS 6A & 6B	(1) (4)	N
M	2' X 4' FCP	96	ASSUMED	1,800 S	CLASSROOMS 6A, 6B, & 10	(1) (4)	N
M	12" ACT	97	ASSUMED	850 S	GIRL'S & BOY'S RESTROOMS	(5) (6) MINOR WATER DAMAGE ON ACTS IN BOY'S & GIRL'S RESTROOMS.	N
M	12" ACT	98	ASSUMED	5,728 S	CLASSROOMS 3-5 & 7-9	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	50 S	MAIN BOILER ROOM AT BOILERS	(12) UNABLE TO LOCATE THE MATERIAL.	N
M	PLASTER	101	ASSUMED	600 S	BOY'S & GIRL'S RESTROOMS	(1) (4)	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit H

Material Class	Material	Hom. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition, Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	4,500 S	ALL ROOMS	(1) (4) (11) THE 9" VFT COULD BE UNDER THE CARPET IN CLASSROOMS 11, 13, & 14.	N
M	2' X 4' FCP	92	ASSUMED	4,500 S	ALL ROOMS	(1) (4)	N
M	12" VFT	93	ASSUMED	900 S	LIBRARY	(1) (12) (4) 9" VFT WAS CONCEALED BY CARPET AND 12" VFT WAS REPLACED WITH 12" VFT WHITE WITH BLUE.	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE WINDOWS	(1) (4) APPROXIMATELY 18 PANELS.	N
M	12" VFT WHITE W/BUE	150	ASSUMED	305 S	STAFF LOUNGE	(1) (4)	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 15-22

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	80	ASSUMED	2,400 S	PORTABLES 18A-22	(1) (4)	N
M	DRYWALL	81	ASSUMED	10,000 S	PORTABLES 18A-22	(1) (4)	N
M	2' X 4' FCP	89	ASSUMED	8,000 S	PORTABLES 18A-22	(1) (4)	N
M	LINOLEUM	100	ASSUMED	500 S	RESTROOM PORTABLES	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Building: Portables 23 & 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	12" VFT BLUE	102	ASSUMED	180 S	PORTABLES 23 & 24	(1) (4)	N
M	TAGBOARD	103	ASSUMED	960 S	PORTABLES 23 & 24	(1) (4)	N
M	2' X 4' FCP'S (FIBERGLASS)	104	ASSUMED	900 S	PORTABLES 23 & 24	(1) (4)	N
M	CARPET	105	ASSUMED	780 S	PORTABLES 23 & 24	(1) (4)	N
						NOTE: THE DISTRICT MUST OBTAIN CERTIFICATION LETTERS ON ANY PORTABLES MANUFACTURED AFTER OCTOBER 12, 1988.	

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**



**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

Inspector: Leroy Christophersen

Unit B

District: Chico Unified School District

School: Marigold Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(11) LOCKED	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT CREAM	2	1-5%	3,160 S	KITCHEN, MULTI PURPOSE ROOM, STORAGE, PIP ROOM, AND HEALTH OFFICE	(1) (4)	N
M	COLD BOX CEILING	6	30-35%	20 S	COLD BOX	(11) LOCKED	N
S	PLASTER	75	ASSUMED	1,000 S	KITCHEN AND RESTROOMS	(1) (4)	N
M	12" ACT	90	ASSUMED	2,500 S	MULTI-PURPOSE ROOM	(1) (4)	N
M	2' X 4' FCP	91	ASSUMED	5,000 S	PRINCIPALS OFFICE, OFFICE, PIP ROOM, CLASSROOM A (FKA LIBRARY), AND HEALTH OFFICE	(1) (4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Marigold Elementary School

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Fiabile Yes/No
M	9" VFT	2	1-5%	2,800 S	CLASSROOMS 1 & 2	(1)(4)	N
M	2' X 4' FCP	94	ASSUMED	1,800 S	CLASSROOMS 1 & 2	(1)(4)	N
M	TRANSITE PANELS	99	ASSUMED	300 S	ABOVE GLASS PANELS	(1)(4)	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**