

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL McManus Elementary INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
MAT.#				
A	Wall plas	5-10	Kitchen, Admin., halls	1-4
A	9" VFT	5-10	Kitchen	1-4
A	TOC	1-5	Kitchen pantry	1-4
A	PW & Debr	10-15	Admin attic above men's rr	7 July '93
A	PW Str	40-45	Kitchen attic	7 July '93
A	Air cell	Assumed	Custodial closet	7 July '93
A	Tran pipe	Assumed	Kitchen heater closet	1-4
B	Wall plas	5-10	RR, hall area, boiler room	1-4
B	TOC	1-5	Custodial room & hall	1-4
B	Mud Jnt	25-30	Main boiler room	7
B	Counter-top lino	1-5	Classroom areas	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL McManus Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	9" VFT	1-5	Rm 9 & rest of wing	7 July '93
B	Air Cell	Assumed	Main B/R room, custodial room attic	1-4
B	Tank Wrap	Assumed	Main B/R room	1-4
B	B/R air cell	Assumed	Main B/R room	1-4
B	Pipewrap	60-70%	In attics and walls	11
C	Duct wrap	70-75	Sm B/R room, attic	7 July '93
C	Wall plas	5-10	Old RR, B/R room	Retested - no asbestos
C	9" VFT	5-10	Rm 2 and rest of wing	7 July '93
D	Wall plas	5-10	Cust. rm, hall, RR area	1-4
D	9" VFT	5-10	Hall, classroom areas	1-4
D	TOC	1-5	Hall & custodial room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL McManus Elementary INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	PW	20-25		Custodial room	1-4 PW Str-fiber., PW Cnr-ACM
Port	Drywall	Assumed		Behind tagboard	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 2/23/99

SCHOOL McManus Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Wall plas	5-10	Kitchen, Admin., halls	1-4
A	9" VFT	5-10	Kitchen	1-4
A	TOC	1-5	Kitchen pantry	1-4
A	PW & Debr	10-15	Admin attic above men's rr	7 July '93
A	PW Str	40-45	Kitchen attic	7 July '93
A	Air cell	Assumed	Custodial closet	7 July '93
A	Tran pipe	Assumed	Kitchen heater closet	1-4
B	Wall plas	5-10	RR, hall area, boiler room	1-4
B	TOC	1-5	Custodial room & hall	1-4
B	Mud Jnt	25-30	Main boiler room	7
B	Counter-top lino	1-5	Classroom areas	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



DISTRICT Chico Unified School District DATE 2/23/99

SCHOOL McManus Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	9" VFT	1-5	Rm 9 & rest of wing	7 July '93
B	Air Cell	Assumed	Main B/R room, custodial room attic	1-4
B	Tank Wrap	Assumed	Main B/R room	1-4
B	B/R air cell	Assumed	Main B/R room	1-4
B	Pipewrap	60-70%	In attics and walls	11
C	Duct wrap	70-75	Sm B/R room, attic	7 July '93
C	Wall plas	5-10	Old RR, B/R room	Retested - no asbestos
C	9" VFT	5-10	Rm 2 and rest of wing	7 July '93
D	Wall plas	5-10	Cust. rm, hall, RR area	1-4
D	9" VFT	5-10	Hall, classroom areas	1-4
D	TOC	1-5	Hall & custodial room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 2/23/99

SCHOOL McManus Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	PW	20-25	Custodial room	1-4 PW Str-fiber., PW Cnr-ACM
Port	Drywall	Assumed	Behind tagboard	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)