

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE Dec. 5, 1990

SCHOOL Parkview Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(1) Good 4
B	9" VFT Gn	1-5	All rooms (white/brown)	(1) Good 4
B	Tran panl	Assumed	Under Windows	(1) Good 4
C	9" VFT Gn	1-5	Room 8 & rest of wing	(1) Good 4
C	Tran panl	Assumed	Under Windows	(1) Good 4
D	PW Cnr lg	20-25	Boiler Room	(2)-(5) <10% 4" tear by gate valve, cracks above 2nd sign, wrap coming off
D	Ceill Plas	1-5	Boys & Girls restrooms	(1) Good 4
E	PW Cnr sm	15-20	Boiler Room	Couldn't find
E	Ceill Plas	1-5	Staff Room	(1) Good 4
E	Tran panl	Assumed	Under Windows	(1) Good 4
E*	VFT blue		Staff room (storage)	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 3

DISTRICT Chico Unified School District DATE Dec. 5, 1990SCHOOL Parkview Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	No Test
E*	VFT gn, wh		Office & Hall	No Test
F	9" VFT bg	1-5	Library work room	(1) Good 4
F	PW Cnr	1-5	RR attic	(1) Good 4
G	PW Cnr	5-10	Rm 18	Nothing found
H	PW Cnr sm	15-20	Rooms off stage	(2) Damaged (4) <1% Left side
H	Ceill Plas	1-5	MPR	(1) Good 4
H	12" VFT r	1-5	Kitchen	(1) Good 4
H	PW Str	10-15	MPR Stage West	(1) Good 4
H	Vent Duct connector	Assumed	Rooms off stage	(1) Good 4
H	Tran pipe	Assumed	MPR Kitchen	(1) Good 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 5, 1990

SCHOOL Parkview Elementary INSPECTOR Robert Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS
 BLDG. MAT.#

H	PW Str	10-15	MPR Stage West	(1) Good 4
H	Vent Duct connector	Assumed	Rooms off stage	(1) Good 4
H	Tran pipe	Assumed	MPR kitchen	(1) Good 4
H*	VFT Beige		MPR	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 10, 1990

SCHOOL Parkview Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(1) Good
B	9" VFT Gn	1-5	All rooms (white/brown)	(1) Good
B	Tran panl	Assumed	Under Windows	(1) Good
C	9" VFT Gn	1-5	Room 8 & rest of wing	(1) Good
C	Tran panl	Assumed	Under Windows	(1) Good
D	PW Cnr lg	20-25	Boiler Room	(2), 5 <1%
D	Ceill Plas	1-5	Boys & Girls restrooms	(1) Good
E	PW Cnr sm	15-20	Boiler Room	Couldn't find
E	Ceill Plas	1-5	Staff Room	(1) Good
E	Tran panl	Assumed	Under Windows	(1) Good
E*	VFT blue		Staff room (storage)	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 10, 1990

SCHOOL Parkview Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	No Test
E*	VFT gn, wh		Office & Hall	No Test
F	9" VFT bg	1-5	Library work room	(1) Good
F	PW Cnr	1-5	RR attic	(1) Good
G	PW Cnr	5-10	Rm 18	Nothing found
H	PW Cnr sm	15-20	Rooms off stage	(2) Damaged (5) <1% Left side
H	Ceill Plas	1-5	MPR	(1) Good
H	12" VFT r	1-5	Kitchen	(1) Good
H	PW Str	10-15	MPR Stage West	(1) Good
H	Vent Duct connector	Assumed	Rooms off stage	(1) Good
H	Tran pipe	Assumed	MPR Kitchen	(1) Good

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Parkview Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15	MPR Stage West	(1) Good
H	Vent Duct connector	Assumed	Rooms off stage	(1) Good
H	Tran pipe	Assumed	MPR kitchen	(1) Good
H*	VFT Beige		MPR	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)