

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: A

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
PLASTER	3	CUST/STRG/ADMIN OFFs	00-00	2700 S	N
AC PLASTER	4	ADMIN & CORRIDOR	01-05	3200 S	N
9" VFTs	5	Admin & Corridor	01-05	1000 S	N
12" VFTS	14	STAFF ROOM	00-00	14 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: B

Material	Homog. Mat. #	Locations	% Asb	Footage Y or N	Friable?
9" VFTs	5	ENTIRE WING	01-05	4000 S	N
ACT	6	ALL ROOMS	00-00	4000 S	N
TRANS PANELS	99	BELOW WINDOWS	99-99 ASSUMED	1000 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: C

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
9" VFTs	5	ENTIRE WING	01-05	4000 S	N
ACT	6	ALL ROOMS	00-00	4000 S	N
TRANS PANELS	99	BELOW WINDOWS	99-99 ASSUMED	1000 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD

School: Parkview

Date Inspected: 04/16/92

BUILDING: D

Material	Homog. Mat. #	Locations	% Asb	Footage Y or N	Friable?
LRG PW (jnt?)	2	BLR RM	20-25	25 S	N
PLASTER	3	BOILER ROOM	00-00	4200 S	N
AC PLASTER	4	RRs (BOTH b & g)	01-05	300 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: E

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
SML PW CNR	1	BLR RM	15-20	14	N
AC PLASTER	4	STAFF RM	01-05	50 S	N
9" VFTS	5	Storage Room	01-05	150 S	N
ALL ROOMS	6	ACT	00-00	2766 S	N
Linoleum	75	Classrooms	00-00	200 S	N
TRANS PANELS	99	BELOW WINDOWS	99-99 ASSUMED	120 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: F

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
LIBRARY WK RM	11	ACT	00-00	150 S	N
FCP	12	LIBRARY	00-00	2200 S	N
9" VFTs	13	All RMs	01-05	5000 S	N
PW CNR	15	RR ATTIC	01-05	12	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD

School: Parkview

Date Inspected: 04/16/92

BUILDING: G

Material	Homog. Mat. #	Locations	% Asb	Footage Y or N	Friable?
BRN 12" VFT	16	RM 18	00-00	72 S	N
FCP	17	ALL ROOMS	00-00	3840 S	N
PW CNR	18	RM 18	05-10	20	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: H

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
SML PW CNR	1	ROOMS OFF STAGE	15-20	10	N
PLASTER	3	KITCHEN	00-00	1200 S	N
AC PLASTER	7	MPR	01-05	2176 S	N
9" VFT	8	MPR	01-05	2176 S	N
12" VFT	9	KITCHEN (RED)	01-05	544 S	N
PW STR	10	Rooms Off stage	10-15	30 S	N
TRANSITE PIPE	97	KITCHEN	99-99 ASSUMED	15 L	N
VENT DUCT CNT	98	ROOMS OFF STAGE	99-99 ASSUMED	4	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

Homogeneous Materials Record

School Dist: Chico USD

School: Parkview

Date Inspected: 04/16/92

BUILDING: Old Portable

Material	Homog. Mat. #	Locations	% Asb	Footage Y or N	Friable?
12" VFTs	78	By Sink	00-00	200 S	N

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

Hazard Management Services, Inc. Bulk Sample Analysis Request Form

AHERA THREE YEAR REINSPECTION SAMPLES

Please Send Results To: P.O. Box 576848 Modesto, CA 95357-6848

Samples Collected by: Michael Sharp on 04/16/92

Client: Chico Unified S.D. Site: Parkview

Turn Around Time: Extended, Results Needed By April 30th, if possible.

Sample Number	Material	Location
HMS-CUSD-PRKV-75	Linoleum	Unit E at entrance to west room.
	Result: None Detected	
HMS-CUSD-PRKV-76A	Drywall	Unit F
	Result: None Detected	
HMS-CUSD-PRKV-76B	Drywall	Unit F
	Result: None Detected.	
HMS-CUSD-PRKV-76C	Drywall	Unit F
	Result: Trace asbestos in Skim coat only	
HMS-CUSD-PRKV-77A	Drywall	Unit G
	Result: None Detected	
HMS-CUSD-PRKV-77B	Drywall	Unit G
	Result: None Detected.	
HMS-CUSD-PRKV-77C	Drywall	Unit G
	Result: None detected	
HMS-CUSD-PRKV-78A	12" vfts	Portable at entry
	Result: None detected	



Bulk Asbestos Analysis Summary

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client ID: 1146
Report Number: 177331
Date Received: 04/21/92

P.O. Num:

Job ID: Chico Unified School District
Site: Parkview

Sample Number	Date Col.	Lab Num.	Asbestos Present	(Breakdown by type)
HMS-CUSD-PRKV-75 Unit E at entrance to West room, linoleum.	04/16/92	19220531	Non-Det.	
HMS-CUSD-PRKV-76A Unit F, drywall.	04/16/92	19220532	Non-Det.	
HMS-CUSD-PRKV-76B Unit F, drywall.	04/16/92	19220533	Non-Det.	
HMS-CUSD-PRKV-76C Unit F, drywall.	04/16/92	19220534	Trace	Chrysotile (Trace)
HMS-CUSD-PRKV-77A Unit G, drywall.	04/16/92	19220535	Non-Det.	
HMS-CUSD-PRKV-77B Unit G, drywall.	04/16/92	19220536	Non-Det.	
HMS-CUSD-PRKV-77C Unit G, linoleum.	04/16/92	19220537	Non-Det.	
HMS-CUSD-PRKV-78A Portable at entry, 12" VETS.	04/16/92	19220538	Non-Det.	

Analytical Method: 40 CFR 763, Subpart F, Appendix A (AMERL)

See Reverse for Explanation of Terms and Reporting Practices



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220531

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-75

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit E at entrance to vest room, linoleum.

Gross Description: Off-white linoleum with fibrous backing, brown adhesive and plaster.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %
Non-Det. %

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose
Fibrous Glass
Synthetic

40-45 %
Trace %
Trace %

40-45 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

55-60 %

Janis Oeschman

Janis Oeschman, Director of Laboratory Services, Hazard Management Services, Inc.

Analyst's initials: J.O. Date: 04/21/92, Report # 177331

See Reverse for Explanation of Terms and Reporting Practices



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220532

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-76A

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing, brown
fibrous cellulose and paint.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Non-Det.

Non-Det.

Amosite

Non-Det.

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

45-50 %

Cellulose

45-50 %

Fibrous Glass

Trace %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

50-55 %

Janis Oestman

Janis Oestman, Director of Laboratory Services, Superior Laboratories

Analyst: [Signature] Analyst: [Signature] Analyst: [Signature]

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 800/827-EAST Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.

Modesto Location

P.O. Box 576848

Modesto, CA 95357-6848

Client Number: 1146

Report Number: 177331

Date Received: 04/21/92

Lab Number: 19220533

Date Collected: 04/16/92

Sample Number: HMS-CUSD-FRMV-76B

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing and skin coat.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Non-Det.

Non-Det.

Amosite

Non-Det.

%

%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

35-40 %

Cellulose

30-35 %

Fibrous Glass

1-5 %

%

%

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

60-65 %

Janis Friedman

Janis Friedman, Director of Laboratory Services, Environmental Sciences

Analysed at: 4000 1st St., Suite 101, Hayward, CA 94541 (AMSL)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 • 800/827-FAS • Fax: 510/887-4218

Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 • Fax: 310/763-8684



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220534

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-76C

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing, skim coat and paint.

Comments: Asbestos in skim coat (trace). Composite reported.

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Trace

Trace

Amosite

Non-Det.

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

35-40

Cellulose

30-35

Fibrous Glass

1-5

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

60-65

Janis Jacobman

Janis Jacobman, Director of Laboratory Services, Hayward Laboratory

Analysed under 40 X magnification, Subject F, Appendix A (ASBESTOS)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 • 800/827-FAS • Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 • Fax: 310/763-8684



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220535

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-77A

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit G, drywall.

Gross Description: White drywall plaster with fibrous backing, skin coat, fibrous weave backing and paint.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Non-Det. %

Non-Det. %

Amosite

Non-Det. %

%

%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

40-45 %

Cellulose

35-40 %

Fibrous Glass

1-5 %

%

%

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

55-60 %

Janis Dickman

Janis Dickman, Director of Laboratory Services, Bayview Laboratory

Analysed and found to contain 0% asbestos, 40-45% cellulose, 1-5% fibrous glass, 55-60% non-fibrous material.

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 800/827-FASI Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684



Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220536

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-77B

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit G, drywall.

Gross Description: White drywall plaster with fibrous backing, fibrous waste and paint.

Contents:

Microscopic Description

TOTAL ASBESTOS PRESENT.

Chrysotile

2000 5 25

37-50-264.1

Nov - Dec. 2

4

5

Non-Det. 8

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

30-35 9

Cellulose

30-35

Fibrous Glass

Non-Det. %

2

5

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

65-70 2

Janis Dieckman

James Franklin, Director of Laboratory Services, Bureau of Agriculture

Revised: 10/17/11, 10/18/11, 10/19/11, 10/20/11, 10/21/11, 10/22/11, 10/23/11, 10/24/11, 10/25/11, 10/26/11, 10/27/11, 10/28/11, 10/29/11, 10/30/11, 10/31/11, 11/1/11, 11/2/11, 11/3/11, 11/4/11, 11/5/11, 11/6/11, 11/7/11, 11/8/11, 11/9/11, 11/10/11, 11/11/11, 11/12/11, 11/13/11, 11/14/11, 11/15/11, 11/16/11, 11/17/11, 11/18/11, 11/19/11, 11/20/11, 11/21/11, 11/22/11, 11/23/11, 11/24/11, 11/25/11, 11/26/11, 11/27/11, 11/28/11, 11/29/11, 11/30/11, 12/1/11, 12/2/11, 12/3/11, 12/4/11, 12/5/11, 12/6/11, 12/7/11, 12/8/11, 12/9/11, 12/10/11, 12/11/11, 12/12/11, 12/13/11, 12/14/11, 12/15/11, 12/16/11, 12/17/11, 12/18/11, 12/19/11, 12/20/11, 12/21/11, 12/22/11, 12/23/11, 12/24/11, 12/25/11, 12/26/11, 12/27/11, 12/28/11, 12/29/11, 12/30/11, 12/31/11, 1/1/12, 1/2/12, 1/3/12, 1/4/12, 1/5/12, 1/6/12, 1/7/12, 1/8/12, 1/9/12, 1/10/12, 1/11/12, 1/12/12, 1/13/12, 1/14/12, 1/15/12, 1/16/12, 1/17/12, 1/18/12, 1/19/12, 1/20/12, 1/21/12, 1/22/12, 1/23/12, 1/24/12, 1/25/12, 1/26/12, 1/27/12, 1/28/12, 1/29/12, 1/30/12, 1/31/12, 2/1/12, 2/2/12, 2/3/12, 2/4/12, 2/5/12, 2/6/12, 2/7/12, 2/8/12, 2/9/12, 2/10/12, 2/11/12, 2/12/12, 2/13/12, 2/14/12, 2/15/12, 2/16/12, 2/17/12, 2/18/12, 2/19/12, 2/20/12, 2/21/12, 2/22/12, 2/23/12, 2/24/12, 2/25/12, 2/26/12, 2/27/12, 2/28/12, 2/29/12, 2/30/12, 3/1/12, 3/2/12, 3/3/12, 3/4/12, 3/5/12, 3/6/12, 3/7/12, 3/8/12, 3/9/12, 3/10/12, 3/11/12, 3/12/12, 3/13/12, 3/14/12, 3/15/12, 3/16/12, 3/17/12, 3/18/12, 3/19/12, 3/20/12, 3/21/12, 3/22/12, 3/23/12, 3/24/12, 3/25/12, 3/26/12, 3/27/12, 3/28/12, 3/29/12, 3/30/12, 3/31/12, 4/1/12, 4/2/12, 4/3/12, 4/4/12, 4/5/12, 4/6/12, 4/7/12, 4/8/12, 4/9/12, 4/10/12, 4/11/12, 4/12/12, 4/13/12, 4/14/12, 4/15/12, 4/16/12, 4/17/12, 4/18/12, 4/19/12, 4/20/12, 4/21/12, 4/22/12, 4/23/12, 4/24/12, 4/25/12, 4/26/12, 4/27/12, 4/28/12, 4/29/12, 4/30/12, 5/1/12, 5/2/12, 5/3/12, 5/4/12, 5/5/12, 5/6/12, 5/7/12, 5/8/12, 5/9/12, 5/10/12, 5/11/12, 5/12/12, 5/13/12, 5/14/12, 5/15/12, 5/16/12, 5/17/12, 5/18/12, 5/19/12, 5/20/12, 5/21/12, 5/22/12, 5/23/12, 5/24/12, 5/25/12, 5/26/12, 5/27/12, 5/28/12, 5/29/12, 5/30/12, 5/31/12, 6/1/12, 6/2/12, 6/3/12, 6/4/12, 6/5/12, 6/6/12, 6/7/12, 6/8/12, 6/9/12, 6/10/12, 6/11/12, 6/12/12, 6/13/12, 6/14/12, 6/15/12, 6/16/12, 6/17/12, 6/18/12, 6/19/12, 6/20/12, 6/21/12, 6/22/12, 6/23/12, 6/24/12, 6/25/12, 6/26/12, 6/27/12, 6/28/12, 6/29/12, 6/30/12, 7/1/12, 7/2/12, 7/3/12, 7/4/12, 7/5/12, 7/6/12, 7/7/12, 7/8/12, 7/9/12, 7/10/12, 7/11/12, 7/12/12, 7/13/12, 7/14/12, 7/15/12, 7/16/12, 7/17/12, 7/18/12, 7/19/12, 7/20/12, 7/21/12, 7/22/12, 7/23/12, 7/24/12, 7/25/12, 7/26/12, 7/27/12, 7/28/12, 7/29/12, 7/30/12, 7/31/12, 8/1/12, 8/2/12, 8/3/12, 8/4/12, 8/5/12, 8/6/12, 8/7/12, 8/8/12, 8/9/12, 8/10/12, 8/11/12, 8/12/12, 8/13/12, 8/14/12, 8/15/12, 8/16/12, 8/17/12, 8/18/12, 8/19/12, 8/20/12, 8/21/12, 8/22/12, 8/23/12, 8/24/12, 8/25/12, 8/26/12, 8/27/12, 8/28/12, 8/29/12, 8/30/12, 8/31/12, 9/1/12, 9/2/12, 9/3/12, 9/4/12, 9/5/12, 9/6/12, 9/7/12, 9/8/12, 9/9/12, 9/10/12, 9/11/12, 9/12/12, 9/13/12, 9/14/12, 9/15/12, 9/16/12, 9/17/12, 9/18/12, 9/19/12, 9/20/12, 9/21/12, 9/22/12, 9/23/12, 9/24/12, 9/25/12, 9/26/12, 9/27/12, 9/28/12, 9/29/12, 9/30/12, 10/1/12, 10/2/12, 10/3/12, 10/4/12, 10/5/12, 10/6/12, 10/7/12, 10/8/12, 10/9/12, 10/10/12, 10/11/12, 10/12/12, 10/13/12, 10/14/12, 10/15/12, 10/16/12, 10/17/12, 10/18/12, 10/19/12, 10/20/12, 10/21/12, 10/22/12, 10/23/12, 10/24/12, 10/25/12, 10/26/12, 10/27/12, 10/28/12, 10/29/12, 10/30/12, 10/31/12, 11/1/12, 11/2/12, 11/3/12, 11/4/12, 11/5/12, 11/6/12, 11/7/12, 11/8/12, 11/9/12, 11/10/12, 11/11/12, 11/12/12, 11/13/12, 11/14/12, 11/15/12, 11/16/12, 11/17/12, 11/18/12, 11/19/12, 11/20/12, 11/21/12, 11/22/12, 11/23/12, 11/24/12, 11/25/12, 11/26/12, 11/27/12, 11/28/12, 11/29/12, 11/30/12, 12/1/12, 12/2/12, 12/3/12, 12/4/12, 12/5/12, 12/6/12, 12/7/12, 12/8/12, 12/9/12, 12/10/12, 12/11/12, 12/12/12, 12/13/12, 12/14/12, 12/15/12, 12/16/12, 12/17/12, 12/18/12, 12/19/12, 12/20/12, 12/21/12, 12/22/12, 12/23/12, 12/24/12, 12/25/12, 12/26/12, 12/27/12, 12/28/12, 12/29/12, 12/30/12, 12/31/12, 1/1/13, 1/2/13, 1/3/13, 1/4/13, 1/5/13, 1/6/13, 1/7/13, 1/8/1

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 31777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 • 800/827-4ASI Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220537

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-77C

P.O. Name:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit G, linoleum.

Gross Description: Fibrous backing with skim coat, fibrous weave
backing and paint.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Non-Det. %

Non-Det. %

Amosite

Non-Det. %

%

%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

30-35 %

Cellulose

30-35 %

Fibrous Glass

Non-Det. %

%

%

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

65-70 %

Janis Dickman

Janis Dickman, Director of Laboratory Services, Bayview Laboratory

Analyst's initials: 40 CSD 700, Subject F, Appendix A (XRTM)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 • 800/827-FASL Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8664



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220538

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-78A

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Portable at entry, 12" VFTS.

Gross Description: White tile with yellow adhesive.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %

Non-Det. %

%

%

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose
Fibrous Glass

1-5 %

Non-Det. %

%

%

1-5 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

95-99 %

Janis Fischman

Janis Fischman, Director of Laboratory Services, Hayward Laboratory

Analytical methods 40 CFR 763, Subpart F, Appendix B (AHSI)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 • 800/827-EASI Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684

DISTRICT Chico Unified SCHOOL Parkview

[illegible]

DISTRICT	SCHOOL
Chicago Unified	Parkview

ADDRESS

[illegible]

DISTRICT	SCHOOL	Parkview
Chicago Unified		

ADDRESS[illegible]

DISTRICT	SCHOOL	Part view
Chicago Unified		

ADDRESS

[illegible]

DISTRICT	SCHOOL	Parkview
Chico unified		

ADDRESS[illegible]

DISTRICT	SCHOOL	Parkview
Chicago Unified		

ADDRESS[illegible]

DISTRICT	SCHOOL
Union Unified	Parkview 3

ADDRESS

[illegible]

HOMOGENEOUS MATERIAL RECORDS

DISTRICT Chico Unified SCHOOL Parkview

ADDRESS _____

BLDG.	MAT. CLASS.	MATERIAL	HOMOG. SAMPLE		LOCATION	% ASBESTOS	FOOTAGE FT ² OF LF	PRIABLE	
			MAT. #	NUMBER				YES	NO
H	TSE	Small dia PW CNR	01	01	Rooms off Stage	15-20	10 JNTS		X
H	SMA	PLASTER	03	03A-E	Kitchen	<1	1200 #		X
H	Surf	ACOUSTIC PLASTER	07	07A-C	MPR	1-5	3,176 #		X
H	Misc	Red 12" VFT	09	09	Kitchen	1-5	544 #		X
H	TSE	PW STR	10	10	MPR Stage west	10-15	18 LF		X
H	TSE	VENT DUCT Conch	98	NS	Rooms off Stage	Assumed	4 ENTRES		X
It	Misc	TRANSITE PIPE	97	NS	MPR Kitchen	Assumed	15 #		X
PORT					NO ACBM				
NEW PORT					NO ACBM				

HMS, INC.
HAZARD MANAGEMENT SERVICES, INC.

CHICO UNIFIED SCHOOL DISTRICT
PARKVIEW ELEMENTARY SCHOOL
AHERA THREE-YEAR REINSPECTION SUMMARY
APRIL, 1992

Attached you will find a computer print-out of your original "Homogeneous Materials Record Sheets". You will find these sheets easier to read than the original copies. If additional samples were collected at this site, the results are listed at the end of the new "homogeneous" sheets. A comment on drywall sampling and lab accreditation sheets are added as appropriate.

At this site all previously or currently identified asbestos-containing materials were in good condition, i.e., non-friable.

We have given you a new index to insert into your management plan to account for new sections VIII and IX. We have added section VIII in which you should include results of your six-month inspections. We have also included a sheet on drywall sampling with recommendations on handling drywall. We also want to remind you that new buildings or portables must either be inspected or exempted by letter by your architect or builder.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: A

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
AC PLASTER	4	ADMIN & CORRIDOR	01-05	3200 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	5	Admin & Corridor	01-05	1000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: B

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	5	ENTIRE WING	01-05	4000 S	1-4
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

TRANS PANELS	99	BELOW WINDOWS	01-99	1000 S	1-4
			(ASSUMED)		
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **C**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	5	ENTIRE WING	01-05	4000 S	1-4

3 Year Inspection Notes:

Condition of Material: **GOOD**

Change in Condition? **NO** Abated? **NO**

Comments:

TRANS PANELS	99	BELOW WINDOWS	01-99 (ASSUMED)	1000 S	1-4
--------------	----	---------------	--------------------	--------	-----

3 Year Inspection Notes:

Condition of Material: **GOOD**

Change in Condition? **NO** Abated? **NO**

Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition: (N or 4) No (Y) Yes (Please explain)

Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: **MIKE SHARP**

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **D**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
LRG PW (jnt?)	2	BLR RM	20-25	25 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

AC PLASTER	4	RRs (BOTH b & g)	01-05	300 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **E**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
SML PW CNR	1	BLR RM	15-20	14	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
AC PLASTER	4	STAFF RM	01-05	50 S	0-
3 Year Inspection Notes: Condition of Material: MATERIAL NOT FOUND Change in Condition? NO Abated? NO Comments: Did not find, may not exist.					
9" VFTS	5	Storage Room	01-05	150 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
TRANS PANELS	99	BELOW WINDOWS	01-99 (ASSUMED)	120 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
 Change in Condition: (N or 4) No (Y) Yes (Please explain)
 Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: **MIKE SHARP**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **F**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	13	All RMs	01-05	5000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
PW CNR	15	RR ATTIC	01-05	12	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
Drywall	76	All Rooms	00-01 (TRACE)	3000 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Trace amount of asbestos in skim coat only.					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
 Change in Condition: (N or 4) No (Y) Yes (Please explain)
 Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: G

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
PW CNR	18	RM 18	05-10	20	1-4
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments: Above FCPs.					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/16/92

School: Parkview

BUILDING: H

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
SML PW CNR	1	ROOMS OFF STAGE	15-20	10	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
AC PLASTER	7	MPR	01-05	2176 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFT	8	MPR	01-05	2176 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
12" VFT	9	KITCHEN (RED)	01-05	544 S	0-1
3 Year Inspection Notes: Condition of Material: NO SURVEILLANCE DATA Change in Condition? NO Abated? Comments:					
PW STR	10	Rooms Off stage	10-15	30 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
TRANSITE PIPE	97	KITCHEN	01-99 (ASSUMED)	15 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **H**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
VDUCT CONNTR	98	ROOMS OFF STAGE	01-99	4	1-4
3 Year Inspection Notes:			(ASSUMED)		
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/16/92**

School: **Parkview**

BUILDING: **Old Portable**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
Drywall	80	Behind Tag Board	01-99	1500 S	1-4
3 Year Inspection Notes:			(ASSUMED)		
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: MIKE SHARP

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

UNIVERSITY OF CALIFORNIA BERKELEY UNIVERSITY EXTENSION

This is to certify that

MICHAEL C. SHARP

has attended the

AHERA Refresher Course for Asbestos Inspectors and
Management Planners
November 26, 1991

Certificate number:

1428

Valid until: November 26, 1992



Deloral DN.

Chair
Programs in Environmental Hazard
Management

UNIVERSITY OF CALIFORNIA BERKELEY UNIVERSITY EXTENSION

This is to certify that

MICHAEL C. SHARP

has attended the

AHERA Refresher Course for Asbestos Abatement Project Designers
October 22, 1991

Certificate number:

Valid until: October 22, 1992



Deloral DN.

Chair
Programs in Environmental Hazard
Management

SIX-MONTH SURVEILLANCE

Page 1 of 3

DISTRICT Chico Unified School DistrictDATE December 22, 1992SCHOOL Parkview ElementaryINSPECTOR Michael Fender *MF*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(1) Good 4
B	9" VFT Gn	1-5	All rooms (white/brown)	(2) (5) tiles broken in rm. 6
B	Tran panl	Assumed	Under Windows	(1) Good 4
C	9" VFT Gn	1-5	Room 8 & rest of wing	(1) Good 4
C	Tran panl	Assumed	Under Windows	(1) Good 4
D	PW Cnr lg	20-25	Boiler Room	(5)-(3) <25% 4" tear by gate valve, cracks above 2nd sign, wrap coming off
D	Ceill Plas	1-5	Boys & Girls restrooms	(1) Good 4
E	PW Cnr sm	15-20	Boiler Room	Couldn't find
E	Ceill Plas	1-5	Staff Room	(1) Good 4
E	Tran panl	Assumed	Under Windows	(1) Good 4
E*	VFT blue		Staff room (storage)	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 3

DISTRICT Chico Unified School District DATE December 22, 1992SCHOOL Parkview Elementary INSPECTOR Michael Fender *MF*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	No Test
E*	VFT gn,wh		Office & Hall	No Test
F	9" VFT bg	1-5	Library work room	(1) Good 4
F	PW Cnr	1-5	RR attic	(1) Good 4
G	PW Cnr	5-10	Rm 18	Nothing found
H	PW Cnr sm	15-20	Rooms off stage	(2) (4) <10%
H	Ceill Plas	1-5	MPR	(1) Good 4
H	12" VFT r	1-5	Kitchen	(1) Good 4
H	PW Str	10-15	MPR Stage West	(1) Good 4
H	Vent Duct connector	Assumed	Rooms off stage	(1) Good 4
H	Tran pipe	Assumed	MPR Kitchen	(1) Good 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DATE December 22, 1992

INSPECTOR Michael Fender

BLDG.	HOMOG.	ASBESTOS MATERIAL	MAT.#
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			
51			
52			
53			
54			
55			
56			
57			
58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
93			
94			
95			
96			
97			
98			
99			
100			

LOCATION

[illegible]

CONDITION CODES

GENERAL CONDITION:

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220532
Sample Number: HMS-CUSD-PRKV-76A
P.O. Num:
Job ID: Chico Unified School District
Site: [REDACTED]

Date Collected: 04/16/92

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing, brown
fibrous cellulose and paint.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Non-Det. %

Chrysotile

Non-Det. %

Amosite

Non-Det. %

%
%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

45-50 %

Cellulose

45-50

%

Fibrous Glass

Trace

%

%

%

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

50-55 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 753, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices



Bulk Material Analysis

Client:

Hazard Management Services, Inc.

Modesto Location

P.O. Box 576848

Modesto, CA 95357-6848

Client Number: 1146

Report Number: 177331

Date Received: 04/21/92

Lab Number: 19220533

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-76B

P.O. Num:

Job ID: Chico Unified School District

Site: Parkview

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing and skim coat.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Amosite

Non-Det. %

Non-Det. %

%

%

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose

Fibrous Glass

30-35

1-5

%

%

%

%

35-40 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

60-65 %

Janis Teichman
Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 703, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices



Forensic Analytical
Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220534
Sample Number: HMS-CUSD-PRKV-76C
P.O. Num:
Job ID: Chico Unified School District
Site: Parkview

Date Collected: 04/16/92

Location: Unit F, drywall.

Gross Description: White fibrous plaster with fibrous backing, skim coat and paint.

Comments: [REDACTED] Composite reported.

Macroscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Trace %
Non-Det. %
%
%

Trace %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose
Fibrous Glass

30-35 %
1-5 %
%
%

35-40 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

60-65 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart F, Appendix A (ANERA)

See Reverse for Explanation of Terms and Reporting Practices

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, California 94545 • Telephone: 510/887-8828 800/827-FASL Fax: 510/887-4218
Los Angeles Office: 19443 Laurel Park Road, Suite 101, Rancho Dominguez, California 90220 • Telephone: 310/763-2374 Fax: 310/763-8684



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220535

Date Collected: 04/16/92

Sample Number: HMS-CUSD-PRKV-77A

P.O. Num:

Job ID: Chico Unified School District

Site: [REDACTED]

Location: Unit G, drywall.

Gross Description: White drywall plaster with fibrous backing, skim coat, fibrous weave backing and paint.

Comments:

Microscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %

Non-Det. %

%

%

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose

35-40

%

Fibrous Glass

1-5

%

%

%

%

40-45 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

55-60 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart Y, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices



Bulk Material Analysis

Client:

Hazard Management Services, Inc.
Modesto Location
P.O. Box 576848
Modesto, CA 95357-6848

Client Number: 1146
Report Number: 177331
Date Received: 04/21/92

Lab Number: 19220536
Sample Number: HMS-CUSD-PRKV-77B
P.O. Num:
Job ID: Chico Unified School District
Site: Parkview

Date Collected: 04/16/92

Location: Unit G, drywall.

Gross Description: White drywall plaster with fibrous backing, fibrous weave and paint.

Comments:

Macroscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile
Amosite

Non-Det. %
Non-Det. %

Non-Det. %

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose
Fibrous Glass

30-35 %
Non-Det. %

30-35 %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

65-70 %

Janis Teichman

Janis Teichman, Director of Laboratory Services, Hayward Laboratory

Analytical method: 40 CFR 763, Subpart F, Appendix A (AHERA)

See Reverse for Explanation of Terms and Reporting Practices