

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters 2.12.

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
A	Tran Panl	Assumed	Below Windows	(1) (4)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1) (4)
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1) (4)
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	(7)
E	Ceill Plas	1-5	Staff Room	(1) (4)
E	Tran panl	Assumed	Under Windows	(1) (4)
E*	VFT blue		Staff room (storage)	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4) Rm 2 abated 7/95
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	All Rooms	(1) (4)
F	PW Cnr	1-5	RR attic	(1) (4)
G	PW Cnr	5-10	Rm 18	(1) (4) Above FCPs
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) (4)
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996  
 SCHOOL Parkview Elementary INSPECTOR Rob Peters

HOMOG. ASBESTOS  
 MAT.# MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15			MPR Stage West	(7)
H	Vent Duct connector	Assumed			Rooms off stage	(7)
H	Tran pipe	Assumed			MPR kitchen	(7)
H*	VFT Beige				MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
A	Tran Panl	Assumed	Below Windows	(1) (4)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1) (4)
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1) (4)
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	(7)
E	Ceill Plas	1-5	Staff Room	(1) (4)
E	Tran panl	Assumed	Under Windows	(1) (4)
E*	VFT blue		Staff room (storage)	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4) Rm 2 abated 7/95
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	All Rooms	(1) (4)
F	PW Cnr	1-5	RR attic	(1) (4)
G	PW Cnr	5-10	Rm 18	(1) (4) Above FCPS
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) (4)
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS  
 BLDG. MAT.#

H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR kitchen	(7)
H*	VFT Beige		MPR	(7)

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)