

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Parkview Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
A	Tran Panl	Assumed	Below Windows	(1) (4)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1) (4)
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1) (4)
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	(7)
E	Ceill Plas	1-5	Staff Room	(1) (4)
E	Tran panl	Assumed	Under Windows	(1) (4)
E*	VFT blue		Staff room (storage)	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Parkview Elementary INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4) Rm 2 abated 7/95
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	All Rooms	(1) (4)
F	PW Cnr	1-5	RR attic	(1) (4)
G	PW Cnr	5-10	Rm 18	(1) (4) Above FCPS
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) (4)
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Parkview Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR kitchen	(7)
H*	VFT Beige		MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE 2/24/99

SCHOOL Parkview Elementary

INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
A	Tran Panl	Assumed	Below Windows	(1) (4)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1) (4)
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1) (4)
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	(7)
E	Ceill Plas	1-5	Staff Room	(1) (4)
E	Tran panl	Assumed	Under Windows	(1) (4)
E*	VFT blue		Staff room (storage)	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



DISTRICT Chico Unified School District DATE 2/24/99

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4) Rm 2 abated 7/95
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	All Rooms	(1) (4)
F	PW Cnr	1-5	RR attic	(1) (4)
G	PW Cnr	5-10	Rm 18	(1) (4) Above FCPS
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) (4)
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 2/24/99

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR kitchen	(7)
H*	VFT Beige		MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

9/16/98


DISTRICT Chico Unified School District DATE December 20, 1996

SCHOOL Parkview Elementary INSPECTOR Rob Peters V.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
A	Tran Panl	Assumed	Below Windows	(1)(4)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1)(4)
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1)(4)
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	(7)
E	Ceill Plas	1-5	Staff Room	(1)(4)
E	Tran panl	Assumed	Under Windows	(1)(4)
E*	VFT blue		Staff room (storage)	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED



MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 20, 1996 9/16/99

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4) Rm 2 abated 7/95
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	All Rooms	(1) (4)
F	PW Cnr	1-5	RR attic	(1) (4)
G	PW Cnr	5-10	Rm 18	(1) (4) Above FCPS
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) (4)
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE Page 3 of 3

DISTRICT Chico Unified School District DATE December 20, 1996 9/16/99

SCHOOL Parkview Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR kitchen	(7)
H*	VFT Beige		MPR	(7)

CONDITION CODES (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 GENERAL CONDITION:

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)