

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

Inspector: Robert Baughma

District: Chico Unified School District

School: Parkview Elementary School

Building:           

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	85	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, & OFFICE CORRIDOR	(1) <i>Asbestos removed</i>	N
M	12" VFT	86	ASSUMED	3,000 S	3 OFFICES, SPEECH ROOM, & OFFICE CORRIDOR	(1) <i>Asbestos removed</i>	N
T	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4)	N

Building:           

School: Parkview Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	850 S	ROOMS 3-6 & WORKROOM	(1) REPLACED GREEN 9" VFT. (7) <i>Asbestos removed</i>	N
M	2' X 4' FCP	87	ASSUMED	3,200 S	ROOMS 3-6 & WORKROOM	(1) <i>Asbestos removed</i>	N
T	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1) (4) <i>Asbestos removed</i>	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building:

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	82	ASSUMED	800 S	MEN'S & WOMEN'S RESTROOMS	(1)	N
M	12" VFT	86	ASSUMED	400 S	ROOMS 7-10	(1) REPLACED GREEN 9" VFT. <i>Asbestos removed</i>	N
M	2' X 4' FCP	87	ASSUMED	3,600 S	ROOMS 7-10	(1)	N
T	TRANSITE PANELS	99	ASSUMED	1,000 S	BELOW WINDOWS	(1)(4) <i>Asbestos removed</i>	N

School: Parkview Elementary School

Building:

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	1-5%	1,100 S	BOY'S & GIRL'S RESTROOM WALLS & CUSTODIAN ROOM	(1)(4)	N
M	DRYWALL	83	ASSUMED	300 S	BOY'S & GIRL'S RESTROOM CEILING	(1) <i>Asbestos removed</i>	N

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building:

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	CEILING PLASTER	4	1-5%	50 S	STAFF ROOM	(1) (4) SAME 12/03/03	N
M	12" ACT	6	NONE DETECTED	2,800 S	ENTIRE WING	(13) REPRESENTED BY SAMPLE HMS-PKY-06 COLLECTED ON 4-1-88.	N/A
T	TRANSITE PANELS	99	ASSUMED	300 S	BELOW WINDOWS	(1) (4) SAME 12/03/03	N
M	LINOLEUM	100	ASSUMED	80 S	CLASSROOM 1	(7) NEW FLOOR 2003	N
M	9" VFT GREEN/WHITE	101	ASSUMED	150 S	OFFICE, HALL, & STORAGE ROOM	(12) COULD NOT FIND THIS MATERIAL. SAME 12/03/3	N
M	12" VFT	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2	7) NEW FLOOR 2003	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

# SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building:

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	13	1-5%	5,000 S	CLASSROOMS 14-17 & SER ROOM	(1) (4) Same 12/03/03	N
T	PIPE WRAP CORNER	15	1-5%	12 EACH	RESTROOM ATTIC	(1) (4) Same 12/03/03	N
M	DRYWALL	76	TRACE IN SKIM COAT	3,000 S	ALL ROOMS	(1) (4) Same 12/03/03	N
M	2' X 4' FCP'S	12	NONE DETECTED	4,500 S	CLASSROOMS 14-17 & LIBRARY	(1) SAMPLE HMS-PKV-12 COLLECTED ON 3-31-88.	N/A
M	12" ACT	97	ASSUMED	250 S	SER ROOM	(1) Same 12/03/03	N

### CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building:

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	16	NONE DETECTED	640 S	ROOMS 18-21	(13) SAMPLE HMS-PKV-16 WAS COLLECTED ON 4-1-88.	N/A
M	2' X 4' FCP'S	17	NONE DETECTED	3,800 S	ROOMS 18-21	(13) SAMPLE HMS-PKV-17 COLLECTED ON 4-1-88.	N/A
T	PIPE WRAP CORNER	18	5-10%	20 S	ROOM 18	(1) (4) ABOVE FCP'S. SAME 12/03/03	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building: \_\_\_\_\_

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	NONE DETECTED	1,200 S	KITCHEN	(1) REPRESENTED BY SAMPLES HMS-PKV-03A-F COLLECTED ON 4-1-88.	N/A
M	12" VFT RED	9	1-5%	540 S	KITCHEN (NORTH WEST CORNER)	(1) (4) SAME 12/03/03	N
M	DRYWALL	11	ASSUMED	60 S	GIRL'S & BOY'S RESTROOM	(1)	N
M	12" VFT	92	ASSUMED	1,800 S	MPR, KITCHEN, & CLOSET ON EACH END OF STAGE	(1) 7 - Asbestos Removed	N

School: Parkview Elementary School

Building: Portable 1

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	12	ASSUMED	120 S	ROOMS 11 & 11A	(1) SAME 12/03/03	N
M	2' X 4' FCP'S	14	ASSUMED	900 S	ROOMS 11 & 11A	(1) SAME 12/03/03	N

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building: Portables 12 & 1

Material Class	Material	Homo. Mat. #	% Asb.	F <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 12 & 13	THESE TWO PORTABLES WERE NOT IN OUR ORIGINAL INSPECTION. MANUFACTURES DATE UNREADABLE. BOTH HAVE 12" VFT & 2' X 4' FCP'S. DISTRICT MUST CERTIFY IF MANUFACTURE DATES FOR THESE PORTABLES ARE PAST 10-12-88.	

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**SIX MONTH SURVEILLANCE  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection 12/03/2003

District: Chico Unified School District

Inspector: Robert Baughma

School: Parkview Elementary School

Building: Portables 22-2

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLES 22-25 <b>Letters on File</b>	PORTABLES 22-25 REQUIRE CERTIFICATION. PORTABLE 22 MANUFACTURERS DATE 1995. PORTABLES 23-25 MANUFACTURERS DATE 1997.	

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**





**Forensic Analytical**  
Analytical Report

**Final FAX**

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist  
Rob Peters

2455 Carmichael Drive  
Chico, CA 95928

Client ID: 2921  
Report Number: B052332  
Date Received: 07/03/03  
Date Analyzed: 07/07/03  
Date Printed: 07/07/03

**Job ID / Site:** Parkview Elem. Chico High, *PVHS*

**FASI Job ID:** 2921-68

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
BR-2 <i>Park View</i>	10248228						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
Cellulose (40%)      Fibrous Glass (35%)

BR-3 <i>Parkview</i>	10248229						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
Cellulose (40%)      Fibrous Glass (35%)

BR-1 <i>Parkview</i>	10248230						
Layer: Stones			ND				
Layer: Tars			ND				
Layer: Felts			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
Cellulose (Trace%)      Fibrous Glass (60%)

PCF-1 <i>Chico High</i>	10248231						
Layer: Off-White Tile			ND				
Layer: Yellow Mastic			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
Cellulose (Trace%)

*C. Tracy  
Kip  
Bob - m.  
Lab.  
CSH bindles (3)  
Parkview bindles (3)  
CSH side  
Parkview side  
MHS bindles (3)  
MHS felt*



**Forensic Analytical**  
Analytical Report

**Final FAX**

# Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist  
Rob Peters

2455 Carmichael Drive  
Chico, CA 95928

**Client ID:** 2921  
**Report Number:** B052332  
**Date Received:** 07/03/03  
**Date Analyzed:** 07/07/03  
**Date Printed:** 07/07/03

**Job ID / Site:** Parkview Elem. Chico High, *PVHS*

**FA SI Job ID:** 2921-68

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
JR-1 <i>PVHS</i>	10248232						
		Layer: Off-White Sheet Flooring		ND			
		Layer: Fibrous Backing		ND			

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
Cellulose (20%)      Synthetic (15%)

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the samples tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921-68

Maintenance and Operations  
2455 Carmichael Drive  
Chico, CA 95928  
Phone: (530) 891-3195  
Fax: (530) 891-3190

# Chico Unified School District

July 2, 2003

Forensic Analytical Specialties, Inc.  
3777 Depot Road, Suite 409  
Hayward, CA 94545

Re: Parkview Elementary, Chico High, Pleasant Valley High

To Whom It May Concern:

Please test the enclosed roof samples from Parkview Elementary, Chico High and Pleasant Valley High for asbestos. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Parkview Elementary School  
Location: Bike Rack Roof  
Date Sampled: July 2, 2003  
Number of Samples: Three (#BR-1, #BR-2, #BR-3)


Site Sampled: Chico High  
Location: Floor - Portable #PC-13  
Date Sampled: July 2, 2003  
Number of Samples: One (#PCF-1)

Site Sampled: Pleasant Valley High  
Location: Unit J Restroom Floor  
Date Sampled: July 2, 2003  
Number of Samples: One (#JR-1)

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters  
Maintenance/Operations Supervisor

RP:djg  
Enclosures



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS:  2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/2/03
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	Results Needed:
		PLM: Standard / Point Count	Gravimetry Prep
CONTACT: ROIB PETERS		TEM: QUAL. / QUANT. / WATER	
P.O.#	JOB #	AA/Flame	AA/Furnace ICP
SITE: Chico High, Parkview, P.V.H.S		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
13R-2	7/2	PARKVIEW BIKE RACK ROOF
13R-3	7/2	" " " "
13R-1	7/2	" " " "
PCF-1	7/1/03	CHICO HIGH PORTABLE FLOOR PC-13
JR-1	7/1/03	P.V.H.S. P.V. RESTROOM FLOOR UNIT 5

Sampled by: ROIB PETERS	Date: 7/2/03	Time: 9:30am
Relinquished by:	Received By: [Signature]	7/3/03 109pm
Date/Time:	Date/Time:	Sealed Condition (circle one) YES / NO
Relinquished by:	Received By:	
Date/Time:	Date/Time:	Sealed Condition (circle one) YES / NO



# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Rob Peters

2455 Carmichael Drive  
Chico, CA 95928

**Client ID:** 2921  
**Report Number:** B052332  
**Date Received:** 07/03/03  
**Date Analyzed:** 07/07/03  
**Date Printed:** 07/07/03  
**First Reported:** 07/07/03

**Job ID / Site:** Parkview Elem, Chico High, *PVHS*

**FASI Job ID:** 2921-68

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
<b>BR-2 Parkview</b>	10248228						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
 Cellulose (40%)    Fibrous Glass (35%)  
 Comment: Collected on 07/02/2003

<b>BR-3 Parkview</b>	10248229						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
 Cellulose (40%)    Fibrous Glass (35%)  
 Comment: Collected on 07/02/2003


<b>BR-1 Parkview</b>	10248230						
Layer: Stones			ND				
Layer: Tars			ND				
Layer: Felts			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
 Cellulose (Trace%)    Fibrous Glass (60%)  
 Comment: Collected on 07/02/2003

*C: Mary  
Kip  
Bob M.  
Rob  
Bundles (300)  
dies (100)*

<b>PCF-1 Chico High</b>	10248231						
Layer: Off-White Tile			ND				
Layer: Yellow Mastic			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**  
 Cellulose (Trace%)  
 Comment: Collected on 07/01/2003





# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist  
Rob Peters

2455 Carmichael Drive  
Chico, CA 95928

**Client ID:** 2921  
**Report Number:** B052332  
**Date Received:** 07/03/03  
**Date Analyzed:** 07/07/03  
**Date Printed:** 07/07/03  
**First Reported:** 07/07/03

**Job ID / Site:** Parkview Elem, Chico High

**FASI Job ID:** 2921-68

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
JR-1 - 0785	10248232						
Layer: Off-White Sheet Flooring				ND			
Layer: Fibrous Backing				ND			

Total Composite Values of Fibrous Components: **Asbestos:(ND)**

Cellulose (20%) Synthetic (15%)

Comment: Collected on 07/01/2003

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



BULK SAMPLE REQUEST FORM

<b>CLIENT NAME &amp; ADDRESS:</b>  2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928	PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/2/03
	Circle the Method and Turn Around Time  24 hr/12hr/4hr/48hr/Ext	Results Needed:
	PLM: Standard / Point Count	Gravimetry Prep
	TEM: QUAL. / QUANT. / WATER AA/Flame AA/Furnace ICP	
CONTACT: ROIB PETERS		METALS:
P.O.#	JOB #	
SITE: Chico High, Parkview, P.V.H.S.		

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
13R-2	7/2	PARKVIEW BIKE RACK ROOF
13R-3	7/2	" " " "
13R-1	7/2	" " " "
PCF-1	7/1/03	CHICO HIGH PORTABLE FLOOR. PC-13
JR-1	7/1/03	P.V. RESTROOM FLOOR UNIT 5

Sampled by: ROIB PETERS	Date: 7/2/03 Time: 9:30am.
Relinquished by:	Received By: [Signature] 7/3/03 109pm
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO
	Sealed Condition (circle one) YES / NO

Maintenance and Operations  
2455 Carmichael Drive  
Chico, CA 95928  
Phone: (530) 891-3195  
Fax: (530) 891-3190

# Chico Unified School District

July 2, 2003

Forensic Analytical Specialties, Inc.  
3777 Depot Road, Suite 409  
Hayward, CA 94545

Re: Parkview Elementary, Chico High, Pleasant Valley High

To Whom It May Concern:

Please test the enclosed roof samples from Parkview Elementary, Chico High and Pleasant Valley High for asbestos. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Parkview Elementary School  
Location: Bike Rack Roof  
Date Sampled: July 2, 2003  
Number of Samples: Three (#BR-1, #BR-2, #BR-3)

Site Sampled: Chico High  
Location: Floor – Portable #PC-13  
Date Sampled: July 2, 2003  
Number of Samples: One (#PCF-1)

Site Sampled: Pleasant Valley High  
Location: Unit J Restroom Floor  
Date Sampled: July 2, 2003  
Number of Samples: One (#JR-1)

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters  
Maintenance/Operations Supervisor

RP:dlg  
Enclosures



CERTIFICATION OF COMPLIANCE FOR BUILDING MATERIALS


This is to certify, in accordance with the Environmental Protection Agency requirements, that the materials and equipment used in the construction of the: \_\_\_\_\_  
Parkview Elementary School for the Chico Unified \_\_\_\_\_ School District of Butte \_\_\_\_\_ County, California, are asbestos free and are, therefore, not subject to monitoring for asbestos contamination.

Project Name: Parkview Elementary School

Address: 1770 E. 8th  
Chico, CA 95926

Contractor: Don C. George, Inc dba George Roofing

Address: 6810 Lincoln Blvd  
Oroville, CA 95966-7716

Signature: 

Title: President

SEPARATE CERTIFICATE IS REQUIRED FOR EACH SITE